

MGARAGE(EAST) PTE LTD

23 Kaki Bukit Avenue 4 AAS Kaki Bukit Centre #04-01 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 200913013D

TO	: AXA	DATE	: 24/01/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLK1097P		
MODEL	: KIA CARENS 1.7		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 23-Jan-19
		TIME	: 12:00HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Replaced</i>	1	\$ 1,553.90	\$ 1,553.90
2	TAILGATE LOGO	1	\$ 92.00	\$ 92.00
3	TAILGATE EMBLEM 'CRDI'	1	\$ 62.00	\$ 62.00
4	TAILGATE EMBLEM 'CARENS'	1	\$ 62.00	\$ 62.00
5	TAILGATE EMBLEM 'C&C'	1	\$ 89.00	\$ 89.00
6	TAILGATE LAMP LH <i>Cracked</i>	1	\$ 760.00	\$ 760.00
7	TAILGATE INNER BOARD <i>Cracked</i>	1	\$ 680.90	\$ 680.90
8	TAILGATE LOCK <i>Replaced</i>	1	\$ 322.50	\$ 322.50
9	TAILGATE WEATHERSTRIP <i>Cracked</i>	1	\$ 260.00	\$ 260.00
10	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
11	TAILGATE NUMBER PLATE(SET) <i>new</i>	1	\$ 166.50	\$ 166.50
12	TAILGATE NUMBER PLATE GARNISH <i>Replaced</i>	1	\$ 230.00	\$ 230.00
13	TAILGATE NUMBER PLATE GARNISH CHROME <i>new</i>	1	\$ 180.00	\$ 180.00
14	REAR BUMPER <i>Replaced</i>	1	\$ 720.00	\$ 720.00
15	REAR BUMPER LOWER <i>Replaced</i>	1	\$ 410.00	\$ 410.00
16	REAR BUMPER SKID PLATE LH <i>Cracked</i>	1	\$ 190.50	\$ 190.50
17	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 89.60	\$ 179.20
18	REAR BUMPER REFLECTOR LH <i>Cracked</i>	1	\$ 198.20	\$ 198.20

1196.

425

276.

130.

157.

4.

576.

226.

139.

19	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 480.00	\$ 480.00	✓
20	REAR BUMPER REINFORCEMENT BRACKET <i>Bit Best</i>	2	\$ 122.30	\$ 244.60 122.30	✓
21	REAR BUMPER SENSOR <i>2 pieces Brgd</i>	4	\$ 211.00	\$ 844.00 422	✓
22	REAR BUMPER SENSOR RUBBER <i>new</i>	4	\$ 60.50	\$ 242.00 40	✓
23	REAR BUMPER SENSOR WIREHARNES <i>new</i>	1	\$ 388.90	\$ 388.90	✓
24	TAILLAMP LH <i>Amold.</i>	1	\$ 780.00	\$ 780.00	✓
25	REAR FENDER INNE RTRIM LH <i>new Amold</i>	1	\$ 830.50	\$ 830.50 325	✓
26	REAR END PANEL <i>Dented</i>	1	\$ 758.90	\$ 758.90	✓
27	REAR END PANEL TOP GARNISH <i>Amold</i>	1	\$ 260.50	\$ 260.50	✓
28	REAR FLOOR PANEL TOP COVER <i>new</i>	1	\$ 580.00	\$ 580.00	✓

7187
6468.30

TOTAL PRICE \$ 11,746.10
LESS 10% \$ 1,174.61
SUB TOTAL PRICE \$ 10,571.49

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new Dented</i>	1	\$ 50.00	\$ 50.00	✓
2	TAILGATE INNER BOARD CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
3	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00 60	✓
4	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
5	REAR END PANEL INSULATOR SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 60	✓
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 10	✓
7	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	✓

220

TOTAL \$ 830.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,600.00	800	
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,200.00	800	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
6	TRANSFER TAILGATE MECHANISM	\$ 120.00	80	
7	TRANSFER TAILGATE WINDSCREEN	\$ 120.00	✓	

1930

TOTAL

\$3,510.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,401.49
TOTAL LABOUR COST : \$ 3,510.00
TOTAL REPAIR COST : \$ 14,911.49

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian Lij total: 866.30
L/s 23/01/19. 4/s: 6.9K
06 Days. (6.9K)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: