

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
 SINGAPORE 528840
 TEL :67853933 FAX:67883933
 R.O.C No. 200104141D GST Reg No. 20-0104141-D

Survey 25/01
10am

TO : S7797085A
 NICOLE THAM WEI MIN (NICOLE TAN HUIMIN)
 BLK 21 PASIR RIS LINK
 01-01
 SINGAPORE 518168
 TEL: FAX :
 PH : 90613624
 ATTN :

ESTIMATE BILL

Number : EBK0000265
Date : 24/01/2019
Case No : ADK0000337
Vehicle No : SLK815R
Chassis:
Year of Mfr
Policy No
Model : KIA SORENTO 2.4(A)
 GDI HID S/R

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRT BUMPER <i>20/12</i>	1.0	709.00	10	638.10
2	FRT BUMPER CLIPS <i>12/11</i>	12.0	5.00	10	54.00
List Price - Parts Sub Total					692.10
3	FRT NUMBER PLATE W HOLDER <i>But</i>	1.0	70.00	0	70.00
Special Nett Price - Parts Sub Total					70.00
Parts Total					762.10
4	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	600.00	0 <i>150</i>	600.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	400.00	0 <i>200</i>	400.00
Labour 1 Sub Total					1,000.00
<i>not allowed labor thought before survey.</i>					
<i>2 day 25/1/19</i>					
SINGAPORE DOLLARS : ONE THOUSAND EIGHT HUNDRED EIGHTY-FIVE AND CENTS FORTY-FIVE ONLY					
Less Excess					0.00
SUBTOTAL					1,762.10
GST 7.00%					123.35
TOTAL					1,885.45

Check into Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To resurvey damaged part(s) during resurvey
 • Repair prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Date of accident : 22/01/2019 05:15 PM. Place : ALONG ROAD 1 SIMEI ST 2 CARPARK LOT 19

E. & O. E. HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE AUTHORISED SIGNATURE