

15/5/2010

INS. CASE OWNER:

CC 3/QBE1900 1698, KPH 52

LKK:  
IDAC:

Surveyor:

Kamneti

DOI:

ASSIGNMENT

24/1/19

Date / Time:

24/1/19

Registered in Merimen:

Pre-assign / CCU / FTE

6B62379J



Insured Vehicle No. :

Name of Insured :

ONE HEART CLEANING DL

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

2/1/19

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident :

If NO. Driver Name / Age : ANH PENG SOON

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

NISSAN

Place of Accident :

RACE COURSE RD TAXI STAND

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

6K65477R



INRS: TRANS  
WSP: cab  
Tel :  
Liability :  
RMKS:



INRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time

6K65477R - 4

6B62379J - 4

17-10-19

FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: ksc

Repair Cost: 43 S\$3,950

( 25 days) Reduction:

86 %

Email

Call

FINAL SETTLEMENT

Date/Time: 13.12.19

Confirm with: WAH YIN

Email

Call

Final Liability:

% 100

( Agreed / Assessed) BOLA S/N No.:

26

(operator)

If NO or B 28, Ass. Lia :

Repair Cost: 21651 S\$4,236.50

Loss of Rental (LOR):

SS 397.96

( 3 days) x 99.32

Loss of Use (LOU):

SS -

(5 x 3 days)

Loss of Income (LOI):

SS 150.00

(S 50 x 3 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIALTA Search

SS 7.44

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +400

Total:

SS 4,681.95

Global Sum S\$:

FINAL PAYMENT

Date/Time: 13.12.19

Confirm with: WAH YIN

Email

Call

Payee 1:

SS 4,681.95

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

ASS. REC. BY:

REF: QBE1


Kenneth

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Tans Cab  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 1/2 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 5433R Yr Regn: 11, 14  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Traller or \_\_\_\_\_  
 Make: Renault Longitude c.c. 1995  
 Colour: M. White / Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 547300 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VI-1ABC15AUC 279862  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: NJ / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Giti  
 Front  
 R/Bal. 9 mm  
 L/Bal. 9 mm  
 D.O.A. 22/1/19  
 Rear  
 R/Bal. 8 mm  
 L/Bal. 8 mm  
 D.O.I. 24/1/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>25/1</u>	<u>File pass to Car</u>
	<u>LI Log @ 39501</u>
	<u>(BSP: 25.016-73 86/2)</u>

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee:

Transportation:	_____
S - RS, SI	_____
Fixturs	_____
Others	_____
TOTAL	_____

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/QBE19001698/Kpb3

Date: 25.01.2019

The Motor Claims Department  
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC5433R**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.01.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	28,966.72
Revised Estimate Amount	: S\$	3,850.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
O/S Body



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 2.5 days

Yours faithfully,

**KENNETH KONG**  
**Licensed Appraiser**

**Trans-cab Auto Services Pte Ltd**

AAD1901-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5433R

*Not Authored*

*L/Imp @ 38501*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHC 5433R**  
VF1ABL15AUC279862  
RENAULT  
LATITUDE  
22.1.2019  
**QBE**  
19/11/2014

PART		LIST	
1	DOOR PANEL FRT RH	\$	<i>Btl/wing</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>Sn</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>Sn</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>N</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT RH	\$	<i>N</i> 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>Sn</i> 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Sn</i> 120.97
1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>N</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Sn</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sn</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82

X

**Trans-cab Auto Services Pte Ltd**

AAD1901-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5433R**

1	DOOR MOULDING CLIP L70Y	\$	<i>nn</i>	5.92	} X
1	DOOR MOULDING SCREW L70Y	\$	<i>nn</i>	6.91	
1	DOOR CASING REAR RH	\$	<i>sn</i>	1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	<i>sn</i>	30.39	
1	DOOR CASING CLIP	\$	<i>nn</i>	12.63	
1	DOOR CASING LIGHT L70Y	\$	<i>sn</i>	48.74	
1	DOOR FINISHER INNER REAR RH	\$	<i>sn</i>	323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>sn</i>	46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>sn</i>	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>sn</i>	20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>sn</i>	20.33	
1	DOOR GRAB HANDLE REAR RH	\$	<i>sn</i>	210.96	
1	DOOR BLIND REAR RH	\$	<i>sn</i>	741.80	
1	DOOR WHEATHESTRIP REAR RH	\$	<i>sn</i>	410.66	
1	DOOR SEAL REAR RH	\$	<i>sn</i>	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	<i>sn</i>	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>sn</i>	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	<i>sn</i>	115.64	
1	DOOR MIRROR ASSY RH	\$	<i>cm</i>	1,483.40	

\$	<b>20,094.54</b>
10% \$	<b>2,009.45</b>
\$	<b>18,085.09</b>

**Special Nett**

1	FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>nc</i>	80.00	<i>60sn</i>
1	FRONT DOOR STICKER 'CHASSIS'	\$	<i>nc</i>	50.00	<i>15sn</i>
1	REAR DOOR STICKER '6555-3333'	\$	<i>nc</i>	80.00	<i>60sn-</i>
1	DOOR CHECK BOLT	\$	<i>nn</i>	22.69	X
1	DOOR GUIDE SCREW	\$	<i>nn</i>	10.85	X
1	DOOR HINGE BOLT	\$	<i>nn</i>	10.85	X

**Trans-cab Auto Services Pte Ltd**

AAD1901-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5433R

1	DOOR HINGE NUT RH	\$	<i>nn</i> 14.60	} X
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69	
1	DOOR CHECK NUT	\$	<i>nn</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i> 10.06	

<b>TOTAL</b>	<b>\$</b>	<b>311.63</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>18,396.72</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>300/</i>
Putty and spray painting of the affected portion.	\$	4,200.00	<i>500/</i>
To rust-proofing of the affected areas.	\$	170.00	<i>30/</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>20/</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	<i>60/</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

<b>TOTAL</b>	<b>\$</b>	<b>10,570.00</b>
--------------	-----------	------------------

<b>Over All Total</b>	<b>\$</b>	<b>28,966.72</b>
-----------------------	-----------	------------------

**LUMP SUM ( REPAIR DAY)****15 DAYS***2 1/2 days*

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	387BK
<b>Vehicle Details</b>	
Vehicle No.:	SHC5433R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002140
Chassis No.:	VF1ABL15AUC279862
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	19 Nov 2014
First Registration Date:	19 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2022
PARF Rebate Amount:	\$9,373.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Nov 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,337.00
COE Rebate Amount:	\$24,523.00
<b>Total Rebate Amount:</b>	<b>\$33,896.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Jan 2019

OK

## Shu Pei (LKKAuto)

---

**From:** Joyce Foo <joyce.foo@qbe.com>  
**Sent:** Tuesday, 26 February 2019 4:55 PM  
**To:** Shu Pei (LKKAuto); Hsiao Tong (LKKAuto)  
**Subject:** RE: Direct Settlement - Accident Involving GBG2379J (OI : QBE - TBA) and SHC5433R (TP : LKK REF - CC3/QBE19001698/Kpb3 ) on 22.01.2019  
**Attachments:** GBG2379J.pdf

Our Ref. VC012278


Hi

Attached Insured's report for your retention.

Thanks & Best Regards

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: [joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Tuesday, 26 February 2019 4:28 PM  
**To:** Joyce Foo <joyce.foo@qbe.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Subject:** RE: Direct Settlement - Accident Involving GBG2379J (OI : QBE - TBA) and SHC5433R (TP : LKK REF - CC3/QBE19001698/Kpb3 ) on 22.01.2019

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joyce Foo <[joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)>

**Sent:** Tuesday, 29 January 2019 8:28 AM

**To:** Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** FW: Direct Settlement - Accident Involving GBG2379J (OI : QBE - TBA) and SHC5433R (TP : LKK REF - CC3/QBE19001698/Kpb3 ) on 22.01.2019

Our Ref. VC012278


Hi Shu Pei

FYI our insured has yet to report.

Thanks & Best Regards

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: [joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



---

**From:** Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>

**Sent:** Friday, 25 January 2019 4:49 PM

**To:** Joyce Foo <[joyce.foo@qbe.com](mailto:joyce.foo@qbe.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** Direct Settlement - Accident Involving GBG2379J (OI : QBE - TBA) and SHC5433R (TP : LKK REF - CC3/QBE19001698/Kpb3 ) on 22.01.2019

**WITHOUT PREJUDICE**

Dear Sir /Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5433R at M/s Trans-cab Auto Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----  
IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

-----  
IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE19001698/Keb3s2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 26-12-2019	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 2379J	Veh. Inspected	SHC 5433R
Policy No.		Coverage (\$)	0.00
Claim No.	VC012278	Excess (\$)	0.00
Assign From		Assign Date	24/01/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC279862	Colour	METALLIC WHITE / RED
Odometer	547300	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/01/2019	Inspection Date	24/01/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5433R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	DOOR PANEL FRT RH	BENT / WARPED	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH	TO REPAIR SEE LABOUR	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH	TO REPAIR SEE LABOUR	1,135.10	-

Report Ref No. CC3/QBE19001698/Keb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	NOT NECESSARY	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASINF LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	SERVICEABLE	115.64	-
1	DOOR MIRROR ASSY RH	CRACKED	1,483.40	1,483.40
	LESS 10% DISCOUNT		-2,009.45	-432.81
			18,085.09	3,895.25
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CHASSIS' (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-

Report Ref No. CC3/QBE19001698/Keb3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			311.61	135.00
	<b>LABOUR</b>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR HANDLE OUTER FRT RH, DOOR REGULATOR FRT RH, DOOR PANEL REAR RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK REAR RH AND DOOR REGULATOR REAR RH.		4,500.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	500.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			-	-
			-	-
			-	-
			10,570.00	910.00
	<b>GRAND TOTAL</b>		<b>28,966.70</b>	<b>4,940.25</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,950.00</b>



Report Ref No. CC3/QBE19001698/Keb3s2

A handwritten signature in black ink, consisting of the letters 'KSC' in a cursive, stylized font.

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
**No liability of responsibility whatsoever, in contact or fort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**