

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9813G**AAD1901-224***Not Notarised
L 1 Long @ 3550/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9813G

VF1ABL15AUC273090

RENAULT

LATITUDE

23.1.2019

EQ

20/8/2013

PART**LIST**

1	BUMPER COVER FRT	\$	<i>Build</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>DI</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 } X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	HEADLAMP LH	\$	<i>mgcm</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75 } X
1	RADIATOR FAN COWLING	\$	<i>SL</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>SL</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>SL</i> 1,479.46
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	AIR CLEANER BOX	\$	<i>SL</i> 464.20
1	AIR CLEANER HOSE	\$	<i>SL</i> 175.85

Trans-cab Auto Services Pte Ltd**AAD1901-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9813G

TOTAL	\$	18,891.00
10%	\$	1,889.10
	\$	17,001.90

Special Nett

1SET	BUMPER CLIP FRT	\$	na	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	} X
1	LEFT FRONT TYRE RIM	\$	su	380.00	
1	LEFT FRONT TYRE		su	300	
		\$		988.00	
TOTAL PARTS		\$		17,989.90	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	500
Putty and spray painting of the affected portion.	\$	3,000.00	700
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	20

Trans-cab Auto Services Pte Ltd**AAD1901-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9813G

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X

TOTAL	\$	9,090.00
--------------	-----------	-----------------

Over All Total	\$	27,079.90
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~*24 days*