



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2019



User ID : GohKK2

Section A - Accident Details

Registration Number	SG1762R
Case Reference Number	BUS/01/19/7024
Registration Date	18/10/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Tee Fong Kiow
Type of Accident	Side Swipe
Accident Date and Time	23/1/2019 5:13 PM
Accident Reported Date and Time	23/1/2019 5:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1762R - REAR RIGHT PORTION PC3804Y (TP) - INSURED WITH AXA.
Prepared Date and Time	24/1/2019 3:57 PM
Chassis Number	WMAA22ZZ4JF006977
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$2,654.22	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,895.22	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	24/01/2019 4:02 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00 530	
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00 324	
Total Spray Painting & Panel Beating	\$446.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010299	VE	88-25320-6008	LAMP INDICATOR LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace /	SLR
6010298	VE	88-25225-6039	LAMP STOP LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace /	SLR
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	0.00	\$235.00	Replace /	CRA
Total					\$2,650.80		\$2,409.22		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
6012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	0.00	\$245.00	Replace /	CRA
Total					245.00		0.00		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK
25/1/19

P/P 2days

Photo before paint

as