

Joy

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
#02-37 Premier @ Kaki Bukit
Singapore 415875
Tel : 94513429

2/28 4204.44

Not Allowed
Make

19/2/19

take photo before painting
3 dy.

-1

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

Date : 17.01.2019
Vehicle No. : SJP 82K
Make/Model : M/BENZ GLC 250
Chassis/Eng# :
Accident Date : 17.01.2019

Parts

01) Rear bumper	20/22 1851.32	\$	2,250.00	/
02) Rear bumper bracket @\$250.80 x 2	11	\$	501.60	X
03) Rear bumper retainer @125 x 2	11	\$	250.00	X
04) Rear bumper lower pad (Black)	22	\$	380.50	/
05) Rear bumper lower chrome	one	\$	650.80	/
06) Rear bumper reinforcement	20/22 725.10	\$	980.50	/
07) Rear end panel	2	\$	1,850.00	X
08) Rear bumper clips	22 60.00	\$	120.00	/
09) Reverse sensor 1 set	11	\$	1,000.00	X
10) Lower sensor	shrub 315	\$	850.00	122
		\$	8,833.40	
	Less 10%	\$	(883.34)	
		\$	7,950.06	

S/Nett

Labour charges

12) To check wiring	\$	200.00	50
17) To knock out dents on effected areas and renew parts	\$	1,000.00	350
18) To putty & respray painting	\$	1,200.00	400
	\$	2,400.00	

Grand Total \$ 10,350.06

for JA AUTOCARE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-378272
102
3404.44
4204.44