



Not Allowed
 2 days before
 30/1/19

P/P # 3029.94

TRANS EUROKARS PTE LTD
 NO:5 UBI CLOSE, SINGAPORE 408605
 ESTIMATE COST OF REPAIRS

EUROKARS GROUP

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Johari Bin Abdullah @Johari Bin Mahn WIP : 41535 ADDRESS : 804 Chai Chee Road #09-620 Singapore 460804 TEL : 96206477FADHIL		EXCESS : DATE: 24-Jan-19	
VEH NO :	SLZ4130C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BN22A8J0201101	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	30-Apr-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	10/2	\$ 1,074.80
2	BRACKET CENTER	1	MKD53-50-251	11	\$ 5.10
3	REAR REINFORCEMENT	1	MB45A-50-260	11	\$ 537.30
4	RETAINER, CENTER, SENSOR	2	MKD47-67-UC5A53	11	\$ 34.60
5	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 53	11	\$ 344.40
6	TAPE PROTECTOR, SENSOR	3	MGS1D-50-EM1A	11	\$ 24.30
7	RIVET, REAR BUMPER	4	MBBM4-50-355	11	\$ 16.80
8	CLIP, REAR BUMPER	2	MGJ21-50-049	11	\$ 6.40
9	FASTENER, REAR BUMPER	4	MB45A-56-146A	11	\$ 11.20
10	GROMMET, REAR BUMPER	2	M9991-00-501	11	\$ 5.60
11	GROMMET, REAR BUMPER	4	MBHN1-50-021A	11	\$ 10.00
12	GASKET LHS, TAILLAMP	1	MB45A-51-3J8	11	\$ 20.90
13	GASKET RHS, TAILLAMP	1	MB45A-51-3H8	11	\$ 20.90
TOTAL PARTS					\$ 2,112.30
LESS 10%					\$ 211.23
TOTAL PARTS COST					\$ 1,901.07
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			660 \$ 1,980.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.			630 \$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			200 NETT \$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			111X \$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120 -	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING	200	NETT \$ 800.00
8	MZ-BR-SUNDRI	SUNDRIES.	all 20	NETT \$ 100.00
			TOTAL LABOUR	\$ - \$ 5,950.00
			TOTAL PARTS	\$ - \$ 1,901.07
			TOTAL	\$ - \$ 7,851.07
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Let's Auto Consultants hence notify the Repairer of the following:

- Full body before/after spray painting
- To quote (repaired part/s) during resurvey
- All work subject to confirmation
- All work to be done on a "Without Prejudice" basis
- No cash payment is allowed
- Repaired work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____



EQ INSURANCE COMPANY LTD		NAME : Mr Johari Bin Abdullah @Johari Bin Mahn WIP :		41535
5 Maxwell Road		ADDRESS : 804 Chai Chee Road		EXCESS :
#17-00 Tower Block		#09-620		DATE: 24-Jan-19
MND Complex, Singapore 069110		Singapore 460804		
ATTN :	MOTOR CLAIMS	TEL :	96206477FADHIL	
FAX :				
VEH NO :	SLZ4130C	DATE IN :		CONTACT PERSON : Ronald 63957875
CHASSIS NO :	JM68N22A8J0201101	MILEAGE :		TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	30-Apr-18	POLICY NO. :

NATURE OF WORKS

NO	Parts Description		REVISED	PRICES
	QTY			
1	REAR BUMPER	1		
2	BRACKET CENTER	1	\$ 1,074.80	\$ 1,074.80
3	REAR REINFORCEMENT	1		\$ 5.10
4	RETAINER, CENTER, SENSOR	2		\$ 537.30
5	SENSOR CENTER, ULTRASONIC	2		\$ 34.60
6	TAPE PROTECTOR, SENSOR	3		\$ 344.40
7	RIVET, REAR BUMPER	4		\$ 24.30
8	CLIP, REAR BUMPER	2	\$ 16.80	\$ 16.80
9	FASTENER, REAR BUMPER	4	\$ 6.40	\$ 6.40
10	GROMMET, REAR BUMPER	2	\$ 11.20	\$ 11.20
11	GROMMET, REAR BUMPER	4	\$ 5.60	\$ 5.60
12	GASKET LHS, TAILLAMP	1	\$ 10.00	\$ 10.00
13	GASKET RHS, TAILLAMP	1	\$ 20.90	\$ 20.90
			\$ 20.90	\$ 20.90
		TOTAL PARTS	\$ 1,166.60	\$ 2,112.30
		LESS 10%	\$ 116.66	\$ 211.23
		TOTAL PARTS COST	\$ 1,049.94	\$ 1,901.07

Labour Description

		Work Description		
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,980.00
2		TO RESPRAY REAR BUMPER.	\$ 630.00	\$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 200.00	\$ 330.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00

6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING	\$ 200.00	\$ 800.00
8	MZ-BR-SUNDRI	SUNDRIES	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 1,980.00	\$ 5,950.00
TOTAL PARTS			\$ 1,049.94	\$ 1,901.07
TOTAL			\$ 3,029.94	\$ 7,851.07
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,029.94	
GST 7%			\$ 212.10	\$ -
GRAND TOTAL			\$ 3,242.04	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)