

ASS. REC. BY:

REF

CT119001723 / Kv d3

n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Chong Ben Sun

of

CT1

Date/Time:

25/1/19 @ 11.23am

Estimated Cost:

Bill to:

OD (TP/WS/TP RES / OD RES / EVA / INV / MV) CS

To Inspect Vehicle No:

SKX 4259M

Insured:

SKX 9538A

at Workshop m/s

Ah Lim Motor

Tel:

64831244

of

No.10 AMK Ind. park 2A #01-09

Policy No:

DMPC SN 31225318022

Claim No:

SNM 190200419C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/01/2019

CA / REV / REP. / REV 24 HRS

'up'

28/1/19 @ 1030am

H.O.D. Endorsement:

Date/Time:

11.36am 25/1/19

Person Contacted:

Zila

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKX 4259M -X

SKX 9538A -X

28/2/19

@ 306pm Mui Hong said vehicle just released, will email finalise when ready

23/4/19

82578.36 email confirmed by email (Red 4041.04, 6/9/19) (No LS)

REF: CT1

ASSIGNMENT

From: Date: 28/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 8KX 4259M

at Workshop m/s

of 10 AMK Ind. park 2A # 01-09

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10:30am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4-5 days Res: Yes or No

Lump Sum: 1-131 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SKX 4259M

12 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda A) Vozel

G.C.

1488

Colour:

A. Maroon

A/C

Insured / Std / NI / NA

Sp. Reading

60236

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1107633

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

7

L/Bal.

7

D.O.A.

22/1/19

D.O.I.

28/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 APR 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 25/4 - typist

Report Format:

Lump Sum / I.B.I. / I.S.

merimen

2576.36

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fees:

Transportation

) S + RS. St

) Photos

) Films

) ...

TOTAL

220

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2019		02 Apr 2019 10:41 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	TEO ENG KIONG , ID: S7526662F
Vehicle Reg. No.:	SKX4259M
Claim Type:	TP / SNM19D200419C02
Vehicle Reg. No. (Insured):	SKX9538A
Date of Loss:	22/01/2019 07:00 - :59
Policy/Cover Note No.:	DMPCSN31225318022
Policy No. (Claimant):	GA283498
Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/04/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: muihong@ahlimmotor.com.sg
Sent: Tuesday, 23 April 2019 11:01 AM
To: Kenneth Kong (LKKAUTO)
Subject: Re: Draft Finalisation - SKX4259M

Dear Kenneth,

Noted and will submit as such

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: Kenneth Kong (LKKAUTO)
Sent: Tuesday, April 23, 2019 8:20 AM
To: muihong@ahlimmotor.com.sg
Subject: RE: Draft Finalisation - SKX4259M

Attach finalised for SKX 4259M. Kenneth

From: muihong@ahlimmotor.com.sg [mailto:muihong@ahlimmotor.com.sg]
Sent: Monday, 22 April, 2019 5:50 PM
To: Kenneth Kong (LKKAUTO); Veron Chen (LKKAUTO)
Subject: Draft Finalisation - SKX4259M

Dear Kenneth / Veron,

Pls see attached the Draft Finalisation – SKX4259M for your approval.

Pls advise.

Thanks

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint

Singapore 568047

Tel : 64831244 Fax : 64836170

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 25 January 2019 11:23 AM
To: assignments
Subject: FW: TP / OUR CLIENT SKX4259M DOA: 22/01/2019 POLICY NO. GA283498 YOUR INSURED SKX9538A
Attachments: 4259 - AXA.PDF; 4259.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Friday, 25 January 2019 11:22 AM

To: zila <zila@ahlimmotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: TP / OUR CLIENT SKX4259M DOA: 22/01/2019 POLICY NO. GA283498 YOUR INSURED SKX9538A

Without Prejudice

Dear Zila,

We will appoint LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore)

Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: zila [mailto:zila@ahlimmotor.com.sg]

Sent: Friday, 25 January, 2019 9:12 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: TP / OUR CLIENT SKX4259M DOA: 22/01/2019 POLICY NO. GA283498 YOUR INSURED SKX9538A

Hi,

We choose Kenneth Kong to be the surveyor.
Thanks.

Best Regards,

Zila

Ah Lim Motor

Tel: 64831244 Fax: 64836170

On 25/01/2019 8:43 AM, Chong Boon Sen wrote:

> *Without Prejudice*

>

> Dear Sirs

>

> We intend to conduct a pre-repair survey of the damage to your
> client's vehicle jointly with your client/your motor workshop. We
> propose to use one of the following motor surveyors to conduct the
> joint pre-repair survey as a single joint expert.

>

> ADRIAN LING

>

> Kelvin Ang

>

> SEE CHEW SENG

>

> MOHD FADHILAH BIN OSMAN

>

> XING QUO QIANG

>

> KENNETH KONG

>

> SIMON HO

>

> CHUA WEIJIE

>

> MARCUS CHUA

>

> HENRY NG

>

>

> Please let us know within two(2) working days whether you agree to the
> appointment of any of these motor surveyors as a single joint expert.

>

> You may select one of the listed motor surveyors and we will bear the
> cost of the pre-repair survey carried out by the single joint expert.
>
> **Thank you.
>
> Regards,
>
> */_Chong Boon Sen_**/_/_/*
>
> Claims Executive
>
> Claims
>
> *China Taiping Insurance (Singapore) Pte. Ltd.*
>
> 3 Anson Road #16-00 Springleaf Tower
>
> Singapore 079909
>
> Co. Reg. No. 200208384E
>
> DID: 63896171
>
> Fax: 62247175
>
> Email: boonsen.chong@sg.cntaiping.com
>
> Website: www.sg.cntaiping.com
>
> /Disclaimer : ///
>
> /This message is confidential; its contents do not constitute a
> commitment by China Taiping Insurance (Singapore) Pte. Ltd. except
> where provided for in a written agreement between you and China
> Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure,
> use or dissemination, either in whole or partial, is prohibited. If
> you are not the intended recipient of the message, please notify the
> sender immediately. /
>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6662F

Vehicle Details

Vehicle No.:

SKX4259M

Vehicle to be Exported:

No

Intended Deregistration Date:

22 Jan 2019

Vehicle Make:

HONDA

Vehicle Model:

VEZEL 1.5X A

Primary Colour:

Red

Manufacturing Year:

2015

Engine No.:

L15B4027637

Chassis No.:

RU11107633

Maximum Power Output:

96.0 kW (128 bhp)

Open Market Value:

\$19,503.00

Original Registration Date:

11 Dec 2015

First Registration Date:

11 Dec 2015

Transfer Count:

0

Actual ARF Paid:

\$9,503.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

10 Dec 2025

PARF Rebate Amount:

\$7,127.00

Intended COE Rebate Details

COE Expiry Date:

10 Dec 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$56,001.00

COE Rebate Amount:

\$38,542.00

Total Rebate Amount:

\$45,669.00

The information contained herein is correct as at 22 Jan 2019

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TEO ENG KIONG
 BLK 295 PUNGGOL CENTRAL
 #11-517
 SINGAPORE 820295
 TEL: 98416695

ATTN:

Your Ref No: SKX4259M

Claim Type: Third Party - CHINA TAIPING

Accident Date: 22/01/2019

TP Veh Reg No: SKX9538A

Estimate No: MC1900083

Date: 24 Jan 2019

Policy No: GA283498

Veh Reg No: SKX4259M

Make/Model: HONDA VEZEL 1.5X A

Not Authored

Running by paint

4-5 days

Estimate Repair Cost to Vehicle No :SKX4259M

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	✓
2 TAILGATE	1 PC	972.40	✓
3 TAILGATE ABSORBER	2 PC	360.00	X
4 TAILGATE EMBLEM	1 PC	15.70	X
5 TAILGATE LOGO (VEZEL) LH	1 PC	43.00	✓
6 TAILGATE LAMP	2 PC	529.20	X
7 TAILGATE REVERSE CAMERA	1 PC	597.30	X
8 TAILGATE INNER LOCK	1 PC	157.00	✓
9 TAILGATE INNER TRIMBOARD	1 PC	153.40	✓
10 TAILGATE RUBBER (AT BODY)	1 PC	96.80	✓
11 TAILGATE INNER SIDE HOLDER COVER RH - CHECK PRICE	1 PC	0.00	✓
12 REAR BUMPER	1 PC	463.70	✓
13 REAR BUMPER SIDE RETAINERS	2 PC	35.00	X
14 REAR BUMPER CLIPS	12 PC	45.60	✓
15 REAR BUMPER LOWER REFLECTOR	2 PC	282.20	X
16 REAR END PANEL	1 PC	411.90	✓
17 REAR END PANEL TOP GARNISH	1 PC	92.30	✓
18 SPARE TYRE LOWER OUTER COVER BIG	1 PC	190.00	✓
		4,565.50	
	Less 20%	913.10	3,652.40
Special Nett			
19 NUMBER PLATE → (Rear)	1 PC	35.00	X
20 REVERSE SENSOR	1 SET	200.00	X
21 WINDSCREEN SEALANT	1 PC	60.00	40.50 ✓
22 INNER SEAL	1 PC	40.00	30.50 ✓
23 END PANEL TOP GARNISH ALUMINIUM PLATE - CHECK PRICE	1 PC	0.00	✓
24 TRANSFORMER LOGO - CHECK PRICE	1 PC	0.00	✓
		335.00	335.00
LABOUR			
25 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15 ✓
26 TO REMOVE & INSTALL REAR CAMERA RECORDER	1 PC	60.00	50 ✓
27 TO REMOVE AND REINSTALL/REPLACE FRONT REAR WINDSCREEN.	1 PC	150.00	120 ✓
28 TO REPLACE REAR REVERSE CAMERA	1 PC	80.00	X



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TEO ENG KIONG
 BLK 295 PUNGGOL CENTRAL
 #11-517
 SINGAPORE 820295

TEL: 98416695

ATTN:

Your Ref No: SKX4259M

Claim Type: Third Party

Accident Date: 22/01/2019

TP Veh Reg No: SKX9538A

Estimate No: MC1900083
Date: 24 Jan 2019
Policy No: GA283498
Veh Reg No: SKX4259M
Make/Model: HONDA VEZEL 1.5X A

Estimate Repair Cost to Vehicle No :SKX4259M

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
29 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	X
30 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	50 ✓
31 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50 ✓
32 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	100.00	X
33 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	100.00	X
34 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL, REAR BUMPER TOR SIDE SMALL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	? ✓ 400
35 TO SPRAY TAILGATE,END PANEL,SPARE TYRE PANEL, REAR BUMPER TOP SIDE SMALL.	1 PC	800.00	? ✓ 220
	6617.40	2,470.00	2,470.00
	Total		S\$ 6,457.40
		Add GST @ 7%	452.02
		Total Amount Payable	S\$ 6,909.42

TOTAL: SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED AND NINE AND CENTS FORTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver:
 Signature:
 Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TEO ENG KIONG
BLK 295 PUNGGOL CENTRAL
#11-517
SINGAPORE 820295
TEL: 98416695
ATTN:

Estimate No: MC1900083
Date: 24 Jan 2019
Policy No: GA283498
Veh Reg No: SKX4259M
Make/Model: HONDA VEZEL 1.5X A

Your Ref No: SKX4259M
Claim Type: Third Party - *CHINA*
Accident Date: 22/01/2019 *TODAY*
TP Veh Reg No: SKX9538A

10.30
10.30
10.30

Not Authorise PIP
Recovery 84 paint
10.45 AM
4-5 days

Estimate Repair Cost to Vehicle No :SKX4259M

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	<i>mu</i> 120.00	✓
2 TAILGATE	1 PC	<i>B1</i> 972.40	✓
3 TAILGATE ABSORBER	2 PC	<i>mu</i> 360.00	X
4 TAILGATE EMBLEM	1 PC	<i>mu</i> 15.70	X
5 TAILGATE LOGO (VEZEL) LH	1 PC	<i>mu</i> 43.00	✓
6 TAILGATE LAMP	2 PC	<i>mu</i> 529.20	X
7 TAILGATE REVERSE CAMERA	1 PC	<i>mu</i> 597.30	X
8 TAILGATE INNER LOCK	1 PC	<i>mu</i> 157.00	✓ <i>Photo</i>
9 TAILGATE INNER TRIMBOARD	1 PC	<i>mu</i> 153.40	?
10 TAILGATE RUBBER (AT BODY)	1 PC	<i>mu</i> 96.80	?
11 TAILGATE INNER SIDE HOLDER COVER RH - CHECK PRICE	1 PC	<i>mu</i> 0.00	?
12 REAR BUMPER	1 PC	<i>B1</i> 463.70	✓
13 REAR BUMPER SIDE RETAINERS	2 PC	<i>mu</i> 35.00	X
14 REAR BUMPER CLIPS	12 PC	<i>mu</i> 45.60	✓
15 REAR BUMPER LOWER REFLECTOR	2 PC	<i>mu</i> 282.20	X
16 REAR END PANEL	1 PC	<i>mu</i> 411.90	?
17 REAR END PANEL TOP GARNISH	1 PC	<i>mu</i> 92.30	?
18 SPARE TYRE LOWER OUTER COVER BIG	1 PC	<i>mu</i> 190.00	?
		4,565.50	
		Less 20%	913.10
			3,652.40
Special Nett			
19 NUMBER PLATE <i>→ (Recon)</i>	1 PC	<i>mu</i> 35.00	X
20 REVERSE SENSOR	1 SET	<i>mu</i> 200.00	X
21 WINDSCREEN SEALANT	1 PC	<i>mu</i> 60.00	40.00
22 INNER SEAL	1 PC	<i>mu</i> 40.00	30.00
23 END PANEL TOP GARNISH ALUMINIUM PLATE - CHECK PRICE	1 PC	<i>mu</i> 0.00	2.00 <i>Photo</i>
24 TRANSFORMER LOGO - CHECK PRICE	1 PC	<i>mu</i> 0.00	✓
		335.00	335.00
LABOUR			
25 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
26 TO REMOVE & INSTALL REAR CAMERA RECORDER	1 PC	60.00	50/
27 TO REMOVE AND REINSTALL / REPLACE FRONT REAR WINDSCREEN.	1 PC	150.00	120/
28 TO REPLACE REAR REVERSE CAMERA	1 PC	<i>mu</i> 80.00	X



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 368047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TEO ENG KIONG
BLK 295 PUNGGOL CENTRAL
#11-517
SINGAPORE 820295
TEL: 98416695

Estimate No: MC1900083
Date: 24 Jan 2019
Policy No: GA283498
Veh Reg No: SKX4259M
Make/Model: HONDA VEZEL 1.5X A

ATTN:
Your Ref No: SKX4259M
Claim Type: Third Party
Accident Date: 22/01/2019
TP Veh Reg No: SKX9538A

Estimate Repair Cost to Vehicle No :SKX4259M

Description	Quantity	List Price	Amount
		S\$	S\$
29 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	?
30 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	501
31 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	501
32 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	100.00	?
33 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	100.00	X
34 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL, REAR BUMPER TOR SIDE SMALL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	?
35 TO SPRAY TAILGATE, END PANEL, SPARE TYRE PANEL, REAR BUMPER TOP SIDE SMALL.	1 PC	800.00	?
		2,470.00	2,470.00
	Total		S\$ 6,457.40
	Add GST @ 7%		452.02
	Total Amount Payable		S\$ 6,909.42

TOTAL: SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED AND NINE AND CENTS FORTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by: *For: driver*
Signature:
Date:

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore-568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : TEO ENG KIONG
 BLK 295 PUNGGOL CENTRAL
 #11-517
 SINGAPORE 820295
 TEL: 98416695
 ATTN:
 Your Ref No: SKX4259M
 Claim Type: Third Party
 Accident Date: 22/01/2019
 TP Veh Reg No: SKX9538A

Claim No: MC1900083
 No: MF1900191
 Date: 22 Apr 2019
 Policy No: GA283498
 Veh Reg No: SKX4259M
 Make/Model: HONDA VEZEL 1.5X A

82576.36

4 day

Repair Cost to Vehicle No (For Finalization):SKX4259M

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	120.00	
2 TAILGATE	1 PC	972.40	
3 TAILGATE LOGO (VEZEL) LH	1 PC	43.00	
4 TAILGATE INNER LOCK	1 PC	157.00	
5 REAR BUMPER	1 PC	463.70	
6 REAR BUMPER CLIPS	12 PC	45.60	
		1,801.70	
	Less 20%	360.34	1,441.36
Special Nett			
7 WINDSCREEN SEALANT	1 PC	40.00	
8 INNER SEAL	1 PC	30.00	
9 END PANEL TOP GARNISH ALUMINIUM PLATE	1 PC	150.00	
10 TRANSFORMER LOGO	1 PC	10.00	
		230.00	230.00
LABOUR			
11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
12 TO REMOVE & INSTALL REAR CAMERA RECORDER	1 PC	50.00	
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
14 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	50.00	
15 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
16 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL, REAR BUMPER TOR SIDE SMALL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC 400	800.00	→ plz advise
17 TO SPRAY TAILGATE,END PANEL,SPARE TYRE PANEL, REAR BUMPER TOP SIDE SMALL.	1 PC 220	800.00	→ plz advise
		1,885.00	1,885.00

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore-568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : TEO ENG KIONG
BLK 295 PUNGGOL CENTRAL
#11-517
SINGAPORE 820295
TEL: 98416695
ATTN:
Your Ref No: SKX4259M
Claim Type: Third Party
Accident Date: 22/01/2019
TP Veh Reg No: SKX9538A

Claim No: MC1900083
No: **DRAFT** MF1900191
Date: 22 Apr 2019
Policy No: GA283498
Veh Reg No: SKX4259M
Make/Model: HONDA VEZEL 1.5X A

Repair Cost to Vehicle No (For Finalization):SKX4259M

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
		Total	SS 3,556.36
		Less Excess	SS 0.00
		Amount Before GST	SS 3,556.36
		Add GST @ 7%	248.95
		Total Amount Payable	SS 3,805.31

TOTAL: SINGAPORE DOLLAR THREE THOUSAND EIGHT HUNDRED AND FIVE AND CENTS THIRTY ONE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 28/01/2019

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001723/KVD3N2

Date: 30/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN31225318022
Claimant Vehicle No :	SKX4259M	Insured Vehicle No :	SKX9538A
Date of Loss:	22/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200419C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4259M	Engine No:	L15B4027637
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11107633
Reg. Date:	11/12/2015 (Man. Year: 2015)	Odometer:	60236 km
Colour:	Metallic Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R19	Rear Tyre Size:	225/45R19
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,147.40	1,671.36	2,476.04	59.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	905.00	1,565.00	63.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,617.40	2,576.36	4,041.04	61.07
+ GST 7.00/7.00% (S\$)	463.22	180.35	282.87	61.07
Nett Amount (S\$)	7,080.62	2,756.71	4,323.91	61.07

INSPECTION

Date of Assignment:	02/04/2019	
Date Inspected:	28/01/2019 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Apr 2019)	
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKX4259M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
2	1	*TAILGATE	Bent	972.40 FL	*972.40 FL
3	2	*TAILGATE ABSORBER	Serviceable	360.00 FL	*- FL
4	1	*TAILGATE EMBLEM	Not Necessary	15.70 FL	*- FL
5	1	*TAILGATE LOGO (VEZEL) LH	Necessary	43.00 FL	*43.00 FL
6	2	*TAILGATE LAMP	Serviceable	529.20 FL	*- FL
7	1	*TAILGATE REVERSE CAMERA	Serviceable	597.30 FL	*- FL
8	1	*TAILGATE INNER LOCK	Dented	157.00 FL	*157.00 FL
9	1	*TAILGATE INNER TRIMBOARD	Serviceable	153.40 FL	*- FL
10	1	*TAILGATE RUBBER (AT BODY)	Serviceable	96.80 FL	*- FL
11	1	*TAILGATE INNER SIDE HOLDER COVER RH (NPA)	Serviceable	0.00 FL	*- FL
12	1	*REAR BUMPER	Bent	463.70 FL	*463.70 FL
13	2	*REAR BUMPER SIDE RETAINERS	Serviceable	35.00 FL	*- FL
14	12	*REAR BUMPER CLIPS	Necessary	45.60 FL	*45.60 FL
15	2	*REAR BUMPER LOWER REFLECTOR	Serviceable	282.20 FL	*- FL
16	1	*REAR END PANEL	Repair	411.90 FL	*- FL
17	1	*REAR END PANEL TOP GARNISH	Serviceable	92.30 FL	*- FL
18	1	*SPARE TYRE LOWER OUTER COVER BIG	Serviceable	190.00 FL	*- FL
19	1	*NUMBER PLATE (REAR)	Serviceable	35.00 FS	*- FS
20	1	*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
21	1	*WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
22	1	*INNER SEAL	Necessary	40.00 FS	*30.00 FS
23	1	*END PANEL TOP GARNISH ALUMINIUM PLATE	Necessary	150.00 FS	*150.00 FS
24	1	*TRANSFORMER LOGO	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,060.50	2,031.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	913.10	360.34
Total Parts (\$\$)	4,147.40	1,671.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO REMOVE & INSTALL REAR CAMERA RECORDER	New	60.00	50.00
3	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	150.00	120.00
4	TO REPLACE REAR REVERSE CAMERA	New	80.00	0.00
5	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	0.00
6	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	80.00	50.00
7	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS	New	80.00	50.00
8	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	100.00	0.00
9	TO REALIGN,DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE	New	100.00	0.00
10	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL,REAR BUMPER TOR SIDE SMALL INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
11	TO SPRAY TAILGATE,END PANEL,SPARE TYRE PANEL,REAR BUMPER TOP SIDE SMALL	New	800.00	220.00
Gross Labour Cost (S\$)			2,470.00	905.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >