•	not i	Andrew!
ACTECHAN		ble.
ASTECH AU	IOPIELTD	1
BLK1 KAKI BL	1 \ 10 7	16001 11
#01 <b>-</b> 46/48/50 /		1 /20/18
SINGAPORE	417883	07,12/11
EHICLE NO:SO	SU 71B	
YTC	PARTICULAR	
I PCS	BOOTLID	↑ \$1,455.10
1 PCS	BOOTLID REAR LOGO	rec \$68.50_
1 PCS	BOOTLID 'CAMRY' EMBLEM	NU \$66.20
PCS	BOOTLID 'HYBRID' EMBLEM	Mc \$85.90
PCS	BOOTLID '2.0' EMBLEM	nu \$58.00
PCS	BOOTLID 'HYBRID SYNERGY DRIVE' EMBLEM	nn \$85.00
PCS	BOOTLID REFLECTORS @\$681.10	11 \$1,362.20 🔀
I PCS	BOOTLID INNER LOCK	17 \$399.50 ×
I PCS	BOOTLID WEATHERSTRIP	Tw/ \$315.10
I PCS	REAR BUMPER 699.10	\$898.10
I PCS	REAR BUMPER REINFORCEMNT	\$415.50
2 PCS	REAR BUMPER SIDE RETAINERS @\$145.00	Sel \$290.00
SET	REAR BUMPER CLIPS	un \$50.00
I PCS	REAR BUMPER LOWER SKIRTING	of ni \$850.00_
2 PCS	REAR BUMPER REFLECTORS @\$105.00	17 \$210.00 X
1 PCS	REAR END PANEL	\$815.10
1 PCS	REAR END PANEL TOP GARNISH	4m/ \$499.50
PCS	TAILLAMPS @\$850.00	CN \$1,700.00
1 PCS	REAR EXHAUST  DEAR ELOOP PANEL TOP BOARD  252	\$1,021.10
1 PCS	REAR FLOOR PANEL TOP BOARD	17 \$411.50 CX
	CIA C	\$11,056.30
	S. NETT SIEZE	5 hold \$380.00 200
SET	REAR BUMPER REVERSE SENSOR	11 \$50.00 ×
I PCS	REAR END PANEL SEALANT	12 \$250.00
SET	REAR FLOOR PANEL INSULATOR	7/1 \$250.00
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00
	TO DISMANTLE & REFIX BOOTLID MECHANISM	1 n \$120.00 X
	TO DISMANTLE & REFIX SEAT , CUSHION UPHOLSTREY	\$100.00 80
	TO DISMANTLE & REFIX REAR EXHAUST	1 100.00 €
	AND A CONTRACTOR OF THE PROPERTY OF THE PROPER	\$120.00 50
	TO SPRAY RUST PROOFING LABOUR FOR PANEL BEATING & REPLACING PARTS	the second secon
	A CONTRACTOR OF THE PROPERTY O	\$1,200.00
	TO PUTTY & SPRAY PAINTING	\$1,500.00 PDO TO \$15,036.30
The second secon	LKK Auto Consultants hence notify	
	the Repairer of the following:  • To resurvey before after spray painting  • To display damaged part(s) during resurvey  • Parts prices are subject to confirmation  • Third party survey is on a "Without Prejudice" basis  • No illegal modification(s) is allowed  • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$7.93·1
	Acknowledged by Repairer Signature;	