

22/03/2002

ASS. REC. BY:

REF: CS/FCL19001764/R1sd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

CWS Henry Kuo

of

FCL

Date/Time:

28/01/2019 932am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMH 3675L

Insured:

SHA 8910X

at Workshop m/s

TTS Eurocars

Tel:

of

383 Sin ming Drive

Policy No:

Claim No:

D19000688mfsy

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

335 Smith St Chinatown

Complex Level 4

23/01/2019

CA / REV / REP. / REV 24 HRS 'wp'

20-01-2019 @ 2pm - 3pm

Midm Tun - 9792 7754

H.O.D. Endorsement:

Date/Time:

28/01/2019 1025am

Person Contacted:

Kavi

Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | SMH 3675L - X |
| | SHA 8910X - CS / INC 08031815 / Kedi |
| 31/01/19 | @ 17:53 p.m. received RA to Henry Kuo via email. |
| | |
| | |
| | |

DPA: 01/02/2008

Form

REF:

4751A

ASSIGNMENT

From: _____ Date: _____ Vch No: **SMH 3675L** Yr Regn: **2019 JAW**

Estimated Cost: _____ Type: **MC** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

OD: **TP** / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SMH 3675L** Make: **B.M.W 218I** C.C: **1499**

at Workshop m/s Colour: **WHITE** A/C: Insured / Std / NI / NA

of **335, Smith ST - CHINA TOWN complex** Sp. Reading: **00668** T/Radio: Insured / Std / NI / NA

Insured: **Level 4 FCI** Eng/No: _____

Policy No. C/No: **WBA 20320305 J58506**

Claims No. Gen. Cond: Good / **Fair** / Poor / Burnt

Sum Insured: _____ Excess: _____ Steering: **Inorder** / Jammed / Leaked / Burnt or

(Client's Record) Brake: **Inorder** / Jammed / Leaked / Burnt or

Make of Veh: _____ Modi: Nil / **S/Rim** / STD A/Rim or

Mdm TAN @ 9792754 Tyre Size F: **245/45R18**
(Policy Condition) R: **2'**

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Continental**

Front Rear

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **23/01/19** D.O.I. **30/01/19**

Survey held at **335, SMITH ST**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **0/8 FRT**

The U/C / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

| Date / Time | Action / Instruction |
|-------------|--|
| 05/03/19 | Confirmed P/P \$ 5,436.93 @ 4 days with Resul (\$ 4,682.10 Red - 46%) |

RECEIVED 07 MAR 2019

Date/Time, File Pass to? ☐ : Preli. Report
07/03/19
1) Typ 4 ☒ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.F. (\$) **5,436.93 dp**

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

| | |
|----------------|-----|
| Survey Fee | 170 |
| Transportation | 50 |
| 3 + RS | 50 |
| Photos | 41 |
| Other | |
| TOTAL | 311 |

MOTOR SURVEY ASSIGNMENT

| | | |
|---------------------------|-------------------------------|-------------------------------------|
| Date | 25-01-2019 | Our Ref No. D19000688MFSH |
| Accident Date | 23-01-2019 | Claim Type. Third Party |
| Insured Vehicle | SHA8910X | Third Party Vehicle. SMH3675 |
| Survey Location | TTS CENTRE 383 SIN MING DRIVE | |
| Contact Person. | KAVI | |
| Contact No. | 82927422/ 0 | Fax No. 67411626 |
| Survey Type | WITHOUT PREJUDICE: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|--------------------------|----------------------|--------------------------------|
| Cc : Workshop | TTS EUROCARS PTE LTD | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | HENRY KAO | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

| | |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 4751A |

Vehicle Details

| | |
|-------------------------------|-----------------------------|
| Vehicle No.: | SMH3675L |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 31 Jan 2019 |
| Vehicle Make: | B.M.W. |
| Vehicle Model: | 218I SPORT GRAN TOURER AUTO |
| Primary Colour: | White |
| Manufacturing Year: | 2017 |
| Engine No.: | 31889960B38A15A |
| Chassis No.: | WBA2D320305J58506 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$32,205.00 |
| Original Registration Date: | 21 Jan 2019 |
| First Registration Date: | 21 Jan 2019 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$37,087.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 20 Jan 2029 |
| PARF Rebate Amount: | \$27,815.00 |

Intended COE Rebate Details

| | |
|-----------------------------|----------------------------------|
| COE Expiry Date: | 20 Jan 2029 |
| COE Category: | E - Open - all except motorcycle |
| COE Period(Years): | 10 |
| QP Paid: | \$32,909.00 |
| COE Rebate Amount: | \$32,104.00 |
| Total Rebate Amount: | \$59,919.00 |

The information contained herein is correct as at 30 Jan 2019

OK

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 7 March 2019 11:32 AM
To: kavi@tts.com.sg; shabir@tts.com.sg
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SMH3675K - FINALISE

Hi Kavi,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Kavi [mailto:kavi@tts.com.sg]

Sent: Thursday, 7 March, 2019 11:12 AM

To: shabir@tts.com.sg; Rasul (LKKAuto)

Subject: RE: SMH3675K - FINALISE

Dear Rasul,

Please find attached amended invoice.

Repair cost \$5436.93 before GST.

Repair days 04

Please confirm

Regards,

Ms. Kavi

Motor Claims Officer

-----Original Message-----

From: Shabir [mailto:shabir@tts.com.sg]

Sent: 27 February, 2019 4:09 PM

To: rasul@lkkauto.com

Cc: kavi@tts.com.sg

Subject: SMH3675K - FINALISE

Hi Rasul,

Refer to attached finalise invoice.

Repair cost \$4,681.24 before GST.

Repair days 04

Please confirm

Best Regards
Mohamed Shabir
After Sales Manager

We are committed to the preservation of the environment. Please print this email only if it is absolutely necessary.

TTS Motor Group Pte Ltd (Co Reg No: 198702999Z) TTS Eurocars Pte Ltd (Co Reg
No: 200413930H)

383 Sin Ming Drive TTS Centre Singapore 575717

Tel: (65) 6462 1111 Ext123 Fax: (65) 6741 1626

Email: shabir@tts.com.sg Website: www.tts.com.sg

Disclaimer: The information contained in this email, including any attachments, may contain confidential information of TTS Motor Group Pte Ltd / TTS Eurocars Pte Ltd. This email is intended only for the use of the addressee(s) listed above. Unauthorized review, dissemination or any other use of the information contained in this email is strictly prohibited. If you have received this email in error or have reason to believe that you are not authorized to receive it, please notify the sender by return email and promptly delete this email .****

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 31 January 2019 5:53 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: 'assignments'; 'SUR'; 'Admin-D (LKKAuto)'
Subject: RE: SURVEY ASSESSMENT - D19000688MFSH/1
Attachments: SMH 3675L - Preli Advise.pdf

Dear Henry,

Enclosed preliminary revised of vehicle SMH 3675L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 28 January 2019 10:28 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000688MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 28 January, 2019 9:32 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000688MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000688MFSH

Date: 31 January 2019

Our Ref: CS/FCI19001764/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMH 3675L.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/01/2019 at the premises of M/s TTS Eurocars Pte Ltd and have the following to report:-

| | |
|--------------------------|------------------------|
| Workshop Estimate Amount | : <u>S\$ 10,119.03</u> |
| Revised Estimate Amount | : <u>S\$ 5,370.43</u> |
| "Check" Items Amount | : <u>S\$ 1,771.35</u> |
| Market Value | : <u>S\$</u> |
| LTA Reimbursement Value | : <u>S\$</u> |
| Nett Value | : <u>S\$</u> |

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 6 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|---|
| Date Of Report | 24/01/2019 19:11 |
| Date Of Accident | 23/01/2019 04:20 |
| Exact Location Of Accident | LIANG COURT DROP OFF POINT |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | SMH3675L |
| Insured/Policyholder | |
| Name Of Registered Owner | TAN SIAK KIANG |
| NRIC No | S1144751A |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97927754 |
| Alternative Phone No | OFFICE-93233180 |
| Vehicle Particulars | |
| Manufacturer | BMW |
| Model | 218I-1.5 ACTIVE TOURER BUSINESS (F45) (A) |
| Exact Purpose for which vehicle was being used at time of accident | PERSONAL |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | HL ASSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | MP309205 |
| Cover Note Number | |
| Driver | |
| Name of Driver | TAN SIAK KIANG |
| NRIC No | S1144751A |
| Date Of Birth | 04/07/1955 |
| Occupation | INDOOR |
| Date Of Driving Pass | 17/11/1995 |
| Driving Experience | 23 YEARS AND 2 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-97927754 |
| Fax Number | |
| Contact Number | OFFICE-93233180 |
| EMail Address | NOEMAIL |

| | |
|---|---------------------------|
| Address | 89 PASIR RIS GROVE #11-25 |
| Postcode | 518214 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------------|
| Type Of Accident | COLLISION - OPENING DOOR OF VEHICLE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------------------------|
| Vehicle Registration Number | SHA8910X |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | TAXI |
| Name of Driver | YONG SEET LOONG (YANG XULONG) |
| NRIC/Passport Number | S7334882Z |
| Contact Number | 92702682 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Sketch Plan #2

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A - SMIT367SL
B - SHAS910E

The diagram shows a road layout with two parallel horizontal lines representing the road boundaries. A dashed horizontal line runs across the center of the road. Two vehicles, represented by rectangles with a pointed front, are positioned on the dashed line. Vehicle A is above vehicle B. A line connects the front of vehicle A to the front of vehicle B, indicating a path or relationship between them.

WHILE DRIVING PASTED LIANG COURT, PASSENGER FROM TAXI
SHA 8910 X ALIGHT FROM LEFT REAR AND HIT MY CAR ON MY
FRONT RIGHT. VIDEO AS ATTACHED:

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 18/2/2016

RE: VEHICLE REPAIR QUOTATION

| | | |
|-------------------|---|-------------------------|
| Insurance Company | : | First Capital Insurance |
| Vehicle Reg No | : | SMH3675C |
| Name of Insured | : | |
| Policy Number | : | |
| Date of Accident | : | 23.01.2019 |
| Tyre of Claim | : | Third Party Claim |
| Model | : | BMW 218i |
| Chassis No | : | WBA2D320305J58506 |

We are please to submit our estimate of repairs to the above mention vehicle.

| | | Parts | Labour |
|----|--|-----------|--------|
| 1 | FRONT BONNET <i>BA</i> | \$ 987.00 | |
| | FRONT BONNET INSULATOR/ HEAT <i>X nn</i> | | |
| 2 | SHIELD <i>X nn</i> | \$ 120.00 | |
| 3 | FRONT BUMPER <i>cut</i> | \$ 915.46 | |
| 4 | FRONT BUMPER LOGO <i>nn</i> | \$ 98.00 | |
| 5 | RHF HEADLAMP <i>scd</i> | \$ 951.45 | |
| 6 | RHF HEADLAMP BRACKET <i>? ? } x su</i> | \$ 124.80 | |
| 7 | RHF HEADLAMP BALLAST <i>? ? }</i> | \$ 777.68 | |
| 8 | RHF HEADLAMP ECU/ECM <i>?</i> | \$ 892.10 | |
| 9 | RHF FENDER <i>BA</i> | \$ 671.70 | |
| 10 | FRONT BUMPER SIDE RETAINER <i>LH RH nn</i> | \$ 70.00 | |
| 11 | BUMPER CLIPS @ \$8.00 x 5pcs <i>nn</i> | \$ 40.00 | |
| 12 | RH SIDE MIRROR <i>X (inconsistent) nn</i> | \$ 740.00 | |
| 13 | RH SIDE MIRROR COVER <i>X nn</i> | \$ 190.00 | |
| 14 | RH SIDE MIRROR SIGNAL LAMP <i>X nn</i> | \$ 105.00 | |

Sub Total Parts \$ 6,683.19

Less 5% \$ 334.16

Total Parts \$ 6,349.03

| | | |
|---|---|-------------------------|
| 1 | Sundries | \$ 30 80.00 |
| 2 | Wiring connection and check. | \$ 60 120.00 |
| 3 | Tuff kote and spray anti rust proofing | \$ 40 120.00 |
| 4 | Labour charges to dismantle & refix RHF fender bonnet, front bumper, front headlamp and side mirror To repair and adjust affected portion to specific dimension. | \$ 750 1,200.00 |
| 5 | To spray paint front bonnet, front bumper, front RH fender, RH side mirror and all other accident affected portion | \$ 750 1,200.00 |
| 6 | To remove and refix rh door panel, trim board to replace rh side mirror | \$ nn 200.00 |

| | | |
|----------------|--|--------------------------|
| 7 | To conduct and adjust headlamp focus and angle, calibration and coding for steering radius | \$ 30 150.00 |
| 8 | Sealant for body panel, front bonnet and front rh fender | \$ 60 150.00 |
| 7 | To conduct ECU programming, check and clear fault codes, restore programme modules | \$ 150 550.00 |
| Total (Labour) | | \$ 3,770.00 |
| Sub Total : | | \$ 10,119.03 |
| GST 7% | | \$ 708.33 |
| Grand Total : | | \$ 10,827.36 |

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Date: _____
Signature: _____
Acknowledged by Repairer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Resul
Hp 90010068
4-6 days
P/P
30/01/19 @ 1440
Resurvey 54 part

TAX INVOICE

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01

CITY HOUSE

SINGAPORE 068877

Vehicle No : SMH3675L

BMW 2181 SPORT GRAN TOUR

Mileage : 1635

Document No: IN19-300153

Date : 07/03/2019

Staff ID : KAVIDHA

Account No : FIRSTCAP

Job No : T19-100208

Page 1

| Description | Quantity | U Price | Disc% | Amount |
|--|----------|---------|-------|---------|
| FRONT BONNET | 1 | 987.00 | | 987.00 |
| FRONT BUMPER | 1 | 915.46 | | 915.46 |
| FRONT BUMPER LOGO | 1 | 98.00 | | 98.00 |
| RHF HEADLAMP | 1 | 951.45 | | 951.45 |
| RHF FENDER | 1 | 671.70 | | 671.70 |
| FRONT BUMPER SIDE RETAINER | 1 | 70.00 | | 70.00 |
| BUMPER CLIPS | 5 | 8.00 | | 40.00 |
| LESS 5% PARTS DISCOUNT | 1 | -186.68 | | -186.68 |
| SUNDRIES | 1 | 30.00 | | 30.00 |
| WIRING AND CONNECTION CHECK | 1 | 60.00 | | 60.00 |
| TUFF KOTE AND SPRAY ANTI RUSTING | 1 | 60.00 | | 60.00 |
| LABOUR CHARGE TO DISMANTLE AND REFIX RHF FENDER BONNET | 1 | 750.00 | | 750.00 |
| FRT BUMPER FRT HEADLAMP AND SIDE MIRROR TO REPAIR AND ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION | | | | |
| SPRAY PAINT FRT BONNET FRT BUMPER FRT RH FENDER RH SIDE MIRROR AND ALL OTHER ACCIDENT AFFECTED PARTS | 1 | 750.00 | | 750.00 |
| CONDUCT AND ADJUST HEADLAMP FOCUS AND ANGLE CALIBRATION | 1 | 30.00 | | 30.00 |
| CODING FOR STEERING RADIUS | | | | |
| SEALANT FOR BODY PANEL FRT BONNET AND FRT RH FENDER | 1 | 60.00 | | 60.00 |
| CONDUCT ECU PROGRAMMING CHECK/CLEAR FAULTCODE | 1 | 150.00 | | 150.00 |
| RESTORE PROGRAMMING MODULES | | | | |

3733.61
52
3546.92

1890

3546.92
1890.00
5436.92

Total 5,436.93

0.00

7.00% GST Pay 380.59

Nett Total 5,817.52

* Acknowledgement by Customer *

I confirm that the goods stated in this invoice have been received by me in good working order and condition. I further confirm that all services and/or repair jobs stated in this invoice are completed and done to my satisfaction.

TTS EUROCARS PTE LTD



Name/Signature/NRIC No/Co Stamp (where applicable)

Authorized Signature

**TTS EUROCARS** pte ltd

A member of the TTS Motor Group

Company Reg. No: 200413930H GST No: 20-0413930-H

383 Sin Ming Drive, TTS Centre, Singapore 575717 • Sales: +65 6842 2222 • Admin: +65 6757 0122 • After Sales: +65 6757 2622 • Fax: +65 6741 1626

Branch: 15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 • Tel: +65 6462 1111 • Fax: +65 6252 4834

24 Hours Emergency Assistance: +65 6475 2722

Website: www.tts.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--------------------------------|-----------------|------------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD | | | Ref : CS/FCI19001764/R1sd3e2 | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | | Date : 08-03-2019 | |
| | | | Code : FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHA 8910X | Veh. Inspected | SMH 3675L | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | D19000688MFSH | Excess (\$) | 0.00 | |
| Assign From | HENRY KAO | Assign Date | 28/01/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | B.M.W. 218I | c.c | 1499 | |
| Engine No. | HIDDEN | Year of Reg. | 2019 | |
| Chassis No. | WBA2D320305J58506 | Colour | WHITE | |
| Odometer | 668 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 245/45 R18 | CONTINENTAL | 6 mm | |
| L/H Front Tyre | 245/45 R18 | CONTINENTAL | 6 mm | |
| R/H Rear Tyre | 245/45 R18 | CONTINENTAL | 6 mm | |
| L/H Rear Tyre | 245/45 R18 | CONTINENTAL | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 23/01/2019 | Inspection Date | 30/01/2019 | |
| Survey held at | 335 SMITH ST CHINATOWN COMPLEX | | | |
| Repairer | TTS EUROCARS PTE LTD | | | |
| 5a. Remarks | | | | |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 3675L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|--------------------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT BONNET | BENT | 987.00 | 987.00 |
| 1 | FRONT BONNET INSULATOR / HEAT (NPA) | NOT NECESSARY | - | - |
| 1 | SHIELD | NOT NECESSARY | 120.00 | - |
| 1 | FRONT BUMPER | CUT | 915.46 | 915.46 |
| 1 | FRONT BUMPER LOGO | NECESSARY | 98.00 | 98.00 |
| 1 | RHF HEADLAMP | SCRATCHED | 951.45 | 951.45 |
| 1 | RHF HEADLAMP BRACKET | SERVICEABLE | 124.80 | - |
| 1 | RHF HEADLAMP BALLAST | SERVICEABLE | 777.68 | - |
| 1 | RHF HEADLAMP ECU / ECM | SERVICEABLE | 892.10 | - |
| 1 | RHF FENDER | BENT | 671.70 | 671.70 |
| 1 | FRONT BUMPER SIDE RETAINER RH | NECESSARY | 70.00 | 70.00 |
| 5 | BUMPER CLIPS @\$8.00 | NECESSARY | 40.00 | 40.00 |
| 1 | RH SIDE MIRROR (NOT NECESSARY) | NOT CONSISTENT WITH THE IMPACT | 740.00 | - |
| 1 | RH SIDE MIRROR COVER | NOT NECESSARY | 190.00 | - |
| 1 | RH SIDE MIRROR SIGNAL LAMP | NOT NECESSARY | 105.00 | - |
| | LESS 5% DISCOUNT | | -334.16 | -186.68 |
| | | | 6,349.03 | 3,546.93 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 80.00 | 30.00 |
| | | | 80.00 | 30.00 |
| <u>LABOUR</u> | | | | |
| | WIRING CONNECTION AND CHECK. | | 120.00 | 60.00 |
| | TUFF KOTE AND SPRAY ANTI RUST PROOFING. | | 120.00 | 60.00 |
| | LABOUR CHARGES TO DISMANTLE & REFIX RHF FENDER BONNET, FRONT BUMPER, FRONT HEADLAMP AND SIDE MIRROR TO REPAIR AND ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION. | | 1,200.00 | 750.00 |
| | TO SPRAY PAINT FRONT BONNET, FRONT BUMPER, FRONT RH FENDER, RH SIDE MIRROR AND ALL OTHER ACCIDENT AFFECTED PORTION. | | 1,200.00 | 750.00 |

Report Ref No. CS/FCI19001764/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------|---|---------------|---------------------------|-------------------|
| | TO REMOVE AND REFIX RH DOOR PANEL, TRIM BOARD TO REPLACE RH SIDE MIRROR. | NOT NECESSARY | 200.00 | - |
| | TO CONDUCT AND ADJUST HEADLAMP FOCUS AND ANGLE, CALIBRATION AND CODING FOR STEERING RADIUS. | | 150.00 | 30.00 |
| | SEALANT FOR BODY PANEL, FRONT BONNET AND FRONT RH FENDER. | | 150.00 | 60.00 |
| | TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES, RESTORE PROGRAMME MODULES. | | 550.00 | 150.00 |
| | | | 3,690.00 | 1,860.00 |
| GRAND TOTAL | | | 10,119.03 | 5,436.93 |

| | | | |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS | | | 5,436.93 |
|-----------------------------|--|--|----------|

Report Ref No. CS/FC119001764/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.