

22/03/2002

ASS. REC. BY:

REF: CS/FCL/9001765

Tled35

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Ong May Chua

of

FCL

Date/Time: 28/01/2019 904am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No:

FBL 554G

Insured:

SHD 3220X

at Workshop m/s

Bike Production

Tel:

of

610 Serangoon Rd

Policy No:

Claim No:

D19000630MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

29/01/2019

H.O.D. Endorsement:

Date/Time:

28/01/2019 1006am

Person Contacted:

Wendy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBL 554G - x

SHD 3220X - CS/FCL/0023447/Uqbs

Ref: 07/12/2016

21/01/19

@ 18:00 p.m. revised to May Chua via email.

Tm/ikh

REF: FCI

ASSIGNMENT

From: _____ Date: 30/1/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 554G

at Workshop no: Bike production

of: 610 Serangoon Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 3pm-4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBL 554G Yr Regn: 2016 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Pizzini Vigna CC 155

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 29881 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZAPM8142/0000/190

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 120 / 70 R12.

R: 130 / 70 R12.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.I. D.O.I. 30/1/19

Survey held at: Bike Production.

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

01/04/19 4/5 4000, 6 days confirm with w/s rm phone.
(\$ 5,366.20 res - 57%)

RECEIVED 05 APR 2019

Date/Time: File Pass to?

05/04/19

1) Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 4,000/- H/S

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

1) S + RS \$

2) Photos

3) Video

4) ...

TOTAL

170
50
50 + 50
128
448

4/4/2019

MOTOR SURVEY ASSIGNMENT

Date	22-01-2019	Our Ref No. D19000630MFSH
Accident Date	18-01-2019	Claim Type. Third Party
Insured Vehicle	SHD3220X	Third Party Vehicle. FBL554G
Survey Location	610 SERANGOON ROAD	
Contact Person.	KWAN S.H	
Contact No.	63922555/ 0	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BIKE PRODUCTION PTE LTD	Attention. NIL
Cc : TP Solicitor	APAC LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 31 January 2019 6:00 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: 'assignments'; 'SUR'; 'Admin-D (LKKAuto)'
Subject: RE: SURVEY ASSESSMENT - D19000630MFSH/1
Attachments: FBL 554G - Preli Advise .pdf

Dear May,

Enclosed preliminary revised of vehicle FBL 554G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 28 January 2019 10:09 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000630MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that repairer arrange survey on 29.01.2019.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 28 January, 2019 9:04 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000630MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000630MFSH

Date: 31 January 2019

Our Ref: CS/FCI19001765/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBL 554G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/01/2019 at the premises of M/s Bike Production Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 7,767.20</u> .
Revised Estimate Amount	: <u>S\$ 4,219.70</u> .
"Check" Items Amount	: <u>S\$ 157.50</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the front portion, o/s & n/s body



Comments/ Present Status:

Damages Consistent.
Repair days: 6 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 14:15
Date Of Accident	18/01/2019 19:35
Exact Location Of Accident	ALONG PASIR PANJANG RD ROUNDABOUT NEAR MAPLETREE
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL554G
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD SAIFUL BIN SANUSI
NRIC No	S9129060Z
Email Address	MOHAMMADSAIFUL.1991@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-87520998
Alternative Phone No	OTHERS-87520998

Vehicle Particulars

Manufacturer	PIAGGIO
Model	VESPA SPRINT SPORT 150 ABS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800132430
Cover Note Number	

Driver


Name of Driver	MOHAMMAD SAIFUL BIN SANUSI
NRIC No	S9129060Z
Date Of Birth	24/08/1991
Occupation	INDOOR
Date Of Driving Pass	24/05/2010
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87520998
Fax Number	
Contact Number	OTHERS-87520998
Email Address	MOHAMMADSAIFUL.1991@HOTMAIL.COM

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMMAD SAIFUL BIN SANUSI
Approximate Age	27
Injuries Sustain	HIP AND PELVIS RIGHT , HAND AND WRIST JOINT LEFT , RIGHT FOREARM ABRASION
Injured person in which vehicle?	FBL554G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 2



Refer to Police Report Station...

Please Refer to Police Report No: T/20190114/2101

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 21/01/2019
1400 hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/01/2019
1400 hrs

Reporting Centre Personnel's Signature
Name:
NRIC/EPIC No.:



**SINGAPORE
POLICE FORCE**



T/20190119/2101

Police Station Of Origin:
Telok Blangah NPP
61 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

2 of 3

Report No. T/20190119/2101

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL554G	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800132430	02/11/2018	01/11/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMMAD SAIFUL BIN SANUSI	ID No.	S9129060Z
Related Vehicle	FBL554G (Motorcycle)	Contact No.	87520998
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2 Date of Expiry: NIL
Date Treatment	19/01/2019	Date Discharge	19/01/2019
No. of Days granted Medical Leave	06	Degree of Injury	Slight

Brief Details.

On 18/01/2019 at about 1935hrs, I riding my grey coloured Vespa registered FBL554G. I was near to Mapletree Business city. I was at a roundabout. I was going towards the Mapletree business City exit from The roundabout entry near to the ARC building. I was then hit by a blue Comfort taxi registered SHD3220X. I was on the outer lane and the taxi was on the inner lane and I believe he was going to take the exit towards pasir panjang when this happened. I fell from my motorcycle. I was lying there but still conscious. The driver of the said vehicle came to me and later on assisted to call for the ambulance. There was a passerby who helped me take the necessary photos who later on sent me via WhatsApp. 96968146 is his number and goes by the name of Ikbaf. I was then conveyed to NUH where I was treated and got MC for 6 days.

I have lacerations on my right forearm and I also injured my left lower arm. I am not sure of the damages on my bike.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9060Z
Vehicle Details	
Vehicle No.:	FBL554G
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	VESPA SPRINT SPORT 150 ABS
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	M814M1001442
Chassis No.:	ZAPM8140100001190
Maximum Power Output:	-
Open Market Value:	\$3,245.00
Original Registration Date:	16 May 2016
First Registration Date:	16 May 2016
Transfer Count:	3
Actual ARF Paid:	\$487.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,502.00
COE Rebate Amount:	\$4,633.00
Total Rebate Amount:	\$4,633.00

The information contained herein is correct as at 29 Mar 2019

MV - \$8K

OK

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 21 Jan 2019

ASSESSMENT FOR REPAIR: VESPA SPRINT SPORT 150 ABS - FBL554G

Chassis No.: ZAPM8140100001190

Engine No.: M814M1001442

Qty	Description	Estimate
1 pc	Front Mudguard	\$290.00 cut ✓ 200
1 pc	Headlight with twin	\$205.00 X cut ✓ 120
1 pc	Front fork assy	\$790.00 X cut ✓ 120
1 pc	Front fork assy cover	\$75.00 cut ✓
1 pc	Front body cover	\$540.00 Rx
1 pc	Handle bar	\$175.00 cut ✓
1 pc	Brake caliper assy	\$450.00 X cut ✓
1 pc	Brake disk	\$195.00 X cut ✓
1 pc	Taillamp	\$185.00 X cut ✓
1 pc	Left brake lever	\$48.00 cut ✓
1 pc	Belt cover assembly	\$390.00 cut ✓
1 pc	Mainstand	\$275.00 cut ✓ 180
1 pc	Body Trimming	\$220.00 cut ✓ 150
1 pc	Lower cover assembly	\$295.00 cut ✓
1 pc	Lower inner footstep cover	\$195.00 cut ✓
1 pc	Left rear foot rest	\$105.00 cut ✓
1 pc	Right rear foot rest	\$105.00 cut ✓
1 pc	Rear right bumper	\$540.00 cut ✓ 400
1 pc	Rear left bumper	\$540.00 Rx
1 pc	Rear right bumper emblem and labels	\$95.00 cut ✓
1 pc	Rear left bumper emblem and labels	\$95.00 cut ✓
Less discount 10%		\$5,808.00
		\$580.80
		\$5,227.20
		2628
		supp - 940
		3568
		10% - 3211.20
		\$30.00 cut ✓
		\$440.00 cut ✓ *clerk price
		-340
		\$80.00 60.
		\$800.00 400
		\$500.00 300.
		\$60.00 30.
		\$180.00 120
		\$450.00 200
		\$7,767.20
		1600
		supp - 150
		labour 1750
		3211.20
		1750
		4961.20
		4000 6 days.
Total Estimate		4961.20

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd

TP

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 19 Feb2019

ASSESSMENT FOR REPAIR: VESPA SPRINT SPORT 150 ABS - FBL554

Chassis No.: ZAPM8140100001190

Engine No.: M814M1001442

Qty	Description	Estimate
1 pc	Rear left signal ^{right}	A \$140.00 as 70
1 pc	Right footrest cover lower	A \$75.00 de
1 pc	Left footrest cover lower	A \$75.00 de
1 pc	Right footrest cover upper	A \$75.00 de
1 pc	Left footrest cover upper	A \$75.00 de
1 pc	Centre floor step	A \$350.00 as 250
1 pc	Centre Inner cover	A \$420.00 de 320
		\$1,210.00
	Less discount 10%	\$121.00
		\$1,089.00

Special net items

2)	Additional labour	150 A \$390.00
	Total Estimate	
		\$1,479.00

Note: The above estimate is subjected to the prevailing GST of 7%

Y

For Bike Production Pte Ltd



Signature 20/9/19

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC / GST Reg No.: 200007407G

Date: 21 Jan 2019

ASSESSMENT FOR REPAIR: VESPA SPRINT SPORT 150 ABS - FBL554G

Chassis No.: ZAPM8140100001190

Eng. No.: MB14M1001442

Qty	Description	Estimate
1 pc	Front Mudguard	\$290.00 <i>cut</i>
1 pc	Headlight with trim	\$205.00 <i>cut</i>
1 pc	Front fork assy	\$790.00 <i>R 4120SV</i>
1 pc	Front fork assy cover	\$75.00 <i>cut</i>
1 pc	Front body cover	\$540.00 <i>Ry</i>
1 pc	Handle bar	\$175.00 <i>? bt</i>
1 pc	Brake caliper assy	\$450.00 <i>X</i>
1 pc	Brake disk	\$195.00 <i>X</i>
1 pc	Taillamp	\$185.00 <i>X</i>
1 pc	Left brake lever	\$48.00 <i>cut</i>
1 pc	Belt cover assembly	\$350.00 <i>cut</i>
1 pc	Mainstand	\$275.00 <i>old</i>
1 pc	Body Trimming	\$220.00 <i>cut</i>
1 pc	Lower cover assembly	\$295.00 <i>cut</i>
1 pc	Lower inner footstep cover	\$195.00 <i>cut</i>
1 pc	Left rear foot rest	\$105.00 <i>cut</i>
1 pc	Right rear foot rest	\$105.00 <i>cut</i>
1 pc	Rear right bumper	\$540.00 <i>dd</i>
1 pc	Rear left bumper	\$540.00 <i>Rx</i>
1 pc	Rear right bumper emblem and labels	\$95.00 <i>cut</i>
1 pc	Rear left bumper emblem and labels	\$95.00 <i>cut</i>
		<i>67418434</i>
		<i>Tanfulu 97495749</i>
		<i>-wp</i>
		<i>30/11/19 2430pm</i>
		<i>sur @ lkk auto.com</i>
		<i>tanfulu @ lkk auto.com</i>
		<i>Resurvey after repair</i>
		<i>Lumpsum</i>
		<i>60 days</i>
1 pc	Rear number plate	\$30.00 <i>bt</i>
1 pc	Front sport rim	\$440.00 <i>cut</i> <i>* check price</i>
1)	Towing charges	\$80.00 <i>60</i>
2)	Dismantle, replace, realign and adjust above damaged parts	\$800.00 <i>400</i>
3)	Spray painting	\$500.00 <i>300</i>
4)	Check wiring and lighting system	\$60.00 <i>30</i>
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 <i>120</i>
6)	To knock, straighten chassis & body balancing	\$450.00 <i>200</i>
Total Estimate		\$7,757.20

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

VESPA PRIMAVERA iGET

1pc	L/H Mirror – s\$ 55.00
1pc	L/H Brake Lever - \$ 18.00
1pc	L/H Switch Cover, Front (Matt Silver) – S\$ 26.00
1pc	Handle Cover, Lower (Baby Blue) -= S\$ 66.00 no colour
1pc	Front Cowling Centre Runner (Baby Blue) – S\$ 36.00 no colour
1pc	Front Mudguard (Baby Blue) – S\$ 60.00 no cololur
1set	Front Suspension Cover, Matt – S\$ 20.00
1pc	Crest, Chrome, Front Mudguard – S\$ 12.00
1pc	Front Fork/Stem Unit – S\$ 800.00
1pc	Front Suspension – S\$ 265.00
1pc	Beading, L/H Front Body, Chrome – S\$ 45.00
1pc	Beading, L/H Floorboard, Chrome – S\$ 28.00
1pc	Glove Compartment Body (Baby Blue) – S\$ 150.00 no colour
1pc	Floorboard (Baby Blue) – S\$ 150.00 (no colour)
1pc	L/H Pillion Footrest Pad – S\$ 14.00
1pc	Main Stand – S\$ 100.00
1pc	R/H Swing Arm Block Cover, Matt - ???
1pc	Belt Cover (Grey) – S\$ 250.00
1set	Steering Con Upper/Lower with Bearings – S\$ 50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001765/T1sd3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3220X	Veh. Inspected	FBL 554G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000630MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	PIAGGIO VESPA	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZAPM8140100001190	Colour	GREY	
Odometer	29881	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R12	MICHELIN	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70 R12	MICHELIN	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/01/2019	Inspection Date	30/01/2019	
Survey held at	BIKE PRODUCTION PTE LTD 610 SERANGOON ROAD SINGAPORE 218216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 554G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD	CUT	290.00	200.00
1	HEADLIGHT WITH TRIM	CUT	205.00	120.00
1	FRONT FORK ASSY	NOT NECESSARY	790.00	-
1	FRONT FORK ASSY COVER	CUT	75.00	75.00
1	FRONT BODY COVER	TO REPAIR SEE LABOUR	540.00	-
1	HANDLE BAR	BENT	175.00	175.00
1	BRAKE CALIPER	NOT NECESSARY	450.00	-
1	BRAKE DISK	NOT NECESSARY	195.00	-
1	TAILLAMP	NOT NECESSARY	185.00	-
1	LEFT BRAKE LEVER	CUT	48.00	48.00
1	BELT COVER ASSEMBLY	CUT	390.00	390.00
1	MAINSTAND	DENTED	275.00	180.00
1	BODY TRIMMING	CUT	220.00	150.00
1	LOWER COVER ASSEMBLY	CRACKED	295.00	295.00
1	LOWER INNER FOOTSTEP COVER	CUT	195.00	195.00
1	LEFT REAR FOOT REST	CUT	105.00	105.00
1	RIGHT REAR FOOT REST	CUT	105.00	105.00
1	REAR RIGHT BUMPER	DENTED	540.00	400.00
1	REAR LEFT BUMPER	TO REPAIR SEE LABOUR	540.00	-
1	REAR RIGHT BUMPER AMBLEM AND LABELS	NECESSARY	95.00	95.00
1	REAR LEFT BUMPER AMBLEM AND LABELS	NECESSARY	95.00	95.00
1	REAR RIGHT SIGNAL (ADDITIONAL)	CRACKED	140.00	70.00
1	RIGHT FOOTREST COVER LOWER (ADDITIONAL)	DEFORMED	75.00	75.00
1	LEFT FOOTREST COVER LOWER (ADDITIONAL)	DEFORMED	75.00	75.00
1	RIGHT FOOTREST COVER UPPER (ADDITIONAL)	DEFORMED	75.00	75.00
1	LEFT FOOTREST COVER UPPER (ADDITIONAL)	DEFORMED	75.00	75.00
1	CENTRE FLOOR STEP (ADDITIONAL)	CRACKED	350.00	250.00
1	CENTRE INNER COVER (ADDITIONAL)	DEFORMED	420.00	320.00

Report Ref No. CS/FCI19001765/T1sd3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-701.80	-356.80
			6,316.20	3,211.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	FONT SPORT RIM (SN)	CUT	440.00	340.00
			470.00	370.00
	<u>LABOUR</u>			
	TOWING CHARGES.		80.00	60.00
	DISMANTLE, REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BODY COVER AND REAR LEFT BUMPER.		800.00	400.00
	SPRAY PAINTING.		500.00	300.00
	CHECK WIRING AND LIGHTING SYSTEM.		60.00	30.00
	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.		180.00	120.00
	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.		450.00	200.00
	FORK ALIGNMENT.		120.00	120.00
	ADDITIONAL LABOUR.		390.00	150.00
			2,580.00	1,380.00
GRAND TOTAL			9,366.20	4,961.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/FCI19001765/T1sd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.