

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

28/01/2019 13:00

OWNER'S PARTICULARS

JOB-NO: 50111358

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILSLICENSE NO: SHB4918X
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP
TRANS: AUTO
SA: Ding Auto User 1CHASSIS: KMHLB41UMEU061602
ENGINE: D4DFU550915CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	800.00	0.00	800.00		Y	300.
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		Y	X
3 CHECK WIRING	1.00	150.00	0.00	150.00		Y	30.
4 R&R REAR REVERSE SENSOR AND DRILL	1.00	150.00	0.00	150.00		Y	30
5 RUSH PROOFING	1.00	150.00	0.00	150.00		Y	X
6 SPRAY PAINTING REAR BUMPER ,BOOTLID ,REAR DIFFUSER	1.00	800.00	0.00	800.00		Y	40
TOTAL:		2,200.00	0.00	2,200.00			

MATERIALS

1 REAR BUMPER	1.00	599.68	119.94	479.74	L	Y	de
2 REAR BUMPER REINF	1.00	484.10	96.82	387.28	L	Y	?
3 REAR BUMPER REINF SPONGE	1.00	159.68	31.94	127.74	L	Y	?
4 REAR BUMPER REINF ARM LH	1.00	98.63	19.73	78.90	L	Y	X
5 REAR BUMPER REINF ARM RH	1.00	98.63	19.73	78.90	L	Y	X
6 BOOTLID	1.00	1,949.50	389.90	1,559.60	L	Y	Ry
7 EMBLEM - i40	1.00	38.55	7.71	30.84	L	Y	ne
8 EMBLEM - LOGO	1.00	45.55	9.11	36.44	L	Y	ne
9 EMBLEM - CRDI	1.00	38.55	7.71	30.84	L	Y	ne
10 REAR DIFFUSER	1.00	228.40	45.68	182.72	L	Y	af
11 REAR BUMPER CLIPS	1.00	35.00	0.00	35.00	S	Y	ne
12 REVERSE SENSOR	1.00	250.00	0.00	250.00	S	Y	200.00
13 REAR NUMBER PLATE	1.00	45.00	0.00	45.00	S	Y	are
14 BOOTLID STICKER COMFORT DELGRO	1.00	150.00	0.00	150.00	S	Y	ne
15 BOOTLID STICKER 65521111	1.00	150.00	0.00	150.00	S	Y	ne
16 REAR BUMPER PROTECTOR PAD	1.00	180.00	0.00	180.00	S	Y	ne
TOTAL:		4,551.27	748.27	3,803.00			

TOTAL PARTS & LABOUR : 6,751.27 748.27 6,003.00

EXCESS/LOADING:\$S 0.00

No. Of Day: 3 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$S

DATE OF SURVEY: 28 / 1 / 19

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY: TunjiCONTACT NO: 0749344FAX NO: wp

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hereby notify the Repairer of the following:

- To resur
- To dist
- Parts
- Third party survey is or
- No illeg
- Supplier
- is subject

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants hereby notify the Repairer of the following:

- To resur
- To dist
- Parts
- Third party survey is or
- No illeg
- Supplier
- is subject

Acknowledged by Repairer:

Signature:

Date: