

12/03/2002

ASS. REC. BY:

REF: CS/FCL19001770/Agds¹⁷

Special Instruction:

Surveyor:

AKK/Am

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

FCL

Date/Time:

25/01/2019 6:39pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 7042H

Insured:

SHC 19L

at Workshop m/s

N° 51 Automotiv

Tel:

of

2 KUKI BUKIT AVE 2 # 01-17

Policy No:

Claim No:

D19000699MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/01/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

28/01/2019 10am

Person Contacted:

Hui Xin

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 7042H - NA / NCI9001705 / HUI
	SHC 19L - X
28/1/19 @ 4.15pm	revised to Henry Kao by email. US \$ 6350, 7 days (led to 4905.56, 44%).

REF: FCI

ASSIGNMENT

From: _____ Date: **28/01/2019**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SMD 7042H**

at Workshop n/s **N-51**

of **2 Kaki Bukit Ave 2 #01-17**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SMD7042H** Yr Regn: **2018 August**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **Honda Freed Hybrid CC 1496**

Colour: **White** AC: Insured / Std / NI / NA

Sp Reading: **41236** T/Radio: Insured / Std / NI / NA

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or No

GIA / PR Seen: _____ Consistent? : **Yes** or No

Est. Repairs: **7** days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS **'09'**

Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Eng/No: _____

C/No: **GB71067313**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **205/60 R16**
R: **205/60 R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: **06** mm R/Bal: **06** mm

L/Bal: **06** mm L/Bal: **06** mm

D.O.A. _____ D.O.I. **28/01/19**

Survey held at **N51**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time: _____ Action / Instruction: **TP 1st Cap.**

RECEIVED 07 JUN 2019

Date/Time, File Pass to? Preli. Report

11/01/19 Final Report

Date/Time, File Return to? _____

Report Format: **TP**

Lump Sum / I.B.F. (\$) **6350**

Days Of Repair: **7**

Resurvey No. of Trip: **2**

Add Fee: Site Insp (\$) Interview (\$) Tech Invs (\$) Weekend (\$)

Survey Fee: _____

Transportation: _____

Other: **OSP 19/6/19**

170+15
50
50+50
106
441

TOTAL



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000699MFSH

Date: 29 January 2019

Our Ref: CS/FCI19001770/Aqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 7042H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/01/2019 at the premises of M/s N-51, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 11,255.56</u>
Revised Estimate Amount	: <u>S\$ 8,034.64</u>
"Check" Items Amount	: <u>S\$ 540.00</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	25-01-2019	Our Ref No. D19000699MFSH
Accident Date	24-01-2019	Claim Type. Third Party
Insured Vehicle	SHC0019L	Third Party Vehicle. SMD7042H
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	MELODY CHIN	
Contact No.	68420051/ 67440510	Fax No. 67410610
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 29 January 2019 4:15 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000699MFSH/1
Attachments: CSFCI19001770Aqd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SMD 7042H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 28 January 2019 10:01 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000699MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 25 January, 2019 6:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000699MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delnd</i>	1	925.00	925.00 ✓
REAR BUMPER CENTER BRACKET L/R <i>Best</i>	2	30.50	61.00 ✓
REAR BUMPER INNER GUIDE GARNISH L/R <i>Delnd</i>	2	35.00	70.00 ✓
REAR BUMPER REFLECTOR L/R <i>Delnd</i>	2	42.80	85.60 ✓
REAR BUMPER SIDE BRACKET L/R <i>Delnd</i>	2	30.20	60.40 ✓
REAR BUMPER SIDE RETAINER L/R <i>Delnd</i>	2	24.90	49.80 ✓
REAR BUMPER TOW HOOK COVER <i>Delnd</i>	1	18.50	18.50 ✓
REAR BUMPER UNDER COVER <i>Delnd</i>	1	135.00	135.00 ✓
REAR END PANEL (INNER) <i>Delnd</i>	1	230.00	230.00 ✓
REAR END PANEL (OUTER) <i>Delnd</i>	1	623.70	623.70 ✓
REAR END PANEL INNER TOP GARNISH <i>Delnd</i>	1	115.00	115.00 ✓
REAR FENDER INNER TRIM BOARD L/R <i>Delnd</i>	2	268.00	536.00 ✓
REAR TAILGATE <i>Disturbed</i>	1	1100.00	1,100.00 ✓
REAR TAILGATE 'FREED' EMBLEM <i>Delnd</i>	1	55.00	55.00 ✓
REAR TAILGATE 'HYBRID' EMBLEM <i>Delnd</i>	1	55.00	55.00 ✓
REAR TAILGATE 'LOGO' EMBLEM <i>Delnd</i>	1	32.50	32.50 ✓
REAR TAILGATE DAMPER L/R <i>Delnd</i>	2	135.00	270.00 ✓
REAR TAILGATE HINGES L/R <i>Delnd</i>	2	50.00	100.00 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

REAR TAILGATE INNER PULL HANDLE <i>Delvond</i>	1	23.40	23.40	✓
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	10.50	21.00	+
REAR TAILGATE INNER TRIM BOARD <i>cancel</i>	1	288.00	288.00	✓
REAR TAILGATE LOCK STRIKER <i>new Bent</i>	1	27.50	27.50	✓
REAR TAILGATE MECHANISM LOCK <i>Delvond</i>	1	189.90	189.90	✓
REAR TAILGATE NUMBER PLATE LAMP L/R <i>new</i>	2	38.50	77.00	+
REAR TAILGATE OUTER CHROME HANDLE <i>new</i>	1	320.40	320.40	+
REAR TAILGATE OUTER LOCK SWITCH <i>new</i>	1	175.50	175.50	+
REAR TAILGATE REFLECTOR INNER RUBBER GASKET L/R <i>new</i>	2	18.50	37.00	✓
REAR TAILGATE REFLECTOR L/R <i>cancel</i>	2	360.00	720.00	✓
REAR TAILGATE WEATHER STRIP <i>lot</i>	1	168.50	168.50	✓
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	120.00	120.00	✓
REAR TAILLAMP L/R <i>cancel</i>	2	580.00	1,160.00	✓
Subtotal before discount			7,850.70	
Percentage discount 20%			1,570.14	
Sub-total 1			6,280.56	
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00	✓
REAR BUMPER REVERSE SENSOR - SET <i>cancel</i>	1	350.00	350.00	✓
			200	

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

REAR BUMPER UNDER COVER CLIPS - SET <i>rec</i>	1	40.00	<i>30</i> 40.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>rec</i>	1	40.00	<i>20</i> 40.00 10
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>not rec</i>	2	40.00	80.00 X
REAR FLOOR PANEL INSULATOR MAT <i>nn</i>	1	300.00	300.00 X
REAR TAILGATE CAMERA <i>the nn</i>	1	800.00	800.00 ✓
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>rec</i>	1	30.00	30.00 ✓
REAR TAILGATE NUMBER PLATE <i>the nn</i>	1	25.00	25.00 ✓
REAR TAILGATE NUMBER PLATE HOLDER <i>rec</i>	1	50.00	50.00 ✓
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET <i>nn</i>	1	50.00	50.00 X
REAR TAILGATE WINDSCREEN SEALANT <i>rec</i>	1	100.00	100.00 60
REAR TAILLAMP CLIPS L/R - SET <i>rec</i>	2	20.00	<i>20</i> 40.00 ✓
		Subtotal before discount	1,985.00
Percentage discount 0%			0.00
		Sub-total 2	1,985.00
		Parts-total	8,265.56

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	100.00 <i>70</i>
To remove, reinstall tailgate windscreen	150.00 <i>120</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00 <i>60</i>

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SHENGLONG
BLK 755 WOODLANDS AVE 4 #05-303
SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
Date in : 25/01/2019
Vehicle Num. : SMD7042H
Model : HONDA FREED HYBRID 1.5G AUTO
Chassis/Eng# : GB71067313/LEB5600568

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 <i>800</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,400.00 <i>1000</i>
To apply anti-rust chemical on repaired and replaced panel.	120.00 <i>60</i>
To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.	80.00 ✓
Labour Total	2,990.00
Parts & Labour Total	11,255.56

*** This is a computer-generated document which requires no signature.***

page 4

Adrian Ling
4/5 28/01/19
07 Pmp

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

*T? 1st Corp.
 Xiao Chen.*

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Del'd</i>	1	925.00	925.00 ✓
REAR BUMPER CENTER BRACKET L/R <i>Best</i>	2	30.50	61.00 ✓
REAR BUMPER INNER GUIDE GARNISH L/R <i>Del'd</i>	2	35.00	70.00 ✓
REAR BUMPER REFLECTOR L/R <i>Del'd</i>	2	42.80	85.60 ✓
REAR BUMPER SIDE BRACKET L/R <i>Del'd</i>	2	30.20	60.40 ✓
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	24.90	49.80 ✓
REAR BUMPER TOW HOOK COVER <i>new</i>	1	18.50	18.50 +
REAR BUMPER UNDER COVER <i>Del'd</i>	1	135.00	135.00 ✓
REAR END PANEL (INNER) <i>? Del'd</i>	1	230.00	230.00 ✓
REAR END PANEL (OUTER) <i>? Del'd</i>	1	623.70	623.70 ✓
REAR END PANEL INNER TOP GARNISH <i>Del'd</i>	1	115.00	115.00 ✓
REAR FENDER INNER TRIM BOARD L/R <i>Del'd</i>	2	268.00	536.00 ✓
REAR TAILGATE <i>Disturbed</i>	1	1100.00	1,100.00 ✓
REAR TAILGATE 'FREED' EMBLEM <i>? new</i>	1	55.00	55.00 ✓
REAR TAILGATE 'HYBRID' EMBLEM <i>? new</i>	1	55.00	55.00 ✓
REAR TAILGATE 'LOGO' EMBLEM <i>? new</i>	1	32.50	32.50 ✓
REAR TAILGATE DAMPER L/R <i>new</i>	2	135.00	270.00 +
REAR TAILGATE HINGES L/R <i>the new</i>	2	50.00	100.00 +

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

REAR TAILGATE INNER PULL HANDLE <i>Delvnd</i>	1	23.40	23.40	✓
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>Ne n</i>	2	10.50	21.00	+
REAR TAILGATE INNER TRIM BOARD <i>cancel</i>	1	288.00	288.00	✓
REAR TAILGATE LOCK STRIKER <i>Ne n Best</i>	1	27.50	27.50	✓
REAR TAILGATE MECHANISM LOCK <i>Repl</i>	1	189.90	189.90	✓
REAR TAILGATE NUMBER PLATE LAMP L/R <i>Ne n</i>	2	38.50	77.00	+
REAR TAILGATE OUTER CHROME HANDLE <i>Ne n</i>	1	320.40	320.40	+
REAR TAILGATE OUTER LOCK SWITCH <i>Ne n</i>	1	175.50	175.50	+
REAR TAILGATE REFLECTOR INNER RUBBER GASKET L/R <i>Ne n</i>	2	18.50	37.00	✓
REAR TAILGATE REFLECTOR L/R <i>cancel</i>	2	360.00	720.00	✓
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	168.50	168.50	✓
REAR TAILGATE WINDSCREEN MOULDING <i>Ne n</i>	1	120.00	120.00	✓
REAR TAILLAMP L/R <i>cancel</i>	2	580.00	1,160.00	✓
Subtotal before discount			7,850.70	
Percentage discount 20%			1,570.14	
Sub-total 1			6,280.56	
REAR BUMPER CLIPS - SET <i>Ne n</i>	1	80.00	80.00	
REAR BUMPER REVERSE SENSOR - SET <i>2nd</i>	1	350.00	350.00	
			200	

*** This is a computer-generated document which requires no signature.***

6868.30
137366
~~*200*~~
5494.60

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

REAR BUMPER UNDER COVER CLIPS - SET <i>Neu</i>	1		40.00	40.00 30
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Neu</i>	1		40.00	40.00 20
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>Not Neu</i>	2		40.00	80.00 X
REAR FLOOR PANEL INSULATOR MAT <i>Not Neu</i>	1		300.00	300.00 +
REAR TAILGATE CAMERA <i>Not Neu</i>	1		800.00	800.00 +
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Neu</i>	1	420	30.00	30.00 ✓
REAR TAILGATE NUMBER PLATE <i>Neu</i>	1		25.00	25.00 +
REAR TAILGATE NUMBER PLATE HOLDER <i>Neu</i>	1		50.00	50.00 +
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET <i>Neu</i>	1		50.00	50.00 +
REAR TAILGATE WINDSCREEN SEALANT <i>Neu</i>	1	436	100.00	100.00 60
REAR TAILLAMP CLIPS L/R - SET <i>Neu</i>	2	730	20.00	40.00 20
			Subtotal before discount	1,985.00
Percentage discount 0%				0.00
			Sub-total 2	1,985.00
			Parts-total	8,265.56

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	100.00 70
To remove, reinstall tailgate windscreen	150.00 120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00 60

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SHENGLONG
 BLK 755 WOODLANDS AVE 4 #05-303
 SINGAPORE 730755

Contact : 87165255

ESTIMATE

Repair Code : CLM15034
 Date in : 25/01/2019
 Vehicle Num. : SMD7042H
 Model : HONDA FREED HYBRID 1.5G AUTO
 Chassis/Eng# : GB71067313/LEB5600568

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 800
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,400.00 1000
To apply anti-rust chemical on repaired and replaced panel.	120.00 60
To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.	80.00 ✓
Labour Total	2,990.00
Parts & Labour Total	11,255.56

2190

2190.00

*** This is a computer-generated document which requires no signature.***
 page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary items must be received and is subject to final LKK Auto Consultants insurance company

Acknowledged by Repairer
 Signature:
 Date:

5494.64
 2190.00
 730.00

 8414.64
 - 2021682.92

 6731.71

Adrian Ling
 H/S 28/01/19
 07 Pmp
 total 796704
 H/S: 6350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001770/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-06-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 19L	Veh. Inspected	SMD 7042H
Policy No.		Coverage (\$)	0.00
Claim No.	D19000699MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	25/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71067313	Colour	WHITE
Odometer	41236	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	DUNLOP	6 mm
L/H Front Tyre	205/60 R16	DUNLOP	6 mm
R/H Rear Tyre	205/60 R16	DUNLOP	6 mm
L/H Rear Tyre	205/60 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/01/2019	Inspection Date	28/01/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 7042H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	925.00	925.00
2	REAR BUMPER CENTER BRACKET L/R @\$30.50	BENT	61.00	61.00
2	REAR BUMPER INNER GUIDE GARNISH L/R @\$35.00	DEFORMED	70.00	70.00
2	REAR BUMPER REFLECTOR L/R @\$42.80	CRACKED	85.60	85.60
2	REAR BUMPER SIDE BRACKET L/R @\$30.20	DAMAGED	60.40	60.40
2	REAR BUMPER SIDE RETAINER L/R @\$24.90	NECESSARY	49.80	49.80
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	18.50	-
1	REAR BUMPER UNDER COVER	DEFORMED	135.00	135.00
1	REAR END PANEL (INNER)	DENTED	230.00	230.00
1	REAR END PANEL (OUTER)	DENTED	623.70	623.70
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	115.00	115.00
2	REAR FENDER INNER TRIM BOARD L/S @\$268.00	CRACKED	536.00	536.00
1	REAR TAILGATE	DISTORTED	1,100.00	1,100.00
1	REAR TAILGATE "FREED" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE "LOGO" EMBLEM	NECESSARY	32.50	32.50
2	REAR TAILGATE DAMPER L/R @\$135.00	NOT NECESSARY	270.00	-
2	REAR TAILGATE HINGES L/R @\$50.00	NOT NECESSARY	100.00	-
1	REAR TAILGATE INNER PULL HANDLE	DEFORMED	23.40	23.40
2	REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R @\$10.50	NOT NECESSARY	21.00	-
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	288.00	288.00
1	REAR TAILGATE LOCK STRIKER	BENT	27.50	27.50
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	189.90	189.90
2	REAR TAILGATE NUMBER PLATE LAMP L/R @\$38.50	NOT NECESSARY	77.00	-
1	REAR TAILGATE OUTER CHROME HANDLE	NOT NECESSARY	320.40	-
1	REAR TAILGATE OUTER LOCK SWITCH	NOT NECESSARY	175.50	-
2	REAR TAILGATE REFLECTOR INNER RUBBER GASKET L/R @\$18.50	NECESSARY	37.00	37.00
2	REAR TAILGATE REFLECTOR L/R @\$360.00	CRACKED	720.00	720.00
1	REAR TAILGATE WEATHER STRIP	CUT	168.50	168.50

Report Ref No. CS/FC119001770/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	120.00	120.00
2	REAR TAILLAMP L/R @\$580.00 LESS 20% DISCOUNT	CRACKED	1,160.00 -1,570.14	988.00 -1,339.26
			6,280.56	5,357.04
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	SET REAR BUMPER UNDER COVER CLIPS (SN)	NECESSARY	40.00	30.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
1	REAR TAILGATE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR TAILGATE OUTER CHROME HANDLE CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
2	SET REAR TAILLAMP CLIPS L/R @\$20.00 (SN)	NECESSARY	40.00	20.00
			1,985.00	390.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	70.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR).		140.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,400.00	1,000.00

Report Ref No. CS/FCI19001770/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
	TO TRANSFER REAR TAILGATE INNER TRIM BOARD,WIPER MOTOR,MECHANISM LOCK OUTER HANDLE.		80.00	80.00
			2,990.00	2,190.00
GRAND TOTAL			11,255.56	7,937.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,350.00

Report Ref No. CS/FCI19001770/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.