

INS CASE OWNER:

Surveyor:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

Is driver the owner?

( YES ☒ NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKW 5676R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Finnchur  
Finnchur

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

( days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. 28 (3ce 01/1/19)

FNO or B 28, Ass. Lin: 1677.45

Repair Cost: (w/gst)

\$S 16050.00

Loss of Rental (LOR):

\$S

( days)

Loss of Use (LOU):

\$S

720.00 (\$ 60 x 12 days)

Loss of Income (LOI):

\$S

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$S

7.45

Medical:

\$S

-

Disbursement:

\$S

-

Legal Cost

\$S

-

Total:

\$S 1677.45

Global Sum \$S: 16700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

16700.00

Name 1:

Fastech Auto Pte Ltd

Payee 2: (if any)

\$S

-

Name 2:

-

Payee 3: (if any)

\$S

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format: R

3) Survey fee: 1320

21/1/19

11/1/19 Well  
S. REC. BY: 407545

REF: A.61

ASSIGNMENT

on: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
D ( ) TP / WS / TP RES / OD RES / EVA / INV / MV  
> Inspect Vehicle No: SKW 5676R  
Workshop m/s: ff  
Insured: SLK 4717  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: 69  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
G/A / PR Seen: 9 Consistent? : Yes or No  
Est. Repairs: 10 days Res.: Yes or No  
Lump Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

N/S	O/S

Veh No: SKW 5676R Regn: 11/15  
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CAI  
Make: Honda mobilio c.c. 1497  
Colour: White A/C: Insured / Std / Nil / NA  
Sp. Reading: 74162 T/Radio: Insured / Std / Nil / NA  
Eng/No: \_\_\_\_\_  
C/No: MRHDD4870FP000354  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modl: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 185/65R15  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: 7 mm Rear: 7 mm  
R/Bal: 7 mm L/Bal: 7 mm  
D.O.A: 26/1/19 D.O.L: 28/1/19  
Survey held at: \_\_\_\_\_  
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
Rear & RL  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>CNY 5-2-19 47AS3419</u>
	<u>have h.a by 10th. net 15781</u>
<u>29/3/19</u>	<u>confirmed 2/5 @ 15,000 with Alan</u>
	<u>(Red \$ 28333.10 / 65%)</u>

Date/Time, File Pass to? ☐ : Prel. Report  
1) ☐ : Final Report  
Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

Survey Fee:	
Transportation:	
\$ - RS \$:	
Photos	
Others	
TOTAL	

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ )

FASTECT AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46/48/50 AUTOBAY  
SINGAPORE 417883

Not Allowed  
Nak  
28/1/19  
2/5  $\frac{15,000}{10 \text{ day}}$

VEHICLE NO:SKW 5676R

QTY	PARTICULAR			
1 PCS	REAR WINDSCREEN MOULDING		rel	\$161.10 ✓
1 PCS	TAILGATE	1125.00	Bonny 20	\$1,266.30 ✓
1 PCS	TAILGATE 'H' LOGO	38.00	rel	\$45.80 ✓
1 PCS	TAILGATE 'Mobilio' EMBLEM		rel	\$48.80 ✓
1 PCS	TAILGATE 'RS' EMBLEM		rel	\$45.00 ✓
1 PCS	TAILGATE 'IVTEC' EMBLEM		rel	\$48.50 ✓
2 PCS	TAILGATE REFLECTORS @\$488.10		11	\$976.20 ✓
1 PCS	TAILGATE OUTER GARNISH		4-1/2cm	\$385.40 ✓
1 PCS	TAILGATE INNER LOCK	178.20	00/5m	\$266.20 ✓
1 PCS	TAILGATE LOCK SENSOR		11	\$285.50 ✓
1 PCS	TAILGATE LOCK BUZZER		11	\$208.30 ✓
1 PCS	TAILGATE INNER TRIM BORAD	466.05	De/Fin	\$650.10 ✓
1 SET	TAILGATE INNER TRIM BORAD CLIPS		rel	\$50.00 ✓
1 PCS	TAILGATE WEATHERSTRIP		1m	\$188.20 ✓
1 PCS	TAILGATE REAR WIPER MOTOR		11	\$825.00 ✓
1 PCS	REAR BUMPER	463.70	11	\$845.10 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$45.00		11	\$90.00 ✓
1 SET	REAR BUMPER CLIPS		rel	\$45.00 ✓
1 PCS	REAR BUMPER TOP PROTECTOR		11	\$311.20 ✓
1 PCS	REAR BUMPER TOP PROTECTOR CHROME		11	\$288.50 ✓
2 PCS	REAR BUMPER REFLECTORS @\$45.00		11	\$90.00 ✓
2 PCS	REAR BUMPER SIDE GRILLES @\$85.00		11	\$170.00 ✓
1 PCS	REAR END PANEL	444.70	3-1/2m	\$611.20 ✓
1 PCS	REAR END PANEL TOP GARNISH		11	\$298.30 ✓
1 PCS	REAR EXHAUST		11	\$688.50 ✓
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00		11	\$90.00 ✓
2 PCS	REAR FENDERS @\$1105.10		11	\$2,210.20 ✓
2 PCS	REAR FENDER INNER BOARDS @\$485.0		De/Fin	\$970.00 ✓
1 PCS	REAR FLOOR PANEL		11	\$1,120.10 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD		11	\$660.50 ✓
2 PCS	TAILLAMPS @\$680.10	385.50 x 2 = 771.00	11	\$1,360.20 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$255.00		11	\$510.00 ✓
1 PCS	REAR SPARE TYRE BRACKET		3-1/2m	\$322.20 ✓
2 PCS	REAR FENDER INNER GARNISH @\$145.00		11	\$290.00 ✓
1 PCS	BONNET		11	\$866.20 ✓
1 PCS	BONNET RUBBER		11	\$85.00 ✓
2 PCS	BONNET HINGES @\$105.00		11	\$210.00 ✓
1 PCS	BONNET INSULATOR		11	\$245.50 ✓
1 PCS	BONNET INSULATOR CLIPS		11	\$45.00 ✓
1 PCS	BONNET LOCK		11	\$165.00 ✓
1 PCS	FRONT BUMPER	566.05	11	\$745.30 ✓
2 PCS	FRONT BUMPER SIDE REATINERS @\$45.00		11	\$90.00 ✓
1 SET	FRONT BUMPER CLIPS		11	\$45.00 ✓
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE		11	\$211.20 ✓
2 PCS	FRONT BUMPER FOG LAMPS @\$650.00	495 x 2 = 990	11	\$1,300.00 ✓

202

2 PCS	FRONT BUMPER FOG LAMP COVERS @\$150.00	136.20 x 2 = 272.40	FW	\$300.00	✓
1 PCS	FRONT BUMPER REINFORCEMENT		7.5	\$315.20	✓
1 PCS	FRONT GRILLE	242.60	CM	\$385.40	✓
1 PCS	FRONT GRILLE OUTER CHROME	250.00	CM	\$311.50	✓
1 PCS	FRONT GRILLE 'H' LOGO		RM	\$38.50	✓
2 PCS	FRONT FOG LAMP CHROME MOULDINGS @\$110.00		17	\$220.00	X
1 PCS	FRONT SUPPORT PANEL	664.30	Self/Pat	\$754.50	✓
1 PCS	FRONT SUPPORT PANEL TOP GARNISH		17	\$288.20	X
2 PCS	HEADLAMPS \$1450.00	820.20 x 2 = 1640.40	CM	\$2,900.00	✓
1 PCS	AIR CON CONDENSER	866.20	Self/Pat	\$1,100.20	✓
1 PCS	RADIATOR	1415.30	Self/Pat	\$1,866.20	✓
1 PCS	RADIATOR FAN MOTOR		17	\$395.00	X
1 PCS	RADIATOR FAN COWLING		17	\$145.00	X
1 PCS	RADIATOR FAN BLADE		17	\$152.00	X
2 PCS	FRONT FENDERS @\$611.00		2	\$1,222.00	X
2 PCS	FRONT FENDER INNERSHIELDS @\$165.00		17	\$330.00	X
1 SET	FRONT FENDER INNERSHIELD CLIPS		17	\$50.00	X
1 PCS	ALTERNATOR		17	\$1,205.00	X
1 PCS	AIR CON COMPRESSOR		17	\$1,866.10	X
1 PCS	AIR CON SUCTION HOSE		17	\$325.30	X
1 PCS	AIR CON DISCHARGE HOES		17	\$388.20	X
1 PCS	AIR CON PIPE		17	\$195.20	X
				\$35,183.10	
	S.NETT				
1 SET	REAR BUMPER REVERSE SENSOR		shdd	\$280.00	200
1 PCS	REAR WINDSCREEN SEALANT		RM	\$50.00	✓
1 PCS	REAR END PANEL SEALANT		RM	\$50.00	✓
1 SET	REAR FLOOR PANEL INSULATOR		RM	\$180.00	✓
1 SET	REAR REVERSE CAMERA		shdd	\$380.00	✓
1 PCS	REAR LICENCE PLATE W/HOLDER		Self	\$50.00	40
1 PCS	FRONT LICENCE PLATE W/HOLDER		Self	\$50.00	40
1 BOL	RADIATOR COOLANT		RM	\$50.00	✓
	LABOUR CHARGES:				
	TO CHECK WIRING			\$80.00	30
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00	50
	TO TRANSFER TAILGATE MECHANISM			\$120.00	80
	TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00	120
	TO DISMANTLE & REFIX REAR EXHAUST			\$100.00	60
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY			\$150.00	100
	TO MOUNT VEHICLE ON CAR-OLINER		17	\$380.00	X
	TO REFILL AIR CON GAS			\$150.00	100
	TO SPRAY RUST PROOFING			\$150.00	✓
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$3,200.00	2200
	TO PUTTY & SPRAY PAINTING			\$2,500.00	2000
			TO	\$43,333.10	





AVIVA

20% off now, promo code: CAR20

Get a quote







Advanced Search

Home &gt; Used Cars &gt; ValueCars Auto Traders &gt; Honda Mobilio 1.5A RS i-VTEC Luxe

## Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle



Want to keep up with the competition?

## Honda Mobilio 1.5A RS i-VTEC Luxe

Overview Financial Insurance Accessories Similar Research Photos Map

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

## Car Details

<b>Price</b>	<b>\$69,800</b>	
<b>Depreciation</b>	\$8,840 /yr	<a href="#">View models with similar depreciation</a>
<b>Reg Date</b>	24-Nov-2015	(6yrs 9mths 26days COE left)
<b>Manufactured</b>	2015	
<b>Mileage</b>	53,633 km (16.9k /yr)	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,497 cc	
<b>Road Tax</b>	\$884 /yr	
<b>Power</b>	88.0 kW (118 bhp)	<a href="#">View specs of the Honda Mobilio (2015-2017)</a>
<b>Curb Weight</b>	1,160 kg	
<b>Features</b>	Fuel Saving 1.5L SOHC i-VTEC Engine, 6 Speed CVT Transmission, Electric Steering, Keyless Entry, Engine Immobilizer, SRS Airbags, ABS.	
<b>Accessories</b>	Sports Rims, Leather Seats, Multi Function Steering Wheel, Electrical Retractable Side Mirror, Rear Aircon, Knockdown Rear Seats.	
<b>Description</b>	Genuine Lowest Mileage 53,633 Km! 1 Owner Owned Honda Mobilio 1.5A SVI Full Service Recorded In Ksh Motor Agent! Probably The Best Honda Mobilio In This Market Now! This Model No Longer On Sale For New Car Stock List!! Please Grab This Chance To Come View This Genuine Mobilio! Come View And We Discuss Further, Thanks!	
<b>COE</b>	\$56,001	
<b>OMV</b>	\$18,965	
<b>ARF</b>	\$18,965	
<b>Dereg Value</b>	\$52,443 as of today (change)	
<b>No. of Owners</b>	1	
<b>Type of Veh</b>	MPV	
<b>Category</b>	MPV Car	
<b>Availability</b>	Available	

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 27 Jan 2019 | Last Updated on: 27 Jan 2019

Tags: Honda Mobilio, Honda mobilio, 2015 Honda Mobilio, 2015 Honda mobilio, Honda, Mobilio, mobilio, Used Honda



## Seller Information

<b>Company</b>	ValueCars Auto Traders + dealer's pricelist + 38 vehs sold   16 vehs available	
<b>Address</b>	61 Ubi Avenue 2 #02-06 Search cars nearby this location	
<b>Location</b>	Automobile Megamart	
<b>Office No</b>	68410062	
<b>Contact Person(s)</b>	Audrey Richard	96528622 88222308

## Useful Services

STA  
SPECIALIST TRADING ASSOCIATES

Afraid of lemons? Request to have this car evaluated professionally.

**Vehicle Evaluation**

Find out the market value for your car. Get a free Car Valuation.

**Free Valuation**

## Upfront Payment

[+ more Financial info](#)

<b>Transfer Fee</b>	\$25	
<b>Down Payment</b>	\$20,940 (change)	Maximum 70% Loan
<b>1st Instalment</b>	\$725	
	\$1,838 onwards	

[Compare](#)

Mobilio Price Range Depreciation 2015 Vehicle Type Submit

Advanced Search

Home > Used Cars > Zion Auto Gallery > Honda Mobilio 1.5A RS i-VTEC Luxe

## Resources

Car Buying  
Car Selling  
Car Ownership  
Car Aftermarket  
On The Move  
Lifestyle

## Car Rental



Ad

## Honda Mobilio 1.5A RS i-VTEC Luxe

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

## CAR DETAILS

**Price** \$65,800  
**Depreciation** \$5,430 /yr  
View models with similar depreciation

**Reg Date** 02-Oct-2015  
(6yrs 9mths 3days COE left)

**Manufactured** 2015

**Mileage** 69,000 km (20.7% /yr)

**Transmission** Auto

**Engine Cap** 1,497 cc

**Road Tax** \$684 /yr

**Power** 88.0 kW (118 bhp)  
View specs of the Honda Mobilio (2015-2017)

**Curb Weight** 1,160 kg

**Features** 1.5L SOHC VTEC Engine Producing 118bhp, CVT Auto Transmission, Multi Function Steering Control, Airbags, Climate Control, Retractable Side Mirrors.

**Accessories** Full RS Bodykits, Sports Rims, Premium Leather Seats, Alpine Touch Screen Player With Steering Control, Navigation/Bluetooth, Front/Rear Aircon. Etc.

**Description** 1 Owner, 5 Years Kah Motor Warranty With 3 Years Free Servicing! Most Value For Money Economical Japanese Compact 7 Seater MPV In The Market With 2nd And 3rd Row Able To Properly Fit Full Length Adults. Immaculate Condition.

**COE** \$57,498

**OMV** \$18,965

**ARF** \$18,965

**Dereg Value** \$52,629 as of today (change)

**No. of Owners** 1

**Type of Veh** MPV

**Category** PARF Car, Premium Ad Car

**Availability** Available

Add to Shortlist Add to Compare Add a Note

Posted on: 26-Jan-2019 | Last Updated on: 26-Jan-2019

Tags: Honda Mobilio, honda mobilio, 2015 Honda Mobilio, 2015 honda mobilio, Honda, Mobilio, mobilio, Used Honda

## Upfront Payment

> more Financial info.

**Transfer Fee** \$25  
**Down Payment** \$19,740 (change) Maximum 70% Loan  
**1st Instalment** \$690

Compare



## Seller Information

**Company** Zion Auto Gallery  
= dealer's pricelist  
= 4 vehs sold / 7 vehs available  
**Address** 159 Sin Ming Road #01-01  
Search cars nearby this location  
**Location** Antech Building  
**Office No** 64552535  
**Contact Person(s)** Edwin 94882373

## Useful Services

**STP** Afraid of lemons? Request to have this car evaluated professionally.  
**Vehicle Evaluation**  
Find out the market value for your car. Get a free Car Valuation.  
**Free Valuation**

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1243J
<b>Vehicle Details</b>	
Vehicle No.:	SKW5676R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	MOBILIO SV 1.5 CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15Z12101405
Chassis No.:	MRHDD4870FP000354
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,572.00
Original Registration Date:	03 Nov 2015
First Registration Date:	03 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,572.00 9786
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Nov 2025
PARF Rebate Amount:	\$14,679.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,301.00
COE Rebate Amount:	\$38,740.00
<b>Total Rebate Amount:</b>	<b>\$53,419.00</b>

The information contained herein is correct as at 28 Jan 2019

OK



View Received Message

This mail is associated with :  
  
**\*SKW5676R (84776831055G)**  
**[SLL471T]**  
TP  
MR TEO SZE CHENG  
Jan 26 2019 3:00PM  
[LCRF Pte Ltd]  
Fastech Auto Pte Ltd

ReplyReply AllMark as UnreadPrint MessageDelete MessageForward

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 03/06/2019 10:08 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$16777.45) - SKW5676R - Claim Handler: Boyogan, Joane

Approved:16777.45.

**DOCUMENTS SUMMARY**  
There are no documents.



## Jia Le (LKK Auto)

---

**From:** Boyogan, Joane <Joane.Boyogan@aig.com>  
**Sent:** Monday, 3 June 2019 10:10 AM  
**To:** Jia Le (LKK Auto)  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: (Seek Mandate) Our ref:CC6/LCR19001779/Upa3q2, Your ref: 8477683105SG ACCIDENT INVOLVING SLL471T(OI) AND SKW5676R(TP) ON 26/01/2019

Dear Carlor,

Mandate approved in Merimen

Thank you

Regards,

**Joane Boyogan**  
AIG  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +65 64191898  
[joane.boyogan@aig.com](mailto:joane.boyogan@aig.com) | [www.aig.sg](http://www.aig.sg)



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.  
[Click here to find out more](#)

Follow us:



### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Jia Le (LKK Auto) [mailto:[JiaLe@lkkauto.com](mailto:JiaLe@lkkauto.com)]  
**Sent:** Wednesday, May 29, 2019 5:30 PM  
**To:** Boyogan, Joane  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** [EXTERNAL] (Seek Mandate) Our ref:CC6/LCR19001779/Upa3q2, Your ref: 8477683105SG ACCIDENT INVOLVING SLL471T(OI) AND SKW5676R(TP) ON 26/01/2019

This message is from an external sender; be cautious with links and attachments.

AIG Ref: **8477683105SG**

LKK Ref: CC6/LCR19001779/Upa3q2

Dear Sirs/Madam,

**ACCIDENT INVOLVING SLL 471T(OI) AND SKW 5676R(TP) ON 26/01/2019**

We refer to the above matter.

3 vehicles chain collision, insured driver was the last vehicle. Liability is not in our driver's favour. We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "**Fastech Auto Pte Ltd**" is as follows: -

	<b>Claimed Amount</b>	<b>Revised Amount</b>
1. Cost of Repair (w/GST)	\$ 46,366.42	\$ 16,050.00
2. Loss of Use (10days x \$60.00)	\$ 720.00	\$ 720.00 (10days x \$60.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
<b>Total</b>	<b>\$ 47,093.87</b>	<b>\$ 16,777.45</b>

\*\*10days recommendation for repair + 1Sunday + 1PH = 12days

All the relevant documents had been uploaded in Merimen.

**Kindly let us have your mandate in Merimen.**

Best Regards,

**Carlor Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Date : 09.04.2019

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Dear Sir/Madam,

## ACCIDENT INVOLVING VEHICLES SKW 5676R / SLL 471T ON 26.01.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SKW 5676R**, which was involved in the captioned accident with your insured vehicle no: **SLL 471T**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 16,050.00
2) Loss of Use (10Days + 2 Sunday X \$ 60)	\$ 720.00
3) LTA Search Fee	\$ 7.45
	<u>\$ 16,777.45</u>

We enclosed herewith the following documents to support the claims:

- |                                    |                                  |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice            | b) LTA Search Result             |
| c) Letter of Authorisation, etc... | d) GIA Report                    |
| e) Police Report                   | f) I/C & Driving Licence         |
| g) Insurance Certificate           | h) Vehicle Registration Log Card |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you.

Yours faithfully,



Jason Tang (jason@fastechauto.com.sg)

For FASTECH AUTO PTE LTD

## Jia Le (LKK Auto)

---

**From:** Jia Le (LKK Auto)  
**Sent:** Tuesday, 4 June 2019 3:14 PM  
**To:** jason@fastechauto.com.sg  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: Your ref: SKW5676R \*Our Ref: CC6/LCR19001779/Upa3 [ACCIDENT INVOLVING SLL471T & SKW5676R ON 26/01/2019]  
**Attachments:** SKW 5676R.pdf

### WITHOUT PREJUDICE

Dear Sirs/Mdm,

Please duly sign the DV enclosed and return to us.

Thank you.

Best Regards,

**Carlor Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jason Fastech Auto [mailto:jason@fastechauto.com.sg]  
**Sent:** Tuesday, 4 June 2019 2:43 PM  
**To:** Jia Le (LKK Auto)  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: Your ref: SKW5676R \*Our Ref: CC6/LCR19001779/Upa3 [ACCIDENT INVOLVING SLL471T & SKW5676R ON 26/01/2019]

### **Without Prejudice**

Dear Sirs/Mdm,

*We do accept your offer as below.*

Regards,

Lina

For and on behalf of Jason

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

---

**From:** Jia Le (LKK Auto) [mailto:[Jiale@lkkauto.com](mailto:Jiale@lkkauto.com)]  
**Sent:** Monday, June 3, 2019 1:30 PM  
**To:** [jason@fastechauto.com.sg](mailto:jason@fastechauto.com.sg)  
**Cc:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** Your ref: SKW5676R \*Our Ref: CC6/LCR19001779/Upa3 [ACCIDENT INVOLVING SLL471T & SKW5676R ON 26/01/2019]

**WITHOUT PREJUDICE**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$16,700.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Carlur Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Monday, 4 March 2019 10:50 AM  
**To:** 'Insurance LCR SG'; 'Eileen, May Hwee Yap'  
**Subject:** ACCIDENT INVOLVING SLL 471T(AIG) /SKW 5676R/ OTHERS ON 26/01/2019

Your Ref: **SLL 471T**  
Our Ref: CC6/LCR19001779/Upa3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLL 471T(AIG) /SKW 5676R/ OTHERS ON 26/01/2019**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SKW 5676R against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**


I, TEO SZE CHENG ("the third party claimant")  
of Blk 639 Bedok Reservoir Road #08-53 (S) 410639 (address),  
owner of SKW 5676R (vehicle no.) hereby authorize  
FASTECH AUTO PTE LTD

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SKW 5676R that was  
damaged pursuant to the accident which occurred on 26.01.2019 (date) along  
Pan Island Expressway (location)  
involving vehicle no/s SLL 471T ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 28 day of JANUARY (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"



DATE : 26.01.2019

TO : AIG Asia Pacific Insurance Pte. Ltd.

RE : ACCIDENT INVOLVING VEHICLE NO. SKW 56T6R / SLL 471T

ALONG Pan Island Expressway

ON 26-01-2019

I/We, TEO SEE CHENG

of (NRIC No./ROC No.) S 1711243J

of BLK 639 bedok reservoir road #08-53 S.410639

owner of vehicle no. SKW 56T6R in consideration of M/s FASTECH AUTO PTE LTD repairing my/our vehicle SKW 56T6R at my/our instruction and hereby authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost which may arisen therewith.

Signature of Owner :



Name of Owner :

TEO SEE CHENG

P \*\*\* This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an Evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **FASTECH AUTO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$16,700.00** (Global Sum) for vehicle no. **SKW 5676R** that was damaged pursuant to the accident which occurred on **26/01/2019** (date) along **PIE TWDS CHANGI AFTER TOA PAYOH EXIT** involving vehicle no/s **SLL 471T**.

This is pursuant to the inspection conducted on **28/01/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TEO SZE CHENG** ("the third party claimant") of vehicle no. **SKW 5676R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKW 5676R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 08<sup>th</sup> (day) of July (month) 2019 (year)



Signed by appointed surveyor

Signed by "the workshop" (with chop)

## TAX INVOICE

### **FASTECH AUTO PTE LTD**

**1 Kaki Bukit Ave 6 #01-48 Autobay**

**Singapore 417883**

**Tel No: 67452063 / 67467158 Fax No: 67458520**

**Tax Reg No: 200006262D**

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn : Motor Claim Department

Tax Invoice : 20845

Date : 09.04.2019

Vehicle No : SKW 5676R

Make/Model : HONDA MOBILIO

Chassis/Eng# :

Accident Date : 26.01.2019

Claim No :

Reference : 0119 -20845

Policy No :

---

	Amount
To proceed on lump sum repair	S\$ 15000.00

E. & O. E.

Total : S\$ 15000.00

GST @ 7% : S\$ 1050.00

*Amount Due* : **S\$ 16050.00**

  
for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

[Back to OneMotoring](#)


Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 28 Jan 2019 / 09:24:14

Receipt Date/Time : 28 Jan 2019 / 09:24:14

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-190128-000328

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLL471T				
As at 26 Jan 2019/15:45:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLL471T			
	Enquiry Fee	7.00	0.49	7.49
	20190128092327838891			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	20190128092338748	Direct Debit: eNETS Debit (Internet Banking)		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019 <a href="#">Edit Reg</a>		28 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$15,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$15,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K								
Main Claimant:	MR TEO SZE CHENG, ID: S17112433								
Vehicle Reg. No.:	SKW5676R	Date of Loss:	26/01/2019 15:00 - :59 [38 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8477683105SG	Policy/Cover Note No.:	0999994805 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLL471T	Policy No. (Claimant):	18-MW009668-R03						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Boyogan, Joane</b> ] Joane.Boyogan@aig.com								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 08/02/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (03/06/2019): Alert - Adj Mandate Approved (S\$16777.45) - SKW5676R - Claim Handler: Boyogan, J...</li> <li>AIG_SG (29/01/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKW5676R (8477683105SG)  
[SLL471T]  
TP  
MR TEO SZE CHENG  
Jan 26 2019 3:00PM  
[LCRF Pte Ltd]  
Fastech Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** View in Browser

**Letters/Correspondences**


















































1 per page
☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		<input type="checkbox"/>



















































**Photos/Images**



















































3 per page
☒


































No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 18:21	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	28/01/19 18:21	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
24	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
25	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
27	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
28	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
29	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
30	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
31	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
32	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
33	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>
34	28/01/19 18:22	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
35	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
36	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
37	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
38	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
39	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
40	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
41	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
42	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
43	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
44	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
45	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
46	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
47	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
48	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
49	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
50	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
51	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
52	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
53	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
54	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
55	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
56	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
57	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
58	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
59	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
60	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
61	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
62	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
63	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
64	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
65	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
66	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
67	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
68	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
69	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
70	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
71	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
72	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
73	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
74	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
75	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
76	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
77	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
78	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
79	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
80	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
81	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
82	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>
83	28/01/19 18:22	General View		Load JPG	<input checked="" type="checkbox"/>



Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	28/01/19 18:22	General View	 Load JPG	<input checked="" type="checkbox"/>
85	28/01/19 18:22	General View	 Load JPG	<input checked="" type="checkbox"/>
86	28/01/19 18:22	General View	 Load JPG	<input checked="" type="checkbox"/>
87	28/01/19 18:22	General View	 Load JPG	<input checked="" type="checkbox"/>
88	28/01/19 18:22	General View	 Load JPG	<input checked="" type="checkbox"/>
89	28/01/19 18:22	General View	 Load JPG	<input checked="" type="checkbox"/>
90	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	28/01/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	28/01/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/19 17:50	TP GIA REPORT	 Load PDF	
2	28/05/19 14:54	LTA SEARCH	 Load PDF	
3	28/05/19 14:54	LETTER TO OI	 Load PDF	
4	29/05/19 17:10	TP ESTIMATE - MARKED	 Load PDF	
5	29/05/19 17:10	WORKSHOP INVOICE	 Load PDF	
6	16/07/19 11:27	AUTHORISATION TO ACT FORM	 Load PDF	
7	16/07/19 11:27	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/01/19 10:38	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL471T (Insd veh)	Model:	HONDA MOBILIO SV 1.5 CVT
	SKW5676R (TP veh)		(A)
Date of Accident:	26/01/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No
Repair Estimate	:	\$	46,366.42
Final Repair Cost	:	\$	16,700.00
Loss of Use	:	\$	12.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	16,700.00

Is Third Party Workshop GIA Registered? ☐ [ ] YES ☒ [ X ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ 100 \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 16,700.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

16 Jul  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR19001779/UPA3Q2

Date: 16/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994805  
**Claimant Vehicle No :** SKW5676R **Insured Vehicle No :** SLL471T  
**Date of Loss:** 26/01/2019 **Nature of Claim:** TP **Claim No:** 8477683105SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW5676R**  
 Make & Model: HONDA MOBILIO SV, 1.5 CVT (A) Engine No: L15Z12101405  
 Reg. Date: 03/11/2015 (Man. Year: 2015) Chassis No: MRHDD4870FP000354  
 Colour: White Odometer: 74162 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15  
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,273.10	13,910.88	22,362.22	61.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,060.00	4,890.00	2,170.00	30.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>43,333.10</b>	<b>18,800.88</b>	<b>24,532.22</b>	<b>56.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>15,000.00</b>		
(S\$)	43,333.10	15,000.00	28,333.10	65.38
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,033.32</b>	<b>1,050.00</b>	<b>1,983.32</b>	<b>65.38</b>
<b>Nett Amount (S\$)</b>	<b>46,366.42</b>	<b>16,050.00</b>	<b>30,316.42</b>	<b>65.38</b>
<b>+ Loss of Use (12.0 x S\$60.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>16,777.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>16,700.00</b>		

### INSPECTION

Date of Assignment: 28/01/2019  
 Date Inspected: 28/01/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 10.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	161.10 F	*161.10 FL
2	1		*TAILGATE	Badly Dented	1,266.30 F	*1,125.00 FL
3	1		*TAILGATE H LOGO	Necessary	45.80 F	*38.00 FL
4	1		*TAILGATE MOBILLO EMBLEM	Necessary	48.80 F	*48.80 FL
5	1		*TAILGATE RS EMBLEM	Necessary	45.00 F	*45.00 FL
6	1		*TAILGATE IVTEC EMBLEM	Necessary	48.50 F	*48.50 FL
7	2		*TAILGATE REFLECTORS	Not Necessary	976.20 F	*- FL
8	1		*TAILGATE OUTER GARNISH	Twisted / Cracked	385.40 F	*385.40 FL
9	1		*TAILGATE INNER LOCK	Dented / Jammed	266.20 F	*178.20 FL
10	1		*TAILGATE LOCK SENSOR	Not Necessary	285.50 F	*- FL
11	1		*TAILGATE LOCK BUZZER	Not Necessary	208.30 F	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	650.10 F	*466.05 FL
13	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	188.20 F	*188.20 FL
15	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	825.00 F	*- FL
16	1		*REAR BUMPER	Distorted	845.10 F	*463.70 FL
17	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*- FL
18	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
19	1		*REAR BUMPER TOP PROTECTOR	Not Necessary	311.20 F	*- FL
20	1		*REAR BUMPER TOP PROTECTOR CHROME	Cracked	288.50 F	*288.50 FL
21	2		*REAR BUMPER REFLECTORS	Not Necessary	90.00 F	*- FL
22	2		*REAR BUMPER SIDE GRILLES	Not Necessary	170.00 F	*- FL
23	1		*REAR END PANEL	Badly Dented	611.20 F	*414.70 FL
24	1		*REAR END PANEL TOP GARNISH	Distorted	298.30 F	*298.30 FL
25	1		*REAR EXHAUST	Repair	688.50 F	*- FL
26	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
27	2		*REAR FENDERS	Repair	2,210.20 F	*- FL
28	2		*REAR FENDER INNER BOARDS	Deformed / Torn	970.00 F	*970.00 FL
29	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,120.10 F	*1,120.10 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	660.50 F	*- FL
31	2		*TAILLAMPS	Cracked	1,360.20 F	*771.00 FL
32	2		*TAILLAMP HOUSING PANELS	Repair	510.00 F	*- FL
33	1		*REAR SPARE TYRE BRACKET	Bent	322.20 F	*322.20 FL
34	2		*REAR FENDER INNER TOP GARNISH	Not Necessary	290.00 F	*- FL
35	1		*BONNET	Dented / Buckled	866.20 F	*866.20 FL
36	1		*BONNET RUBBER	Necessary	85.00 F	*85.00 FL
37	2		*BONNET HINGES	Not Necessary	210.00 F	*- FL
38	1		*BONNET INSULATOR	Not Necessary	245.50 F	*- FL
39	1		*BONNET INSULATOR CLIPS	Not Necessary	45.00 F	*- FL
40	1		*BONNET LOCK	Twisted	165.00 F	*165.00 FL
41	1		*FRONT BUMPER	Distorted	745.30 F	*566.05 FL
42	2		*FRONT BUMPER SIDE RETAINERS	Necessary / Bent	90.00 F	*90.00 FL
43	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
44	1		*FRONT BUMPER LOWER CENTRE GRILLE	Torn	211.20 F	*211.20 FL
45	2		*FRONT BUMPER FOG LAMPS	Cracked	1,300.00 F	*990.00 FL
46	2		*FRONT BUMPER FOG LAMP COVERS	Twisted	300.00 F	*272.40 FL
47	1		*FRONT BUMPER REINFORCEMENT	Distorted	315.20 F	*315.20 FL
48	1		*FRONT GRILLE	Cracked	385.40 F	*242.60 FL
49	1		*FRONT GRILLE OUTER CHROME	Cracked	311.50 F	*250.00 FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRONT GRILLE H LOGO	Necessary	38.50 F	*38.50 FL
51	2		*FRONT FOG LAMP CHROME MOULDINGS	Not Necessary	220.00 F	*- FL
52	1		*FRONT SUPPORT PANEL	Bent / Twisted	754.50 F	*664.30 FL
53	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	288.20 F	*- FL
54	2		*HEADLAMPS	Cracked	2,900.00 F	*1,640.40 FL
55	1		*AIR CON CONDENSER	Bent / Punctured	1,100.20 F	*866.20 FL
56	1		*RADIATOR	Bent / Punctured	1,866.20 F	*1,415.30 FL
57	1		*RADIATOR FAN MOTOR	Not Necessary	395.00 F	*- FL
58	1		*RADIATOR FAN COWLING	Not Necessary	145.00 F	*- FL
59	1		*RADIATOR FAN BLADE	Not Necessary	152.00 F	*- FL
60	2		*FRONT FENDERS	Repair	1,222.00 F	*- FL
61	2		*FRONT FENDER INNERSHIELDS	Not Necessary	330.00 F	*- FL
62	1		*SET FRONT FENDER INNERSHIELD CLIPS	Not Necessary	50.00 F	*- FL
63	1		*ALTERNATOR	Not Necessary	1,205.00 F	*- FL
64	1		*AIR CON COMPRESSOR	Not Necessary	1,866.10 F	*- FL
65	1		*AIR CON SUCTION HOSE	Not Necessary	325.30 F	*- FL
66	1		*AIR CON DISCHARGE HOSE	Not Necessary	388.20 F	*- FL
67	1		*AIR CON PIPE	Not Necessary	195.20 F	*- FL
68	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
69	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
70	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
71	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*380.00 FS
72	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	180.00 FS	*180.00 FS
73	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
74	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
75	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>36,273.10</b>	<b>17,141.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>3,230.22</b>
<b>Total Parts (\$\$)</b>	<b>36,273.10</b>	<b>13,910.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
6	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	New	150.00	100.00
7	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
8	TO REFILL AIR CON GAS	New	150.00	100.00
9	TO SPRAY RUST PROOFING	New	150.00	150.00
10	LABOUR FOR PANEL BEATING & REPACING PARTS	New	3,200.00	2,200.00
11	TO PUTTY & SPRAY PAINTING	New	2,500.00	2,000.00
<b>Gross Labour Cost (S\$)</b>			<b>7,060.00</b>	<b>4,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >