

15/5/2019

INS. CASE OWNER:

Bernard

CC 3/AIG1900

1785, Jf6b52

LKK:
IDAC:

Surveyor:

Hj.

DOI:

ASSIGNMENT

15/1/19

Date / Time:

Registered in Merimen:

pohkin

15/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMA 8822H

Name of Insured:

BIS MOTORING PTE LTD

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

22/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

GOW SENG HONG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

2222222222

Policy No.:

999994322

Make / Model:

LIA

Place of Accident:

232 COMMONWEALTH TOWN

CONDO MINIMUM DROFF POINT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC4355T

INSRS:
WSP:
Tel:
Liability:
RMKS:

SMRT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHC4355T 22/1/19 11:14:00 24/01/19 11:14:00

19/1/19 OSD receiving and colliding into 7P taxi, send letter for

pending LOO ✓

before point photo ✓

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	19/1/19
Documentation Check List:	
Notification ltr (if non-pickup)	☐
After call ltr to OI:	☒
Authorisation To Act:	☒
Release Voucher:	☒
Final Repair Bill:	☒
Car Rental Invoice:	☒
Towing Invoice:	☐
LTA / GIA:	☒
Medical Bill:	☐
PIR:	☐
Mandate/Reject Instruction:	☐
LOD:	☒
Payment Breakdown Form:	☐
Post-Repair Photos:	☐
Others:	☐

PRELIMINARY ADVICE Date/Time: 28/1/2019 Sent By: LSP

FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS 1,212.51	(3 days)	Reduction: 78.50 %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 11/3/2019 Confirm with Lee Gek				
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No.:	NI
Repair Cost:	SS 1,212.51			
Loss of Rental (LOR):	SS 535	(4 days)	x \$133.75	
Loss of Use (LOU):	SS -	(S x days)		
Loss of Income (LOI):	SS -	(S x days)		
LOR only ☒	LOU only ☐	LOR + LOU ☐	LOR + LO ☐	[Tick only one]
GIA/LTA Search	SS 7.00			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost	SS -			
Total:	SS 1,754.51		Global Sum SS: 1,750.00	
FINAL PAYMENT Date/Time: Confirm with: Email ☒ Call ☐				
Payee 1:	SS 1,750.00	Name 1:	SMRT TAXIS PTE LTD	
Payee 2: (Strike if N.A.)	SS -	Name 2:		
Payee 3: (Strike if N.A.)	SS -	Name 3:		

COPY SENT 11/3/2019

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: 7P
 3) Survey fee: + 320.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG19001785/Jfb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 28-01-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 8822H	Veh. Inspected	SHC 4755T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/01/2019	Inspection Date	25/01/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Poh kin

Finalized - Hwee Jie

Section A - Accident Details

Registration Number	SHC4755T
Case Reference Number	TAX01/19/2115
Registration Date	1/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SENA YEO SAY KIM
Type of Accident	Rear To Head
Accident Date and Time	23/1/2019 10:43 PM
Accident Reported Date and Time	24/1/2019 2:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099830
Special Instruction to ARC, if any	TSS
Prepared Date and Time	24/1/2019 4:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$350.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$3,786.62	\$412.51
Total Other Cost	\$240.00	\$50.00
TOTAL COST	\$5,638.62	\$1,212.51 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	24/01/2019 4:38 PM	25/01/2019 2:13 PM
Signature		
Remarks	P/P REPAIR, PHOTO BEFORE PAINT.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1902-0085	Invoice Number	
Quotation Date	09.02.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$350.00
Total Labour	\$676.00	\$350.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$240.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given
		52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given
		52811-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given
		81529-47080	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Not Given
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		81230-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
		52116-47040	BUMPER SUPPORT-FILH	0.00	\$76.40	0.00	\$0.00	Replace	Check
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		61521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	100.00	\$0.00	Replace	Repair

	53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X	hh
	52181-16010	BUMPER CLIPS	10.00	\$1.61 ^{16.10}	25.00	\$12.08	Replace	Replace	✓	nec
	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X	hh
Total				\$4,686.91		\$412.51				

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

6553.40

$$\begin{array}{r}
 412.51 \\
 + 350.00 \\
 + 450.00 \\
 \hline
 1212.51
 \end{array}$$

15/2/19 - Finalized P/P \$1212.51/- 3days.





Case Details

Case Reference Number :

TAX/01/19/2115

Type of Repair : Accident Repair

Vehicle Registration Number :

SHC4755T

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-5492-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Accident Date and Time : 23/01/2019 02:43 PM

Vehicle Age(In Months) : 33

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Replace ▾ BUC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give ▾ NN
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check ▾
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give ▾
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give ▾
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give ▾

Total Spare Part Cost 3,786.62

Lump Sum Discount (%) 0.00

Final Spare Part Cost 3,786.62

Surveyor Total 412.50

Lump Sum Dis (%) 0

Final Sur Total 412.50

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give ▾
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give ▾
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give ▾
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	1	0	Repair ▾
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check ▾
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give ▾
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give ▾
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair ▾
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give ▾
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give ▾
Total Spare Part Cost									3,786.62	Surveyor Total		412.50	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0	
Final Spare Part Cost									3,786.62	Final Sur Total		412.50	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	676.00	350	
Total:			676.00	350.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			240.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,786.62	412.50
Total Labour Cost	676.00	350.00
Total Spray Painting	936.00	400.00
Other	240.00	50.00
Overall Total	5,638.62	1,212.50
Lump Sum Repair Option		
Lump Sum Total	0.00	1,212.50

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Approved Amount

1,212.50

No of Repair Days*

5

3

Remarks

P/P REPAIR, PHOTO BEFORE PAINT.

Surveyor Name

Hwee jie

Signature



Save

Clear

Survey Date

25/01/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poh Kin (LKKAUTO)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Monday, 11 March 2019 5:42 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: LOD Re: Accident on 23/1/2019 involving SHC 4755T & SMA 8822H (AIG's insured)
Our Ref: TAX/01/19/2115/lg

Dear Poh Kin,

We accept your global offer of \$1750.00 for our own losses. Please let us have your DV. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: 11/03/2019 16:53
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Admin A
Subject: RE: LOD Re: Accident on 23/1/2019 involving SHC 4755T & SMA 8822H (AIG's insured) Our Ref: TAX/01/19/2115/lg
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIGI19001785/Jfb3
Your Ref: TAX/01/19/2115/lg

Dear Lee Gek,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$1,750.00(all in)** on this matter.

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 11 March 2019 4:53 PM
To: 'Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)'
Cc: Admin A
Subject: RE: LOD Re: Accident on 23/1/2019 involving SHC 4755T & SMA 8822H (AIG's insured) Our Ref: TAX/01/19/2115/lg

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIGI19001785/Jfb3
Your Ref: TAX/01/19/2115/lg

Dear Lee Gek,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$1,750.00(all in)** on this matter.

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Monday, 11 March 2019 4:24 PM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 23/1/2019 involving SHC 4755T & SMA 8822H (AIG's insured)
Our Ref: TAX/01/19/2115/lg
Attachments: TAX 01 19 2115.pdf

Dear All,

We quantify our own losses as follows:-

Cost of Repair	\$1212.51
Loss of Rental	\$601.88 (4.5 days x \$133.75)
LTA Search Fee	\$7.00
Total	\$1821.39

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019 Edit Reg		25 Jan 2019 00:00 Edit Adj Rpt	S\$1,212.51 Edit Estimates	S\$1,212.51 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D		
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC4755T	Date of Loss:	23/01/2019 00:00 - :59 [33 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2620496894SG	Policy/Cover Note No.:	0999994322 (Comprehensive)
Vehicle Reg. No. (Insured):	SMA8822H	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 08/02/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SHC4755T (2620496894SG)
[SMA8822H]**

TP

SMRT TAXIS PTE LTD

Jan 23 2019 12:00AM

[BIS MOTORING PTE LTD]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit
Photos/Images			3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	29/01/19 09:36	General View	1	Load JPG ☒
2	29/01/19 09:36	General View	1	Load JPG ☒
3	29/01/19 09:36	General View	1	Load JPG ☒
4	29/01/19 09:36	General View	1	Load JPG ☒
5	29/01/19 09:36	General View	1	Load JPG ☒
6	29/01/19 09:36	General View	1	Load JPG ☒
7	29/01/19 09:36	General View	1	Load JPG ☒
8	29/01/19 09:36	General View	1	Load JPG ☒
9	29/01/19 09:36	General View	1	Load JPG ☒
10	29/01/19 09:36	General View	1	Load JPG ☒
11	29/01/19 09:36	General View	1	Load JPG ☒
12	29/01/19 09:36	General View	1	Load JPG ☒
13	29/01/19 09:36	General View	1	Load JPG ☒
14	29/01/19 09:36	General View	1	Load JPG ☒
15	29/01/19 09:37	Replacement Part Photo	1	Load JPG ☒
16	29/01/19 09:37	Replacement Part Photo	1	Load JPG ☒
17	29/01/19 09:37	Replacement Part Photo	1	Load JPG ☒
Documentation			1 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/01/19 17:50	TP ESTIMATE- MARKED	1	Load PDF
2	28/01/19 17:50	TP GIA REPORT	1	Load PDF
3	20/02/19 17:31	LETTER TO OI	1	Load PDF
4	15/03/19 09:34	AUTHORISATION TO ACT	1	Load PDF
5	15/03/19 09:34	LTA SEARCH	1	Load PDF
6	15/03/19 09:34	RELEASE VOUCHER	1	Load PDF
7	15/03/19 09:34	RENTAL MILEAGE	1	Load PDF
8	15/03/19 09:34	RENTAL RECEIPT	1	Load PDF
9	15/03/19 09:34	WORKSHOP INVOICE	1	Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	29/01/19 14:20	OI GIA REPORT	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMA8822H (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4755T (TP veh)		
Date of Accident:	23/01/2019		

Global Sum Settlement	:	[X] Yes	[] No	
Repair Estimate	:	\$		6,553.40
Final Repair Cost	:	\$		1,750.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		4 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		1,750.00

Is Third Party Workshop GIA Registered?	[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	: \$	1,750.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

15 Mar
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001785/JFB3S2

Date: 15/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994322

Claimant Vehicle No: SHC4755T

Insured Vehicle No: SMA8822H

Date of Loss: 23/01/2019

Nature of Claim: TP

Claim No: 2620496894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4755T

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR6588830

Reg. Date: 01/04/2016 (Man. Year: 2015)

Chassis No: JTDKN36U805767765

Colour: Maroon

Odometer: 304402 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Chilles 6 mm

Rear Left Side:

Chilles 6 mm

Front Right Side: Chilles 6 mm

Rear Right Side:

Chilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,701.40	412.51	4,288.89	91.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,852.00	800.00	1,052.00	56.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,553.40	1,212.51	5,340.89	81.50
+ Car Rental (4.0 x S\$133.75/day) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,754.51		
Global Sum Settlement (S\$)		1,750.00		

INSPECTION

Date of Assignment: 25/01/2019

Date Inspected: 25/01/2019 Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=787363&extid=293821&CFID=49825271&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
2	1		*BUMPER FRT (DISC 25%)	Buckled	482.00 F	*361.50 F
3	1		*BUMPER CLIPS (DISC 25%)	Necessary	16.10 F	*12.08 F
			10pcs			
4	1		*BRACKET, FR TURN UPPER LH	Not Necessary	24.40 F	*- F
5	1		*BUMPER GRILLE SUB-ASSY, LOWER	Not Necessary	311.10 F	*- F
6	1		*COVER, FR BUMPER HOLE LH	Not Necessary	18.50 F	*- F
7	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
8	1		*BRACKET, FR TURN LOWER LH	Not Necessary	26.00 F	*- F
9	1		*BRACKET, FR TURN CENTER LH	Not Necessary	58.20 F	*- F
10	1		*FOG LAMP LH	Not Necessary	280.10 F	*- F
11	1		*HEAD LAMP LH	Not Necessary	945.20 F	*- F
12	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
13	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
14	1		*FENDER LINER FRT/LH	Not Necessary	171.70 F	*- F
15	1		*ARM SUB-ASSY, FR BUMPER LH	Not Necessary	250.40 F	*- F
16	1		*FENDER LINER PAD, FR WHEEL LH	Not Necessary	49.30 F	*- F
17	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
18	1		*FENDER FRT/LH	Repair	723.40 F	*- F
19	1		*LENS & BODY, FR TURN LH	Repair	511.80 F	*- F

F=Franchise part.

Total Parts (\$\$)	4,701.40	412.51
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BDOYWORK.	New	676.00	350.00
2	SPRAY PAINTING.	New	936.00	400.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	30.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
5	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			1,852.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >