

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMA6886L

Chassis No : JHMRC1880JC201615

Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)

Owner's Name : YIM HOONG KWONG

Ins Policy No. :

Date of Accident : 25/1/2019

Document No. : SQT19000452 Page 1

Date : 25. Jan 2019

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72400618

Date | Time : 25. Jan 2019 4:45:28 PM

Surveyor Name :

Survey Date : DID : +65 6846 5673
HP : +65 8100 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YIM HOONG KWONG OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 25/01/19 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SJV4605U						
68100-T6A-Q10ZZ	TAILGATE COMP <i>Revised</i>	1	1070.80	25	✓ 803.10	56.22	<i>859.32</i>
74440-T6A-003	WEATHERSTRIPTAILGATE <i>new</i>	1	117.40	25	✗ 88.05	6.16	94.21
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		? 320.00	22.40	342.40
04715-T6A-900ZZ	FACERR.BUMPER <i>old</i>	1	568.30	25	✓ 426.22	29.84	456.06
71507-T6A-003ZK	FACE,L.RR.BUMPER <i>old</i>	1	76.80	25	✓ 57.60	4.03	61.63
71517-T6A-901ZM	SPOILER ASSY,L.RR. <i>2yr</i>	1	93.00	25	✗ 69.75	4.88	74.63
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>3yr</i>	1	19.10	25	✓ 14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	✓ 14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER <i>new</i>	8	2.30	25	✓ 13.80	0.97	14.77
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>new</i>	1	45.40	25	✗ 34.05	2.38	36.43
75722-T6A-901	EMBLEM,RR. <i>new</i>	1	31.00	25	✓ 23.25	1.63	24.88
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	✓ 27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	✓ 12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	✓ 12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	✓ 11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.70	25	✓ 2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	✓ 12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	✓ 3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		✓ 60.00	4.20	64.20
Sum Item					2007.62	140.53	2,148.15

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMA6886L

Chassis No : JHMRC1880JC201615

Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)

Owner's Name : YIM HOONG KWONG

Ins Policy No. :

Date of Accident : 25/1/2019

Document No. : SQT19000452

Date : 25. Jan 2019

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : K24W72400618

Date | Time : 25. Jan 2019 4:45:28 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	30.00		23 30.00	2.10	32.10
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00		✓ 100.00	7.00	107.00
BOMISC	TO REPROGRAMME AND RESET KEYLESS ENTRY	1	280.00		✓ 280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00		✓ 280.00	19.60	299.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	300.00		✓ 300.00	21.00	321.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1500.00		1120 1500.00	105.00	1605.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1600.00		1350 1600.00	112.00	1712.00
Sum Labor					<u>4090.00</u>	<u>286.30</u>	<u>4,376.30</u>

Survey By

Date & Time

Excess

Status

Signature

Adrian L
30/01/19.
05 Days.
Not Authorised
[Signature]

Total Amount 6,097.62 426.83 6,524.45

Total (Inclusive of GST) 6,524.45

Printed on 25/1/2019 5:44:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)