

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLF 6268G
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES1991107/YISHUN
 Date: 29 Jan 2019
 Policy No: 5083994955-02
 Veh Reg No: SLF6268G
 Make/Model: TOYOTA COROLLA
 AXIO 1.5G CVT ABS
 D/AIRBAG 2WD

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 21/01/2019
 TP Veh Reg No: SJP8037P

Chassis No: NRE1610019983
 Engine No: 2NR8651892
 Reg. Date: 14/09/2016

Not Authair

Resumy B4 paint

3 days

Estimate Repair Cost to Vehicle No :SLF6268G

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	530.50	1 PC	<i>Be</i> 530.50	—
2 REAR BUMPER CLIPS	3.90	6 PCS	<i>M</i> 23.40	—
3 REAR BUMPER RH SIDE RETAINER	92.33	1 PC	<i>D, I</i> 92.33	—
4 REAR BOOT	845.90	1 PC	<i>B</i> 845.90	—
5 REAR BOOT LOGO	52.50	1 PC	<i>M</i> 52.50	—
6 REAR BOOT EMBLEM (COROLLA)	40.50	1 PC	<i>M</i> 40.50	—
7 REAR BOOT EMBLEM (AXIO)	51.45	1 PC	<i>M</i> 51.45	—
8 REAR BOOT EMBLEM (G)	37.43	1 PC	<i>M</i> 37.43	—
9 REAR BOOT INNER LOCK	360.42	1 PC	360.42	?
10 REAR BOOT INNER RUBBER	287.10	1 PC	287.10	?
11 REAR BOOT OUTER MOULDING	313.88	1 PC	313.88	?
12 RH TAILLAMP	548.20	1 PC	548.20	?
13 REAR PANEL	602.10	1 PC	602.10	?
14 REAR PANEL INNER TOP GARNISH	218.90	1 PC	<i>nd</i> 218.90	✓
			4,004.61	
		Less 25%	1,001.15	3,003.46
Labour				
15 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR SPARE TYRE PANEL, REAR RH FENDER & REALIGN THE SAME	800.00	1 LA	800.00	<i>850</i>
16 PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR FENDER, REAR BUMPER, BOOT	800.00	1 LA	800.00	<i>720</i>
17 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
18 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,710.00	1,710.00
		Total	S\$ 4,713.46	
		Add GST @ 7%	329.94	
		Total Amount Payable	S\$ 5,043.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE