

AH LIM MOTOR COMPANY

176 SIN MING DRIVE #05-12
SIN MING AUTOCARE Singapore 575721
Tel: 64563637 Fax: Email:
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	MCS1900016
Policy No:	PNPV2018-00012112	Date of Loss:	25/01/2019
Vehicle Reg. No.:	SDH53H	Driveable?	
Driver Age/Info:	41 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	SIO WEE SYN		
Driver:	YVONNE GOH HWEE PENG		

Make/Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Vehicle Reg. Date:	23/09/2009
Vehicle Colour:	BLUE		
Engine No:	1AZH365038	Chassis No:	JTEGH23B800026986
Odometer:	0 KM		

Paint Type: *18*
Total Loss? **NO**
Est. Duration of Repair (day) *18 6 days*

Description of Accident/Loss: REFER TO ATTACH POLICE REPORT NO. T/20190125/2075 DD. 25/01/2019

Remarks: CAR IS IN OUR SIN MING WORKSHOP. PLS ARRANGE FOR SURVEY SOONES

Present Location: AH LIM MOTOR COMPANY (SIN MING)

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

UKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	Amount
Signature:	2,413.00
Date:	0.00
	2,000.00
	0.00
	0.00

Gross Total (S\$)	4,413.00
+ GST 7.00% (S\$)	308.91
Nett Amount (S\$)	4,721.91

This claim is handled by: KEE MUI HONG

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2019)**Parts:** M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SDH53H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*RADIATOR COOLANT	M 0	0.00	*35.00 FS	✓
2	1		*NUMBER PLATE	CM 0	0.00	*35.00 FS	25.52
3	1		*FRONT BONNET	0.00	M 0.00	*210.00 F	✓
4	2		*FRONT BONNET HINGE LH / RH	0.00	R 0.00	*50.00 F	x
5	1		*FRONT BUMPER	M 0.00	0.00	*180.00 F	✓
6	2		*FRONT BUMPER SIDE RETAINER LH / RH	DIY 0.00	0.00	*80.00 F	✓
7	20		*FRONT BUMPER CLIPS	M 0.00	0.00	*20.00 F	✓
8	1		*FRONT BUMPER REINFORCEMENT	M 0.00	0.00	*95.00 F	✓
9	2		*FRONT BUMPER REINFORCEMENT BRACKET LH / RH	0.00	0.00	*60.00 F	?
10	1		*FRONT BUMPER SPONGE	CM 0.00	0.00	*48.00 F	✓
11	1		*FRONT FENDER RH	Bu 0.00	0.00	*175.00 F	✓
12	10		*FRONT FENDER COWLING CLIPS	M 0.00	0.00	*10.00 F	✓
13	1		*FRONT FENDER LOGO	M 0.00	0.00	*10.00 F	✓
14	1		*RADIATOR GRILLE C/W GRILLE LOGO	CM 0.00	0.00	*165.00 F	✓
15	1		*RADIATOR SUPPORT PANEL	Bu 0.00	0.00	*240.00 F	✓
16	1		*BRACE PANEL	R 0.00	0.00	*40.00 F	✓
17	1		*RADIATOR	0.00	0.00	*480.00 F	?
18	1		*AIR CON CONDENSER	M / Bu 0.00	0.00	*480.00 F	✓
19	1		*AIR CON CONDENSER HIGH PRESSURE PIPE - CHK PRICE	0.00	0.00	*- F	?
20	2		*HEADLAMP LH / RH - CHK PRICE	NLS M / M 0.00	0.00	*- F	✓
21	1		*FRONT BONNET LOCK - CHK PRICE	R 0.00	0.00	*- F	✓

F=Franchise part. S=SpcNett.

Total Parts (S\$)**2,413.00**

Report was unsubmitted during this print-out.

Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	200 30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100 120.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL ; TO REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	600 750.00
4	TO SPRAY BONNET; FRONT BUMPER; FRONT FENDER LH/RH; FRONT DOOR LH/RH AND FRONT SUPPORT PANEL	New	900 1,100.00
Gross Labour Cost (S\$)			2,000.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >