LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd 6 Temasek Boulevard 51 Ubi Ave 1 #01-25 #18-01 Suntec Tower 4 Paya Ubi Industrial Park Singapore 038986 Singapore 408933

Attn: Josey Loh Date: 30 Apr 2019

Preliminary Advice

Vehicle No : SDH53H Accident Date : 25/01/2019

: TOYOTA PICNIC : PNPV2018-00012112 Make Policy No.

Assignment Date : 28/01/2019 **Excess** : S\$600.00 Date of Inspection Est. Duration of Repair : 6.00 : 28/01/2019

Inspection At : AH LIM MOTOR COMPANY (SIN MING)

176 SIN MING DRIVE #05-12, SIN MING AUTOCARE

SINGAPORE 575721

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,813.00
Revised Amount	:S\$	3,483.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,483.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

18,000.00 Pre-Accident Value :S\$ COE / PARF Rebate 13,361.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 4,639.00

Remarks

X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: