

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-001

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without prejudice" basis

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Acknowledged by Repairer

Signature:

Date: GST REG. NO : M2 - 0020081 - X

Survey & repair 25.02 @ 10am
a survey before 12pm
Change appointment to 26/02 @ 10am
Survey & repair on 25.02 @ 10am



25 JAN 2019

ESTIMATE

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

first survey

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper, attachments, repair front bumper and repair tail panel.

Painting front bumper, rear bumper and tail panel.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

① To supply front emboss number plate.

② To remove and install boot compartment carpet and garnish to facilitate repairs.

③ To replace rear exhaust silencer including alignment system and conduct checks for leak.

④ Sundries.

	VALUE
4,120	3,400.00
2,562	2,819.00
225.90	177.00
	83.00
230 207	271.00
405.90	531.00
405.90	150.00
505.80	
Total Labour 1:	7,431.00

DESCRIPTION	QTY	PRIC	VALUE
① REAR SILENCER	1	1,465.05	1,465.05
TAILPIPE TRIM CHROME	2	107.85	215.70
TRIM PANEL AIRDUCT (X LINE)	1	153.30	153.30
④ FRT BUMPER PANEL LOWER SECTION (PDC)	1	281.80	281.80
② RR BUMPER CARRIER	1	493.85	493.85
③ MOUNTING SMART OPENER	1	45.30	45.30
REAR TRIM UNDERRIDE PROTECTION (X L)	1	105.40	105.40
REAR TRIM UNDERRIDE PROTECTION (X L)	1	105.40	105.40
⑦ RR BUMPER RH CORNER MOUNTING	1	141.90	141.90
⑧ RR BUMPER RH CORNER MOUNTING	1	141.90	141.90
REAR BUMPER PANEL PRIMED	1	770.80	770.80
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	242.80	242.80
REAR BUMPER BOTTOM TRIM PANEL (LINE)	1	231.25	231.25
⑪ LICENCE PLATE HOLDER ECE	1	70.65	70.65

Store
83278813
25/2/19
12-30pm
13 days
wil p/p
14 days
Roc bec & Ah spry

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION
REAR BUMPER HEAT INSULATION ? 00

QTY	PRIC	VAL
1	69.55	69.

Total Parts : 4,534.

Labour 1	:	7,431.
Parts	:	4,534
Labour 2	:	0
Excess	:	0
Total GST @ 7%	:	837
Grand Total	:	12,803.

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Supp. Supply
GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50390**
Date Estimated : **05/03/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244**- ACCOUNT - 238**

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION ^{3 (A1)} ⁴
To replace air duct(front support),tail panel and trunk floor.

VALUE
5,950.00

Painting Trunk floor.

572.00

⑤ To carry out body cavity preservation.
(For cut panel).

405.90

451 / 531.00

Total Labour 1: **7,053.00****DESCRIPTION**

⑬ TRUNK FLOOR / DO
⑭ TAIL PANEL / DO
⑮ FRT BUMPER TOP CARRIER (Refined) / DO
⑯ AIR DUCT / RR
BLIND RIVET AVIBVLB / NEC
SCREW (SF PLUS M5X15) / NEC
(DG/SL) BODY ADHESIVE K5B (195ML) / NEC
(DG) BODYWORK ADHESIVE K5A (50ML) / NEC
(DG) CLEANER R1 (100ML) / NEC
PUNCH RIVET N4 / NEC
(S/L) SEAM SEAL 300ML / NEC

QTY	PRIC	VALUE
1	452.00	452.00
1	401.75	401.75
1	373.95	373.95
1	246.00	246.00
60	0.55	33.00
10	0.55	5.50
1	326.80	326.80
1	112.70	112.70
1	26.15	26.15
30	0.55	16.50
1	33.80	33.80

Total Parts : **2,028.15**

Labour 1	:	7,053.00
Parts	:	2,028.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	635.68
Grand Total	:	9,716.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Supp.

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50390
Date Estimated : 05/03/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace air duct(front support),tail panel and trunk floor. *3 1/2 (1/2) 4 8 1/2*

Painting Trunk floor.

To carry out body cavity preservation.
(For cut panel).

10/4/19 *5100* *5,950.00*

Total Labour 1: **7,053.00**

DESCRIPTION

TRUNK FLOOR ✓
TAIL PANEL ✓
FRT BUMPER TOP CARRIER *Ref L* ✓
AIR DUCT ✓
BLIND RIVET AVIBVLB ✓
SCREW (SF PLUS M5X15) ✓
(DG/SL) BODY ADHESIVE K5B (195ML) ✓
(DG) BODYWORK ADHESIVE K5A (50ML) ✓
(DG) CLEANER R1 (100ML) ✓
PUNCH RIVET N4 ✓
(S/L) SEAM SEAL 300ML ✓

QTY	PRIC	VALUE
1	452.00	452.00
1	401.75	401.75
1	373.95	373.95
1	246.00	246.00
60	0.55	33.00
10	0.55	5.50
1	326.80	326.80
1	112.70	112.70
1	26.15	26.15
30	0.55	16.50
1	33.80	33.80

Total Parts : **2,028.15**

Labour 1	:	7,053.00
Parts	:	2,028.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	635.68
Grand Total	:	9,716.83

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Main + Supplementary

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Change appointment to 26/02 @ 10am
Survey before 12pm

Survey & repair on 25.02 @ 10am

Steve
83278813
25/2/19
12-30pm

13 days

GST REG. NO : M2 - 0020081 - X

25 JAN 2019

ESTIMATE

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

1340069

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION

To replace rear bumper, attachments, repair front bumper and repair tail panel.

1700 3,400.00

Painting front bumper, rear bumper and tail panel.

2537 1868 2,819.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

83.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451 531.00

Sundries.

2 150.00

Total Labour 1: 7,431.00

DESCRIPTION

REAR SILENCER
TAILPIPE TRIM CHROME
TRIM PANEL AIRDUCT (X LINE)
FRT BUMPER PANEL LOWER SECTION (PDC)
RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L)
REAR TRIM UNDERRIDE PROTECTION (X L)
RR BUMPER RH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER BOTTOM TRIM PANEL (LINE)
LICENCE PLATE HOLDER ECE

QTY	PRIC	VALUE
1	1,465.05	1,465.05
2	107.85	215.70
1	153.30	153.30
1	281.80	281.80
1	493.85	493.85
1	45.30	45.30
1	105.40	105.40
1	105.40	105.40
1	141.90	141.90
1	141.90	141.90
1	770.80	770.80
1	242.80	242.80
1	231.25	231.25
1	70.65	70.65