

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Part(s) subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowedSupplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

GST REG. NO : M2 - 0020081 - X

ESTIMATEA survey before 12pm
appointment to 26/02/2019
Survey & repair
on 25.02 @ 10am
25 JAN 2019Store
83278813
25/12/19
12-39pmwil park PIP
5 days Rec bef d Ah spyEstimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Leslie Lam Kwok Tai
10B Rochalie Drive

Singapore 248244

- ACCOUNT - 238AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTIONTo replace rear bumper, attachments, repair front
bumper and repair tail panel.

1700 3,400.00

Painting front bumper, rear bumper and tail panel.

1868 2,819.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

✓ 83.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

? 271.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

? 531.00

Sundries.

? 150.00

Total Labour 1: **7,431.00****DESCRIPTION**

REAR SILENCER ?

QTY	PRIC	VALUE
1	1,465.05	1,465.05
2	107.85	215.70
1	153.30	153.30
1	281.80	281.80
1	493.85	493.85
1	45.30	45.30
1	105.40	105.40
1	105.40	105.40
1	141.90	141.90
1	141.90	141.90
1	770.80	770.80
1	242.80	242.80
1	231.25	231.25
1	70.65	70.65

TAILPIPE TRIM CHROME X

TRIM PANEL AIRDUCT (X LINE) ?

FRT BUMPER PANEL LOWER SECTION (PDC) ✓ CUT

RR BUMPER CARRIER

MOUNTING SMART OPENER ?

REAR TRIM UNDERRIDE PROTECTION (X L CRITER) 00

REAR TRIM UNDERRIDE PROTECTION (X L Repair) X

RR BUMPER RH CORNER MOUNTING

LH RR BUMPER RH CORNER MOUNTING ?

REAR BUMPER PANEL PRIMED ✓ 00

REAR BUMPER MIDDLE TRIM PANEL (PDC) ✓ 00

REAR BUMPER BOTTOM TRIM PANEL (LINE) ✓ 00

LICENCE PLATE HOLDER ECE ✓ RR



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49905
Date Estimated : 25/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EG1001U	5G65917	08/03/2017	X1 sDrive20i	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER HEAT INSULATION ?	1	69.55	69.55

Total Parts : 4,534.65

Labour 1	:	7,431.00
Parts	:	4,534.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	837.60
Grand Total	:	12,803.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **