

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0121/2019/PH
Date : 26-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SLT 4486 H

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr Teo Jun Wei , Justin
Address : Blk 90A Telok Blangah Street 31
: #17-239
Singapore 101090
Telephone : (HP) 96466362
Type of Claim : Third Party Claims
Policy No. : A 80448661 QMY
Vehicle No : **SKR 9029 J**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Mar-15
Engine No : CZC 232969
Chassis No : WAUZZZ8V0F1094530
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Jan-19
Place of Accident : Junction of Tampines Ave 4 & Tampines Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 9029 J - Front.

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00
2	To dismantle and renew front bumper and lhs headlights. To repair bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 1,800.00
3	To respray front bumper and bonnet.	\$ 1,400.00
TOTAL LABOUR CHARGES		: \$ 3,560.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 9029 J - Rear.

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid.Check function.	S/N \$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00
3	To dismantle and renew rear bumper and rear lid.Re-organise rear crash management components.Reinstall all parts removed.	\$ 1,800.00
4	To respray rear bumper and rear lid.	\$ 1,500.00
5	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,052.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 9029 J - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	FRONT BUMPER	\$	1,830.00
2	FIXING PARTS FOR FRONT BUMPER	\$	170.00
3	FRONT BUMPER COVER TRIM - LH	\$	148.00
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	148.00
5	FRONT BUMPER PULL STRAP	4 \$	187.00
6	FRONT BUMPER GUIDE SECTION - LH	\$	35.00
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	99.00
8	RADIATOR GRILLE	\$	637.00
9	COVER FOR RADIATOR GRILLE	\$	89.00
10	FRONT REINFORCEMENT	\$	660.00
11	FOAM FILLER PIECE	\$	125.00
12	FRONT REINFORCEMENT COVER	\$	51.00
13	"CAUTION" SIGN STICKER	\$	13.00
14	HEADLIGHT - LH	\$	1,825.00
15	LIFT CYLINDER FOR HEADLIGHT WASHER SYS-LH	\$	181.00
16	FRONT NUMBER PLATE	S/N \$	25.00
SUB-TOTAL SPARE PARTS CHARGES		:	\$ 6,223.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 9029 J - REAR

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
21	REAR BUMPER	\$	1,708.00
22	FIXING PARTS FOR REAR BUMPER	\$	175.00
23	REAR BUMPER GUIDE SECTION - LH/RH	2 \$	30.00
24	REAR BUMPER LOCKING MECHANISM	2 \$	53.00
25	REAR BUMPER LIGHT REFLECTOR - LH	\$	38.00
26	REAR BUMPER SPOILER - LH	\$	216.00
27	REAR REINFORCEMENT	\$	522.00
28	REAR BUMPER BRACKET - LH/RH	2 \$	24.00
29	REAR BUMPER GUIDE SECTION - LH/RH	2 \$	120.00
30	REAR BUMPER SENSOR	2 \$	462.00
31	REAR BUMPER SENSOR SEAL	4 \$	12.00
32	REAR LID	\$	2,417.00
33	ATTACHMENT PARTS FOIR REAR LID	\$	267.00
34	GASKET FOR FLAP	\$	185.00
35	PACKING ADHESIVE	\$	18.00
36	AUDI' EMBLEM	\$	113.00
37	A3' EMBLEM	\$	87.00
38	'TFSI' EMBLEM	\$	87.00
39	TRIM FOR EXHAUST TAIL PIPE - LH CHROME	TBC	
40	REAR NUMBER PLATE	S/N \$	25.00
40	SUNDRIES	\$	500.00
TOTAL SPARE PARTS CHARGES		: \$	13,282.00
TOTAL LABOUR CHARGES		\$	7,612.00
GRAND TOTAL		\$	20,894.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant