



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR EM222Z

Tang Yong Choo

616 Dunearn Road
Singapore 289620

Mobile: 90699222

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

30454

EM222Z / 28/08/2017

WDD1179422N496702

27091031253009

MB/MB CLA 180 S/B (X117) "FACELIFT"

021 191 Cosmos Blac/ 041 151 Lther ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSI00001	Cash	26/01/2019/ 11:12	CH	371 / Go Chee Han					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : 5102921358 // 21-1-2019									
DRIVE IN/TP VEH : // SCL1511L - AXA									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
A BPILAB									
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.									1680.00
A BPIRES									
RESPRAY REAR BUMPER									960.00
A BPILAB									
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								0.10	380.00
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT									120.00
M REAR TRIM BUMPER									
1.00 1140.97 00.00									1140.97
M TOP BASIC MOUNTING FOR BUMPER									
1.00 119.90 00.00									119.90
M LH/BUMPER BRACKET									
1.00 27.62 00.00									27.62
M RH/BUMPER BRACKET									
1.00 27.62 00.00									27.62
M LOWER TRIM BUMPER									
1.00 135.86 00.00									135.86
M CHROME MOULDING									
1.00 156.78 00.00									156.78
M LH/TAI PIPE BRACKET									
1.00 57.85 00.00									57.85
M RH/TAI PIPE BRACKET									
1.00 57.85 00.00									57.85
M RIVET									
10.00 1.27 00.00									12.70
M EXPANSION RIVET									
8.00 2.07 00.00									16.56
M LH TAIL PIPE CHROME COVER									
1.00 295.95 00.00									295.95
M RH TAIL PIPE CHROME COVER									
1.00 295.95 00.00									295.95
M SPRING NUT									
4.00 3.08 00.00									12.32
M TAPPING SCREW									
4.00 2.64 00.00									10.56
M NUT-AND-WASHER ASSEMBLY									
6.00 3.08 00.00									18.48
M DISTANCE SENSOR									
2.00 177.22 00.00									354.44
M SPACER RING									
2.00 6.42 00.00									12.84

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR EM222Z

Tang Yong Choo

616 Dunearn Road
Singapore 289620

Mobile: 90699222

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

30454

EM222Z / 28/08/2017

WDD1179422N496702

27091031253009

MB/MB CLA 180 S/B (X117) "FACELIFT"

021 191 Cosmos Blac/ 041 151 Lther ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	26/01/2019/ 11:12	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR CROSS MEMBER	1.00	579.21	00.00	579.21

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Confirmed & accepted by

7% GST on **Nett 6,473.46**
6473.46 453.14

Authorized signatory and company stamp

Total Payable 6,926.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg