



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Page 1 / 2

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003385

Date : 26/01/2019
Vehicle Num. : SLP8947P
Make/Model : TOYOTA SIENTA
Chassis/Eng# : NSP170-7052893
Accident Date : 26/01/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE		1,110.00
2.	1	TAILGATE LOCK		410.00
3.	1	TAILGATE GLASS		1,250.00
4.	2	TAILGATE GLASS MOULDING	45.00	90.00
5.	2	TAILGATE LAMP LH/RH	541.80	1,083.60
6.	1	TAILGATE LOGO		72.20
7.	1	TAILGATE POCKET HANDLE		38.50
8.	1	TAILGATE WEATHERSTRIP		385.00
9.	1	TAILGATE OUTER GARNISH		275.10
10.	1	REAR WIPER MOTOR		717.50
11.	1	REAR WIPER BLADE		85.70
12.	1	REAR END PANEL INNER		585.00
13.	1	REAR END PANEL OUTER		519.80
14.	2	TAILLAMP LH/RH	514.80	1,029.60
15.	1	TAIL LAMP PANEL LH		195.00
16.	1	SPARE TYRE BOARD		295.00
17.	1	REAR BUMPER		645.00
18.	1	REAR BUMPER GARNISH		176.40
19.	1	REAR BUMPER CENTRE PAD		423.07
20.	1	REAR BUMPER SPONGE		60.00
21.	1	LH REAR FENDER TRIMBOARD		428.95
22.	1	KEY SENSOR ANTENNAE		155.00
List TotalS\$:				10,030.42
25.00% Discount S\$:				2,507.61
				7,522.81

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003385

Date : 26/01/2019
Vehicle Num. : SLP8947P
Make/Model : TOYOTA SIENTA
Chassis/Eng# : NSP170-7052893
Accident Date : 26/01/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	SPECIAL NETT ITEMS :		
2.	1	TAILGATE GLASS SEALANT		40.00
3.	1	REAR NUMBER PLATE		45.00
4.	1	REVERSE SENSOR		200.00
5.	1	REAR CAMERA		600.00
5.	12	ASSORTED CLIPS	3.00	36.00
Special Nett Total S\$:				921.00
LABOUR :				
TOWING CHARGE				60.00
TO REMOVE/REPLACE REAR WINDSCREEN GLASS				100.00
TO REMOVE/REPLACE REVERSE SENSOR & CAMERA				120.00
TO TRANSFER TAILGATE PARTS/MECHANISM				50.00
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS				150.00
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				1,300.00
TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING				150.00
TO CUT OUT/REWELD REAR END PANEL, INNER - OUTER, LH TAIL LAMP PANEL, REPAIR SPARE TYE PANEL, REAR CHASSIS, REAR FENDERS INCLUDES KNOCKING & REPLACEMENT OF PARTS				1,000.00
Labour Total S\$:				2,930.00

E. & O.E.

Total S\$: 11,373.81



for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg