

FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003385

Date : 26/01/2019
Vehicle Num. : SLP8947P
Make/Model : TOYOTA SIENTA
Chassis/Eng# : NSP170-7052893
Accident Date : 26/01/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	TAILGATE		1,110.00 <i>bt</i>
2.	1	TAILGATE LOCK		410.00 <i>bt</i>
3.	1	TAILGATE GLASS		1,250.00 <i>bra</i>
4.	2	TAILGATE GLASS MOULDING	45.00	90.00 <i>re</i>
5.	2	TAILGATE LAMP LH/RH	541.80	1,083.60 <i>crs</i>
6.	1	TAILGATE LOGO		72.20 <i>re</i>
7.	1	TAILGATE POCKET HANDLE		38.50 <i>crs</i>
8.	1	TAILGATE WEATHERSTRIP		385.00 <i>tr</i>
9.	1	TAILGATE OUTER GARNISH		275.10 <i>de</i>
10.	1	REAR WIPER MOTOR		717.50 <i>znn</i>
11.	1	REAR WIPER BLADE <i>/arm</i>		85.70 <i>at</i>
12.	1	REAR END PANEL INNER		585.00 <i>bt</i>
13.	1	REAR END PANEL OUTER		519.80 <i>bt</i>
14.	2	TAILLAMP LH/RH	514.80	1,029.60 <i>crs</i>
15.	1	TAIL LAMP PANEL LH		195.00 <i>znn</i>
16.	1	SPARE TYRE BOARD		295.00 <i>de</i>
17.	1	REAR BUMPER		645.00 <i>de</i>
18.	1	REAR BUMPER GARNISH <i>LH</i>		176.40 <i>at</i>
19.	1	REAR BUMPER CENTRE PAD		423.07 <i>de</i>
20.	1	REAR BUMPER SPONGE		60.00 <i>crs</i>
21.	1	LH REAR FENDER TRIMBOARD		428.95 <i>at</i>
22.	1	KEY SENSOR ANTENNAE		155.00 <i>crs</i>

List TotalS\$:

25.00% Discount S\$:

10,030.42

2,507.61

7,522.81

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003385

Date : 26/01/2019
Vehicle Num. : SLP8947P
Make/Model : TOYOTA SIENTA
Chassis/Eng# : NSP170-7052893
Accident Date : 26/01/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	1	TAILGATE GLASS SEALANT		40.00 <i>re</i>
2.	1	REAR NUMBER PLATE		45.00 <i>cut</i>
3.	1	REVERSE SENSOR		200.00 <i>re</i>
4.	1	REAR CAMERA		600.00 <i>re</i>
5.	12	ASSORTED CLIPS	3.00	36.00 <i>re</i>

Special Nett Total S\$:

921.00

LABOUR :

TOWING CHARGE	60.00 <i>✓</i>
TO REMOVE/REPLACE REAR WINDSCREEN GLASS	100.00 <i>✓</i>
TO REMOVE/REPLACE REVERSE SENSOR & CAMERA	120.00 <i>80</i>
TO TRANSFER TAILGATE PARTS/MECHANISM	50.00 <i>40</i>
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS	150.00 <i>80</i>
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER	1,300.00 <i>1100</i>
TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING	150.00 <i>80</i>
TO CUT OUT/REWELD REAR END PANEL, INNER-OUTER, LH TAIL LAMP PANEL, REPAIR SPARE TYE PANEL, REAR CHASSIS,	
REAR FENDERS INCLUDES KNOCKING & REPLACEMENT OF PARTS	1,000.00 <i>800</i>

Labour Total S\$:

2,930.00

E. & O.E.

Total S\$: 11,373.81

for FALCON AIR AUTO SERVICES PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary term(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

File 97495749
WP
28/1/19 @ 4pm
67 days
Resurvey before paint
sure lkk auto can

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg