

INS CASE OWNER:

cc 4, LOR 1900 1812, B ja34

LKK:
IDAC:

Surveyor:

Mr. Lim

DOI:

ASSIGNMENT

28/11/19

Date / Time:

28/01/19

Registered in Merimen:

28/01/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLG 3718P

Name of Insured:

LKF PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/01/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJZ 5226 C

INSRS:
WSP:
Tel:
Liability:
RMKS:

Ryder Auto

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

12/2
JingSJZ 5226 C - C44/AXA 11023409 / UWA / M / 100% / 100%
SLG 3718P - X
K2R

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI: 20/11-3-19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	☒	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice	☒	☐
LTA / GIA:	☒	☐
Medical Bill:	☒	☐
PIR:	☒	☐
Mandate/Reject Instruction:	☒	☐
LOD	☐	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

11-3-19 LOD IN. FOR MANDATE

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time: 25.3.19	Confirm with: ORSON
Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.: 27
Repair Cost:	SS	7,050	
Loss of Rental (LOR):	SS		(days)
Loss of Use (LOU):	SS	960	(\$ 80 x 12 days)
Loss of Income (LOI):	SS		(\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	SS	29	
Medical:	SS		
Disbursement:	SS		(e.g. Tow/ Independent)
Legal Cost	SS		
Total:	SS	8,039.44	Global Sum SS: 8,000.xx
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	8,000.44	Name 1: RYDER AUTO PTE LTD.
Payee 2 (S/N P. if N.A.):	SS		Name 2: X
Payee 3 (Str. if N.A.):	SS		Name 3: X

REF: All

ASSIGNMENT

From: Date: 28-01-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SJZ 5226C Yr Registr: 1/12/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CNX 1.8 cc 1799

Colour: BROWN

AC: Insured / Std / NI / NA

Sp. Reading: F9327

T/Radio: Insured / Std / NI / NA

Eng. No: R18A15000338

Ch. No: JHMFD1F30A5E00150

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55/16

R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 26/1/19

D.O.I: 23/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

MV 30,000/-

PV 22,400/-

NV 7,555/-

L/S \$7,050.00

R(\$10,885.52/61%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

to

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

(2)

Transportation

Add Fee: ☐ Site Insp: \$

) 3 + PS 24

☐ Interview: \$

) Photo

☐ Tech. Insp: \$

) Other:

☐ Weekend: \$

) 3

Report Format:

Lump Sum / I.B.F: \$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7484H
Vehicle Details	
Vehicle No.:	SJZ5226C
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L 5AT
Primary Colour:	Brown
Manufacturing Year:	2009
Engine No.:	R18A15000338
Chassis No.:	JHMFD1630AS200150
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,597.00
Original Registration Date:	01 Dec 2010
First Registration Date:	01 Dec 2010
Transfer Count:	2
Actual ARF Paid:	\$25,597.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2020
PARF Rebate Amount:	\$14,078.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$45,501.00
COE Rebate Amount:	\$8,367.00
Total Rebate Amount:	\$22,445.00

The information contained herein is correct as at 28 Jan 2019

OK

Dep 3,695/yr
805/mth

MV 30,000
PV 22,445
NV 7,555


29/1/19

dyson cyclone v10

Celebrate this New Year with Dyson technology

Shop Now



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mid 2013 BMW 318i Sport As 465k With Warranty.



Beautiful Metallic Black, 1
Careful Owner, High COE And
DHL Under Warranty
Direct Owner Thank!



Browse by Category ▼

Sort by Date Posted ▼

100 results/page ▼

29 vehicles

Honda Civic

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection Honda Civic		Any	Any	2010	Any	Any	Any	All
	Honda Civic Hybrid 1.3A	\$25,688	\$11,900 /yr	17-May-2010	1,329 cc	-	Sedan	Available
Fuel Type: Petrol-Electric Down \$5360 Per Month At \$726 Only! Seller Consignment Car, Please Call For Appointment Before Coming Now, Accidents Free, Idea Car For Short Term Usage, New Set Of Tires, Flexible Loan, Balloon Scheme... Auto [In]								
Posted: 27-Jan-2019 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic 1.6A VTI-S	\$23,800	\$8,820 /yr	05-May-2010	1,595 cc	-	Sedan	Available
S Pass, EP Or LTV Pass Welcome To Loan! In House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Viewing And Test Drive Availab... SS Motor Trading								
Posted: 26-Jan-2019 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic 1.8A VTI-S	\$29,288	\$9,690 /yr	25-Oct-2010	1,799 cc	133,000 km	Sedan	Available
Enjoy Low Interest Rate From 2.18% Agent Unit. Most Welcomed And Facelifted FD1 Honda Civic. Low Mileage! Well Known For Its Top Reliable Model Across All Asian Sedan. Affordable, Spacious And Comfort... Euro Performance Asia Pte Ltd								
Posted: 26-Jan-2019 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic Type R 2.0M (New 10-yr COE)	\$82,800	\$8,270 /yr	08-Jun-2010	1,998 cc	151,600 km	Sports	Available
1 Owner Only! Fresh Coat Of Stock Championship White Paintwork Fresh From Oven! New Battery, LTA Compliant Toda Exhaust With Cert, CE28 Rims, Never Been To Track, Vehicle Is In Stock Condition With No... Car (S) Pte Ltd								
Posted: 25-Jan-2019 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic 1.8A VTI-S	-	N/A	20-Jul-2010	1,799 cc	-	Sedan	SOLD
(100% Showroom Condition!) Buy With Confidence From CaseTrust Accredited Dealer. Purchase Comes With 6 Months Engine And Gearbox Protection With 24/7 Roadside Assistance. STA/VICOM/AA Evaluation Frien... Sincere Motoring Pte Ltd								
Posted: 25-Jan-2019 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic 2.0A Si	\$22,800	\$8,650 /yr	05-Mar-2010	1,998 cc	100,000 km	Sedan	Available
Cheapest 2.0L Civic In The Market. Very Well Maintained By Previous Owner. 18" Vossen Rims W/ 2 Months Old Pirelli P Zero Tires With 80% Tread Left. Original Paintwork, Well Taken Care Black Leather S... Car Empire Automobiles Pte Ltd								
Posted: 22-Jan-2019 Tags: 2010 Honda Civic, 2010 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda								
	Honda Civic 1.6M VTI	\$24,000	\$7,730 /yr	04-Aug-2010	1,595 cc	-	Sedan	Available
Very Well Maintained! Free Servicing And 6 Months Warranty! Excellent Condition, View To Believe! Up To 80% Financing Possible! Trade In								

Compare

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (3) Check (4) Not Checked (5) Not Working

Rear Portion

NAC	INC	Item	CON	AC	Q
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Roverac Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJE 5226C

NAC	INC	Item	CON	AC	Q
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 28

Assessor: J. J. J.

20/1/13

Polish/light
chassis
(canopy)

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Fax: 64815390

ESTIMATE OF REPAIR

SJZ5226C Pg 1/3

Veh # : SJZ5226C Model : HONDA CIVIC 1.8L (1/12/2010)

Date Of Accident: 26/1/2019 3P : SLG3718P (AIG)

Location : AFTER ENG NEO

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>List Items</u>				
1 pc	Rear bumper	DLV	638.00	920.00	
10 pcs	Rear bumper clips	NECV		31.20	✓
1 pc	Rear bumper exhaust garnish	DDV		17.00	
2 pcs	Rear bumper exhaust garnish clips	NNX		7.80	
2 pcs	Rear bumper o/s & n/s bracket	?	BTV	47.80	✓
2 pcs	Rear bumper o/s & n/s retainer	?	NECV	49.20	✓
2 pcs	Rear bumper o/s & n/s corner clips	?	NECV	86.00	XNN
1 pc	Rear bumper enforcement	?	NNX	568.80	
1 pc	Rear bumper screw (Lower)	?	NNX	24.20	
1 pc	Rear tail lamp panel Rear End panel	?	BTV	300.50	✓
1 pc	Rear tail lamp panel inner trim Rear end panel trim	?	BRV	60.80	✓
4 pcs	Rear tail lamp panel inner trim clips	?	NEC	18.00	✓
2 pcs	Rear o/s & n/s tail-lamp @ 308.70	BRV		610.00	✓
2 pcs	Rear o/s & n/s tail-lamp sealant	NNX		47.00	
4 pcs	Rear o/s & n/s tail-lamp clips	NECV		14.00	XNN
2 pcs	Rear o/s & n/s tail-lamp panel @ 122.10	?	DDV	244.20	
1 pc	Rear boot cover	BTV		610.00	✓
1 pc	Rear boot cover weather-strips	?	EUT	97.60	✓
1 pc	Rear boot cover emblem		52.20	76.90	
2 pcs	Rear boot cover emblem clips			8.00	✓
1 pc	Rear boot cover 'CIVIC' emblem	NECV		29.00	✓
1 pc	Rear boot cover '1.8' emblem			18.00	✓
1 pc	Rear boot cover 'i-VTEC' emblem			34.00	✓
2 pcs	Rear boot cover o/s & n/s reflector @ 202.90	BRV		291.80	✓
2 pcs	Rear boot cover o/s & n/s reflector sealant	NNX		48.20	
4 pcs	Rear boot cover o/s & n/s reflector clips	NECV	✓	34.00	XNN
1 pc	Rear boot cover lock (Upper)	?	BTV	205.00	✓
1 pc	Rear boot cover lock (Inner)	?	NNX	22.00	
1 pc	Rear boot cover lock washer	?	NNX	18.00	

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
1 pc	Rear boot cover inner trim	? TN ✓		233.70	✓
8 pcs	Rear boot cover inner trim clips	? NEC ✓		36.00	✓
2 pcs	Rear boot cover o/s & n/s stopper	? NNX		14.00	
2 pcs	Rear boot cover o/s & n/s hinges @ 48.60 / pc N ^u	? 48.60		97.20	
1 pc	Rear boot cover lock snap	? NNX		4.00	
1 pc	Rear boot cover lock silencer	? NNX		380.00	
1 pc	Rear boot floor panel	? DD ✓ 311.40		948.50	
1 pc	Rear boot floor panel cross-member	? NNX		1,920.80	
1 set	Rear boot floor panel insulator	? NEC ✓		155.00	✓
1 pc	Rear boot floor panel cover (Inner)	? NNX		125.00	
4 pcs	Rear boot floor panel cover clips (Inner)	? NNX		15.60	
1 pc	Rear boot floor panel tool tray sponge	? BR ✓		205.00	✓
1 pc	Rear spare wheel board cover	? TN ✓		316.00	✓
1 set	Rear windscreen moulding	? NNX		216.40	
14 pcs	Rear windscreen moulding clips	? NNX		65.00	
1 pc	Rear n/s fender	? NNX		741.50	
2 pcs	Rear o/s & n/s fender air vent duct @ 24.30	? BR ✓		48.60	✓
2 pcs	Rear o/s & n/s fender inner padding	? NNX		783.50	
8 pcs	Rear o/s & n/s fender inner padding clips	? NNX		64.00	
2 pcs	Rear o/s & n/s fender inner trim @ 242.80	? TN ✓		291.80	✓
16 pcs	Rear o/s & n/s fender inner trim clips (3 pcs)	? NEC ✓ 30.00		72.00	✓
2 pcs	Rear o/s & n/s fender wheel guard LH	MIS 1 pc		292.20	
16 pcs	Rear o/s & n/s fender wheel guard clips LH 5 pcs	MIS 2 pcs		72.00	
1 pc	Rear n/s chassis frame 1,174.80	? DD ✓		1,460.00	
1 pc	Rear exhaust muffler 850.00	? DD ✓		1,150.00	
1 pc	Rear exhaust muffler tail pipe	BT ✓ 157.00		165.80	✓
2 pcs	Rear exhaust muffler mounting (rubber)	? TN ✓		25.00	✓
1 pc	Rear exhaust muffler insulator shield	? TN ✓ DD ✓		43.80	
1 pc	Rear exhaust muffler gasket	? NEC ✓		12.20	✓
	Sub-Total			14,689.40	
	After -20%			11,751.52	

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$
	<u>Special Nett Items</u>			
1 pc	Rear reverse sensor	CUT	210.00	280.00
1 pc	Rear regn. no. plate	? NNX		45.00
1 pc	Rear regn. no. plate bracket	? BR ✓	25.00	29.00
1 pc	Rear windscreen sealant	? } NNX		60.00
1 pc	Rear windscreen inner seal	? }		50.00
	Sub-Total			464.00
	<u>Labour</u>			
1	To dismantle rear portion damaged parts, straighten rear n/s chassis frame, rear boot floor panel, rear o/s & n/s fender.	?	1200.00	2200.00
2	To putty and spray painting.	?	800.00	1,600.00
3	To re-align rear chassis frame.	? NNX		380.00
4	To check rear wheel alignment (Before & After).	NNX		240.00
5	To replace rear exhaust muffler.	80.00	400.00	300.00
6	To remove and refit rear windscreen, seats and roof lining to facilitate repairs.	? NNX		300.00
7	To remove and refit fuel tank.	NNX		200.00
8	To check wiring.		50.00	420.00
9	To re-seal anti-rust.		60.00	380.00
	Sub-Total			5,720.00
	Total			17,935.52
	After -20%			14,348.42

Resurvey 29/1/19
TGIN Lin 1450

TGIN Lin 29/1/19 1510

? Photo

Lump sum repair
10 days

[Signature]
30/1/19

Chan San Choon

Director

DipEng. AAE MIM, MSAE(Aust), AMMAEA

 **BOK SENG**
(heavy vehicles, marine vessels)

 **iiv**
INSURANCE INVESTMENT VEHICLE

Acknowledged by Repairer
Authorised Workshop
Authorised Reporting Centre

AL 8778 1999
24 hr accident call

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Joy Irene (LKKAuto)

From: Tan, Wilson-KL <Wilson-KL.Tan@aig.com>
Sent: Tuesday, 19 March 2019 5:31 PM
To: Joy Irene (LKKAuto)
Cc: Admin A
Subject: RE: TP / 7672879877SG / SLG 3718P ON 26.01.2019

Mandate given

Try to settle at \$8K

Wilson Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1753 | Fax +(65) 6835 7416

Wilson-KL.Tan@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more.](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]
Sent: Tuesday, March 19, 2019 5:18 PM
To: Tan, Wilson-KL
Cc: Admin A
Subject: TP / 7672879877SG / SLG 3718P ON 26.01.2019

Dear Wilson,

Kindly look into our mandate request in Merimen. TP is chasing for an offer.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 @ Kaki Bukit Auto Hub, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 079120

26/2/2019

Attn: Motor Claims Dept

LETTER OF DEMAND

Our Ref : SJZ5226C Your Ref :

Dear Sir,

VEHICLE # : SJZ5226C

ACCIDENT INVOLVING : SJZ5226C & SLG3718P AFTER ENG NEO ON 26/1/2019

LUMP SUM REPAIR : S\$7,050.00

LOSS OF USE : S\$2,160.00

{10 WORKING DAYS + 6 DAYS WEEKEND (26 & 27 JAN 2, 3, 9 & 10 FEB) + 2 DAYS PH (5 & 6 FEB)) X S\$120

LTA & GIA SEARCH : \$29

TOTAL : S\$9,239.00

DOLLARS: NINE THOUSAND TWO HUNDRED AND THIRTY-NINE ONLY.


Please arrange for DV to be signed by us (workshop) because we are authorised by client to sign on behalf. Please see attached Letter of authorisation (see note 5).

For your prompt payment.

Thank you.

Yours faithfully,

Ryder Auto Pte Ltd



Chan San Choon

Director

DipEng, AAE MIMI, MSAE(Aust), AffMIAEA

 **BOK SENG**
(heavy vehicles, marine vessels)

 **iD**
Authorised Workshop
Authorised Reporting Centre

 **8778 1999**
24 hr accident call

Mobil 1

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 @ Kaki Bukit Auto Hub, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 079120

26/2/2019

Attn: Motor Claims Dept

INVOICE

Our Ref : SJZ5226C Your Ref :

Dear Sir,

VEHICLE # : SJZ5226C

ACCIDENT INVOLVING : SJZ5226C & SLG3718P AFTER ENG NEO ON 26/1/2019

LUMP SUM REPAIR : S\$7,050.00

LOSS OF USE : S\$2,160.00

(10 WORKING DAYS + 6 DAYS WEEKEND (26 & 27 JAN 2, 3, 9 & 10 FEB) + 2 DAYS PH (5 & 6 FEB)) X S\$120

LTA & GIA SEARCH : \$29

TOTAL : S\$9,239.00

DOLLARS: NINE THOUSAND TWO HUNDRED AND THIRTY-NINE ONLY.


Please arrange for DV to be signed by us (workshop) because we are authorised by client to sign on behalf. Please see attached Letter of authorisation (see note 5).

For your prompt payment.

Thank you.

Yours faithfully,

Ryder Auto Pte Ltd



Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust), AffMIAEA

 **BOK SENG**
(heavy vehicles, marine vessels)

 **Insurance Recovery**
Authorised Workshop
Authorised Reporting Centre

 **8778 1999**
24 hr accident call

Mobil 1

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Monday, 11 March 2019 4:24 PM
To: 'insurance@lioncityrentals.com.sg'
Cc: Admin A; Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLG 3718P (LCR) & SJZ 5226C ON 26/01/2019 ALONG PIE

LCRF PTE LTD

Policy Holder

Your Ref: SLG 3718P
Our Ref: CC4/LCR19001812/Bja3

Dear Sir/Madam,

ACCIDENT INVOLVING SLG 3718P (LCR) & SJZ 5226C ON 26/01/2019 ALONG PIE

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SJZ 5226C** against your insurance policy.

Based on the information on hand, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

To: Ryder Auto Pte Ltd

Re: ACCIDENT ON 26/1/2019 INVOLVING SJZ5226C SLG3718P

ALONG / AT

AFTER ENG NEO

I/We FRANCIS XAVIER LOW AH BEE (NRIC No. S1727484H)

of BLK 144 LORONG 2 TOA PAYOH #08-208 S(310144)

1. The owner of motor vehicle no. SJZ5226C hereby authorise **Ryder Auto Pte Ltd** to commence repairs of the said vehicle forthwith. I/We agree to assign the whole proceeds of my/our third party claim to **Ryder Auto Pte Ltd** including any claim for Loss of Use if a vehicle had been provided by **Ryder Auto Pte Ltd** during the period of repairs to my/our vehicle if applicable. My/our solicitors (to be appointed by **Ryder Auto Pte Ltd** on my/our behalf) shall accept this as my/our irrevocable authority to pay the amount compensated direct to **Ryder Auto Pte Ltd** after deduction of their cost on a solicitor & client basis. **I/We undertake to co-operate fully with Ryder Auto Pte Ltd and/or my/our solicitors and also with a true Motor Accident Report/Police Report until the claim to a successful conclusion including court proceedings, failing which, I/We undertake to bear repair costs, rental, legal costs and any other incidentals incurred.**

2. If the 3rd party claim is unsuccessful or partly successful as the case may be, I/we hereby instruct and authorise **Ryder Auto Pte Ltd** to claim direct from my/our insurance company on my/our vehicle immediately without any delay.

3. If for any reason my/our insurer's are not willing to settle the repair costs either in part or in whole then I/ we undertake to pay **Ryder Auto Pte Ltd** the repair cost.

4. In alternative to serial number 2 and 3 above if the 3rd party claim fails or is only partly successful then I/we undertake to pay **Ryder Auto Pte Ltd** the difference in amount of the repair cost.

5. I/We authorise **Ryder Auto Pte Ltd** to sign all discharge voucher/indemnity forms and all necessary papers on my/our behalf in connection with the above claim. **We confirm full discharge of all property damage claims upon signing of the discharge voucher by our repairer, Ryder Auto Pte Ltd.**

6. I/We also authorise **Ryder Auto Pte Ltd** to appoint such a firm of solicitors on my/our behalf as **Ryder Auto Pte Ltd** deem fit for the purpose of third party/own insurance claims.

7. I/We undertake to inform **Ryder Auto Pte Ltd** and/or the solicitors appointed by **Ryder Auto Pte Ltd** on my/our behalf in the event the third party's insurance company communicate with me/us directly by telephone or in writing and I/We further undertake not to accept any monies or other or settlement from the third party's insurers without first communicating with you.

8. In the event that third party insurer issued the **Agreed Settlement Cheque** to me/us, I/We undertake to either give the said cheque to **Ryder Auto Pte Ltd**, or bank into my/our account and re-issue the cheque amount to **Ryder Auto Pte Ltd**.

DATED THIS _____ DAY OF 26/1/2019 20____



Signature of owner

(Company's stamp - if any)



Signature of Witness

Name of Witness

Ryder Auto Pte Ltd

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, RYDER AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$8,000.00 (Global Sum) for vehicle no. SJZ 5226C that was damaged pursuant to the accident which occurred on 26/01/2019 (date) along PIE / AFTER ENG NEO (location) involving vehicle no/s SLG 3718P. This is pursuant to the inspection conducted on 28/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner FRANCIS XAVIER LOW AH BEE ("the third party claimant") of vehicle no. SJZ 5226C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJZ 5226C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of 3 (month) **2019** (year)



Signed by appointed surveyor

Signed by "the workshop" (with chop)

Ryder Auto Pte Ltd

my execution of this Discharge Voucher is only
for my claim for property damage and not prejudicial
to any other claims arising from the same accident.

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 @ Kaki Bukit Auto Hub, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16
Singapore 079120

26/2/2019

Attn: Motor Claims Dept

INVOICE

Our Ref : SJZ5226C Your Ref :

Dear Sir,

VEHICLE # : SJZ5226C

ACCIDENT INVOLVING : SJZ5226C & SLG3718P AFTER ENG NEO ON 26/1/2019

LUMP SUM REPAIR : S\$7,050.00

DOLLARS: SEVEN THOUSAND AND FIFTY ONLY.


Please arrange for DV to be signed by us (workshop) because we are authorised by client to sign on behalf. Please see attached Letter of authorisation (see note 5) .

For your prompt payment.

Thank you.

Yours faithfully,

Ryder Auto Pte Ltd



Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust), AMIAEA

 **BOK SENG**
(heavy vehicles, marine vessels)

 **iV**
Authorised Workshop
Authorised Reporting Centre

 **8778 1999**
24 hr accident call

Mobil 

TAX INVOICE

Our Ref No: GR-19-016306
Date of Request: 29/01/2019

Your Ref No: Online Purchase

Ryder Auto Pte Ltd
2 Kaki Bukit Ave 2
#02-19 AutoHub @ Kaki Bukit
Singapore 417921

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 26/01/2019
Place of Accident: AFTER ENG NEO
Client Vehicle No: SJZ5226C

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-016308
Date of Request: 29/01/2019

Your Ref No: Online Purchase

Ryder Auto Pte Ltd
2 Kaki Bukit Ave 2
#02-19 AutoHub @ Kaki Bukit
Singapore 417921

Dear Sir/Madam,

Date of Accident: 26/01/2019
Vehicle No: SJZ5226C
Place of Accident: AFTER ENG NEO
Involving Vehicle No: SLG3718P

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLG3718P	AFTER ENG NEO	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jan 2019 Edit Reg		28 Jan 2019 00:00 Edit Adj Rpt	\$57,050.00 Edit Estimates	\$57,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	FRANCIS XAVIER LOW AH BEE, ID: S1727484H								
Vehicle Reg. No.:	SJZ5226C	Date of Loss:	26/01/2019 00:00 - :59 [97 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7672879877SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLG3718P	Policy No. (Claimant):	5102205788						
		Excess:							
Repairer:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 08/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (26/03/2019): Alert - Adj Mandate Approved (\$8000.00) - SJZ5226C - Claim Handler: Tan, Wilson... - AIG_SG_EXPRESS (19/03/2019): Alert - Adj Mandate Maintained - SJZ5226C - Claim Handler: Tan, Wilson-KL - AIG_SG (29/01/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ5226C (7672879877SG)
[SLG3718P]**

TP

FRANCIS XAVIER LOW AH BEE

Jan 26 2019 12:00AM

[LCRF PTE LTD]

Ryder Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	19/03/19 17:14	General View													1	Load JPG	☒			
2	19/03/19 17:14	General View													1	Load JPG	☒			
3	19/03/19 17:14	General View													1	Load JPG	☒			
4	19/03/19 17:14	General View													1	Load JPG	☒			
5	19/03/19 17:14	General View													1	Load JPG	☒			
6	19/03/19 17:14	General View													1	Load JPG	☒			
7	19/03/19 17:14	General View													1	Load JPG	☒			
8	19/03/19 17:14	General View													1	Load JPG	☒			
9	19/03/19 17:14	General View													1	Load JPG	☒			
10	19/03/19 17:14	General View													1	Load JPG	☒			
11	19/03/19 17:14	General View													1	Load JPG	☒			
12	19/03/19 17:14	General View													1	Load JPG	☒			
13	19/03/19 17:14	General View													1	Load JPG	☒			
14	19/03/19 17:14	General View													1	Load JPG	☒			
15	19/03/19 17:14	General View													1	Load JPG	☒			
16	19/03/19 17:14	General View													1	Load JPG	☒			
17	19/03/19 17:14	General View													1	Load JPG	☒			
18	19/03/19 17:14	General View													1	Load JPG	☒			
19	19/03/19 17:14	General View													1	Load JPG	☒			
20	19/03/19 17:14	General View													1	Load JPG	☒			
21	19/03/19 17:14	General View													1	Load JPG	☒			
22	19/03/19 17:14	General View													1	Load JPG	☒			
23	19/03/19 17:14	General View													1	Load JPG	☒			
24	19/03/19 17:14	General View													1	Load JPG	☒			
25	19/03/19 17:14	General View													1	Load JPG	☒			
26	19/03/19 17:14	General View													1	Load JPG	☒			
27	19/03/19 17:14	General View													1	Load JPG	☒			
28	19/03/19 17:14	General View													1	Load JPG	☒			
29	19/03/19 17:14	General View													1	Load JPG	☒			
30	19/03/19 17:14	General View													1	Load JPG	☒			
31	19/03/19 17:14	General View													1	Load JPG	☒			
32	19/03/19 17:14	General View													1	Load JPG	☒			
33	19/03/19 17:14	General View													1	Load JPG	☒			
34	19/03/19 17:14	General View													1	Load JPG				

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	19/03/19 17:14	General View	 Load JPG	☒
36	19/03/19 17:14	General View	 Load JPG	☒
37	19/03/19 17:14	General View	 Load JPG	☒
38	19/03/19 17:14	General View	 Load JPG	☒
39	19/03/19 17:14	General View	 Load JPG	☒
40	19/03/19 17:14	General View	 Load JPG	☒
41	19/03/19 17:14	General View	 Load JPG	☒
42	19/03/19 17:14	General View	 Load JPG	☒
43	19/03/19 17:14	General View	 Load JPG	☒
44	19/03/19 17:14	General View	 Load JPG	☒
45	19/03/19 17:14	General View	 Load JPG	☒
46	19/03/19 17:14	General View	 Load JPG	☒
47	19/03/19 17:14	General View	 Load JPG	☒
48	19/03/19 17:14	General View	 Load JPG	☒
49	19/03/19 17:14	General View	 Load JPG	☒
50	19/03/19 17:14	General View	 Load JPG	☒
51	19/03/19 17:14	General View	 Load JPG	☒
52	19/03/19 17:14	General View	 Load JPG	☒
53	19/03/19 17:14	General View	 Load JPG	☒
54	19/03/19 17:14	General View	 Load JPG	☒
55	19/03/19 17:14	General View	 Load JPG	☒
56	19/03/19 17:14	General View	 Load JPG	☒
57	19/03/19 17:14	General View	 Load JPG	☒
58	19/03/19 17:14	General View	 Load JPG	☒
59	19/03/19 17:14	General View	 Load JPG	☒
60	19/03/19 17:14	General View	 Load JPG	☒
61	19/03/19 17:14	General View	 Load JPG	☒
62	19/03/19 17:14	General View	 Load JPG	☒
63	19/03/19 17:14	General View	 Load JPG	☒
64	19/03/19 17:14	General View	 Load JPG	☒
65	19/03/19 17:14	General View	 Load JPG	☒
66	19/03/19 17:14	General View	 Load JPG	☒
67	19/03/19 17:14	General View	 Load JPG	☒
68	19/03/19 17:14	General View	 Load JPG	☒
69	19/03/19 17:14	General View	 Load JPG	☒
70	19/03/19 17:14	General View	 Load JPG	☒
71	19/03/19 17:14	General View	 Load JPG	☒
72	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
73	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
74	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
75	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
76	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
77	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
78	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
79	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
80	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
81	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
82	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
83	19/03/19 17:14	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	19/03/19 17:14	Reinspection Photo		☒
85	19/03/19 17:14	Reinspection Photo		☒
86	19/03/19 17:14	Reinspection Photo		☒
87	19/03/19 17:14	Reinspection Photo		☒
88	19/03/19 17:14	Reinspection Photo		☒
89	19/03/19 17:14	Reinspection Photo		☒
90	19/03/19 17:14	Reinspection Photo		☒
91	19/03/19 17:14	Reinspection Photo		☒
92	19/03/19 17:14	Reinspection Photo		☒
93	19/03/19 17:14	Reinspection Photo		☒
94	19/03/19 17:14	Reinspection Photo		☒
95	19/03/19 17:14	Reinspection Photo		☒
96	19/03/19 17:14	Reinspection Photo		☒
97	19/03/19 17:14	Reinspection Photo		☒
98	19/03/19 17:14	Reinspection Photo		☒
99	19/03/19 17:14	Reinspection Photo		☒
100	19/03/19 17:14	Reinspection Photo		☒
101	19/03/19 17:14	Reinspection Photo		☒
102	19/03/19 17:14	Reinspection Photo		☒
103	19/03/19 17:14	Reinspection Photo		☒
104	19/03/19 17:14	Reinspection Photo		☒
105	19/03/19 17:14	Reinspection Photo		☒
106	19/03/19 17:14	Reinspection Photo		☒
107	19/03/19 17:14	Reinspection Photo		☒
108	19/03/19 17:14	Reinspection Photo		☒
109	19/03/19 17:14	Reinspection Photo		☒
110	19/03/19 17:14	Reinspection Photo		☒
111	19/03/19 17:14	Reinspection Photo		☒
112	19/03/19 17:14	Reinspection Photo		☒
113	19/03/19 17:14	Reinspection Photo		☒
114	19/03/19 17:14	Reinspection Photo		☒
115	19/03/19 17:14	Reinspection Photo		☒
116	19/03/19 17:14	Reinspection Photo		☒
117	19/03/19 17:14	Reinspection Photo		☒
118	19/03/19 17:14	Reinspection Photo		☒
119	19/03/19 17:14	Reinspection Photo		☒
120	19/03/19 17:14	Reinspection Photo		☒
121	19/03/19 17:14	Reinspection Photo		☒
122	19/03/19 17:14	Reinspection Photo		☒
123	19/03/19 17:14	Reinspection Photo		☒
124	19/03/19 17:14	Reinspection Photo		☒
125	19/03/19 17:14	Reinspection Photo		☒
126	19/03/19 17:14	Reinspection Photo		☒
127	19/03/19 17:14	Reinspection Photo		☒
128	19/03/19 17:14	Reinspection Photo		☒
129	19/03/19 17:14	Reinspection Photo		☒
130	19/03/19 17:14	Reinspection Photo		☒
131	19/03/19 17:14	Reinspection Photo		☒
132	19/03/19 17:14	Reinspection Photo		☒
133	19/03/19 17:14	Reinspection Photo		☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
135	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
136	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
137	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
138	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
139	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
140	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
141	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
142	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
143	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
144	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
145	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
146	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
147	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
148	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
149	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
150	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
151	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
152	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
153	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
154	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
155	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
156	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
157	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
158	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
159	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
160	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
161	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
162	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
163	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
164	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
165	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
166	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
167	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
168	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
169	19/03/19 17:14	Reinspection Photo	 Load JPG	☒
170	19/03/19 17:15	Photo After Spray	 Load JPG	☒
171	19/03/19 17:15	Photo After Spray	 Load JPG	☒
172	19/03/19 17:15	Photo After Spray	 Load JPG	☒
173	19/03/19 17:15	Photo After Spray	 Load JPG	☒
174	19/03/19 17:15	Photo After Spray	 Load JPG	☒
175	19/03/19 17:15	Photo After Spray	 Load JPG	☒
176	19/03/19 17:15	Photo After Spray	 Load JPG	☒
177	19/03/19 17:15	Photo After Spray	 Load JPG	☒
178	19/03/19 17:15	Photo After Spray	 Load JPG	☒
179	19/03/19 17:15	Photo After Spray	 Load JPG	☒
180	19/03/19 17:15	Photo After Spray	 Load JPG	☒
181	19/03/19 17:15	Photo After Spray	 Load JPG	☒
182	19/03/19 17:15	Photo After Spray	 Load JPG	☒
183	19/03/19 17:15	Photo After Spray	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	19/03/19 17:15	Photo After Spray	 Load JPG	☒
185	19/03/19 17:15	Photo After Spray	 Load JPG	☒
186	19/03/19 17:15	Photo After Spray	 Load JPG	☒
187	19/03/19 17:15	Photo After Spray	 Load JPG	☒
188	19/03/19 17:15	Photo After Spray	 Load JPG	☒
189	19/03/19 17:15	Photo After Spray	 Load JPG	☒
190	19/03/19 17:15	Photo After Spray	 Load JPG	☒
191	19/03/19 17:15	Photo After Spray	 Load JPG	☒
192	19/03/19 17:15	Photo After Spray	 Load JPG	☒
193	19/03/19 17:15	Photo After Spray	 Load JPG	☒
194	19/03/19 17:15	Photo After Spray	 Load JPG	☒
195	19/03/19 17:15	Photo After Spray	 Load JPG	☒
196	19/03/19 17:15	Photo After Spray	 Load JPG	☒
197	19/03/19 17:15	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 15:57	ACKNOWLEDGEMENT EMAIL TO AIG DD 28.01.2019	 Load PDF	
2	28/01/19 15:57	EMAIL FROM AIG DD 28.01.19	 Load PDF	
3	28/01/19 15:57	NOTIFICATION FROM WORKSHOP	 Load PDF	
4	12/02/19 17:23	TP ESTIMATE - MARKED	 Load PDF	
5	12/02/19 17:23	TP GIA REPORT	 Load PDF	
6	19/03/19 16:16	GIA SEARCH	 Load PDF	
7	27/03/19 14:12	WORKSHOP INVOICE	 Load PDF	
8	27/03/19 14:12	AUTHORISATION TO ACT FORM	 Load PDF	
9	27/03/19 14:12	Release Voucher	 Load PDF	
10	27/03/19 14:12	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/01/19 13:31	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLG3718P (Insd veh)	Model:	HONDA CIVIC 1.8 L 5AT (A)
	SJZ5226C (TP veh)		
Date of Accident:	26/01/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$		17,935.52
Final Repair Cost	:	\$		8,000.00
Loss of Use	:	\$		12.00 days at \$80.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		8,000.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ryder Auto Pte Ltd	: \$	8,000.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

27 Mar

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR19001812/BJA3Q2

Date: 27/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJZ5226C

Insured Vehicle No : SLG3718P

Date of Loss: 26/01/2019

Nature of Claim: TP

Claim No: 7672879877SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ5226C

Make & Model: HONDA CIVIC, 1.8 L 5AT (A)

Reg. Date: 01/12/2010 (Man. Year: 2009)

Colour: Brown

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: R18A15000338

Chassis No: JHMF1630AS200150

Odometer: 79327 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,215.52	6,680.84	5,534.68	45.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,720.00	2,190.00	3,530.00	61.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,935.52	8,870.84	9,064.68	50.54
Approved Total (Overridden) (S\$)		7,050.00		
Nett Amount (S\$)	17,935.52	7,050.00	10,885.52	60.69
+ Loss of Use (12.0 x S\$80.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		8,039.00		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 28/01/2019

Date Inspected: 28/01/2019 Inspected At:

 Ryder Auto Workshop LLP (HQ)
 1 Kaki Bukit Ave 6, #01-56, Autobay @
 Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	920.00 FL	*638.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
3	1		*REAR BUMPER EXHAUST GARNISH	Dented	17.00 FL	*17.00 FL
4	2		*REAR BUMPER EXHAUST GARNISH CLIPS	Not Necessary	7.80 FL	*- FL
5	2		*REAR BUMPER O/S & N/S BRACKET	Bent	47.80 FL	*47.80 FL
6	2		*REAR BUMPER O/S & N/S RETAINER	Bent (1 PCS ONLY)	49.20 FL	*49.20 FL
7	2		*REAR BUMPER O/S & N/S CORNER CLIPS	Not Necessary	86.00 FL	*- FL
8	1		*REAR BUMPER ENFORCEMENT	Not Necessary	568.80 FL	*- FL
9	1		*REAR BUMPER SCREW (LOWER)	Not Necessary	24.20 FL	*- FL
10	1		*REAR END PANEL	Bent	300.50 FL	*300.50 FL
11	1		*REAR END PANEL TRIM	Broken	60.80 FL	*60.80 FL
12	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	18.00 FL	*18.00 FL
13	2		*REAR O/S & N/S TAIL-LAMP	Broken	610.00 FL	*610.00 FL
14	2		*REAR O/S & N/S TAIL-LAMP SEALANT	Not Necessary	47.00 FL	*- FL
15	4		*REAR O/S & N/S TAIL-LAMP CLIPS	Not Necessary	14.00 FL	*- FL
16	2		*REAR O/S & N/S TAIL -LAMP PANEL	Dented	460.00 FL	*244.20 FL
17	1		*REAR BOOT COVER	Bent	610.00 FL	*610.00 FL
18	1		*REAR BOOT COVER WEATHER STRIPS	Cut	97.60 FL	*97.60 FL
19	1		*REAR BOOT COVER EMBLEM	Necessary	76.90 FL	*52.20 FL
20	2		*REAR BOOT COVER EMBLEM CLIPS	Necessary	8.00 FL	*8.00 FL
21	1		*REAR BOOT COVER CIVIC EMBLEM	Necessary	29.00 FL	*29.00 FL
22	1		*REAR BOOT COVER 1.8 EMBLEM	Necessary	18.00 FL	*18.00 FL
23	1		*REAR BOOT COVER I-VTEC EMBLEM	Necessary	34.00 FL	*34.00 FL
24	2		*REAR BOOT COVER O/S & N/S REFLECTOR	Broken	291.80 FL	*291.80 FL
25	2		*REAR BOOT COVER O/S & N/S REFLECTOR SEALANT	Not Necessary	48.20 FL	*- FL
26	4		*REAR BOOT COVER O/S & N/S REFLECTOR CLIPS	Not Necessary	14.00 FL	*- FL
27	1		*REAR BOOT COVER LOCK (UPPER)	Bent	205.00 FL	*205.00 FL
28	1		*REAR BOOT COVER LOCK (INNER)	Not Necessary	22.00 FL	*- FL
29	1		*REAR BOOT COVER LOCK WASHER	Not Necessary	18.00 FL	*- FL
30	1		*REAR BOOT COVER INNER TRIM	Torn	233.70 FL	*233.70 FL
31	8		*REAR BOOT COVER INNER TRIM CLIPS	Necessary	36.00 FL	*36.00 FL
32	2		*REAR BOOT COVER O/S & N/S STOPPER	Not Necessary	14.00 FL	*- FL
33	1		*REAR BOOT COVER O/S & N/S HINGES	O/S Necessary	97.20 FL	*48.60 FL
34	1		*REAR BOOT COVER LOCK SNAP	Not Necessary	4.00 FL	*- FL
35	1		*REAR BOOT COVER LOCK SILENCER	Not Necessary	380.00 FL	*- FL
36	1		*REAR BOOT FLOOR PANEL	Dented	948.50 FL	*911.40 FL
37	1		*REAR BOOT FLOOR PANEL CROSS -MEMBER	Not Necessary	1,920.80 FL	*- FL
38	1		*SET REAR BOOT FLOOR PANEL INSULATOR	Necessary	155.00 FL	*155.00 FL
39	1		*REAR BOOT FLOOR PANEL COVER (INNER)	Not Necessary	125.00 FL	*- FL
40	4		*REAR BOOT FLOOR PANEL COVER CLIPS (INNER)	Not Necessary	15.60 FL	*- FL
41	1		*REAR BOOT FLOOR PANEL TOOL TRAY SPONGE	Broken	205.00 FL	*205.00 FL
42	1		*REAR SPARE WHEEL BOARD COVER	Torn	316.00 FL	*316.00 FL
43	1		*SET REAR WINDSCREEN MOULDING	Not Necessary	216.40 FL	*- FL
44	14		*REAR WINDSCREEN MOULDING CLIPS	Not Necessary	65.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR N/S FENDER	Not Necessary	741.50 FL	*- FL
46	2		*REAR O/S & N/S FENDER AIR VENT DUCT	Broken	48.60 FL	*48.60 FL
47	2		*REAR O/S & N/S FENDER INNER PADDING	Not Necessary	783.50 FL	*- FL
48	8		*REAR O/S & N/S FENDER INNER PADDING CLIPS	Not Necessary	64.00 FL	*- FL
49	2		*REAR O/S & N/S FENDER INNER TRIM	Torn	291.80 FL	*291.80 FL
50	1		*REAR O/S & N/S FENDER INNER TRIM CLIPS (16 PCS)	Necessary (8 PCS ONLY)	72.00 FL	*30.00 FL
51	1		*REAR O/S & N/S FENDER WHEEL GUARD	N/S Missing	292.20 FL	*146.10 FL
52	1		*REAR O/S & N/S FENDER WHEEL GUARD CLIPS (16 PCS)	Missing (5 PCS ONLY)	72.00 FL	*22.50 FL
53	1		*REAR N/S CHASSIS FRAME	Dented	1,460.00 FL	*1,174.80 FL
54	1		*REAR EXHAUST MUFFLER	Dented	1,150.00 FL	*850.00 FL
55	1		*REAR EXHAUST MUFFLER TAIL PIPE	Bent	165.80 FL	*157.00 FL
56	2		*REAR EXHAUST MUFFLER MOUNTING (RUBBER)	Torn	25.00 FL	*25.00 FL
57	1		*REAR EXHAUST MUFFLER SHIELD	Dented	43.80 FL	*43.80 FL
58	1		*REAR EXHAUST MUFFLER GASKET	Necessary	12.20 FL	*12.20 FL
59	1		*REAR REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
60	1		*REAR REGN .NO.PLATE	Not Necessary	45.00 FS	*- FS
61	1		*REAR REGN .NO.PLATE BRACKET	Broken	29.00 FS	*25.00 FS
62	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
63	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,153.40** **8,294.80**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 2,937.88 1,613.96

Total Parts (\$\$) **12,215.52** **6,680.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE REAR PORTION DAMAGED PARTS,STRAIGHTEN REAR N/S CHASSIS FRAME ,REPAIR BOOT FLOOR PANEL ,REAR O/S & N/S FENDER	New	2,200.00	1,200.00
2	TO PUTTY AND SPRAY PAINTING	New	1,600.00	800.00
3	TO RE-ALIGN REAR CHASSIS FRAME	New	380.00	0.00
4	TO CHECK REAR WHEEL ALIGNMENT (BEFORE & AFTER)	New	240.00	0.00
5	TO REPLACE REAR EXHAUST MUFFLER	New	300.00	80.00
6	TO REMOVE AND REFIT REAR WINDSCREEN ,SEATS AND ROOF LINING TO FACILITATE REPAIRS	New	300.00	0.00
7	TO REMOVE AND REFIT FUEL TANK	New	200.00	0.00
8	TO CHECK WIRING	New	120.00	50.00
9	TO RE-SEAL ANTI-RUST	New	380.00	60.00
Gross Labour Cost (S\$)			5,720.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >