

Polish/light
change oil
(corner)

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Fax: 64815390

ESTIMATE OF REPAIR

SJZ5226C Pg 1/3

Veh # : SJZ5226C Model : HONDA CIVIC 1.8L (1/12/2010)

Date Of Accident: 26/1/2019 3P : SLG3718P (AIG)

Location : AFTER ENG NEO

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>List Items</u>				
1 pc	Rear bumper	DDV	638.00	920.00	
10 pcs	Rear bumper clips	NECV		31.20	✓
1 pc	Rear bumper exhaust garnish	DDV		17.00	
2 pcs	Rear bumper exhaust garnish clips	NNX		-7.80	
2 pcs	Rear bumper o/s & n/s bracket	? BTV		47.80	✓
2 pcs	Rear bumper o/s & n/s retainer	? NECV BTV		49.20	✓
2 pcs	Rear bumper o/s & n/s corner clips	? NECV		-86.00	XNN
1 pc	Rear bumper enforcement	? NNX		-568.80	
1 pc	Rear bumper screw (Lower)	? NNX		-24.20	
1 pc	Rear tail lamp panel <i>Rear End panel</i>	? BTV		300.50	✓
1 pc	Rear tail lamp panel inner trim <i>Rear end panel trim</i>	? BRV		60.80	✓
4 pcs	Rear tail lamp panel inner trim clips	? NEC		18.00	✓
2 pcs	Rear o/s & n/s tail-lamp @ 308.70	BRV		610.00	✓
2 pcs	Rear o/s & n/s tail-lamp sealant	NNX		-47.00	
4 pcs	Rear o/s & n/s tail-lamp clips	NECV		-14.00	XNN
2 pcs	Rear o/s & n/s tail-lamp panel @ 122.10	? DDV	244.20	-460.00	
1 pc	Rear boot cover	BTV		610.00	✓
1 pc	Rear boot cover weather-strips	? EUT		97.60	✓
1 pc	Rear boot cover emblem		52.20	76.90	
2 pcs	Rear boot cover emblem clips			8.00	✓
1 pc	Rear boot cover 'CIVIC' emblem	NECV		29.00	✓
1 pc	Rear boot cover '1.8' emblem			18.00	✓
1 pc	Rear boot cover 'i-VTEC' emblem			34.00	✓
2 pcs	Rear boot cover o/s & n/s reflector @ 202.90	BRV		291.80	✓
2 pcs	Rear boot cover o/s & n/s reflector sealant	NNX		-48.20	
4 pcs	Rear boot cover o/s & n/s reflector clips	NECV		-14.00	XNN
1 pc	Rear boot cover lock (Upper)	? BTV		205.00	✓
1 pc	Rear boot cover lock (Inner)	? NNX		22.00	
1 pc	Rear boot cover lock washer	? NNX		-18.00	

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
1 pc	Rear boot cover inner trim	? TN ✓		233.70	✓
8 pcs	Rear boot cover inner trim clips	? NEC ✓		36.00	✓
2 pcs	Rear boot cover o/s & n/s stopper	? NNX		14.00	
2 pcs	Rear boot cover o/s & n/s hinges OS @ 48.60 1 pc	? 48.60		97.20	
1 pc	Rear boot cover lock snap	? NNX		4.00	
1 pc	Rear boot cover lock silencer	? NNX		380.00	
1 pc	Rear boot floor panel	? DD ✓ 911.40		948.50	
1 pc	Rear boot floor panel cross-member	? NNX		1,920.80	
1 set	Rear boot floor panel insulator	? NEC ✓		155.00	✓
1 pc	Rear boot floor panel cover (Inner)	? NNX		125.00	
4 pcs	Rear boot floor panel cover clips (Inner)	? NNX		45.60	
1 pc	Rear boot floor panel tool tray sponge	? BR ✓		205.00	✓
1 pc	Rear spare wheel board cover	? TN ✓		316.00	✓
1 set	Rear windscreen moulding	? NNX		216.40	
14 pcs	Rear windscreen moulding clips	? NNX		65.00	
1 pc	Rear n/s fender	? NNX		741.50	
2 pcs	Rear o/s & n/s fender air vent duct @ 24.30	? BR ✓		48.60	✓
2 pcs	Rear o/s & n/s fender inner padding	? NNX		783.50	
8 pcs	Rear o/s & n/s fender inner padding clips	? NNX		64.00	
2 pcs	Rear o/s & n/s fender inner trim @ 242.80	? TN ✓		291.80	✓
16 pcs	Rear o/s & n/s fender inner trim clips (8 pcs)	? NEC ✓ 30.00		72.00	✓
2 pcs	Rear o/s & n/s fender wheel guard LH	MIS 1 pc		292.20	
16 pcs	Rear o/s & n/s fender wheel guard clips LH 5 pcs	MIS 8 pcs		72.00	
1 pc	Rear n/s chassis frame 1,174.80	? DD ✓		1,460.00	
1 pc	Rear exhaust muffler 850.00	? DD ✓		1,150.00	
1 pc	Rear exhaust muffler tail pipe	BT ✓ 157.00		165.80	✓
2 pcs	Rear exhaust muffler mounting (rubber)	? TN ✓		25.00	✓
1 pc	Rear exhaust muffler insulator shield	? DD ✓		43.80	
1 pc	Rear exhaust muffler gasket	? NEC ✓		12.20	✓
	Sub-Total			14,689.40	
	After -20%			11,751.52	

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921
Email: ryderautoworkshop@gmail.com
Fax: 64815390

SJZ5226C Pg 3/3

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$
	<u>Special Nett Items</u>			
1 pc	Rear reverse sensor	CUT	280.00	280.00
1 pc	Rear regn. no. plate	? NN X		45.00
1 pc	Rear regn. no. plate bracket	? BR ✓	25.00	29.00
1 pc	Rear windscreen sealant	? } NN X		60.00
1 pc	Rear windscreen inner seal	? } NN X		50.00
	Sub-Total			464.00
	<u>Labour</u>			
1	To dismantle rear portion damaged parts, straighten rear n/s chassis frame, rear boot floor panel, rear o/s & n/s fender.	?	1200.00	2,200.00
2	To putty and spray painting.	?	800.00	1,600.00
3	To re-align rear chassis frame.	? NN X		380.00
4	To check rear wheel alignment (Before & After).	NN X		240.00
5	To replace rear exhaust muffler.	80.00	100.00	300.00
6	To remove and refit rear windscreen, seats and roof lining to facilitate repairs.	? NN X		300.00
7	To remove and refit fuel tank.	NN X		200.00
8	To check wiring.		50.00	120.00
9	To re-seal anti-rust.		60.00	380.00
	Sub-Total			5,720.00
	Total			17,935.52
	After -20%			14,348.42

Resurvey 29/1/19
TGR in line 1450

llan

TGR in line 28/1/19 1510

? photo

Lump sum repair
10 days

30/1/19

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust), AffMIAEA

@ BOK SENG
(heavy vehicles, marine vessels)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Authorised Workshop
Authorised Reporting Centre

8778 1999
24 hr accident call