



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Pratap Chinnan Nambiar 105C Dalvey Road Singapore 259498 Contact No 67359274	Cust No/Name	KCV05434/Pratap Chinnan Nambiar
	Reg No/Reg Date	SGH8145M / 16/05/201
	Date In/Mileage	/ 0
	Chassis No	JMFXTGA2WFZC14123
	Engine No	4B11RK7318
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV05434	CRDVCH	26/01/2019/ 10:45		442 / CocoLu	35727
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW REAR BUMPER, REAR END PANEL, REPAIR TAILGATE REAR COMPARTMENT				2750.00
E PNT98000	SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, TAILGATE REAR COMPARTMENT				2100.00
E PNT88000	REMOVE & INSTALL PARKING SENSOR				100.00
M SUNDRY	C&C LOGO				40.00
M SUNDRY	SUPPLY PARKING SENSOR				220.00
M SUNDRY	APPLY SEALANT FOR ACCIDENT PORTION				40.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 54900099	CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				200.00
A 54900099	RENEW REAR EXHAUST SYSTEM				300.00
M SUNDRY	Sundry				20.00
E PNT88000	REMOVE & INSTALL REAR COMPARTMENT TRIMS				300.00
M FACE,RR BUMPER		1.00	877.00	00.00	877.00
M BRKT,R/BMPR FACE SUPT,RH		1.00	26.00	00.00	26.00
M BRKT,R/BMPR FACE SUPT,LH		1.00	26.00	00.00	26.00
M BRACKET,RR BUMPER		2.00	15.00	00.00	30.00
M REINFORCEMENT,RR BUMPER		1.00	231.00	00.00	231.00
M COVER,RR FOG LAMP		1.00	43.00	00.00	43.00
M PANEL,RR END		1.00	257.00	00.00	257.00
M PANEL,RR END,INR RH		1.00	28.00	00.00	28.00
M PANEL,RR END,INR LH		1.00	28.00	00.00	28.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Pratap Chinnan Nambiar 105C Dalvey Road Singapore 259498 Contact No 67359274	Cust No/Name	KCV05434/Pratap Chinnan Nambiar
	Reg No/Reg Date	SGH8145M / 16/05/201
	Date In/Mileage	/ 0
	Chassis No	JMFXTGA2WFZC14123
	Engine No	4B11RK7318
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV05434	CRDVCH	26/01/2019/ 10:45		442 / CocoLu	35727		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	MARK,THREE-DIA			1.00	51.00	00.00	✓ 51.00
M	MARK,ASX			1.00	55.00	00.00	✓ 55.00
M	TRIM,RR END			1.00	122.00	00.00	X 122.00
M	MOULDING,RR WHEEL ARCH,RH			1.00	131.00	00.00	✓ 131.00
M	ANT,KEYLESS OPERATION,RR			1.00	95.00	00.00	✓ 95.00
M	BUZZER,KEYLESS OPERATIO,RR			1.00	90.00	00.00	✓ 90.00
M	PROT,UNDER RR FLOOR HEAT			1.00	92.00	00.00	✓ 92.00
M	MUFFLER,EXHAUST MAIN			1.00	479.00	00.00	✓ 479.00
M	HANGER,EXHAUST MUFFLER			1.00	24.00	00.00	✓ 24.00

Estimate

Steve (LKK) with peroxide 11/3/19 11am
 8322 8813 P/P
 Ray bef & AL spray
 7 days

Confirm & accepted by

	Nett	8,785.00
7% GST on	8785.00	614.95
Total Payable		9,399.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.