



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Pratap Chinnan Nambiar  105C Dalvey Road Singapore 259498  Contact No 67359274	Cust No/Name	KCV05434/Pratap Chinnan Nambiar
	Reg No/Reg Date	SGH8145M / 16/05/201
	Date In/Mileage	/ 0
	Chassis No	JMFXTGA2WFZC14123
	Engine No	4B11RK7318
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV05434	CRDVCH	26/01/2019/ 10:45		442 / CocoLu	35727
Description of Goods/Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REAR END PANEL, REPAIR TAILGATE REAR COMPARTMENT					2750.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, TAILGATE REAR COMPARTMENT					2100.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR					100.00
M SUNDRY C&C LOGO					40.00
M SUNDRY SUPPLY PARKING SENSOR					220.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION					40.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM					30.00
A 54900099 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM					200.00
A 54900099 RENEW REAR EXHAUST SYSTEM					300.00
M SUNDRY Sundry					20.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS					300.00
M FACE,RR BUMPER		1.00	877.00	00.00	877.00
M BRKT,R/BMPR FACE SUPT,RH		1.00	26.00	00.00	26.00
M BRKT,R/BMPR FACE SUPT,LH		1.00	26.00	00.00	26.00
M BRACKET,RR BUMPER		2.00	15.00	00.00	30.00
M REINFORCEMENT,RR BUMPER		1.00	231.00	00.00	231.00
M COVER,RR FOG LAMP		1.00	43.00	00.00	43.00
M PANEL,RR END		1.00	257.00	00.00	257.00
M PANEL,RR END,INR RH		1.00	28.00	00.00	28.00
M PANEL,RR END,INR LH		1.00	28.00	00.00	28.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**MITSUBISHI**  
**MOTORS**

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Pratap Chinnan Nambiar  105C Dalvey Road Singapore 259498  Contact No 67359274	Cust No/Name	KCV05434/Pratap Chinnan Nambiar
	Reg No/Reg Date	SGH8145M / 16/05/201
	Date In/Mileage	/ 0
	Chassis No	JMFXTGA2WFZC14123
	Engine No	4B11RK7318
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV05434	CRDVCH	26/01/2019/ 10:45		442 / CocoLu	35727
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	MARK, THREE-DIA	1.00	51.00	00.00	51.00
M	MARK, ASX	1.00	55.00	00.00	55.00
M	TRIM, RR END	1.00	122.00	00.00	122.00
M	MOULDING, RR WHEEL ARCH, RH	1.00	131.00	00.00	131.00
M	ANT, KEYLESS OPERATION, RR	1.00	95.00	00.00	95.00
M	BUZZER, KEYLESS OPERATIO, RR	1.00	90.00	00.00	90.00
M	PROT, UNDER RR FLOOR HEAT	1.00	92.00	00.00	92.00
M	MUFFLER, EXHAUST MAIN	1.00	479.00	00.00	479.00
M	HANGER, EXHAUST MUFFLER	1.00	24.00	00.00	24.00

# Estimate

Confirm &amp; accepted by

7% GST on	Nett 8785.00	8,785.00
		614.95
Total Payable		9,399.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.