

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001825/UDS3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800113557

Claimant
Vehicle No : FBK2957U **Insured Vehicle No :** SKW5138C

Date of Loss: 08/12/2018 Nature of Claim: TP Claim No: 1505257626SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK2957U	Engine No:	E3F5E039271
Make & Model:	YAMAHA YBR125, 123cc (M)	Chassis No:	LBP101000054262
Reg. Date:	20/06/2015 (Man. Year: 2015)	Odometer:	63152 km
Colour:	Grey		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90-90-18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	471.00	175.50	295.50	62.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	70.00	70.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	541.00	245.50	295.50	54.62
+ GST 7.00/7.00% (S\$)	37.87	17.19	20.68	54.61
Nett Amount (S\$)	578.87	262.69	316.18	54.62
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/01/2019

Date Inspected: 28/01/2019 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER TAIL LH (BLACK)	Repair	82.00 F	* - FL
2	1		*COVER TAIL RH (BLACK)	Repair	96.00 F	* - FL
3	1		*CRASH BAR	Bent	195.00 F	*195.00 FL
4	1		*REAR BODY ALIGNMENT	Not Necessary	98.00 F	* - FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	471.00	195.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	19.50
Total Parts (\$)	471.00	175.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	35.00	35.00
2	TRANSPORT CHARGES-FOR COLLECTION ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE	New	35.00	35.00
Gross Labour Cost (\$\$)			70.00	70.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >