

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 18:32
Date Of Accident	24/01/2019 07:15
Exact Location Of Accident	JUNCTION OF SIGLAP ROAD AND EAST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP7792A
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	FAESAL BIN AHMAD SAID BIN TALIB
NRIC No	S7439762Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96873544
Alternative Phone No	Office-96778728

Vehicle Particulars

Manufacturer	MAZDA
Model	5 2.0 SKYACTIV
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100510216-01
Cover Note Number	

Driver

Name of Driver	FAESAL BIN AHMAD SAID BIN TALIB
NRIC No	S7439762Z
Date Of Birth	17/12/1974
Occupation	INDOOR
Date Of Driving Pass	26/04/1997
Driving Experience	21 YEARS AND 8 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-96873544
Fax Number	
Contact Number	OFFICE-96778728
EMail Address	NOEMAIL
Address	626 EAST COAST ROAD SINGAPORE
Postcode	459012
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	FS9106Z - -
Insurance Company of Driver's Own Vehicle	Direct Asia Insurance (Singapore) Pte Ltd - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


Collision - Head to Rear (I hit a third party vehicle), #others, Upload the drawing sketch plan. On 24 Jan 2019 at 0715hrs I was travelling on Siglap Road towards Opera Estate wanting to turn left to East Coast Road. I stopped behind a mcar BMW white SJN2211C at the left filter lane. When I saw the mcar SJN2211C moving off I released my brakes and have not stepped on the gas and my car rolled forward. While I was looking out for traffic the mcar SJN2211C suddenly jammed her brakes suddenly when she was halfway into East Coast Road and as a result the front of car slightly bumped the rear of mcar SJN2211C. There was nil damage observed on both cars as the bump was very soft. Refer to attached pictures. We exchanged contact and I informed the other party that its best to settle ourselves as there was nil damage and I was ready to compensate slightly. I was astonished when she forward the repair bill. Refer attached. I am making this report for record purposes only.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NO VIDEO FILE ATTACHED
Was there any audio recorded?	NO

Vehicle Registration Number	SJN2211C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	91382212
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



Insd's Nric (Front)




Insd's Nric (Back)



Insd's Driving License (Front)



Insd's Driving License (Back)



Individual Statement

Performance Motors Limited

A member of the Sun Group Berhad
Co. Reg. No. 207413399 (M.T. Reg. No. K2-011001)-S101, Alexander Road
2nd Floor, Performance Centre
Singapore 119955
Tel: 67401111 (Office & Admin)
67401111 (Afterhours)
Fax: 67471777281, Selegie Road
2nd Floor, Level 2
Singapore 118444
Tel: 67401111 (Afterhours)
Fax: 67471777111, Alexander Road
2nd Floor, Performance Centre
Singapore 119955
Tel: 67401111 (Afterhours)
67401111 (Afterhours)
Fax: 67401111 (Afterhours)
67401111 (Afterhours)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49894		Page No. : 1 of 4
Date Estimated : 24/01/2019		
Prepared By : Inthiran A/L Thurasamy		
- ESTIMATE REPAIR FOR - Law Seow Khim 2 Everton Road Singapore 089359		- ACCOUNT - 40000 Cash Sales - Service Singapore
REGN. NO.	CHASSIS NO.	REGN. DATE
SJN2211C	ED04985	31/12/2018
MODEL	MILEAGE	
216i GT	0	
DESCRIPTION Removing and installing rear bumper panel Paint rear bumper panel -This quote based on cash repair not for insurance claim purpose.		VALUE 205.00 750.00 0.00
Total Labour is:		955.00
<i>a Duration of repair is 3 working days</i>		
		
Labour 1	:	955.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	66.85
Grand Total	:	1,021.85

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

Accident Photo



Accident Photo



Accident Photo

BMW ONLINE

Performance Motors Limited
 A member of the Sun Group Group
 Tel. 069 400 2814/069 400 2815/069 400 2816/069 400 2817

101, Alexander Road
 Sun Group Performance Centre
 Singapore 11994
 Tel. 011 001 01 (Office & Sales)
 011 001 01 (Afterhours)
 Fax. 011 001 01

201, Selegie Avenue Road
 BMW Credit Centre
 Singapore 11994
 Tel. 011 001 01 (Afterhours)
 Fax. 011 001 01

101, Alexander Road
 Sun Group Performance Centre
 Singapore 11994
 Tel. 011 001 01 (Afterhours)
 011 001 01 (Afterhours)
 Fax. 011 001 01 (Afterhours)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49894	Page No. : 1 of 4
Date Estimated : 24/01/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Law Seow Khim 2 Everton Road Singapore 089359	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN2211C	ED04985	31/12/2018	2161 GT	0

DESCRIPTION	VALUE
Removing and installing rear bumper panel	205.00
Paint rear bumper panel	750.00
-This quote based on cash repair not for insurance claim purpose.	0.00
Total Labour 1:	955.00

** Duration of repair is 3 working days up*

Inthiran A/L Thurasamy
 Performance Motors Limited
 101 Alexander Road
 Sun Group Performance Centre
 Singapore 11994

Labour 1	+	955.00
Parts	+	0.00
Labour 2	+	0.00
Excess	+	0.00
Total GST @ 7%	+	66.85
Grand Total	=	1,021.85

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **