

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0140/2019/KN
Date : 30-Jan-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Dilip. Kadambi
Address : 23 Grange Road
#07-25
Singapore 239698
Telephone : HP +65 91019697
Type of Claim : Third Party Claim
Policy No. : 2100350941-05
Vehicle No : **SJT 1950 C**
Model Code : Audi A6 2.0 TFSI
Model / Year : 28/9/2009
Engine No : BPJ 160010
Chassis No : WAUZZZ4F8AN011605
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Jan-19
Place of Accident : Holland Peak at Holland Hill

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJT 1950 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To check and remove front wire harness for headlight, horns, outside temperature sensor, and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle front bumper, rhs fender and rhs headlight. To repair rhs front door. To renew rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,800.00 1000.	
3	To respray front bumper, rhs front fender and rhs front door.	\$ 2,500.00 1650.	
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To recover and tow vehicle from scene of accident.	S/N \$ 130.00 ? tow by receipt	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,262.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJT 1950 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT WING - RH	\$ 1,202.00	bt ✓
2	FRONT BRACE - RH	\$ 78.00	?
3	FRONT BUMPER SEAL - RH	\$ 43.00	?
4	FRONT BUMPER SEAL - RH	\$ 27.00	?
5	VLIES HOUSING LINER - RH	\$ 461.00	de ✓
6	FRONT SPOILER - RH	\$ 32.00	X
7	S LINE INSCRIPTION	\$ 113.00	net ✓
8	FRONT HEADLIGHT - RH	\$ 2,842.00	?
9	FRONT ALUMINIUM RIM - RH	\$ 1,290.00	X
10	RUBBER VALVE	4 \$ 13.00	X
11	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		\$ 6,401.00	
TOTAL LABOUR CHARGES		\$ 6,262.00	
GRAND TOTAL		\$ 12,663.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Tanpin 97445744
31/1/190 250pm
'WP'
Repair before paint
05 days
sure (handwritten signature)

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant