

ASS. REC. BY:

REF: CS/FCU19001857/Asd3ⁿ² Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter of FCI Date/Time: 28/11/19 @ 5:54pm

Estimated Cost: Bill to:

OD TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJY 9605X Insured: SH 6199D

at Workshop m/s N-51 Automotive Tel: 68420051

of 2 Kaki Bkt Ave 2 # 01-18

Policy No: Claim No: D19000714MFS#

Sum Insured: Excess:

Make of Vch: D.O.A. 26/01/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 29/11/19 @ 9:02am Person Contacted: Melody Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJY 9605X - NA / INC19001742/h4 DUA: 26/01/2019
	SH 6199D - x
24/05/19	Confirmed L/S \$ 7,500/- @ 8 days with Adrian (\$ 7,409.61 Red - 50%)

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

8

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: STY9605XYr Regn: 2010, Oct.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camryc.c. 1998Colour: Grey

A/C: Insured / Std / Nil / NA

Sp. Reading: 106491

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MP053BK4107061758

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal. 06

mm

R/Bal. 06

mm

L/Bal. 96

mm

L/Bal. 96

mm

D.O.A. _____

D.O.I. 29/61/19Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s, u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.MV - 330KLTA - 321,850/-Nett - 88,150.00MV: 30KPV: 21.9KNett: 8.1K

RECEIVED 24 MAY 2019

Resurvey No. of Trip - 2

Date/Time, File Pass to?

Date/Time, File Return to?

1) Typist

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: 7,500/- HS

Part Prices Check:

IN

OUT

Survey Fee:

Date: 4x15:60

Basic & Add.

S + RS, SI

Photos OSPOthers 119TOTAL 499170 + 605050 + 50119499

MOTOR SURVEY ASSIGNMENT

Date	28-01-2019	Our Ref No. D19000714MFSH
Accident Date	26-01-2019	Claim Type. Third Party
Insured Vehicle	SH6199D	Third Party Vehicle. SJY9605X
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	MELODY CHIN	
Contact No.	68420051/ 67440510	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: NO EST. COR (QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 30 January 2019 2:41 PM
To: 'Serene Ler'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D19000714MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SJY 9605X on 29/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 29 January 2019 9:06 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000714MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 28 January 2019 5:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000714MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CONNECTING CAR BUYERS & SELLERS.
 We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

SEARCH

Price Range

▼

Depreciation

▼

2011

▼

Vehicle Type

▼

Search

View All

Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Camry 2.0A

Toyota Camry 2.0A

Toyota Camry 2.0A



Clear All

[Add all to Shortlist](#)

[Add to Shortlist](#)

[Add to Shortlist](#)

[Add to Shortlist](#)

[Back to search result](#)

CAR DETAILS

Price	\$31,888	\$35,788	\$41,800	-
Instalment	\$1,296	\$1,026	\$987	-
Registration Date	12-Aug-2010	25-Apr-2011	29-Sep-2011	-
Manufactured	2010	2011	2011	-
Mileage	135,000 km	83,528 km	137,512 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,998 cc	1,998 cc	1,998 cc	-
Road Tax	\$1,210 /yr	\$1,210 /yr	\$1,210 /yr	-
Power	108.0 kW (144 bhp)	108.0 kW (144 bhp)	108.0 kW (144 bhp)	-
Curb Weight	1,530 kg	1,530 kg	1,530 kg	-
Features	2.0L 4 Cylinders 16 Valves DOHC VVT-i Engine, Automatic Transmission, SRS Airbags, Auto Headlights And Rain Sensors, Traction Control, Cruise Control.	-	Powerful 2.0L 16 Valve Inline DOHC VVT-i, 4 Airbags, ABS, Multi Function Steering Wheel, Dual Climate Digital Control Aircon, Retractable Side Mirror.	-
Accessories	Sports Rims, Leather Seats, Tom Tom Audio With Steering Controls/GPS, Reverse Camera And Sensors, Retractable Side Mirrors, Solar Film, Fog Lights.	-	Factory Fitted Sports Rims, Full Leather Upholstery, Reverse Sensors, Fog Lamps, Factory Audio System With Navigational System.	-
Description	Original Paintwork, Well Kept And Maintained Condition, No More Repair Needed! Ideal For Your Family And Daily Usage. Fuel Saving Yet Powerful Drive, Pristine Interior Condition, Probably The Best Condition In The Market. High And Easy Loan Can Be Arrange.	1 Owner Car! Extremely Well Maintained By Owner! Very Low Mileage Done! Electric Front Seats! Spacious And Luxury Sedan! Full Servicing Done! Original Condition! Great For Short Term Use! Call Me Now Before It Is Gone!	Benefit Auto Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Arrange Call To Our Sales For Appointment!	-
COE	\$43,334	\$57,100	\$62,502	-
OMV	\$26,443	\$23,514	\$22,432	-
ARF	\$26,443	\$23,514	\$22,432	-
Depreciation	\$12,170 /yr	\$10,750 /yr	\$11,470 /yr	-
No. of Owners	2	1	2	-
Type of Vehicle	Luxury	Luxury	Luxury	-
Category	PARF Car	PARF Car	PARF Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3802C
Vehicle Details	
Vehicle No.:	SJY9605X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	1AZE181747
Chassis No.:	MR053BK4107061758
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$26,382.00
Original Registration Date:	18 Oct 2010
First Registration Date:	18 Oct 2010
Transfer Count:	3
Actual ARF Paid:	\$26,382.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Oct 2020
PARF Rebate Amount:	\$14,510.00
Intended COE Rebate Details	
COE Expiry Date:	17 Oct 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$7,340.00
Total Rebate Amount:	\$21,850.00

The information contained herein is correct as at 29 Jan 2019

OK

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ONG CHOON CHYE
 3 TENG TONG ROAD
 SINGAPORE 423495

Contact : 96806723

TP 1st Cap.

Shirley

ESTIMATE

Nett: 8K.

Repair Code : CLM15035

Date in : 26/01/2019

Vehicle Num. : SJY9605X

Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG

Chassis/Eng# : MR053BK4107061758/1AZE181747

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Buckled.</i>	1	888.60	✓ 888.60
REAR BOOTLID '2.0' EMBLEM <i>3 New</i>	1	63.10	✓ 63.10
REAR BOOTLID 'LOGO' EMBLEM	1	53.20	✓ 53.20
REAR BOOTLID INNER UPHOLSTERY TRIM <i>Not New</i>	1	346.80	X 346.80
REAR BOOTLID MECHANISM LOCK <i>New</i>	1	501.70	X 501.70
REAR BOOTLID OUTER GARNISH <i>Cracked</i>	1	381.80	286 X 381.80
REAR BOOTLID REFLECTOR BACK RUBBER GASKET L/R <i>RH New</i>	2	43.70	(20) 87.40
REAR BOOTLID REFLECTOR L/R <i>RH Cracked</i>	2	289.50	289.50 579.00
REAR BOOTLID WEATHER STRIP <i>ut</i>	1	190.40	✓ 190.40
REAR BUMPER <i>Distorted.</i>	1	581.40	✓ 581.40
REAR BUMPER BRACKET L/R <i>New</i>	2	131.35	X 262.70
REAR BUMPER REINFORCEMENT <i>Best</i>	1	326.40	✓ 326.40
REAR BUMPER REINFORCEMENT BRACKET RH <i>New</i>	1	182.20	X 182.20
REAR BUMPER RH REFLECTOR <i>cracked</i>	1	61.20	✓ 61.20
REAR BUMPER SIDE RETAINER L/R <i>RH New</i>	2	131.20	131.20 262.40
REAR END PANEL 'INNER' <i>New</i>	1	791.10	X 791.10
REAR END PANEL 'OUTER' <i>Distorted</i>	1	581.10	✓ 581.10
REAR END PANEL INNER TOP GARNISH <i>Defunct</i>	1	434.20	✓ 434.20

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ONG CHOON CHYE
 3 TENG TONG ROAD
 SINGAPORE 423495

Contact : 96806723

ESTIMATE

Repair Code : CLM15035

Date in : 26/01/2019

Vehicle Num. : SJY9605X

Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG

Chassis/Eng# : MR053BK4107061758/1AZE181747

REAR EXHAUST ALUMINIUM HEAT SHIELD <i>new</i>	1	231.90	<i>+</i> 231.90
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	32.00	<i>+</i> 64.00
REAR EXHAUST SILENCER BOX <i>best</i>	1	987.70	<i>876</i> 987.70
REAR EXHAUST GASKET <i>new</i>	1	41.00	<i>✓</i> 41.00
REAR RH FENDER <i>Distorted</i>	1	972.10	<i>✓</i> 972.10
REAR RH FENDER INNER SHIELD <i>ton</i>	1	171.80	<i>✓</i> 171.80
REAR RH FENDER INNER UPHOLSTERY TRIM <i>new</i>	1	346.80	<i>+</i> 346.80
REAR RH KNUCKLE ARM <i>best</i>	1	580.00	<i>✓</i> 580.00
REAR RH SHOCK ABSORBER <i>best</i>	1	368.00	<i>✓</i> 368.00
REAR RH TAILLAMP INNER PANEL <i>Distorted.</i>	1	281.55	<i>✓</i> 281.55
REAR RH WHEEL BEARING <i>new</i>	1	743.00	<i>✓</i> 743.00
REAR TAILLAMP L/R <i>RH could</i>	2	408.30	<i>128.30</i> 816.60
REAR TAILLAMP LOWER BRACKET L/R <i>RH Rpt</i>	2	161.25	<i>35</i> 322.50
REAR WINDSCREEN MOULDING <i>new</i>	1	181.75	<i>✓</i> 181.75
SPARE TYRE PANEL INNER TOP CARDBOARD <i>ton</i>	1	235.20	<i>✓</i> 235.20
SPARE TYRE RETAINER LOCK <i>could</i>	1	171.80	<i>45</i> 171.80
SPARE TYRE SIDE PANEL RH <i>Rpt</i>	1	261.55	<i>+</i> 261.55
SPARE TYRE SIDE PANEL RH SPONGE <i>could</i>	1	93.20	<i>✓</i> 93.20

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ONG CHOON CHYE
 3 TENG TONG ROAD
 SINGAPORE 423495

Contact : 96806723

ESTIMATE

Repair Code : CLM15035

Date in : 26/01/2019

Vehicle Num. : SJY9605X

Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG

Chassis/Eng# : MR053BK4107061758/1AZE181747

SPARE TYRE SIDE PANEL RH TOP BOARD COVER <i>Neu</i>	1	141.00	141.00
Subtotal before discount			13,586.15
Percentage discount 25%			3,396.54
Sub-total 1			10,189.61
REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS - SET <i>Neu</i>	1	50.00	50.00
REAR BOOTLID OUTER GARNISH CLIPS - SET <i>Neu</i>	1	30.00	20 30.00
REAR BUMPER CLIPS - SET <i>Neu</i>	1	30.00	30.00
REAR BUMPER REVERSE SENSOR - SET <i>2nd</i>	1	250.00	20 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Neu</i>	1	40.00	10 40.00
REAR FENDER INNER SHIELD CLIPS - SET <i>Neu</i>	2	30.00	20 60.00
REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET <i>Neu</i>	1	40.00	30 40.00
REAR TAILLAMP CLIPS L/R - SET <i>Neu</i>	2	30.00	10 60.00
REAR WINDSCREEN SEALANT <i>Neu</i>	1	60.00	60.00
SPARE TYRE PANEL INSULATOR MAT <i>Neu</i>	1	200.00	200.00
Subtotal before discount			820.00
Percentage discount 0%			0.00
Sub-total 2			820.00
Parts-total			11,009.61

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

ONG CHOON CHYE
3 TENG TONG ROAD
SINGAPORE 423495

ESTIMATE

Repair Code : CLM15035

Date in : 26/01/2019

Vehicle Num. : SJY9605X

Model : TOYOTA CAMRY 2.0 AUTO ABS AIRBAG

Chassis/Eng# : MR053BK4107061758/1AZE181747

Contact : 96806723

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

to remove, reinstall windscreen (REAR)

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

50.00

120.00

~~150~~ 180.00

~~80~~ 100.00

~~60~~ 150.00

~~1100~~ 1,400.00

~~80~~ 100.00

~~1400~~ 1,700.00

~~60~~ 100.00

3,900.00

14,909.61

3100

*** This is a computer-generated document which requires no signature.***

page 4

total: 9454.57
L/s 75K
08 Days.

75K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19001857/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6199D	Veh. Inspected	SJY 9605X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000714MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053BK4107061758	Colour	GREY	
Odometer	106491	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	ACHILLES	6 mm	
L/H Front Tyre	215/60 R16	ACHILLES	6 mm	
R/H Rear Tyre	215/60 R16	ACHILLES	6 mm	
L/H Rear Tyre	215/60 R16	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/01/2019	Inspection Date	29/01/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 9605X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	BUCKLED	888.60	888.60
1	REAR BOOTLID "2.0" EMBLEM	NECESSARY	63.10	63.10
1	REAR BOOTLID "LOGO" EMBLEM	NECESSARY	53.20	53.20
1	REAR BOOTLID INNER UPHOLSTERY TRIM	NOT NECESSARY	346.80	-
1	REAR BOOTLID MECHANISM LOCK	NOT NECESSARY	501.70	-
1	REAR BOOTLID OUTER GARNISH	CRACKED	381.80	286.00
2	REAR BOOTLID REFLECTOR BACK RUBBER GASKET L/R @ \$43.70	O/S NECESSARY	87.40	20.00
2	REAR BOOTLID REFLECTOR L/R @ \$289.50	O/S CRACKED	579.00	289.50
1	REAR BOOTLID WEATHER STRIP	CUT	190.40	190.40
1	REAR BUMPER	DISTORTED	581.40	581.40
2	REAR BUMPER BRACKET L/R @ \$131.35	NOT NECESSARY	262.70	-
1	REAR BUMPER REINFORCEMENT	BENT	326.40	326.40
1	REAR BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	182.20	-
1	REAR BUMPER RH REFLECTOR	CRACKED	61.20	61.20
2	REAR BUMPER SIDE RETAINER L/R @ \$131.20	O/S NECESSARY	262.40	131.20
1	REAR END PANEL "INNER"	NOT NECESSARY	791.10	-
1	REAR END PANEL "OUTER"	DISTORTED	581.10	581.10
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	434.20	434.20
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	NOT NECESSARY	231.90	-
2	REAR EXHAUST RUBBER MOUNTING @ \$32.00	NOT NECESSARY	64.00	-
1	REAR EXHAUST SILENCER BOX	BENT	987.70	876.00
1	REAR EXHAUST GASKET	NECESSARY	41.00	41.00
1	REAR RH FENDER	DISTORTED	972.10	972.10
1	REAR RH FENDER INNER SHIELD	TORN	171.80	171.80
1	REAR RH FENDER INNER UPHOLSTERY TRIM	NOT NECESSARY	346.80	-
1	REAR RH KNUCKLE ARM	BENT	580.00	580.00
1	REAR RH SHOCK ABSORBER	BENT	368.00	368.00
1	REAR RH TAILLAMP INNER PANEL	DISTORTED	281.55	281.55
1	REAR RH WHEEL BEARING	NECESSARY	743.00	743.00
2	REAR TAILLAMP L/R @ \$408.30	O/S CRACKED	816.60	408.30

Report Ref No. CS/FCI19001857/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP LOWER BRACKET L/R @\$161.25	O/S DAMAGED	322.50	35.00
1	REAR WINDSCREEN MOULDING	NECESSARY	181.75	181.75
1	SPARE TYRE PANEL INNER TOP CARDBOARD	TORN	235.20	235.20
1	SPARE TYRE RETAINER LOCK	CRACKED	171.80	45.00
1	SPARE TYRE SIDE PANEL RH	TO REPAIR SEE LABOUR	261.55	-
1	SPARE TYRE SIDE PANEL RH SPONGE	CRACKED	93.20	93.20
1	SPARE TYRE SIDE PANEL RH TOP BOARD COVER	NOT NECESSARY	141.00	-
	LESS 25% DISCOUNT		-3,396.54	-2,234.55
			10,189.61	6,703.65
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BOOTLID OUTER GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
2	SET REAR FENDER INNER SHIELD CLIPS @\$30.00 (SN)	NECESSARY	60.00	20.00
1	SET REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	40.00	30.00
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	10.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	200.00	-
			820.00	380.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		50.00	50.00
	TO REMOVE,REINSTALL WINDSCREEN (REAR).		120.00	120.00
	TO REMOVE,CHANGE REAR SUSPENSION PARTS,AXLE CARRIAGE,ABSORBER,LOWER ARM, TOP ARM,TRAILING ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB AND ETC.		180.00	150.00
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	80.00

Report Ref No. CS/FCI19001857/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		150.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,400.00	1,100.00
	TO REMOVE AND CHAGNE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		100.00	80.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF SPARE TYRE SIDE PANEL RH.		1,700.00	1,400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			3,900.00	3,100.00
GRAND TOTAL			14,909.61	10,183.65
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,500.00

Report Ref No. CS/FCI19001857/Asd3n2

MARKET VALUE: \$30,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$21,850.00=NETT VALUE: \$8,150.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.