

22/03/2002

ASS. REC. BY:

REF:

CS/FC119001858/Ksd307

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Sithara

of

FCI

Date/Time:

28/1/19 @ 5:48pm

Estimated Cost:

Bill to:

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 2334K

Insured:

SHC 0082C

at Workshop m/s

MBM Wheel Power

Tel:

93288668

of

160 Sin Ming Drive # 06-03

Policy No:

Claim No:

D19000713MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/01/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

24/1/19 @ 9:30am

Person Contacted:

Danny

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 2334K - X

SHC 82C - CS/SM19001637/Rgd3

DOT: 24012019

01/02/19

@ 14:42 p.m. revised PA to Sithara via email.

20/01/20

@ 10:10 am checked with Danny, vehicle has not sent in for repair.

REF: FCJ

ASSIGNMENT

From: _____ Date: 31/11/19

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLW 2334K

at Workshop mis: MBM Wheel Power

of: 160 Sin Ming Drive #06-03

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$77k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLW 2334K Yr Regn: 02 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda ^A Verel CC 1496

Colour: M. Red A/C Insured / Std / NI / NA

Sp. Reading: 13831 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI 1231667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 8 mm Rear R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 24/11/19 D.O.I. 31/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 JAN 2020

Date/Time, File Pass to? 20/11/20

1) Type

Date/Time, File Return to?

Preli. Report

Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:	170+15
Transportation:	90
Photos:	12
Other:	
TOTAL:	247

Report Format:

Lump Sum / I.B.I: (\$)

MOTOR SURVEY ASSIGNMENT

Date	28-01-2019	Our Ref No. D19000713MFSH
Accident Date	24-01-2019	Claim Type. Third Party
Insured Vehicle	SHC0082C	Third Party Vehicle. SLW2334K
Survey Location	160 SIN MING DRIVE #06-03 SIN MING AUTOCITY	
Contact Person.	DANNY ONG	
Contact No.	62628888/ 93288668	Fax No. 62509015
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MBM WHEELPOWER PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLW2334K		
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Revised Off-Peak Car		
Vehicle Make:	HONDA		
Vehicle Model:	VEZEL 1.5X CVT		
Chassis No.:	RU11231667		
Propellant:	Petrol		
Engine No.:	L15B4431671		
Engine Capacity:	1496 cc		
Maximum Power Output:	96.0 kW (128 bhp)		
Maximum Laden Weight:	1465 kg		
Unladen Weight:	1190 kg		
Year Of Manufacture:	2017		
Original Registration Date:	01 Feb 2018		
Lifespan Expiry Date:	-		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium:	\$36,890.00		
COE Expiry Date:	31 Jan 2028		
Road Tax Expiry Date:	31 Jan 2020		
PARF Eligibility Expiry Date:	31 Jan 2028		
Inspection Due Date:	31 Jan 2021		
Intended Transfer Date:	28 Jan 2019		
CO2 Emission:	117.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$10,000.00		
CO Emission:	0.076000 (g/km)		
HC Emission:	0.014000 (g/km)		
NOx Emission:	0.003000 (g/km)		
PM Emission:	2.900000 (mg/km)		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 1 February 2019 2:42 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19000713MFSH/1
Attachments: SLW 2334K - Preli Advise -.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SLW 2334K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 29 January 2019 9:31 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000713MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 28 January 2019 5:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000713MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000713MFSH

Date: 01 February 2019

Our Ref: CS/FCI19001858/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLW 2334K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/01/2019 at the premises of M/s MBM Wheelpower Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,150.00</u> .
Revised Estimate Amount	: S\$ <u>3,404.00</u> .
"Check" Items Amount	: S\$ <u>1,004.00</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2019 17:51
Date Of Accident	24/01/2019 12:05
Exact Location Of Accident	CANBERRA ROAD (SERVICE ROAD/ BLK 311)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW2334K
Insured/Policyholder	
Name Of Registered Owner	SUBBIAH RAMKUMAR
NRIC No	S7763228Z
Email Address	MOHNISHRAM7708@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81396888
Alternative Phone No	OFFICE-81396888

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01002861
Cover Note Number	

Driver

Name of Driver	SUBBIAH RAMKUMAR
NRIC No	S7763228Z
Date Of Birth	03/04/1977
Occupation	INDOOR
Date Of Driving Pass	18/06/2010
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81396888
Fax Number	
Contact Number	OFFICE-81396888
EMail Address	MOHNISHRAM7708@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was coming back home from my office , after a left turn from Canberra Road to the service road to Blk 311 Canberra road , there is a T junction . I was turning right from the T junction to reach Blk 311 , a taxi turned from my right to his left to go out to the main road Canberra road ... In a fraction of second , the taxi SHC82C banged on my SLW2334K right front door edge during both cars were moving their direction. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC82C
Vehicle Make/Model/Colour	TOYOTA / PRIUS HYBRID / YELLOW
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	WONG SOO KENG
NRIC/Passport Number	S0227113C
Contact Number	96169721
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are permitted to be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
 REPORTING OFFICER
 MOHD FADZLY BIN ISMAIL

Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was coming back home from my office , after a left turn from Canberra Road to the service road to Blk 311 Canberra road , there is a T junction . I was turning right from the T junction to reach Blk 311 , a taxi turned from my right to his left to go out to the main road Canberra road ... In a fraction of second , the taxi SHC82C banged on my SLW2334K right front door edge during both cars were moving their direction. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer




Registered Owner or Driver's Signature

Job Complete Date/Time

25 January 2019 at 10:31 AM

Date/Time:

25 January 2019 at 10:31 AM



mbm wheelpower

MBM WHEELPOWER PTE LTD

Your Ref: SHC82C
Our Ref: SLW2334K

Not Authorized

To: FIRST CAPITAL

Resurvey B4pain

Date: 30/1/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: HONDA VEZEL 1.5X CVT.
Chassis No.: RU11231667
Engine No.: L15B4431671
Year of Make: 2017
Accident Date: 24 January 2019

CC

4 days

Fax

ESTIMATE FOR VEHICLE NO. : SLW2334K

DESCRIPTION	QTY		List Price
FRONT RH FENDER	1	\$	<i>B4</i> 736.00 ✓
FRONT RH FENDER INNER SHIELD	1	\$	<i>7</i> 176.00
FRONT RH FENDER INNER SHIELD CLIPS	10	\$	<i>7</i> 50.00
FRONT RH FENDER WHEEL ARCH MOULDING	1	\$	<i>D17</i> ✓ 195.00
FRONT RH DOOR	1	\$	<i>B4</i> ✓ 1,396.00
FRONT RH DOOR HINGE UPP	1	\$	<i>R</i> X 78.00
FRONT RH DOOR HINGE LOWER	1	\$	<i>B4</i> ✓ 78.00
FRONT RH DOOR INNER TRIM	1	\$	<i>sm</i> X 820.00
FRONT RH DOOR CHECKER	1	\$	<i>7</i> 86.00
FRONT RH WINDOW MOTOR	1	\$	<i>7</i> 507.00
RH SIDE SKIRT	1	\$	<i>B4</i> ✓ 500.00
FRONT RH SHOCK ABOSRBER	1	\$	<i>7</i> 436.00
FRONT RH TIE ROD	1	\$	<i>sm</i> X 305.00
FRONT RH TIE ROD END	1	\$	<i>sm</i> X 292.00
FRONT RH LOWER ARM	1	\$	<i>sm</i> X 460.00
FRONT RH DRIVE SHAFT	1	\$	<i>R</i> X 1,914.00
FRONT RH STABILIZER BAR	1	\$	<i>R</i> X 345.00
FRONT RH STABILIZER LINK	1	\$	<i>sm</i> X 201.00

Total:	\$	8,575.00
LESS 20%	\$	(1,715.00)
Parts Total:	\$	6,860.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SPECIAL NETT

BODY SEALANT	1	\$	<i>nn</i>	80.00)
FRONT RH RIM	1	\$	<i>5n</i>	680.00)

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>500l</i>	1,500.00
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE / FACILITE REPAIR	\$	<i>60l</i>	80.00
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	<i>60l</i>	80.00
TO REMOVE & REPLACE FRONT RH UNDERCARRIAGE	\$	<i>nn</i>	250.00)
TO REMOVE & REPLACE BUMPER SENSORS	\$	<i>nn</i>	40.00)
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>20l</i>	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>440l</i>	1,500.00

Total: \$ 11,150.00

7% GST: \$ 780.50

Grand Total: \$ 11,930.50

Mbm wheelpowerpt
160 SIN MING D

SIN MING AUT
t62628888 f6

Company Registration Number : 200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001858/Ksd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-01-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 82C	Veh. Inspected	SLW 2334K
Policy No.		Coverage (\$)	0.00
Claim No.	D19000713MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	28/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	RU11231667	Colour	METALLIC RED
Odometer	13831	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	8 mm
L/H Front Tyre	215/60 R16	DUNLOP	8 mm
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/01/2019	Inspection Date	31/01/2019
Survey held at	160 SIN MING DRIVE #06-03		
Repairer	MBM WHEELPOWER PTE LTD		
5a. Remarks			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 2334K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RH FENDER	BENT	736.00	736.00
1	FRONT RH FENDER INNER SHIELD	* CHECK	176.00	-
10	FRONT RH FENDER INNER SHIELD CLIPS	* CHECK	50.00	-
1	FRONT RH FENDER WHEEL ARCH MOULDING	DISTORTED	195.00	195.00
1	FRONT RH DOOR	BENT	1,396.00	1,396.00
1	FRONT RH DOOR HINGE UPP	TO REPAIR SEE LABOUR	78.00	-
1	FRONT RH DOOR HINGE LOWER	BENT	78.00	78.00
1	FRONT RH DOOR INNER TRIM	SERVICEABLE	820.00	-
1	FRONT RH DOOR CHECKER	* CHECK	86.00	-
1	FRONT RH WINDOW MOTOR	* CHECK	507.00	-
1	RH SIDE SKIRT	BUCKLED	500.00	500.00
1	FRONT RH SHOCK ABSORBER	* CHECK	436.00	-
1	FRONT RH TIE ROD END	SERVICEABLE	292.00	-
1	FRONT RH LOWER ARM	SERVICEABLE	460.00	-
1	FRONT RH DRIVE SHAFT	TO REPAIR SEE LABOUR	1,914.00	-
1	FRONT RH STABILIZER BAR	TO REPAIR SEE LABOUR	345.00	-
1	FRONT RH STABILIZER LINK	SERVICEABLE	201.00	-
1	FRONT RH TIE ROD	SERVICEABLE	305.00	-
	LESS 20% DISCOUNT		-1,715.00	-581.00
			6,860.00	2,324.00
<u>SPECIAL NETT ITEMS</u>				
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
1	FRONT RH RIM (SN)	SERVICEABLE	680.00	-
			760.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR HINGE UPP, FRONT RH DRIVE SHAFT AND FRONT RH STABILIZER BAR.		1,500.00	500.00
	TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR.		80.00	60.00
	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT.		80.00	60.00
	TO REMOVE & REPLACE FRONT RH UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO RMEOVE & REPLACE BUMPER SENSORS.	NOT NECESSARY	40.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,500.00	440.00
			3,530.00	1,080.00
	GRAND TOTAL		11,150.00	3,404.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,004.00 NETT)			3,404.00

Report Ref No. CS/FCI19001858/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.