

22/03/2019

ASS. REC. BY:

REF:

CS/INC19001864/JH301

Special Instruction:

Surveyor:

Hwee Jie

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time:

29/1/19 @ 9:28am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 3231E

Insured:

SMG 3935S

at Workshop m/s

Auto Insure

Tel:

3157 2626 / 3157 2628

of

G Mariling Lane

Policy No:

Claim No:

MT/1029824-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/1/2019

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9:38am @ 29/1/19

Person Contacted:

Sum

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLK 3231E - X

SMG 3935S - X

REF: INC

Hwee Jie

## ASSIGNMENT

From: Date: 29/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 3231E Yr Regn: 13 Jan 2017

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Attrage C.C. 1193

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 145359 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MMBSTA13AHH003507

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 185/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Road stone

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 26/1/19 D.O.I. 29/1/19 @ 0307 pm

Survey held at Auto Insure

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/3/19 Confirmed P/P \$1993.35/- with delays of repair.  
(Red: 7754.70, 79%)

RECEIVED 25 MAR 2019

Date/Time: File Pass by?

25/3/19 Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / (L.S.): (\$

TP

1993.35

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + PS \$

) Photos

) Other:

) --

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

290

290

## **Nivitha (LKK Auto)**

---

**From:** Annie Koh <annie.koh@income.com.sg>  
**Sent:** Tuesday, 29 January 2019 10:05 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Thio Tse Kiat; Teng Ken Leong  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 29/01/2019

Re-send

Warmest Regards

**Annie Koh**  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



**From:** Annie Koh  
**Sent:** Tuesday, 29 January 2019 9:28 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Thio Tse Kiat; Teng Ken Leong  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 29/01/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1	JARED LIU	MT/1029824-001	SLK3231E	AUTO INSURE PTE LTD	6 MARSILING LANE	Geraldine Lim / 3157 2626		SMG39355	26/1/19
2		Pending advise	PA9468E	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00-16:00	SHB8082E	27/1/19
3	RAJESWARY	MT/1029735-002	PC8885E	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00-16:00	SLP4573K	27/1/19
4	JEFF LIN	MT/1025139-002	SLF8689L	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	15:00-15:30	SLZ2324Z	24/12/18

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

**Annie Koh**  
Senior Admin Assistant, Motor Insurance  
**T +65 6430 7899**  
[www.income.com.sg](http://www.income.com.sg)



---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/01/2019 13:29
Date Of Accident	26/01/2019 17:40
Exact Location Of Accident	BRADDELL RD TURNING INTO LOR 6 TOA PAYOH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLK3231E
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31572626
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995007
Cover Note Number	
Driver	
Name of Driver	PATRICK LIM CHOON MENG
NRIC No	S1805266J
Date Of Birth	12/12/1967
Occupation	OUTDOOR
Date Of Driving Pass	16/06/2012
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85888385
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 166A YUNG KUANG ROAD #04-02
Postcode	611166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NA GENDER: : MALE
Passenger 2	NAME: : NA GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 26/1/2019 AROUND 1740HRS . I WAS TRAVELLING ALONG BRADDELL ROAD . I STOPPED AT THE GIVE WAY LINE BEFORE PROCEED TURNING INTO LOR 6 TOA PAYOH . SUDDENLY VEHICLE B HIT ME FROM THE REAR . THIS ACCIDENT WAS CAPTURED IN MY VIDEO CAMERA .

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG3935S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	M MURALITHARAN
NRIC/Passport Number	S9148758F
Contact Number	87517624
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
(Date & Time):

Driver's Signature  
(if driver is not the policyholder)  
(Date & Time):

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/19 around 17:40hrs. I was travelling along Braddell Road. I stopped at the give way and before proceed turning into Lot 6 Toa Payoh. Suddenly vehicle B hit me from the rear. This accident was captured in my video camera.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Motor Vehicle Accident Report Form



Auto Insure Pte. Ltd.  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SLK3231E (SIEW)**  
Your Ref: **SMG39355**

Date: **28-Jan-19**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

email: [MTCL@income.com.sg](mailto:MTCL@income.com.sg)

1 Maritime Square  
Harbourfront Centre  
#10-01 Singapore 099253

Assessed Vehicle No : **SLK3231E**  
Car Make and Model : **MITSUBISHI ATTRAGE-1.2 CVT (A)**  
Date of Accident : **26-Jan-19**  
Date of Assessment : **28-Jan-19**

We have carried out a physical assessment of SLK3231E at our workshop Auto Insure Pte Ltd sustained damages to the REAR RH portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the REAR RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P  
Adjusted Amount : \$ **10,400.00**  
Est. Repair Days : 6



**\*In considering that our client's vehicle is fairly new  
We will not agree to any repair of parts and only replacement will be done\***

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: SLK3231E

Your Ref: SMG39355

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP	
<b>PARTS REPLACEMENT - LIST ITEMS</b>					
1	1	BOOT LID		\$ 966.80	X
2	1	BOOT LID EMBLEM C&C		\$ 52.80	X
3	1	BOOT LID EMBLEM ATTRAGE		\$ 67.80	X
4	1	BOOT LID EMBLEM LOGO		\$ 95.00	X
5	1	BOOT LID LOCK		\$ 186.90	X
6	1	BOOT LID WEATHERSTRIP		\$ 179.90	X
7	1	REAR BUMPER		\$ 881.50	X
8	1	REAR BUMPER REFLECTOR RH		\$ 139.00	X
9	1	REAR BUMPER SIDE RETAINER RH		\$ 59.00	X
10	1	REAR END PANEL		\$ 658.00	X
11	1	REAR END PANEL EXTRACTOR VENT COVER		\$ 48.50	X
12	1	REAR END PANEL EXTRACTOR VENT		\$ 42.90	X
13	1	REAR BUZZLE KEYLESS OPERATION		\$ 388.90	X
14	1	REAR END PANEL TOP GARNISH		\$ 428.00	X
15	1	REAR SPARE WHEEL COVER BOARD		\$ 228.80	X
16	1	REAR BOOT FLOOR			
17	1	BOOT SIDE TRIM RH		\$ 463.30	X
18	1	REAR TAIL LAMP RH		\$ 685.90	X
19	1	REAR TAIL LAMP PANEL RH		\$ 329.00	X
20	1	REAR FENDER RH		\$ 858.00	X
21	1	REAR FENDER INNER SHIELD RH		\$ 259.50	X
			SUB TOTAL	\$ 7,019.50	
			LESS 10%	\$ 701.95	
			TOTAL AMOUNT	\$ 6,317.55	

Our Ref: SLK3231E

Your Ref: SMG39355

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP	
1	1	REAR BUMPER CLIPS		\$ 30 60.00	✓
2	1 SET	REVERSE SENSOR		\$ 200 300.00	✓
3	1	REAR FENDER BODY SEALANT RH		\$ 80.00	X
4	1	REAR WINDSCREEN MOULDING		\$ 120.00	X
5	1	REAR WINDSCREEN SEALANT		\$ 100.00	X
6	1	REAR END PANEL SEALANT		\$ 80.00	X
			SUB TOTAL	\$ 740.00	
			TOTAL PARTS COST	\$ 7,057.55	

Our Ref: SLK3231E

Your Ref: SMG39355

S/NO	DESCRIPTION	EST. BY WORKSHOP	
<b>LABOUR &amp; PAINTWORK</b>			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 400 800.00	✓
2	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 30 120.00	✓
3	TO REMOVE & REIX REAR WINDSCREEN	\$ 180.00	X
4	TO REMOVE & REFIX REVERSE SENSOR	\$ 30 120.00	✓
5	TO REMOVE & REFIX UPHOLSTERY GARNISH AND ATTACHMENT PARTS	\$ 40 150.00	✓
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 400 900.00	✓

7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$	80.00	X
8	TO RESPRAY UNDERCOATING ON PARTS REPLACED	\$	30 80.00	/
9	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$	60.00	X
10	TO VACUUM, WAXING & CLEAN	\$	100.00	X
11	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$	40 100.00	
TOTAL BEFORE GST		\$	9,747.55	
GST 7%		\$	682.33	
TOTAL (PARTS & LABOUR):		\$	10,429.88	

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 10,400.00 for part by part with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

Total - \$199335

*[Signature]*  
30/1/19

Hwee Jia - LKK

29/1/19

P/P 3 days

*[Signature]*

Photo before paint

91803151

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19001864/Jtd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 28-03-2019



ATTN : JARED LIU

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 3935S	Veh. Inspected	SLK 3231E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1029824-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	29/01/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MMBSTA13AHH003507	Colour	BLACK
Odometer	145359 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R15	ROADSTONE	6 mm
L/H Front Tyre	185/55 R15	ROADSTONE	6 mm
R/H Rear Tyre	185/55 R15	ROADSTONE	6 mm
L/H Rear Tyre	185/55 R15	ROADSTONE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	26/01/2019	Inspect Date / Time	29/01/2019 ( 03:07 PM )
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3231E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOT LID	NOT NECESSARY	966.80	-
1	BOOT LID EMBLEM C&C	NOT NECESSARY	52.80	-
1	BOOT LID EMBLEM ATTRAGE	NOT NECESSARY	67.80	-
1	BOOT LID EMBLEM LOGO	NOT NECESSARY	95.00	-
1	BOOT LID LOCK	NOT NECESSARY	186.90	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	179.90	-
1	REAR BUMPER	DEFORMED	881.50	881.50
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	139.00	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	59.00	-
1	REAR END PANEL	NOT NECESSARY	658.00	-
1	REAR END PANEL EXTRACTOR VENT COVER	NOT NECESSARY	48.50	-
1	REAR END PANEL EXTRACTOR VENT	NOT NECESSARY	42.90	-
1	REAR BUZZLE KEYLESS OPERATION	NOT NECESSARY	388.90	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	428.00	-
1	REAR SPARE WHEEL COVER BOARD	NOT NECESSARY	228.80	-
1	REAR BOOT FLOOR (NPA)	NOT NECESSARY	-	-
1	BOOT SIDE TRIM RH	NOT NECESSARY	463.30	-
1	REAR TAIL LAMP RH	NOT NECESSARY	685.90	-
1	REAR TAIL LAMP PANEL RH	NOT NECESSARY	329.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	858.00	-
1	REAR FENDER INNER SHEILD RH	NOT NECESSARY	259.50	-
	LESS 10% DISCOUNT		-701.95	-88.15
			6,317.55	793.35
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR FENDER BODY SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/INC19001864/Jtd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SAND PAPER, WELDING WIRE ETC) (SN)	NOT NECESSARY	60.00	-
			800.00	230.00
	<b>LABOUR</b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		800.00	400.00
	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUCNTIONS.		120.00	30.00
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIX REVERSE SENSOR.		120.00	30.00
	TO REMOVE & REFIX UPHOLSTERY GARNISH AND ATTACHMENT PARTS.		150.00	40.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		900.00	400.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO RESPRAY UNDERCOATING ON PARTS REPLACED.		80.00	30.00
	TO VACUUM, WAXING & CLEAN.	NOT NECESSARY	100.00	-
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.		100.00	40.00
			2,630.00	970.00
<b>GRAND TOTAL</b>			<b>9,747.55</b>	<b>1,993.35</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,993.35</b>
--	--	--	-----------------

Report Ref No. CS/INC19001864/Jtd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.