

ASS. REC. BY:

REF:

CS / CT119 001867 / Gnd3ⁿ²

Special Instruction:

Surveyor:

GND GARD

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

29/1/19 @ 10:38am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 8838X

Insured:

PC 3522K

at Workshop m/s

Cycle & Carriage

Tel:

8168 0997

of

289 Penden Gardens

9186 5202 - Don

Policy No:

Claim No:

SNM19D200469

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:51am @ 29/1/19

Person Contacted:

Dun Bony

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SLP 8838X - X

PC 3522K - CS / GNE16012435 / Mgh3c2

DCA: 04072016

16/5/19

Final fig \$ 30,189 confirmed by email (Red 15,728, 34/19)


Xbl.

REF: Cfi

7303 F

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop m/s C L C
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: \$92k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / FR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 15 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: SLP 8838X Yr Regn: 16 Jan 2017
 Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mit outlander 2360
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 30/85 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JMYXTGF3W.H800/008
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insider / Jammed / Leaked / Burnt or
 Brake: Insider / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55 R18
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 29-01-19
 Survey held at: W/S 4:30pm
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Tuo Qiang,</u>
	<u>Pls advise repairer repair margin</u>
	<u>RECEIVED 17 MAY 2019</u>
	<u>30/11</u>

Date/Time, File Pass to? ☐ : Prel. Report ☐ : Final Report
 1) _____
 Date/Time, File Return to? 16/5 - typist
 Report Format : merimen
 Lump Sum / I.B.I.: (\$) 30,189/-
 Days Of Repair: 15
 Resurvey No. of Trip: 2
 Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)
 Survey Fee: _____
 Transportation: _____
 Photos: _____
 Others: _____
 TOTAL: 220

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2019		29 Jan 2019 16:12 Edit Adj Rpt				Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	PHUA TIEN KHENG		
Vehicle Reg. No.:	SLP8838X	Date of Loss:	24/01/2019 00:00 - :59
Claim Type:	TP / SNM19D200469	Policy/Cover Note No.:	NA
Vehicle Reg. No. (Insured):	PC3522K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel: 65684501/65684518		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/02/2019]		
Adj Asg. Remarks:	ASSIGN TO LKK VIA EMAIL EARLIER		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

• Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Tuesday, 29 January 2019 10:38 AM
To: assignments
Cc: Don Bong Kiong Hua
Subject: FW: TP CHINA TAIPING CLAIM SLP8838X T YOUR INSURED PC3522K (VEHICLE IN OUR WORKSHOP & PLEASE ARRANGE FOR SURVEY)
Attachments: GIA REPORT & ESTIMATE SLP8838X.pdf; My Movie.mp4
Importance: High

Dear LKK oic

- Without Prejudice -

Please attend to PRI assignment. We will create in Merimen shortly

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909 Direct (65) 6389 6193 www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: Don Bong Kiong Hua [mailto:kionghua.bong@cyclecarriage.com.sg]
Sent: Thursday, 24 January, 2019 2:33 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Catherine Thia <catherine.thia@sg.cntaiping.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>
Subject: RE: TP CHINA TAIPING CLAIM SLP8838X T YOUR INSURED PC3522K (VEHICLE IN OUR WORKSHOP & PLEASE ARRANGE FOR SURVEY)
Importance: High

To Officer In charge,

My client who is driving SLP8838X want to claims against PC3522K which was insured by you.

Attach is the SAS report and repair quotation for your reference.

Please let me know the liability

Don Bong
Claim Division Operations
209 Pandan Gardens
Singapore 609339

Cycle & Carriage Singapore * 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 * F: +65 6565 1240 * H: +65 81680997 * www.cyclecarriage.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 16 May 2019 5:24 PM
To: Cheng Jo Jo; Guo Qiang (LKKAUTO)
Cc: Don Bong Kiong Hua; Loi Ai Ting; Songcuan JR Lauro Araos; Andre Chow En De; SUR
Subject: RE: PENDING FINALISE (3 VEHICLES) - SLP8838X (MIT) / TP CHINA TAIPIING / DOA: 24/01/2019

Dear Jo Jo,

WITHOUT PREJUDICE

Confirmed amount \$30,189 before GST @ 15 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPIING.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>

Sent: Wednesday, 24 April 2019 10:22 AM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>

Cc: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Andre Chow En De

<andre.chow@cyclecarriage.com.sg>

Subject: RE: PENDING FINALISE (3 VEHICLES) - SLP8838X (MIT) / TP CHINA TAIPIING / DOA: 24/01/2019

Hi Guo Qiang,

Attached photo for your reference.

Best Regards,

JoJo Cheng

Customer Service



Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4554 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Cheng Jo Jo
Sent: Monday, 22 April, 2019 7:43 PM
To: Veron Chen (LKKAUTO); GuoQiang@lkkauto.com
Cc: Don Bong Kiong Hua; Loi Ai Ting; Songcuan JR Lauro Araos; Andre Chow En De
Subject: RE: PENDING FINALISE (3 VEHICLES) - SLP8838X (MIT) / TP CHINA TAIPING / DOA: 24/01/2019

Hi Veron,

Attached file for your kind perusal.

Kindly confirm finalise amount at \$ 32,302.23 after GST.

Best Regards,

JoJo Cheng
Customer Service



Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4554 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Andre Chow En De
Sent: Thursday, 18 April, 2019 6:02 PM
To: Veron Chen (LKKAUTO); Don Bong Kiong Hua; Tay Jian Ye; Loi Ai Ting; Songcuan JR Lauro Araos; Coco Lu Ting; Cheng Jo Jo
Subject: RE: PENDING FINALISE (3 VEHICLES)

Hi Veron,

SLP 8838X had a long repair duration due to the extent of damage.

We still need to check through documents, photos in our system before we finalise.

We touch base with your team when ready.

•Regards
Andre

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 18 April, 2019 5:44 PM
To: Don Bong Kiong Hua; Tay Jian Ye; Loi Ai Ting; Songcuan JR Lauro Araos; Coco Lu Ting; Andre Chow En De; Cheng Jo Jo
Subject: RE: PENDING FINALISE (3 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLP 8838X-DOA: 24/1/2019 (CHINA TAIPING TP)
- 2) SKT 1259D-DOA: 6/2/2019 (FCI TP)
- 3) SLS 3974C-DOA: 26/2/2019 (CHINA TAIPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 March 2019 1:34 PM
To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye (jianye.tay@cyclecarriage.com.sg) <jianye.tay@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; 'Songcuan JR Lauro Araos' <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo (jojo.cheng@cyclecarriage.com.sg) <jojo.cheng@cyclecarriage.com.sg>
Subject: PENDING FINALISE (4 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLP 8838X-DOA: 24/1/2019 (CHINA TAIPING TP)

- 2) SMF 8728X-DOA: 2/1/2019 (CHINA TAIPING TP)
- 3) SKT 1259D-DOA: 6/2/2019 (FCI TP)
- 4) SLM 2369M-DOA: 19/1/2019 (CHINA TAPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7303F

Vehicle Details

Vehicle No.:	SLP8838X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.4 CVT 4WD SR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	4B12SD6273
Chassis No.:	JMYXTGF3WHZ001008
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$23,319.00
Original Registration Date:	16 Jan 2017
First Registration Date:	16 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$24,647.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2027
PARF Rebate Amount:	\$18,485.00

Intended COE Rebate Details

COE Expiry Date:	15 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,229.00
COE Rebate Amount:	\$36,796.00
Total Rebate Amount:	\$55,281.00

The information contained herein is correct as at 30 Jan 2019

OK



Certificate of Insurance

account number
03203

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name
Cover
Plan name
NCD applicable
Vehicle registration number
Period of Insurance
Finance loan company

PHUA TIEN KHENG
Comprehensive
Flexi
0%
SLZ9475M SLP8838X
from 07/07/2018 to 15/07/2019 (both dates inclusive)
OCBC BANK LIMITED



Certificate number
Chassis number
Engine number

GA373147 / 1
JMYXTGF3WHZ001008
4812506273

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether stationary, in use or otherwise, is in on or, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	S\$0 700.00
	Windscreen Excess	S\$0 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed Authorised Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

Your Servicing Agent:

Alfa Credit Pte Ltd

1 Commonwealth Lane

#01-24 One Commonwealth

Singapore 149544

Tel: (65) 6241 1228, 6244 4444 Fax: (65) 6449 5813

Email: admin@alfacredit.com.sg

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

1 of 3

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8117303F**

Name: **PHUA TIEN KHENG (PAN ZHANQING)**

Birth Date: **03 Jun 1981**

Issue Date: **08 Feb 2010**

001828717K

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8117303F**

Name: **PHUA TIEN KHENG (PAN ZHANQING)**

潘展庆

Race: **CHINESE**

Date of birth: **03-06-1981** Sex: **M**

Country of birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars < 3500kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 3500kg

PASU DATE: **08 Feb 2010**

NP 425A

Licence No: **S8117303F**

FOR C&C USE ONLY

4845412

NRIC No: **S8117303F**

Date of issue: **28-03-2012**

57 EDGE DALE PLAINS #06-19
SINGAPORE 828881

NRIC No: **S8117303F** Date: **01/12/2017**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 14:09
Date Of Accident	24/01/2019 08:45
Exact Location Of Accident	WEST COAST HIGHWAY EXITING ALEXANDRA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP8838X
Insured/Policyholder	
Name Of Registered Owner	PHUA TIEN KHENG
NRIC No	S8117303F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92395602
Alternative Phone No	OTHERS-92395602

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	OUTLANDER 2.4 CVT AWD (E44)
Exact Purpose for which vehicle was being used at time of accident	DRIVE TO OFFICE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA373147/1
Cover Note Number	

Driver

Name of Driver	PHUA TIEN KHENG
NRIC No	S8117303F
Date Of Birth	03/06/1981
Occupation	INDOOR
Date Of Driving Pass	08/02/2010
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92395602
Fax Number	
Contact Number	OTHERS-92395602
Email Address	NOEMAIL

Address	57 EDGEDALE PLAINS #06-19
Postcode	828681
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC3522K
Vehicle Make/Model/Colour	BLUE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SU XUNHUA
NRIC/Passport Number	
Contact Number	87981859
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLS4061E
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LEONG ZHENG JIE

NRIC/Passport Number

Contact Number

96668042

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 24/1/19
0945

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN

Car C

My car

Bus

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along West Coast Highway exiting to Alexandra road and the traffic is slow so I brake when the car in front stopped. Unfortunately, the bus behind me is unable to stop in time and hit my car from behind. My car got ~~be hit~~ in turn hit the car in front.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 24/1/19

0945

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/201
#06-19	Date In/Mileage / 30185
Singapore 828681	Chassis No JMYXTGF3WHZ001008
Contact No Mobile: 92395602	Engine No 4B12SD6273
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	24/01/2019/ 14:02	QUD	247 / DonBong	35686
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER, CUT/WELD REAR FLOOR PANEL, REAR END PANEL, RH REAR FENDER, LH REAR FENDER, REPAIR BOTH REAR DOOR		✓ 4950		6600.00
E PNT88000	REMOVE AND REPLACE REAR WINDSCREEN GLASS		✓		240.00
M SUNDRY	SUPPLY WINDSCREEN SEALANT		✓		80.00
E PNT88000	LABOUR TRANSFER REAR TAILGATE MECHANISM, DOOR TRIM AND OTHERS ATTACHMENT TO NEW TAILGATE PANEL		✓ 180		200.00
E PNT88000	TO REMOVE REAR TAILGATE CABIN ATTACHMENT TO FACILITATE REPAIR WORK		✓ 180		200.00
E PNT88000	REMOVE AND INSTALL PARKING ASSIST		✓		60.00
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER, FRONT REINFORCEMENT		✓ 550		1650.00
E PNT98000	PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR TAILGATE, REAR BUMPER, RH REAR FENDER, LH REAR FENDER, LH REAR DOOR, RH REAR DOOR, FRONT BUMPER FACE AND AFFECTED PORTION		✓ 2940		4200.00
M SUNDRY	VACCUM SHATTERED GLASS		✓		60.00
M SUNDRY	APPLY BODY SEALANT		✓ 240		380.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM		✓ 80		40.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST		✓		200.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/201
#06-19	Date In/Mileage / 30185
Singapore 828681	Chassis No JMYXTGF3WHZ001008
Contact No Mobile: 92395602	Engine No 4B12SD6273
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	24/01/2019/ 14:02	QUD	247 / DonBong	35686			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								220.00
SUPPLY PARKING ASSIST	NW							50.00
M SUNDRY								100.00
SUPPLY C&C LOGO	MC							480.00
M SUNDRY								550.00
SUPPLY FRONT AND REAR NUMBER PLATE WITH FRAME	scr							300.00
M SUNDRY								50.00
SUPPLY IN CAM RECORDER BLACKVUE DR650	NN							784.00
M SUNDRY								235.00
APPLY ZERTONA PAINT PROTECTION								0.00
M SUNDRY								0.00
SUPPLY REAR REVERSE CAMERA LENS								122.00
M SUNDRY								202.00
SUNDRIES	NN							292.00
M FLOOR,RR	BT	1.00	784.00	00.00				251.00
M PANEL,RR END		1.00	235.00	00.00				14.00
M PANEL,RR END,INR RH	NN	1.00	0.00	00.00				24.00
M PANEL,RR END,INR LH	NN	1.00	0.00	00.00				2.00
M TRIM,RR END		1.00	122.00	00.00				32.00
M BOX,CARGO FLOOR		1.00	202.00	00.00				18.00
M LID,CARGO FLOOR BOX	NN	1.00	292.00	00.00				573.00
M CARRIER,SPARE TIRE		1.00	251.00	00.00				1624.00
M HOLDER,SPARE TIRE CARRIER	NN	1.00	14.00	00.00				211.00
M SPACER,SPARE TIRE CARRIER	NN	1.00	24.00	00.00				924.00
M WASHER,CYLINDER HEAD		2.00	2.00	00.00				489.00
M BOLT,SPARE TIRE CARRIER	NN	1.00	32.00	00.00				
M BRKT,SPARE TIRE CARRIER,LH	NN	1.00	32.00	00.00				
M BRKT,SPARE TIRE CARRIER,RH	NN	1.00	18.00	00.00				
M MUFFLER,EXHAUST MAIN	NN	1.00	573.00	00.00				
M PIPE,EXHAUST,CTR		1.00	1624.00	00.00				
M W/STRIP,TAILGATE OPENING	NN	1.00	211.00	00.00				
M PANEL ASSY,TAILGATE	NN	1.00	924.00	00.00				
M GARNISH,TAILGATE	NN	1.00	489.00	00.00				

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/201
#06-19	Date In/Mileage / 30185
Singapore 828681	Chassis No JMYXTGF3WHZ001008
Contact No Mobile: 92395602	Engine No 4B12SD6273
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	24/01/2019/ 14:02	QUD	247 / DonBong	35686
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M DAM, TAILGATE, UPR	✓	1.00	12.00	00.00	12.00
M DAM, TAILGATE SIDE	✓	2.00	27.00	00.00	54.00
M GLASS, TAILGATE WINDOW	✓	1.00	743.00	00.00	743.00
P STOPPER, WINDSHIELD GLASS	✓	2.00	3.00	00.00	6.00
M DAM, TAILGATE, LWR	✓	1.00	41.00	00.00	41.00
M Δ SENSOR, TAILGATE LOCK, LH	✓	1.00	422.00	00.00	422.00
M Δ SENSOR, TAILGATE LOCK, RH	✓	1.00	422.00	00.00	422.00
M LATCH, TAILGATE	✓	1.00	470.00	00.00	470.00
M STRIKER, TAILGATE LATCH	✓	1.00	19.00	00.00	19.00
M DAMPER, TAILGATE, LWR	✓	2.00	9.00	00.00	18.00
M MOTOR, RR WINDOW WIPER	✓	1.00	500.00	00.00	500.00
M BRACKET, RR WINDOW WIPER	✓	1.00	24.00	00.00	24.00
M ARM ASSY, RR WINDOW WIPER	✓	1.00	64.00	00.00	64.00
M BLADE ASSY, RR WINDOW WIPER	✓	1.00	32.00	00.00	32.00
M MARK, OUTLANDER	✓	1.00	94.00	00.00	94.00
M TRIM ASSY, QTR, LWR RH	✓	1.00	383.00	00.00	383.00
M TRIM ASSY, QTR, LWR LH	✓	1.00	457.00	00.00	457.00
M BUZZER, KEYLESS OPERATION, RR	✓	1.00	90.00	00.00	90.00
M Δ ANT, KEYLESS OPERATION, RR	✓	1.00	84.00	00.00	84.00
M HARNESS, RR BUMPER	✓	1.00	81.00	00.00	81.00
M REINFORCEMENT, RR BUMPER, RH	✓	1.00	78.00	00.00	78.00
M REINFORCEMENT, RR BUMPER, LH	✓	1.00	78.00	00.00	78.00
M BRKT, R/BMPR FACE SIDE, LH	✓	1.00	12.00	00.00	12.00
M FACE, RR BUMPER	✓	1.00	873.00	00.00	873.00
M EXTENSION, RR BUMPER	✓	1.00	230.00	00.00	230.00
M LAMP ASSY, COMB, RR LH	✓	1.00	594.00	00.00	594.00
M LAMP ASSY, COMB, RR RH	✓	1.00	594.00	00.00	594.00
M REFLECTOR, TAIL LAMP, LH	✓	1.00	99.00	00.00	99.00
M REFLECTOR, TAIL LAMP, RH	✓	1.00	94.00	00.00	94.00
M LAMP ASSY, TAIL, LH	✓	1.00	501.00	00.00	501.00
M LAMP ASSY, TAIL, RH	✓	1.00	501.00	00.00	501.00
M LAMP ASSY, LICENSE PLATE	✓	2.00	34.00	00.00	68.00
M PANEL, QTR, OTR LH	✓	1.00	1279.00	00.00	1279.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : HR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/201
#06-19	Date In/Mileage / 30185
Singapore 828681	Chassis No JMYXTGF3WHZ001008
Contact No Mobile: 92395602	Engine No 4B12SD6273
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	24/01/2019/ 14:02	QUD	247 / DonBong	35686
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M PANEL,QTR,OTR RH	✓ Bmc	1.00	1114.00	00.00	1114.00
M EXTENSION,QTR PANEL,OTR LH	✓	1.00	273.00	00.00	273.00
M EXTENSION,QTR PANEL,OTR RH	✓	1.00	273.00	00.00	273.00
M EXTN,QTR PANEL,RR LWR LH	✓	1.00	77.00	00.00	77.00
M EXTN,QTR PANEL,RR LWR RH	✓	1.00	77.00	00.00	77.00
M REINF,GATE PILLAR,LH	✓	1.00	248.00	00.00	248.00
M REINF,GATE PILLAR,RH	✓	1.00	248.00	00.00	248.00
M GLASS,QTR WINDOW,LH	✓	1.00	706.00	00.00	706.00
M GLASS,QTR WINDOW,RH	✓	1.00	810.00	00.00	810.00
M DECAL,MIVEC	✓	1.00	39.00	00.00	39.00
M MOULDING,RR BUMPER,LH	✓	1.00	105.00	00.00	105.00
M MOULDING,RR BUMPER,RH	✓	1.00	105.00	00.00	105.00
M MOULDING,RR WHEEL ARCH,LH	✓	1.00	197.00	00.00	197.00
M MOULDING,RR WHEEL ARCH,RH	✓	1.00	197.00	00.00	197.00
M BRACKET,FR BUMPER SIDE,LH	✓	1.00	18.00	00.00	18.00
M BRACKET,FR BUMPER SIDE,RH	✓	1.00	18.00	00.00	18.00
M FACE,FR BUMPER	✓	1.00	810.00	00.00	810.00
M EXTENSION,FR BUMPER	✓	1.00	421.00	00.00	421.00
M COVER,FR FOG LAMP	✓	1.00	20.00	00.00	20.00
M GARNISH,FR BUMPER,LH	✓	1.00	78.00	00.00	78.00
M GARNISH,FR BUMPER,RH	✓	1.00	78.00	00.00	78.00
M COVER,FR BUMPER	✓	1.00	277.00	00.00	277.00
M GARNISH,FR BUMPER SIDE	✓	1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE	✓	1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE	✓	1.00	218.00	00.00	218.00
M GARNISH,FR BUMPER SIDE	✓	1.00	218.00	00.00	218.00
M GARNISH,FR BUMPER SIDE	✓	1.00	110.00	00.00	110.00
M GARNISH,FR BUMPER SIDE	✓	1.00	110.00	00.00	110.00
M REINFORCEMENT,FR BUMPER	✓	1.00	549.00	00.00	549.00
M REINF,FR BUMPER SIDE,RH	✓	1.00	68.00	00.00	68.00
M REINFORCEMENT,FR BMRP SIDE	✓	1.00	21.00	00.00	21.00
M REINF,FR BUMPER SIDE,LH	✓	1.00	59.00	00.00	59.00
M HEADLAMP ASSY,LH	✓	1.00	2104.00	00.00	2104.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/201
#06-19	Date In/Mileage / 30185
Singapore 828681	Chassis No JMYXTGF3WHZ001008
Contact No Mobile: 92395602	Engine No 4B12SD6273
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	24/01/2019/ 14:02	QUD	247 / DonBong	35686

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HEADLAMP ASSY, RH	1.00	2104.00	00.00	2104.00
M TRIM, TAILGATE, UPR RH	1.00	72.00	00.00	72.00
M TRIM, TAILGATE, UPR	1.00	93.00	00.00	93.00
M TRIM, TAILGATE, UPR LH	1.00	72.00	00.00	72.00
M TRIM, TAILGATE	1.00	286.00	00.00	286.00

Estimate

SURVEYOR NAME: Guo Qiang - 8288 0282SURVEYOR SIGNATURE: [Signature]DATE: 29/1/19REMARKS: Guo Qiang @ lkk auto. com
before paint photos.15 Days.

45,917

Confirm & accepted by

- LKK Auto Consultants hence notify the Repairer of the following:
 - To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	42,877.00
7% GST on	42877.00	3001.39
Total Payable		45,878.39

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Guo Qiang-LKK
Company : China Taiping
DOA : 24/01/2019
CSE : Don
Date of Survey : 29/01/2019

VEHICLE NO : SLP8838X
MODEL : MIT/ OUTLANDER 2.4 CVT AWD
WIP : 35686

Material	:	\$	18,769.00
Labour	:	\$	11,420.00
Sub-Total	:	\$	30,189.00
Less Excess	:	\$	-
Total	:	\$	30,189.00
GST 7%	:	\$	2,113.23
Grand Total	:	\$	32,302.23
Finalise By/Date	:	JoJo dtd	22/04/2019

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 15 WORKING DAYS + 6 Days (3) Weekends
+ 2 Days (1) Public Holiday
TOTAL DAYS REPAIR TOOK = 23

☒ TP Claim China Taiping - PC3522K

☒ Claim GIA / LTA fee \$ 2.00

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Phua Tien Kheng	Cust No/Name	/Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date	SLP8838X / 16/01/2017
#06-19	Date In/Mileage	31/01/2019/ 30185
Singapore 828681	Chassis/Package	JMYXTGF3WHZ00100E
	Engine No	4B12SD6273
Contact No *Mobile: 92395602	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
31/01/	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	22/04/2019/ 17:32	TLD	881 / Jojo Cheng	35686

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER,CUT/WELD, RH REAR FENDER, LH REAR FENDER, CHECK REAR FLOOR PANEL, REAR END PANEL				✓ 4950.00
E PNT88000 REMOVE AND REPLACE REAR WINDSCREEN GLASS				✓ 240.00
M SUNDRY SUPPLY WINDSCREEN SEALANT				✓ 80.00
E PNT88000 LABOUR TRANSFER REAR TAILGATE MECHANISM, DOOR TRIM AND OTHERS ATTACHMENT TO NEW TAILGATE PANEL				✓ 180.00
E PNT88000 REMOVE REAR TAILGATE CABIN ATTACHEMENT TO FACILITATE REPAIR WORK				✓ 60.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				✓ 550.00
E PNT98000 SPRAY PAINT REAR FLOOR PANEL, REAR END PANEL,REAR TAILGATE,REAR BUMPER RH REAR FENDER, LH REAR FENDER,FRONT BUMPER FACE & AFFECTED PORTION				✓ 2940.00
M SUNDRY APPLY BODY SEALANT				✓ 240.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY SUPPLY C&C LOGO				✓ 50.00
M SUNDRY APPLY ZERTONA PAINT PROTECTION				✓ 350.00
M SUNDRY SUNDRIES				✓ 20.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/2017
#06-19	Date In/Mileage 31/01/2019/ 30185
Singapore 828681	Chassis/Package JMYXTGF3WHZ00100E
Contact No *Mobile: 92395602	Engine No 4B12SD6273
31/01/	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	22/04/2019/ 17:32	TLD	881 / Jojo Cheng	35686		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							60.00
VACCU SHATTERED GLASS							60.00
S SPECIALISTJOB							100.00
TO SUPPLY BOTH FRONT & REAR LICENSE PLATE RECTANGUALR & BLACK							100.00
A 30000001							275.00
ADDITIONAL REMOVE AND INSTALL FUEL TANK TO FACILITATE - SUPP (A)							275.00
REPAIR WORK							275.00
A 20000001							275.00
ADDITIONAL REMOVE AND INSTALL ROOF LINING TO FACILITATE REPAIR WORK - SUPP (A)							275.00
S SPECIALISTJOB							220.00
SUPPLY REVERSE SENSOR MIT OUTLANDER / P26							220.00
E PNT98000							420.00
ADDITIONAL PAINT WORK ROOF TOP PANEL AFTER RENEW - SUPP (A)							420.00
REAR FENDER PANEL							420.00
X	PANEL,RR END			1.00	* 243.00	00.00	? 243.00
X	TRIM,RR END			1.00	122.00	00.00	? 122.00
X	BOX,CARGO FLOOR			1.00	202.00	00.00	? 202.00
X	WASHER,CYLINDER HEAD			2.00	2.00	00.00	4.00
X	W/STRIP,TAILGATE OPENING			1.00	211.00	00.00	? 211.00
X	PANEL ASSY,TAILGATE			1.00	* 974.00	00.00	974.00
X	GARNISH,TAILGATE			1.00	489.00	00.00	489.00
X	DAM,TAILGATE,UPR			1.00	12.00	00.00	12.00
X	DAM,TAILGATE SIDE			2.00	27.00	00.00	54.00
X	GLASS,TAILGATE WINDOW			1.00	743.00	00.00	743.00
X	STOPPER,WINDSHIELD GLASS			2.00	3.00	00.00	6.00
X	DAM,TAILGATE,LWR			1.00	41.00	00.00	41.00
X	SENSOR,TAILGATE LOCK,LH			1.00	422.00	00.00	422.00
X	SENSOR,TAILGATE LOCK,RH			1.00	422.00	00.00	422.00
X	ARM ASSY,RR WINDOW WIPER			1.00	64.00	00.00	64.00
X	MARK,OUTLANDER			1.00	94.00	00.00	94.00
X	TRIM ASSY,QTR,LWR RH			1.00	* 398.00	00.00	398.00
X	TRIM ASSY,QTR,LWR LH			1.00	* 398.00	00.00	398.00
X	BUZZER,KEYLESS OPERATIO,RR			1.00	90.00	00.00	? 90.00
* Price Change							

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/2017
#06-19	Date In/Mileage 31/01/2019/ 30185
Singapore 828681	Chassis/Package JMYXTGF3WHZ00100E
Contact No *Mobile: 92395602	Engine No 4812SD6273
31/01/	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	22/04/2019/ 17:32	TLD	881 / Jojo Cheng	35686
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X ANT,KEYLESS OPERATION,RR		1.00	95.00	00.00	95.00
X FACE,RR BUMPER		1.00	873.00	00.00	873.00
X LAMP ASSY,COMB,RR LH		1.00	594.00	00.00	594.00
X LAMP ASSY,COMB,RR RH		1.00	594.00	00.00	594.00
X REFLECTOR,TAIL LAMP,LH		1.00	99.00	00.00	99.00
X REFLECTOR,TAIL LAMP,RH		1.00	94.00	00.00	94.00
X LAMP ASSY,TAIL,LH		1.00	501.00	00.00	501.00
X PANEL,QTR,OTR LH		1.00	1279.00	00.00	1279.00
X PANEL,QTR,OTR RH		1.00	1114.00	00.00	1114.00
X EXTENSION,QTR PANEL,OTR LH		1.00	273.00	00.00	273.00
X EXTENSION,QTR PANEL,OTR RH		1.00	273.00	00.00	273.00
X EXTN,QTR PANEL,RR LWR LH		1.00	73.00	00.00	73.00
X EXTN,QTR PANEL,RR LWR RH		1.00	81.00	00.00	81.00
X REINF,GATE PILLAR,LH		1.00	248.00	00.00	248.00
X REINF,GATE PILLAR,RH		1.00	248.00	00.00	248.00
X GLASS,QTR WINDOW,LH		1.00	706.00	00.00	706.00
X GLASS,QTR WINDOW,RH		1.00	810.00	00.00	810.00
X MOULDING,RR BUMPER,LH		1.00	105.00	00.00	105.00
X MOULDING,RR BUMPER,RH		1.00	105.00	00.00	105.00
X MOULDING,RR WHEEL ARCH,LH		1.00	197.00	00.00	197.00
X MOULDING,RR WHEEL ARCH,RH		1.00	197.00	00.00	197.00
X BRACKET,FR BUMPER SIDE,LH		1.00	18.00	00.00	18.00
X BRACKET,FR BUMPER SIDE,RH		1.00	18.00	00.00	18.00
X FACE,FR BUMPER		1.00	810.00	00.00	810.00
X EXTENSION,FR BUMPER		1.00	421.00	00.00	421.00
X GARNISH,FR BUMPER,LH		1.00	78.00	00.00	78.00
X GARNISH,FR BUMPER,RH		1.00	78.00	00.00	78.00
X COVER,FR BUMPER		1.00	277.00	00.00	277.00
X GARNISH,FR BUMPER SIDE		1.00	48.00	00.00	48.00
X GARNISH,FR BUMPER SIDE		1.00	48.00	00.00	48.00
X GARNISH,FR BUMPER SIDE		1.00	218.00	00.00	218.00
X GARNISH,FR BUMPER SIDE		1.00	218.00	00.00	218.00
X GARNISH,FR BUMPER SIDE		1.00	110.00	00.00	110.00

*Price Change

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Phua Tien Kheng	Cust No/Name /Mr Phua Tien Kheng
57 Edgedale Plains	Reg No/Reg Date SLP8838X / 16/01/2017
#06-19	Date In/Mileage 31/01/2019/ 30185
Singapore 828681	Chassis/Package JMYXTGF3WHZ00100E
Contact No *Mobile: 92395602	Engine No 4B12SD6273
31/01/	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	22/04/2019/ 17:32	TLD	881 / Jojo Cheng	35686

Description of Goods/ Services	Qty	Unit Price	Disc%	Amount
X GARNISH,FR BUMPER SIDE	1.00	110.00	00.00	110.00
X TRIM,TAILGATE	1.00	286.00	00.00	286.00
X HARNESS,RR END	1.00	89.00	00.00	89.00
X TRIM,QTR,UPR RH	1.00	330.00	00.00	330.00
X DUCT,RR VENTILATOR	1.00	44.00	00.00	44.00
X GROMMET,TAIL LAMP	4.00	3.00	00.00	12.00
X GROMMET,TAIL LAMP	4.00	3.00	00.00	12.00
X GROMMET,TAIL LAMP	4.00	3.00	00.00	12.00
X TRIM,QTR,UPR LH	1.00	330.00	00.00	330.00
X SILENCER,RR END PANEL	1.00	9.00	00.00	9.00
X SILENCER,RR END PANEL	1.00	9.00	00.00	9.00
X CAP,TAIL LAMP	2.00	3.00	00.00	6.00
X LAMP ASSY,TAIL,RH	1.00	501.00	00.00	501.00
X EXTENSION,RR BUMPER	1.00	230.00	00.00	230.00
X PILLAR,RR INR RH	1.00	420.00	00.00	420.00
X PILLAR,RR INR LH	1.00	394.00	00.00	394.00
X SILENCER,FLOOR	1.00	14.00	00.00	14.00
X SWITCH,POWER T/GATE CLOSE	1.00	71.00	00.00	71.00

Z TEXT

CHINA TAIPING TP CLAIM PC3522K

DOA: 24/01/2019

SURVEYOR: GUO QIANG 29/01/2019

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	18,769.00	Nett	30,189.00
Labour	10,360.00	7% GST on	2113.23
Standard Menu	0.00		
Specialist Job	320.00	Total Payable	32,302.23
Diagnostics Job	0.00		
Sundry/Others	740.00		
Total(w/o GST)	30,189.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

Car No: SLP 8838X

WIP 35686

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? / Supp	CSA Sign	Photo Taken	Remarks
1	Panel, RR End ✓	① Supp	BA ✓		
2	Extension, QTR PANEL, QTR LLA ✓	① Supp	HA ✓		
3	" " " RH ✓	① Supp	HA ✓		
4	Extension, QTR PANEL, RR LWR ✓	① Supp	HA ✓		
5	" " " RH ✓	① Supp	HA ✓		
6	Extension, RL Pump ✓	① Supp	CM ✓		
7	Antenna, KEYLESS OPERATION ✓	① Supp	at ✓		
8	BOX, CARGO FLOOR ✓	① Supp	CA ✓		
9	WEATHERSTRIP, TAILGATE ✓	① Supp	HA ✓		
10	WEATHERSTRIP, TAILGATE	① Supp			
11	GARNISH, RR END, SOE RH ✓	① Supp	CM ✓	21/00/19 @ (PHO)	
12	HARNESSES, RR END ✓	① Supp	CA ✓		
13	TRIM, RR END ✓	① Supp	DE ✓		
14	TRIM TRIM, QTR, UPR LLA ✓	① Supp	DE ✓		
15	" " " RH ✓	① Supp	DE ✓		
16	DUG, IRR VENTILATOR ✓	① Supp	CA ✓		
17	GARNISH, TAILGATE ✓	① Supp	CA ✓		
18	SENSOR, TAILGATE LOCK ✓	① Supp	HA ✓		
19	" " " RH ✓	① Supp	HA ✓		
20	BROMMET, TAIL LAMP x14 ✓	① Supp	HA ✓		

MUC00036P

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF DAMAGED PARTS (DPS)

PHOTO OF CEILETE BENCH

REMOVE & INSTALL ENGINE

REMOVE & INSTALL DASHBOARD

PHOTO B4 SUSP & U/C REMOVE

TAKEN BY

Model: outlander 2.4

Surveyor: GUO QIANG - LKK

Car No: SLP 8838X WIP 35686

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	GROMMET, TAIL LAMP ✓	? /Supp	✓		MUC00283
2	" " LAMP ✓	? /Supp	✓		MUC000367
3	Buzzer, HELGLESS OPERATOR ✓	? /Supp	✓		✓
4	CLIP, TAIL LAMP ✓	? /Supp	✓		MR 4F2761
5	SILENCER - KK end panel ✓	? /Supp	✓	21/02/19 @ 1410	55 5314A436
6	" " " " ✓	? /Supp	✓		55 5314A438
7	REINFORCING PILLAR ✓	? /Supp	✓		
8	" " " " ✓	? /Supp	✓		
9	PILLAR, INR RA ✓	? /Supp	✓		
10	" " " " ✓	? /Supp	✓		
11	Reinforce but pad ✓	? /Supp	✓		MB 104993
12	Silencer ✓	? /Supp	✓		
13	tailgate Switch ✓	? /Supp	✓		
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

DATE	TAKEN BY
27/2	✓
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CELLITE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO B4 SUSP & U/C REMOVE	

Model: Outlander 2.4

Surveyor: Guo Qianqian - LKK

SUPPLEMENTARY

INSURANCE CO : CHINA TAIPING INSURANCE (S) PTE LTD

REGISTRATION NO : SLP8838X

S/N	Description	Qty	Unit Price	Disc%	Amount
PARTS					
1	HARDNESS, RR END <i>/ CCA</i>	1.00	89.00	0.00	89.00
2	Δ TRIM, QTR, UPR RH <i>/ ee</i>	1.00	330.00	0.00	330.00
3	DUCT, RR VENTILATOR <i>/ CCA</i>	1.00	44.00	0.00	44.00
4	GROMMET, TAIL LAMP <i>/ } mcl.</i>	4.00	3.00	0.00	12.00
5	GROMMET, TAIL LAMP <i>/ }</i>	4.00	3.00	0.00	12.00
6	GROMMET, TAIL LAMP <i>/ }</i>	4.00	3.00	0.00	12.00
7	Δ TRIM, QTR, UPR LH <i>/ ee</i>	1.00	330.00	0.00	330.00
8	SILENCER, RR END PANEL <i>/ } mcl.</i>	1.00	9.00	0.00	9.00
9	SILENCER, RR END PANEL <i>/ }</i>	1.00	9.00	0.00	9.00
10	CAP, TAIL LAMP <i>/ }</i>	2.00	3.00	0.00	6.00
11	EXTENSION, RR BUMPER <i>/ Rept</i>	1.00	230.00	0.00	230.00
12	Δ PILLAR, RR INR RH <i>/ } BT</i>	1.00	420.00	0.00	420.00
13	Δ PILLAR, RR INR LH <i>/ }</i>	1.00	394.00	0.00	394.00
14	SILENCER, FLOOR <i>/ mcl</i>	1.00	14.00	0.00	14.00
15	SWITCH, POWER T/GATE CLOSE <i>/ DM</i>	1.00	71.00	0.00	71.00
LABOUR					
1	REMOVE & INSTALL FUEL TANK	1.00	275.00	0.00	275.00
2	REMOVE & INSTALL ROOF LINING	1.00	275.00	0.00	275.00
3	SPARY PAINT TOP PANEL AFTER RENEW REAR FENDER PANEL	1.00	420.00	0.00	420.00
Total Parts & Labour					2,952.00
7 % GST					206.64
Grand Total					<u>3,158.64</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119001867/GVD3N2

Date: 24/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	NA
Claimant Vehicle No :	SLP8838X	Insured Vehicle No :	PC3522K
Date of Loss:	24/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200469

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8838X	Engine No:	4B12SD6273
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Chassis No:	JMYXTGF3WHZ001008
Reg. Date:	16/01/2017 (Man. Year: 2016)	Odometer:	30185 km
Colour:	Red		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	29,707.00	19,159.00	10,548.00	35.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,210.00	11,030.00	5,180.00	31.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	45,917.00	30,189.00	15,728.00	34.25
+ GST 7.00/7.00% (S\$)	3,214.19	2,113.23	1,100.96	34.25
Nett Amount (S\$)	49,131.19	32,302.23	16,828.96	34.25

INSPECTION

Date of Assignment:	29/01/2019	
Date Inspected:	29/01/2019	Inspected At:
		Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	15.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2019)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8838X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FLOOR,RR	Not Necessary	784.00 FS	*- FS
2	1	*PANEL,RR END	Bent	243.00 FS	*243.00 FS
3	1	*PANEL,RR END ,INR RH (NPA)	Not Necessary	0.00 FS	*- FS
4	1	*PANEL,RR END ,INR LH (NPA)	Not Necessary	0.00 FS	*- FS
5	1	*TRIM,RR END	Deformed	122.00 FS	*122.00 FS
6	1	*BOX,CARGO FLOOR	Cracked	202.00 FS	*202.00 FS
7	1	*LID,CARGO FLOOR BOX	Not Necessary	292.00 FS	*- FS
8	1	*CARRIER,SPARE TIRE	Not Necessary	251.00 FS	*- FS
9	1	*HOLDER,SPARE TIRE CARRIER	Not Necessary	14.00 FS	*- FS
10	1	*SPACER,SPARE TIRE CARRIER	Not Necessary	24.00 FS	*- FS
11	2	*WASHER,CYLINDER HEAD	Necessary	4.00 FS	*4.00 FS
12	1	*BOLT,SPARE TIRE CARRIER	Not Necessary	32.00 FS	*- FS
13	1	*BRKT,SPARE TIRE CARRIER,LH	Not Necessary	32.00 FS	*- FS
14	1	*BRKT,SPARE TIRE CARRIER,RH	Not Necessary	18.00 FS	*- FS
15	1	*MUFFLER,EXHAUST MAIN	Not Necessary	573.00 FS	*- FS
16	1	*PIPE,EXHAUST,CTR	Not Necessary	1,624.00 FS	*- FS
17	1	*W/STRIP,TAILGATE OPENING	Torn	211.00 FS	*211.00 FS
18	1	*PANEL ASSY,TAILGATE	Buckled	974.00 FS	*974.00 FS
19	1	*GARNISH,TAILGATE	Deformed	489.00 FS	*489.00 FS
20	1	*DAM,TAILGATE,UPR	Necessary	12.00 FS	*12.00 FS
21	2	*DAM,TAILGATE SIDE	Necessary	54.00 FS	*54.00 FS
22	1	*GLASS,TAILGATE WINDOW	Smashed	743.00 FS	*743.00 FS
23	2	*STOPPER,WINDSHIELD GLASS	Necessary	6.00 FS	*6.00 FS
24	1	*DAM,TAILGATE,LWR	Necessary	41.00 FS	*41.00 FS
25	1	*SENSOR TAILGATE LOCK,LH	Bent	422.00 FS	*422.00 FS
26	1	*SENSOR TAILGATE LOCK,RH	Bent	422.00 FS	*422.00 FS
27	1	*LATCH,TAILGATE	Not Necessary	470.00 FS	*- FS
28	1	*STRIKER,TAILGATE LATCH	Not Necessary	19.00 FS	*- FS
29	2	*DAMPER,TAILGATE,LWR	Not Necessary	18.00 FS	*- FS
30	1	*MOTOR,RR WINDOW WIPER	Not Necessary	500.00 FS	*- FS
31	1	*BRACKET,RR WINDOW WIPER	Not Necessary	24.00 FS	*- FS
32	1	*ARM ASSY,RR WINDOW WIPER	Cut	64.00 FS	*64.00 FS
33	1	*BLADE ASSY,RR WINDOW WIPER	Not Necessary	32.00 FS	*- FS
34	1	*MARK,OUTLANDER	Necessary	94.00 FS	*94.00 FS
35	1	*TRIM ASSY,QTR,LWR RH	Necessary	398.00 FS	*398.00 FS
36	1	*TRIM ASSY,QTR,LWR LH	Necessary	457.00 FS	*398.00 FS
37	1	*BUZZER,KEYLESS OPERATIO,RR	Damaged	90.00 FS	*90.00 FS
38	1	*ANT,KEYLESS OPERATION,RR	Damaged	95.00 FS	*95.00 FS
39	1	*HARNES,RR BUMPER	Not Necessary	81.00 FS	*- FS
40	1	*REINFORCEMENT,RR BUMPER,RH	Not Necessary	78.00 FS	*- FS
41	1	*REINFORCEMENT,RR BUMPER,LH	Not Necessary	78.00 FS	*- FS
42	1	*BRKT,R/BMPR FACE SIDE,LH	Not Necessary	12.00 FS	*- FS
43	1	*FACE,RR BUMPER	Torn	873.00 FS	*873.00 FS
44	1	*EXTENSION,RR BUMPER	Cracked	230.00 FS	*230.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*LAMP ASSY, COMB, RR LH	Cracked	594.00 FS	*594.00 FS
46	1	*LAMP ASSY, COMB, RR RH	Cracked	594.00 FS	*594.00 FS
47	1	*REFLECTOR, TAIL LAMP, LH	Scratched	99.00 FS	*99.00 FS
48	1	*REFLECTOR, TAIL LAMP, RH	Scratched	94.00 FS	*94.00 FS
49	1	*LAMP ASSY, TAIL, LH	Cracked	501.00 FS	*501.00 FS
50	1	*LAMP ASSY, TAIL, RH	Cracked	501.00 FS	*501.00 FS
51	2	*LAMP ASSY, LICENSE PLATE	Not Necessary	68.00 FS	*- FS
52	1	*PANEL, QTR, OTR LH	Buckled	1,279.00 FS	*1,279.00 FS
53	1	*PANEL, QTR, OTR RH	Buckled	1,114.00 FS	*1,114.00 FS
54	1	*EXTENSION, QTR PANEL, OTR LH	Bent	273.00 FS	*273.00 FS
55	1	*EXTENSION, QTR PANEL, OTR RH	Bent	273.00 FS	*273.00 FS
56	1	*EXTN, QTR PANEL, RR LWR LH	Bent	77.00 FS	*73.00 FS
57	1	*EXTN, QTR PANEL, RR LWR RH	Bent	81.00 FS	*81.00 FS
58	1	*REINF, GATE PILLAR, LH	Bent	248.00 FS	*248.00 FS
59	1	*REINF, GATE PILLAR, RH	Bent	248.00 FS	*248.00 FS
60	1	*GLASS, QTR WINDOW, LH	Necessary	706.00 FS	*706.00 FS
61	1	*GLASS, QTR WINDOW, RH	Necessary	810.00 FS	*810.00 FS
62	1	*DECAL, MIVEC	Not Necessary	39.00 FS	*- FS
63	1	*MOULDING, RR BUMPER, LH	Necessary	105.00 FS	*105.00 FS
64	1	*MOULDING, RR BUMPER, RH	Necessary	105.00 FS	*105.00 FS
65	1	*MOULDING, RR WHEEL ARCH, LH	Necessary	197.00 FS	*197.00 FS
66	1	*MOULDING, RR WHEEL ARCH, RH	Necessary	197.00 FS	*197.00 FS
67	1	*BRACKET, FR BUMPER SIDE LH	Necessary	18.00 FS	*18.00 FS
68	1	*BRACKET, FR BUMPER SIDE RH	Necessary	18.00 FS	*18.00 FS
69	1	*FACE, FR BUMPER	Cracked	810.00 FS	*810.00 FS
70	1	*EXTENSION, FR BUMPER	Cut	421.00 FS	*421.00 FS
71	1	*COVER, FR FOG LAMP	Not Necessary	20.00 FS	*- FS
72	1	*GARNISH, FR BUMPER, LH	Cracked	78.00 FS	*78.00 FS
73	1	*GARNISH, FR BUMPER, RH	Cracked	78.00 FS	*78.00 FS
74	1	*COVER, FR BUMPER	Deformed	277.00 FS	*277.00 FS
75	1	*GARNISH, FR BUMPER SIDE	Missing	48.00 FS	*48.00 FS
76	1	*GARNISH, FR BUMPER SIDE	Missing	48.00 FS	*48.00 FS
77	1	*GARNISH, FR BUMPER SIDE	Cracked	218.00 FS	*218.00 FS
78	1	*GARNISH, FR BUMPER SIDE	Cracked	218.00 FS	*218.00 FS
79	1	*GARNISH, FR BUMPER SIDE	Cracked	110.00 FS	*110.00 FS
80	1	*GARNISH, FR BUMPER SIDE	Cracked	110.00 FS	*110.00 FS
81	1	*REINFORCEMENT, FR BUMPER	Not Necessary	549.00 FS	*- FS
82	1	*REINF, FR BUMPER SIDE, RH	Not Necessary	68.00 FS	*- FS
83	1	*REINFORCEMENT, FR BUMPER SIDE	Not Necessary	21.00 FS	*- FS
84	1	*REINF, FR BUMPER SIDE, LH	Not Necessary	59.00 FS	*- FS
85	1	*HEADLAMP ASSY, LH	Not Necessary	2,104.00 FS	*- FS
86	1	*HEADLAMP ASSY, RH	Not Necessary	2,104.00 FS	*- FS
87	1	*TRIM, TAILGATE UPR RH	Not Necessary	72.00 FS	*- FS
88	1	*TRIM, TAILGATE UPR	Not Necessary	93.00 FS	*- FS
89	1	*TRIM, TAILGATE UPR, LH	Not Necessary	72.00 FS	*- FS
90	1	*TRIM, TAILGATE	Deformed	286.00 FS	*286.00 FS
91	1	*HARDNESS, RR END	Cracked	89.00 FS	*89.00 FS
92	1	*TRIM, QTR, UPR RH	Deformed	330.00 FS	*330.00 FS
93	1	*DUCT, RR VENTILATOR	Cracked	44.00 FS	*44.00 FS
94	4	*GROMMET, TAIL LAMP	Necessary	12.00 FS	*12.00 FS
95	4	*GROMMET, TAIL LAMP	Necessary	12.00 FS	*12.00 FS
96	4	*GROMMET, TAIL LAMP	Necessary	12.00 FS	*12.00 FS
97	1	*TRIM, QTR, UPR LH	Deformed	330.00 FS	*330.00 FS
98	1	*SILENCER, RR END PANEL	Necessary	9.00 FS	*9.00 FS
99	1	*SILENCER, RR END PANEL	Necessary	9.00 FS	*9.00 FS
100	2	*CAP, TAIL LAMP	Necessary	6.00 FS	*6.00 FS
101	1	*EXTENSION, RR BUMPER	Repeated	230.00 FS	*- FS
102	1	*PILLAR, RR INR RH	Bent	420.00 FS	*420.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
103	1		*PILLAR,RR INR LH	Bent	394.00 FS	*394.00 FS
104	1		*SILENCER,FLOOR	Necessary	14.00 FS	*14.00 FS
105	1		*SWITCH,POWER T/GATE CLOSE	Damaged	71.00 FS	*71.00 FS
106	1		*PARKING ASSIST	Not Working	220.00 FS	*220.00 FS
107	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
108	2		*FRONT AND REAR NUMBER PLATE WITH FRAME	Scratched	100.00 FS	*100.00 FS
109	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					29,707.00	19,159.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE,REAR BUMPER,CUT/WELD REAR FLOOR PANEL,REAR END PANEL,RH REAR FENDER,LH REAR FENDER,REPAIR BOTH REAR DOOR	New	6,600.00	4,950.00
2	REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	240.00	240.00
3	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
4	LABOUR TRANSFER REAR TAILGATE MECHANISM,DOOR TRIM AND OTHERS ATTACHMENT TO NEW TAILGATE PANEL	New	200.00	180.00
5	TO REMOVE REAR TAILGATE CABIN ATTACHMENT TO FACILITATE REPAIR WORK	New	200.00	180.00
6	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
7	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER,FRONT REINFORCEMENT	New	1,650.00	550.00
8	PAINT WORK SPRAY REAR FLOOR PANEL,REAR END PANEL,REAR TAILGATE,REAR BUMPER,RH REAR FENDER,LH REAR FENDER,LH REAR DOOR,RH REAR DOOR,FRONT BUMPER FACE AND AFFECTED PORTION	New	4,200.00	2,940.00
9	VACCUM SHATTERED GLASS	New	60.00	60.00
10	APPLY BODY SEALANT	New	380.00	240.00
11	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	40.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
13	SUPPLY IN CAM RECORDER BLACKVUE DR650	New	480.00	0.00
14	APPLY ZERTONA PAINT PROTECTION	New	550.00	350.00
15	SUPPLY REAR REVERSE CAMERA LENS	New	300.00	0.00
16	REMOVE & INSTALL FUEL TANK	New	275.00	275.00
17	REMOVE & INSTALL ROOF LINING	New	275.00	275.00
18	SPRAY PAINT TOP PANEL AFTER RENEW REAR FENDER PANEL	New	420.00	420.00
Gross Labour Cost (S\$)			16,210.00	11,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >