

ASS. REC. BY:

REF:

CS/CT119001873/Gtd307

Special Instruction:

Surveyor:
Munim

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

24/01/2019 2:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 1740S

Insured:

SKC8743R

at Workshop m/s

Kun Fook Sing

Tel:

of

61 Defu Lane 12

Policy No:

DMPCSN30445813077

Claim No:

SNM19D200451C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/01/2019

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

24/01/2019 2:27pm

Person Contacted:

Alice

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJT 1740S - NA / MSG14002752 / d2	DA: 72632014
	SKC 8743R - CC3 / CAL14015653 / Hlypg 2	DA: 13082014
	Part by Part confirm - \$3,158. (Red, 811.20, 20%)	

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 29 January, 2019 2:23 PM
To: mttan
Cc: Admin A; assignments
Subject: CTP REF NO. SNM19D200451C02 KF REF NO. SJT1740S - ACCIDENT INVOLVING SKC8743R AND SJT1740S ON 24 JANUARY 2019
Attachments: 20190129142154.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and your email below.

You have SELECTED, LKK from our list of surveyors.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with Kan Fook Sing Motor.

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 15:27
Date Of Accident	24/01/2019 07:45
Exact Location Of Accident	X-JUNCTION OF MARINA VIEW & COMMERCE ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT1740S
Insured/Policyholder	
Name Of Registered Owner	WONG KEEN SECK KENNETH
NRIC No	S1838191E
Email Address	KPPJW@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96256877
Alternative Phone No	OTHERS-96256877
Vehicle Particulars	
Manufacturer	SUBARU
Model	OUTBACK 2.5I AWD CVT 5DR ABS AIRBAGS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00010450
Cover Note Number	28/09/2018 TO 27/09/2019
Driver	
Name of Driver	CHEW PING PING EILEEN
NRIC No	S7035416J
Date Of Birth	15/10/1970
Occupation	INDOOR
Date Of Driving Pass	07/05/1994
Driving Experience	24 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98391655
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address APT BLK 475C UPPER SERANGOON CRES #17-549 (S) 533475
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name SERANGOON NEIGHBOURHOOD POLICE CENTRE
 Police Station Address **ROAD:** 50 SERANGOON AVE 2 #01-02 , **POSTCODE:** 556129 , **COUNTRY:** SINGAPORE
 Police Station Contact **TEL NO:** 1800-4880999 - **FAX NO:** 64883561
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER WITH ATTACH POLICE REPORT T/20190124/2099

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO FILE SIZE IS TOO LARGE, UNABLE TO UPLOAD
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKC8743R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver CHUA MUI LEE
 NRIC/Passport Number S1643637B
 Contact Number 97520828
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

CHEW PING PING EILEEN

Approximate Age

Injuries Sustain

SHENTON WELLNESS CENTRE -2DAYS MC

Injured person in which vehicle?

SJT1740S

Were seat belts worn?

YES


Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer attach police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Handwritten Signature]

Policyholder's Signature
Date & Time: 24-1-2019
3:47pm

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time: 24/1/19
3.47 p.m



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

CONTINUATION OF REPORT

Driver			
Name	CHEW PING PING EILEEN	ID No.	S7035416J
Related Vehicle	SJT1740S (Car)	Contact No.	98391655
Hospital/Clinic	SHENTON WELLNESS CENTRE	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	24/01/2019	Date Discharge	24/01/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Driver			
Name	CHUA MUI LEE	ID No.	S1643637B
Related Vehicle	NIL	Contact No.	97520828
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 24 January 2019 at about 0747hrs, i was driving my vehicle bearing registration number SJT1740S along Marina View. I then kept to my right and prepare to made a right turn at the junction of Marina View and Commerce Street.

After making sure that there was no oncoming traffic, I proceed with making the right turn when a male pedestrian who suddenly decided to cross the road. I then came to a slow stopped when the vehicle bearing registration number SKC8743R that was travelling behind me collided onto the rear of my vehicle.

The driver of vehicle bearing registration number SKC8743R and I then got out and made checks on our vehicle. We both exchanged contact details before leaving the scene and continued my journey to work. On the same day while I was at work, I felt slight discomfort and decided to see a doctor where I was given 2 days of MC. The doctor says I may get severe whiplash injury a few days later.

I wish to add that I had camera installed inside my vehicle which captured the whole incident. That is all.



Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Staff Sgt SAIFFUDIN BIN ABDUL SATTAR
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No.: 65476204

Signature Of Informant: 
Date/Time: 24/01/2019 15:10
Classification Of Case:

Authentication Stamp
NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8191E
Vehicle Details	
Vehicle No.:	SJT1740S
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	SUBARU
Vehicle Model:	OUTBACK 2.5I AWD CVT 5DR ABS AIRBAGS
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	EJ25D884405
Chassis No.:	JF2BR9K95AG003861
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$30,865.00
Original Registration Date:	28 Sep 2009
First Registration Date:	28 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$30,865.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2019
PARF Rebate Amount:	\$15,432.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,629.00
COE Rebate Amount:	\$1,243.00
Total Rebate Amount:	\$16,675.00

The information contained herein is correct as at 31 Jan 2019

OK

▶ Subaru outback Used Vehicle List (9 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Subaru Legacy Outback 2.5i-S	\$87,500	\$9,900 /yr	31-Aug-2016	2,498 cc	42,000 km	Quality Motor Trading Enterprise	Availabl
Office No. - 64738668 Dominic - 86685757 Sharon - 97882224 Cheapest In Market! 1 Owner, In House Loan And Trade In Available! 5 Star Euro NCAP Rating. Vehicle Dynamics Control System. Rear Vehi Detection. Active Torque Vectoring. Showroom Condition Exactly...							
Subaru Legacy Outback 2.5i	\$30,800	\$9,860 /yr	02-Aug-2010	2,457 cc	133,575 km	Quality Motor Trading Enterprise	Availabl
Loan Available! Mint Condition! Regularly Serviced And Maintained By Previous Owner! Free Engine And Gear Box Warranty Buy At Peace Of Mind! 100% Accident Free Guaranteed! Call Us Now For A Viewing Ap... Office No. - 64738668 Ryan - 90778009 Alann - 86611862							
Subaru Legacy Outback 2.5i-S	\$93,888	\$12,710 /yr	29-Aug-2015	2,498 cc	40,000 km		Availabl
Comes With Warranty And Free Servicing At Motor Image Till Aug 2020 Or 100k Km Mileage. Lowest Depreciation And Highest Paper Value I The Market. Good F/C At 11~12Km/L. Low Mileage 1 Owner Unit, Shel... Office No. - - Ron - 97833464							
Subaru Legacy Outback 2.5i-S	\$80,555	\$10,340 /yr	20-Oct-2015	2,498 cc	70,000 km	Cars Inn Credit Pte Ltd	Availabl
Dont Miss It! CNY Clearance Sale! Sell At Distributor Price! Dealers Are Welcome! New Year Carnival Sale Weekend Offer! 1 Owner Only. Enj 2.28% Loan Interest! 100% Loan Available! Best Deal With The... Office No. - 63654321 Irwin Bin Yaakup - 91824550 John Chua - 98883000							
Subaru Legacy Outback 2.5i-S	\$85,800	\$11,030 /yr	17-Nov-2015	2,498 cc	75,000 km		Availabl
5 Years Warranty With Motor Image 100% Accident Free Full Service Records Absolutely Problem Free Regularly Serviced With Agent With Package (3 More Servicing) Already Paid. SMS Or Whatsapp Only. Office No. - - Jon Ho - 98733877							
Subaru Legacy Outback 2.5i-S	\$83,666	\$10,520 /yr	06-Jan-2016	2,498 cc	45,000 km	Creative Auto	Availabl
Full Loan Amount Stated. High Loan Available! One Owner Unit! Agent Warranty Till 2021! Road Tax Till July 2019, Servicing All Done With Motor Image. Well Maintained Exterior And Interior. Powerful An... Office No. - - Aaron - 98797788 Tony Chia - 97460421 Terence Leow - 90290899							
Subaru Legacy Outback 2.5i-S	\$93,000	\$11,340 /yr	28-Apr-2016	2,498 cc	34,000 km		Availabl
Direct Owner Sale. Five Years Warranty From Agent. Serviced At Agent. Please Call For Viewing. Office No. - - Poon - 90289236							
Subaru Legacy Outback 2.5i-S	\$91,800	\$10,920 /yr	27-May-2016	2,498 cc	26,800 km		Availabl
No Accident. Low Mileage Done At 26,800 Km Over 2 Years 4 Months Period As First Owner. Regularly Serviced At Subaru Leng Kee. Paid Fo The 2019 May Road Tax. Office No. - - Edmund Wong - 83631688							
Subaru Legacy Outback 2.5i-S	\$90,800	\$10,450 /yr	30-Jul-2016	2,498 cc	36,000 km	Highline Automotive	Availabl



簡福星嘍嘍工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on DATE: 24-01-2019 But Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

VEHICLE NO. : SJT1740S
 ACCIDENT DATE : 24-01-2019 07:45
 THIRD PARTY REF. : SKC8743R

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SJT1740S SUBARU OUTBACK 2.5I AWD CVT 5DR

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER / CRA ✓	720.00
2	1	REAR BUMPER REINFORCEMENT X repair. X	232.00
3	1	REAR BUMPER SIDE RETAINER LH - RE ✓	32.00
4	1	REAR BUMPER REFLECTOR LH / CRA ✓	65.00
5	10	REAR BUMPER CLIP@\$3.50 / MC ✓	35.00
6	1	REAR LAMP LOWER BRACKET LH ? + NN	32.00
			<hr/>
			1,116.00
			LESS 20 %
			<hr/>
			223.20
			<hr/>
			TOTAL (A)
			<hr/>
			892.80

SPECIAL NETT ITEMS

1	1	REAR REVERSE SENSOR / DM	200 300.00
			<hr/>
			TOTAL (C)
			<hr/>
			300.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	/ 30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	200 450.00
3	1	SPRAYPAINTING CHARGES	200 450.00
			<hr/>
			TOTAL (D)
			<hr/>
			930.00
			<hr/>
			ESTIMATE TOTAL
			<hr/>
			2,122.80

put by part.
 before paint photos.
 Gino Aiap - 8288082
 30/1/19.
 20 days.

3469.20



簡福星嘜呀工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

DATE : 12-02-2019

VEHICLE NO. : SJT1740S
 ACCIDENT DATE : 24-01-2019 07:45
 THIRD PARTY REF. : SKC8743R

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEICLE SJT1740S SUBARU OUTBACK 2.5I AWD CVT SDR

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	REAR EXHAUST MUFFLER <i>BT</i>	800.00—
1	CENTRE EXHAUST PIPE <i>BT</i>	1308.00—
		2,108.00
	LESS 20 %	421.60
	TOTAL (A)	<u>1,686.40</u>
LABOUR CHARGES		
1	TO REMOVE/REPLACE EXHAUST SYSTEM (REAR AND CENTRE)	✓ 160.00 —
	TOTAL (D)	<u>160.00</u>
	SUPPLEMENTARY TOTAL	<u>1,846.40</u>

簡福星嘍哆工廠
 KAN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582126, 68584361
 FAX: 67481006, 62818428

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

INVOICE NO : TEST
 DATE : 12-02-2019

VEHICLE NO. : SJT1740S
 ACCIDENT DATE : 24-01-2019 07:45
 THIRD PARTY REF. : SKC8743R

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SJT1740S SUBARU OUTBACK 2.5I AWD CVT 5DR

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BUMPER	720.00
1	REAR BUMPER SIDE RETAINER LH	32.00
1	REAR BUMPER REFLECTOR LH	65.00
10	REAR BUMPER CLIP @\$3.50	35.00
1	REAR EXHAUST MUFFLER	800.00
1	CENTRE EXHAUST PIPE	1308.00
		<u>2,960.00</u>
	LESS 20 %	592.00
	TOTAL (A)	<u>2,368.00</u>

CAS / CAS = SBT.

SPECIAL NETT ITEMS

1	REAR REVERSE SENSOR	200.00
	TOTAL (C)	<u>200.00</u>

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	200.00
1	SPRAYPAINTING CHARGES	200.00
1	TO REMOVE/REPLACE EXHAUST SYSTEM (REAR AND CENTRE)	160.00

簡福星嘍哆工廠
KAN FOOK SING MOTOR WORKSHOP
81 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

VEHICLE NO. : SJT1740S
ACCIDENT DATE : 24-01-2019 07:45
THIRD PARTY REF. : SKC8743R

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
	TOTAL (D)	590.00
	TOTAL REPAIR COST :	3,158.00
	G S T % :	221.06
	INVOICE AMOUNT :	3,379.06

2/2



簡福星噴多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

DATE : 24-01-2019

VEHICLE NO. : SJT1740S
 ACCIDENT DATE : 24-01-2019 07:45
 THIRD PARTY REF. : SKC8743R

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SJT1740S SUBARU OUTBACK 2.5I AWD CVT 5DR

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER / CEA	720.00
2	1	REAR BUMPER REINFORCEMENT X repair	232.00
3	1	REAR BUMPER SIDE RETAINER LH - ee	32.00
4	1	REAR BUMPER REFLECTOR LH / CEA	65.00
5	10	REAR BUMPER CLIP @\$3.50 / nec	35.00
6	1	REAR LAMP LOWER BRACKET LH ?	32.00
			1,116.00
LESS 20 %			223.20
TOTAL (A)			892.80

SPECIAL NETT ITEMS

1	1	REAR REVERSE SENSOR / OM	200 300.00
TOTAL (C)			300.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	200 450.00
3	1	SPRAYPAINTING CHARGES	200 450.00
TOTAL (D)			930.00
ESTIMATE TOTAL			2,122.80

part by part.

before part photos.

Uma Airap - 8288 0282

30/1/19.

20 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019		29 Jan 2019 14:41 Edit Adj Rpt	S\$3,158.00 Edit Estimates	S\$3,158.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	WONG KEEN SECK KENNETH								
Vehicle Reg. No.:	SJT1740S	Date of Loss:	24/01/2019 07:00 - :59 [111 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200451	Policy/Cover Note No.:	DMPCSN30445818077						
Vehicle Reg. No. (Insured):	SKC8743R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/02/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJT1740S (SNM19D200451)
[SKC8743R]
TP
WONG KEEN SECK KENNETH
Jan 24 2019 7:00AM
[-]
Kan Fook Sing Motor Workshop

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
2	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
3	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
4	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
5	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
6	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
7	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
8	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
9	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
10	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
11	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
12	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
13	15/04/19 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
14	15/04/19 12:06	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
15	15/04/19 12:06	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
16	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
17	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
18	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
19	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	15/04/19 12:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	15/04/19 12:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	15/04/19 12:08	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/04/19 12:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	15/04/19 12:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	15/04/19 12:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	15/04/19 12:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	15/04/19 12:08	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/19 09:00	Supplementary	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001873/GTD3E2

Date: 25/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30445818077	
Claimant Vehicle No: SJT1740S	Insured Vehicle No: SKC8743R	
Date of Loss: 24/01/2019	Nature of Claim: TP	Claim No: SNM19D200451

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT1740S	Engine No:	EJ25D884405
Make & Model:	SUBARU OUTBACK, 2.5 I-S CVT AWD SR (A)	Chassis No:	JF2BR9K95AG003861
Reg. Date:	28/09/2009 (Man. Year: 2009)	Odometer:	175913 km
Colour:	White		
Engine Capacity:	2457 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,879.20	2,568.00	311.20	10.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	590.00	500.00	45.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,969.20	3,158.00	811.20	20.44
+ GST 7.00/7.00% (S\$)	277.84	221.06	56.78	20.44
Nett Amount (S\$)	4,247.04	3,379.06	867.98	20.44

INSPECTION

Date of Assignment:	29/01/2019		
Date Inspected:	30/01/2019	Inspected At:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12 Singapore 539147
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 25 Apr 2019)
Parts:	N/A SUBARU OUTBACK 2.5 I-S CVT AWD SR (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT1740S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	720.00 FL	*720.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	232.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Deformed	32.00 FL	*32.00 FL
4	1		*REAR BUMPER REFLECTOR LH	Cracked	65.00 FL	*65.00 FL
5	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
6	1		*REAR LAMP LOWER BRACKET LH	Not Necessary	32.00 FL	*- FL
7	1		*REAR REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
8	1		*REAR EXHAUST MUFFLER	Bent	800.00 FL	*800.00 FL
9	1		*CENTRE EXHAUST PIPE	Bent	1,308.00 FL	*1,308.00 FL
Sub Total (S\$)					3,524.00	3,160.00
- List Item Discount on L Items 20.00/20.00% (S\$)					644.80	592.00
Total Parts (S\$)					2,879.20	2,568.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	30.00	30.00
2	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	450.00	200.00
3	SPRAYPAINTING CHARGES	New	450.00	200.00
4	TO REMOVE / REPLACE EXHAUST SYSTEM (REAR AND CENTRE)	New	160.00	160.00
Gross Labour Cost (\$\$)			1,090.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >