



# 簡福星嘜王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 3 ANSON ROAD #16-00 SPRINGLEAF TOWER  
 SINGAPORE 079909

DATE : 12-02-2019

VEHICLE NO. : SJT1740S  
 ACCIDENT DATE : 24-01-2019 07:45  
 THIRD PARTY REF. : SKC8743R

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEICLE SJT1740S SUBARU OUTBACK 2.5I AWD CVT SDR

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR EXHAUST MUFFLER BT	800.00
1	CENTRE EXHAUST PIPE BT	1308.00
		<u>2,108.00</u>
	LESS 20 %	421.60
	TOTAL ( A )	<u>1,686.40</u>
LABOUR CHARGES		
1	TO REMOVE/REPLACE EXHAUST SYSTEM (REAR AND CENTRE)	✓ 160.00
	TOTAL ( D )	<u>160.00</u>
	SUPPLEMENTARY TOTAL	<u>1,846.40</u>