

Cecilia

2143
191

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838


QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT19000516	Page	1
	8 SHENTON WAY	Date	: 30. Jan 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	:		
Registration No	: SLA4830Y	Engine No	: K24W72010879		
Chassis No	: JHMRC1890GC202204	Date Time	: 30. Jan 2019 3:34:24 PM		
Model	: ODYSSEY 2.4 EXV-S 16YM	Surveyor Name	:		
Owner's Name	: NG YONG HWEE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 28/1/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:NG YONG HWEE						
	OWNER INSURER:LIBERTY						
	ACC DATE:28/01/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA						
	TP VEH:SLU4053T						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	100.00	X 1.1	100.00	7.00	107.00
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	100.00	X 1.1	100.00	7.00	107.00
BOJSE	SEALANT FOR TAILGATE	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	250	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL	1	5000.00	1680	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	1350	3000.00	210.00	3210.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00		480.00	33.60	513.60
BML01I	RESET AND CALIBRATE FOR THE SMART ENTRY	1	480.00		480.00	33.60	513.60
	Sum Labor				11500.00	805.00	12,305.00
RS-TMP3040L	VPC 4PCS REAR SENSORS ? X su	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X su	1	45.00		45.00	3.15	48.15

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLA4830Y
Chassis No : JHMRC1890GC202204
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : NG YONG HWEE
Ins Policy No. :
Date of Accident : 28/1/2019

Document No. : SQT19000516 Page 2
Date : 30. Jan 2019
Customer No. : WZA006
Svc Advisor :
Engine No : K24W72010879
Date | Time : 30. Jan 2019 3:34:24 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33500-T6A-003	TAILLIGHT ASSYR. X	1	838.10	25	628.57	44.00	672.57
33550-T6A-003	TAILLIGHT ASSYL X	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR.LID X	1	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL.LID X	1	386.20	25	289.65	20.28	309.93
74890-T6A-J01	GARNISH ASSYRR.LICENSE X	1	230.40	25	172.80	12.10	184.90
68100-T6A-Q10ZZ	TAILGATE COMP M ✓	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE X	1	117.40	25	88.05	6.16	94.21
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN X	1	175.50	25	131.62	9.21	140.83
74900-T6A-003ZB	GARNISH ASSYTAILGATE SPOILER X	1	614.30	25	460.72	32.25	492.97
91513-T6A-003	CLIPTAILGATE SPOILER X	6	2.50	25	11.25	0.79	12.04
75701-T6A-000	EMBLEMH M ✓	1	26.30	25	19.72	1.38	21.10
04715-T6A-900ZZ	FACERR.BUMPER BDC ✓	1	568.30	25	426.22	29.84	456.06
33505-SLJ-013	REFLECTOR ASSYR.RR. X	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. X	1	45.40	25	34.05	2.38	36.43
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH X	1	76.80	25	57.60	4.03	61.63
71507-T6A-003ZB	FACEL.RR.BUMPER GARNISH X	1	76.80	25	57.60	4.03	61.63
71512-T6A-921ZB	SPOILER ASSYR.RR.SIDE X	1	114.10	25	85.57	5.99	91.56
71517-T6A-921ZB	SPOILER ASSYL.RR.SIDE X	1	114.10	25	85.57	5.99	91.56
71593-T6A-003	SPACERR.RR.BUMPER SIDE X	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE M ✓	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER M ✓	7	2.30	25	12.07	0.84	12.91
66100-T6A-300ZZ	PANEL COMPRR. repair	1	460.80	25	345.60	24.19	369.79
04656-T6A-300ZZ	PAN SET3RD SEAT X	1	337.90	25	253.42	17.74	271.16
72841-SH3-315	OILSHEET X	3	40.70	25	91.57	6.41	97.98
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER X	1	206.30	25	154.72	10.83	165.55
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL X	1	10.70	25	8.02	0.56	8.58
84615-T6A-N71ZD	LINING COMPR.RR.SIDE X	1	763.60	25	572.70	40.09	612.79
84640-T6A-003ZA	LINING ASSYRR.PANEL X	1	103.60	25	77.70	5.44	83.14
84643-T6A-Q01ZA	COMP LIDTOOL X	1	61.40	25	46.05	3.22	49.27
84665-T6A-N71ZD	LINING COMPLRR.SIDE X	1	763.60	25	572.70	40.09	612.79

Printed on 30/1/2019 4:02:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLA4830Y
Chassis No : JHMRC1890GC202204
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : NG YONG HWEE
Ins Policy No. :
Date of Accident : 28/1/2019

Document No. : SQT19000516 Page 3
Date : 30. Jan 2019
Customer No. : WZA006
Svc Advisor :
Engine No : K24W72010879
Date | Time : 30. Jan 2019 3:34:24 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>me</i>	2	18.00 ✓	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER <i>me</i>	1	16.90 ✓	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGLR.WINDSHIELD CORNER <i>me</i>	1	16.90 ✓	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>me</i>	4	3.90 ✓	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM <i>me</i>	1	3.70 ✓	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5 <i>me</i>	2	8.50 ✓	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT <i>me</i>	1	4.80 ✓	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>me</i>	2	60.00 ✓		120.00	8.40	128.40
Sum Item					<u>7035.71</u>	<u>492.49</u>	<u>7,528.20</u>

Survey By

Date & Time

Excess

Status

Signature

For
19/02/19 @ 1625

5 days

For

Reserv by part

Total Amount 18,535.71 1,297.49 19,833.20

Total (Inclusive of GST) 19,833.20

Printed on 30/1/2019 4:02:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
 Chassis No: JHMRC1890GC202204
 License No: SLA4830Y
 Mileage: 60631
 Engine No: K24W72010879

Document No: SVO19010970
 Printed By: SHNG
 Order Date: 19. February 2019
 Order Time: 6:41:52 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:NG YONG HWEE OWNER INSURER:LIBERTY ACC DATE:28/01/2019 SURVEYED BY:RASUL DATE:19/02/2019 REF NO: TP INSURER:AXA TP VEH:SLU4053T						
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	✓ 25	803.10	56.22	859.32
75701-T6A-000	EMBLEMH	1	26.30	✓ 25	19.72	1.38	21.10
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	✓ 25	426.22	29.84	456.06
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	✓ 25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	✓ 25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	7	2.30	✓ 25	12.07	0.84	12.91
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	✓ 25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	✓ 25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	✓ 25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	✓ 25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.70	✓ 25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	✓ 25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT	1	4.80	✓ 25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00	✓	120.00	8.40	128.40
	SUM PARTS:				1,492.91	104.50	1,597.41
BOSUN	0701 SUNDRIES	1	30.00	✓	30.00	2.10	32.10
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BOJSE	1610 SEALANT FOR TAILGATE	1	100.00	✓	100.00	7.00	107.00
BML02I	0701 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	✓	180.00	12.60	192.60
BMI02D	0671 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	280.00	✓	280.00	19.60	299.60
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00	✓	560.00	39.20	599.20
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00	✓	560.00	39.20	599.20
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	100.00	✓	100.00	7.00	107.00
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,680.00	✓	1,680.00	117.60	1,797.60

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRC1890GC202204
License No: SLA4830Y
Mileage: 60631
Engine No: K24W72010879

Document No: SVO19010970
Printed By: SHNG
Order Date: 19. February 2019
Order Time: 6:41:52 PM
Service Advisor: NG SIN HAI

BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	1,350.00 ✓	1,350.00	94.50	1,444.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00 ✓	480.00	33.60	513.60
BML01I	RESET AND CALIBRATE FOR THE SMART ENTRY	1	480.00	480.00	33.60	513.60
SUM LABOUR:				5,980.00	418.60	6,398.60
TOTAL SGD				7,472.91	523.10	7,996.01
Total Payable (SGD)						7,996.01

GST Amount is calculated from individual line(s)