

ISS/2010

INS. CASE OWNER:

CC 3 / AIG1900

1881, Kpb3⁵²

LKK:
IDAC:

Surveyor: Fornetun

DOI: 28/1/19

Date / Time: 26/1/19

Registered in Merimen: 26/1/19

Pre-assign / CCU / FTE

SFE 1973M

320030458456



Insured Vehicle No. : _____

Claim No. : _____

Name of Insured : um pury kimw

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :SS

D.O.A : write

Place of Accident : _____

Is driver the owner? (YES) NO)

Nature of Accident : _____

If NO, Driver Name / Age :

OI GIA REPORT YES NO ; TP GIA REPORT YES NO

Driver Tel No. :

(V/L: YES) NO)

Insured Liability : % Final ? Yes / No

SFD 443p



INRS: trans
WSP: cab
Tel :
Liability :
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
19/09/19	Non-Reporting ltr (1st): 12/09/19 Non-Reporting ltr (2nd): 08/10/19 Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: Email 23.09.19 After call ltr to OI:	
	Documentation Check List:	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: WSP

Repair Cost: PIP SS 3,398.44 (2 days) Reduction: 89 % Email Call

FINAL SETTLEMENT Date/Time: 02-10-19 Confirm with WSP YIN Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia :

Repair Cost: WSP SS 3,636.53 OI REAR ENDED TP

Loss of Rental (LOR): SS 211.98 (2 days) x 105.74

Loss of Use (LOU): SS - (5 x days)

Loss of Income (LOI): SS 100.00 (50 x 2 days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search SS 7.49

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 3,958.30 Global Sum SS:

FINAL PAYMENT Date/Time: 02-10-19 Confirm with: WSP YIN Email Call

Payee 1: SS 3,958.30 Name 1: TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.) SS Name 2: _____

Payee 3: (Strike if N.A.) SS Name 3: _____

COPY SENT
10/10/19

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

AAD1901-214

NOT WITHHOLD

Presumy Bepaint

3398-44

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 443P

VF1ABL15AUC283458

RENAULT

LATITUDE

22.1.2019

AIG

3/7/2017

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>nd/w</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>su</i> 113.47
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>su</i> 135.97
5	1 BUMPR RETAINER RH REAR	\$	<i>su</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>su</i> 43.61
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>su</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>su</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>su</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>cm</i> 404.56 ✓
15	1 BOOT REAR	\$	<i>R</i> 2,872.68 X
16	1 TAILLAMP RH	\$	<i>su</i> 552.55 X
17	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
18	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 X

\$	13,256.73
10% \$	1,325.67
\$	11,931.06

Special Nett

1	1SET PARKING AID	\$	<i>su</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>su</i> 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>su</i> 33.00 ✓

Trans-cab Auto Services Pte Ltd

AAD1901-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>pa</i>	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	X
12	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X

TOTAL	\$	445.82
TOTAL PARTS	\$	12,376.88

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1901-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *na* 170.00 *X*

To check steering geometry and computer wheel alignment

\$ *na* 220.00 *X*

TOTAL \$ 7,410.00

Over All Total \$ 31,717.93

20585.87

(PART-BY-PART)

Repair Days

10 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (legal) modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD443P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003332
Chassis No.:	VF1ABL15AUC283458
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jan 2019

OK

View Received Message

This mail is associated with :

*SHD443P (3200304584SG)
[SFE1973M]
TP
TRANS-CAB SERVICES PTE LTD
Jan 22 2019 7:00AM
[LIM PUAY HIAN]
Trans-cab Auto Services Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 11/02/2019 14:27 PM.
To LKK_HQ
CC NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosi
ngh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
Subject Re: No OI GIA Report

Hi,

Be informed that insured has not report accident till date.
Kindly refer to insured contact below for your necessary action.

Thanks & Regards,
Yin Rul, Hor (Viviane)

<-- Original Message -->

From: LKK_HQ
To: AIG_SG; NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com;
Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
Sent On: 11/02/2019 02:00 PM
Subject: Re: No OI GIA Report

Dear Sir / Madam,

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Shu Pei| Admin
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 30/01/2019 10:38 AM
Subject: No OI GIA Report

Hi,

Please be advise that no OI GIA report received.
Please find insured's contact details below for your further actions.

Insured Name: LIM PUAY HIAN

Address: 53 SUNRISE AVENUE #01-17 SINGAPORE 806746

Mobile No.: 93366373

Thanks & Regards,
Yin Rul, Hor (Viviane)

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19001881/Kpb3

12 February, 2019

LIM PUAY HIAN
53 SUNRISE AVENUE #01-17
SINGAPORE 806746

Dear Sirs,

**ACCIDENT INVOLVING SFE 1973M AND SHD 443P ON 22/01/2019 ALONG/
AT BRIGHT HILL ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Hsiao Tong
Claims
Tel : 6742 3197
Fax: 6741 4108
Email : chewht@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Hsiao Tong (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 27 February 2019 5:08 PM
To: Hsiao Tong (LKKAuto)
Cc: jasminetan@transcab.com.sg; claims@transcab.com.sg
Subject: RE: Your ref: AAD1901- 214 (SHD 443P) *Our ref: CC3/AIG19001881/Kpb3 [ACCIDENT INVOLVING SFE 1973M(AIG) & SHD 443P ON 22/01/2019]

WITHOUT PREJUDICE

Dear Hsiao Tong

Our driver no claiming for his injury.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Tuesday, 26 February, 2019 7:26 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your ref: AAD1901- 214 (SHD 443P) *Our ref: CC3/AIG19001881/Kpb3 [ACCIDENT INVOLVING SFE 1973M(AIG) & SHD 443P ON 22/01/2019]

Your ref: **AAD1901- 214 (SHD 443P)**
Our ref: CC3/AIG19001881/Kpb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SFE 1973M(AIG) & SHD 443P ON 22/01/2019

We refer to the above matter.

Kindly advise if there is any injury claim submitted by your client as our insured may consider private settlement.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 26 February 2019 7:26 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; claims@transcab.com.sg
Subject: Your ref: AAD1901- 214 (SHD 443P) *Our ref: CC3/AIG19001881/Kpb3 [ACCIDENT INVOLVING SFE 1973M(AIG) & SHD 443P ON 22/01/2019]

Your ref: **AAD1901- 214 (SHD 443P)**
Our ref: CC3/AIG19001881/Kpb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SFE 1973M(AIG) & SHD 443P ON 22/01/2019

We refer to the above matter.

Kindly advise if there is any injury claim submitted by your client as our insured may consider private settlement.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 8 August 2019 12:59 PM
To: dd173_kongo@yahoo.com.sg
Subject: ACCIDENT INVOLVING SFE 1973M AND SFE 1973M ON 22/01/2019 ALONG BRIGHT HILL ROAD @ 07:30 HOURS

Our Ref: CC3/AIG19001881/Keb3

08 AUG 2019

By Registered Mail

MR LIM PUAY HIAN

Dear Sir/Madam,

ACCIDENT INVOLVING SFE 1973M AND SFE 1973M ON 22/01/2019 ALONG BRIGHT HILL ROAD @ 07:30 HOURS

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **AIG Asia Pacific Insurance Pte Ltd** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of AIG online reporting <https://online.aig.com.sg/AIGSingapore/apps/services/www/AIGSG/desktopbrowser/default/AIGSG.html#accident-report-claim>.

To enable us to look into the matter immediately, please let us hear from you within **fourteen (14)** days from date of this letter (by 22/08/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **AIG Asia Pacific Insurance Pte Ltd** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

ASHER SNG
Case Handler
DID: 6841 6051
Fax: 6741 4108
Email: ashersng@lkkauto.com

c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019 Edit Reg		28 Jan 2019 00:00 Edit Adj Rpt	S\$3,398.44 Edit Estimates	S\$3,398.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	LIM PUAY HIAN, ID: S7300809C		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD443P	Date of Loss:	22/01/2019 07:00 - :59 [18 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3200304584SG	Policy/Cover Note No.:	2100455987-02 (Comprehensive)
Vehicle Reg. No. (Insured):	SFE1973M	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/02/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (11/02/2019): Re: No OI GIA Report AIG_SG (30/01/2019): No OI GIA Report 			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SHD443P (3200304584SG)
[SFE1973M]**

TP

TRANS-CAB SERVICES PTE LTD

Jan 22 2019 7:30AM

[LIM PUAY HIAN]

Trans-cab Auto Services Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/> <input type="button" value="Upload Video"/> <input type="button" value="Upload Audio"/>			View <input type="button" value="View in Browser"/>
Letters/Correspondences			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	<input checked="" type="checkbox"/> Edit
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
2	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
3	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
4	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
5	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
6	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
7	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
8	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
9	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
10	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
11	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
12	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
13	02/03/19 07:53	General View	<input checked="" type="checkbox"/> Load JPG
14	02/03/19 07:53	Odometer Reading	<input checked="" type="checkbox"/> Load JPG
15	02/03/19 07:53	Chassis Number	<input checked="" type="checkbox"/> Load JPG
16	02/10/19 11:27	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
17	02/10/19 11:27	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
18	02/10/19 11:27	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
19	02/10/19 11:27	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	29/01/19 18:50	TP ESTIMATE- MARKED	<input checked="" type="checkbox"/> Load PDF
2	29/01/19 18:50	TP GIA REPORT	<input checked="" type="checkbox"/> Load PDF
3	12/02/19 11:29	Non reporting letter	<input checked="" type="checkbox"/> Load PDF
4	23/09/19 09:49	LETTER TO OI	<input checked="" type="checkbox"/> Load PDF
5	29/10/19 16:27	LOD	<input checked="" type="checkbox"/> Load PDF
6	29/10/19 16:27	AUTHORISATION TO ACT	<input checked="" type="checkbox"/> Load PDF
7	29/10/19 16:27	RELEASE VOUCHER	<input checked="" type="checkbox"/> Load PDF
8	29/10/19 16:27	WORKSHOP INVOICE	<input checked="" type="checkbox"/> Load PDF
9	29/10/19 16:27	RENTAL RECEIPT	<input checked="" type="checkbox"/> Load PDF
10	29/10/19 16:27	RENTAL MILEAGE	<input checked="" type="checkbox"/> Load PDF
11	29/10/19 16:27	LTA SEARCH	<input checked="" type="checkbox"/> Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail Print
1	19/09/19 09:37	OI GIA REPORT	<input checked="" type="checkbox"/> Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SFE1973M (Insd veh)	Model:	RENAULT LATITUDE 2.0 L (A)
	SHD443P (TP veh)		
Date of Accident:	22/01/2019		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:\$		<input checked="" type="checkbox"/>	22,026.88
Final Repair Cost	:\$		<input checked="" type="checkbox"/>	3,636.33
Loss of Use	:\$		<input checked="" type="checkbox"/>	100.00 2.00 days at \$50.00 per day
Rental (if any)	:\$		<input checked="" type="checkbox"/>	211.48 2 days
LTA / GIA Search Fee	:\$		<input checked="" type="checkbox"/>	7.49
Others:	:\$		<input checked="" type="checkbox"/>	
	:\$		<input checked="" type="checkbox"/>	
Final Settlement Sum	:\$		<input checked="" type="checkbox"/>	3,955.30
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)				
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____				
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:\$	3,955.30
2)		:\$	
3)		:\$	
4)		:\$	
5)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

29 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001881/KEB3S2
Date: 29/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100455987-02
Claimant Vehicle No : SHD443P **Insured Vehicle No :** SFE1973M
 Date of Loss: 22/01/2019 Nature of Claim: TP Claim No: 3200304584SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD443P**
 Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C003332
 Reg. Date: 03/07/2017 (Man. Year: 2016) Chassis No: VF1ABL15AUC283458
 Colour: Metallic White/Red Odometer: 154733 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 6 mm Rear Left Side: Goodyear 4 mm
 Front Right Side: Giti 6 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,175.87	2,918.44	10,257.43	77.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,410.00	480.00	6,930.00	93.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,585.87	3,398.44	17,187.43	83.49
+ GST 7.00/7.00% (S\$)	1,441.01	237.89	1,203.12	83.49
Nett Amount (S\$)	22,026.88	3,636.33	18,390.55	83.49
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$105.74/day) (S\$)		211.48		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,955.30		

INSPECTION

Date of Assignment: 28/01/2019
 Date Inspected: 28/01/2019 Inspected At: Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	*404.56 FL
15	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
16	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
17	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
18	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
19	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
21	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
22	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
23	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
24	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
25	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
26	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
27	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
28	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
29	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
31	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,501.54	3,224.38
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,325.67	305.94
Total Parts (\$\$)	13,175.87	2,918.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	220.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
Gross Labour Cost (S\$)			7,410.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >