

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 443P

AAD1901-214

Not Notarised

Resurvey Bkpoint

3398-44

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 443P
 VF1ABL15AUC283458
 RENAULT
 LATITUDE
 22.1.2019
AIG
 3/7/2017

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>nd/w</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>cm</i> 404.56 ✓
15	1 BOOT REAR	\$	<i>R</i> 2,872.68 X
16	1 TAILLAMP RH	\$	<i>Sn</i> 552.55 X
17	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
18	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 X

	\$	13,256.73
10%	\$	1,325.67
	\$	11,931.06

Special Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 ✓

Trans-cab Auto Services Pte Ltd

AAD1901-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>pa</i>	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	X
12	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X

TOTAL	\$	445.82
TOTAL PARTS	\$	12,376.88

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1901-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 443P

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *na* 170.00 *X*

To check steering geometry and computer wheel alignment

\$ *na* 220.00 *X*

TOTAL \$ 7,410.00

Over All Total \$ 31,717.93

(PART-BY-PART)

Repair Days

10 DAYS
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: