

INSURANCE

INS CASE OWNER

CC 4 / III 1900

1885, D

LKK-
IDAC

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

Insured Liability:

TP GIA REPORT: YES / NO

Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting Itr (1st)	
		Non-Reporting Itr (2nd)	
		Non-Reporting Itr (Final)	
		Notification Itr (if non-pickup)	
		Call Itr	
		After call Itr to OI	
		Documentation Check List: Handler	Typist
		Notification Itr (if non-pickup)	
		After call Itr to OI	
		Authorisation To Act	
		Release Voucher	
		Final Repair Bill	
		Car Rental Invoice	
		Towing Invoice	
		LTA / GIA	
		Medical Bill	
		PIR	
		Mandate/Reject Instruction	
		LOD	
		Payment Breakdown Form	
		Post-Repair Photos	
		Others	

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	SS	(days) Reduction:	%	Email	Call
--------------	----	--------------------	---	-------	------

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email	Call
------------------	------------	---------------	-------	------

Final Liability:	%	(Agreed / Agreed) BOLA S/N No.:	
------------------	---	---------------------------------	--

Repair Cost:	SS	(days) x 8117	
--------------	----	----------------	--

Loss of Rental (LOR):	SS	(\$ x 8 days)	
-----------------------	----	----------------	--

Loss of Use (LOU):	SS	(\$ x 8 days)	
--------------------	----	----------------	--

Loss of Income (LOI):	SS	(\$ 40 x 8 days)	
-----------------------	----	-------------------	--

LOR only	LOU only	LOR + LOU	LOR + LO	[Tick only one]
----------	----------	-----------	----------	-----------------

GIA/LTA Search	SS		
----------------	----	--	--

Medical:	SS		
----------	----	--	--

Disbursement:	SS	(e.g. Tow/ Independent)	
---------------	----	-------------------------	--

Legal Cost:	SS		
-------------	----	--	--

Total:	SS	Global Sum SS:	
--------	----	----------------	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email	Call
---------------	------------	---------------	-------	------

Payee 1:	SS	Name 1:	
----------	----	---------	--

Payee 2: (Strike if N.A.)	SS	Name 2:	
---------------------------	----	---------	--

Payee 3: (Strike if N.A.)	SS	Name 3:	
---------------------------	----	---------	--

COPY SENT
26/7/2020

REF:

ASSIGNMENT

COE Dec 2015

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / CO RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop no:

of:

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repair: 6 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC2123E 17 Regn: 2017 Dec

Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 CC 1685

Colour: Blue A/C Insured / Std / NI / NA

Sp Reading: 165922 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDHU730959

C/No: KMHLB41UMHU100087

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Camper

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 26/01/2019 D.O.I: 29/01/2019

Survey held at: Chuppi AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: _____

III SHA 6022Y

15/03/19 Jinnah R 45 12500/- with 6 days of rev

(Real \$ 144365.49544.)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

11

Date/Time, File Return to?

21

Report Format:

Lump Sum / L.B. / 15

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. 15☐ Interview 15☐ Tech. Insp. 15☐ Weekend 15

Survey Fee:

Transportation

1. 3+RS. 5

2. Photo

3. Other

4. ...

TOTAL

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 2123E

DATE : 28.01.2019

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

Indika

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>distorted</i>			\$ 1,052.20	✓
	Front Bumper Bracket (LH) <i>src</i>			\$ 24.60	X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	2 ✓
	Headlamp (LH) <i>mostly broken</i>			\$ 1,388.00	✓
	Front Fender (LH) <i>distorted</i>			\$ 566.30	✓
	Front Fender Apron Panel (LH) <i>distorted</i>			\$ 637.00	2 ✓
	Front Fender Shield (LH) <i>distorted</i>			\$ 174.90	✓
	Air Cleaner Bottom Assy <i>new</i>			\$ 325.00	X
	Front Door (LH) <i>rep photo taken</i>			\$ 2,256.40	X
	Front Door Mirror Assy (LH) <i>broken</i>			\$ 670.00	✓
	Front Windscreen Moulding <i>new</i>			\$ 113.30	2 ✓
	Front Windscreen Pillar Outer (LH) <i>distorted</i>			\$ 1,745.50	X ✓
	Front Wheel Rim (LH) <i>distorted</i>			\$ 325.30	2 ✓
	Front Wheel Hub Cap (LH) <i>fit</i>			\$ 107.10	✓
	Front Wheel Bearing <i>2 Down</i>			\$ 540.50	2 ✓
	Front Shock Absorber (Assy) (LH) <i>2 distorted</i>			\$ 342.20	2 ✓
	Front Shock Absorber Mounting (LH) <i>new</i>			\$ 108.80	X
	Front Drive Shaft (LH) <i>2 Down</i>			\$ 1,030.80	2 ✓
	Rack & Pinion Assy <i>2 Down</i>			\$ 969.60	2 ✓
	STG Tie End <i>2 distorted</i>			\$ 62.60	2 ✓
	Front Suspension Lower Arm (LH) <i>2 distorted</i>			\$ 529.30	2 ✓
	Knuckle Arm (LH) <i>2 distorted</i>			\$ 552.00	2 ✓
	Engine Under Cover <i>new</i>			\$ 334.60	X
	Engine Crossmember <i>2 distorted</i>			\$ 2,094.40	2 ✓
	ABS Sensor, LH <i>new</i>			\$ 234.00	X
	Wiring-Engine <i>mostly broken</i>			\$ 3,326.00	2 ✓
	Electric Power Steering <i>new</i>			\$ 4,880.50	X
			17134.40		
			13707.52		
	SUB TOTAL			\$ 25,298.30	
	LESS 20%			\$ 5,059.66	
	DISCOUNTED TOTAL			\$ 20,238.64	
	Front Door Comfort Logo (LH) <i>new</i>			\$ 75.00	Nett ✓
	Front Windscreen Sealant <i>new</i>			\$ 46.00	Nett ✓
	Front Tyre (LH) <i>src</i>			\$ 216.00	Nett X
			121.00	\$ 337.00	

SHC 2123E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 700/-
	Spray Painting Charge			\$ 1,400.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 44
	Transfer of Door			\$ 120.00 44
	Remove/Refix Undercarriage (FRT)			\$ 200.00 2150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 44
	Remove/Refix Engine			\$ 450.00 44
	Remove/Refix Dashboard			\$ 450.00 44 150/-
	Remove/Refix Fuse Box			\$ 180.00 44 50/-
	Remove/Refix Front Windscreen Glass			\$ 120.00 44 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 44
	Re-set Frt ABS System		2040.00	\$ 200.00
	Re-set Frt Power Window System			\$ 200.00 } 180/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 6,360.00
	ESTIMATE TOTAL			\$ 26,935.64
	29/01/2019 @ 1700hrs		15868.52	
	Not Author		1/512500/-	
	1/512500 6 days.			
				
	LKK Auto			
				
	LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III19001885/Dpb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 29-01-2019	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 6022Y	Veh. Inspected	SHC 2123E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/01/2019	Inspection Date	29/01/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 2123 E

Technician:

Mileage: 165922

Time Printed 29.1.19 5:43 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
4°53'		-3°00' 3°00'
3°51'		-0°19' 5°41'
8°17'		-1°30' 1°30'
15°36'		
20°30'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°59'		-3°00' 3°00'
4°08'		-0°19' 5°41'
-0°02'		-1°30' 1°30'
10°23'		
11°23'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	3°54'		-3°00' 3°00'
Cross Caster	-0°17'		-3°00' 3°00'
Cross SAI	5°13'		-3°00' 3°00'
Total Toe	8°15'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-0°52'		-3°30' 2°30'
-0°09'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°35'		-3°30' 2°30'
-0°09'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°17'		-3°00' 3°00'
Total Toe	-0°18'		-3°00' 3°00'
Thrust Angle	0°00'		-3°00' 3°00'

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 29 January 2019 10:41 AM
To: Chunni Motor; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sherini Pillai; Zuhaidah Samsuri
Subject: RE: Accident involving veh no: SHC 2123E & SHA 6022Y on 26.01.19
Attachments: 28012019165738.pdf

11:07am @ 29/1/19
person @ Lynn
vehicle in
sur @ Bryan

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHC2123E and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: 29 January, 2019 9:25 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Accident involving veh no: SHC 2123E & SHA 6022Y on 26.01.19

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,
Chunni Motor Work P/L

On Tue, Jan 29, 2019 at 9:17 AM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: 28 January, 2019 5:06 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Accident involving veh no: SHC 2123E & SHA 6022Y on 26.01.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Jan 2019 15:48	Clim Veh Model Changed	(205164) HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A).	[A] Lau Shu Pei
2	29 Jan 2019 15:48	Clim Created	Reg No: SHC2123E, Acct Date: 2019/01/26. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Chunni Motor Work Pte Ltd - Amk (HQ)	[A] Lau Shu Pei
3	29 Jan 2019 15:48	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	29 Jan 2019 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/11	[A] Lau Shu Pei
5	29 Jan 2019 15:48	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	29 Jan 2019 15:49	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	29 Jan 2019 15:49	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] Lau Shu Pei
8	12 Feb 2019 19:48	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	12 Feb 2019 19:48	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	20 Feb 2019 17:24	Adj Mandate Request	Cur.Req:0.00:PODS Liability:TBA Remarks: Kindly assist to upload insured video in Merimen for our viewing.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	29 Jan 2019 15:48	Cim Veh Model Changed	(205164) HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A).	[A] Lau Shu Pei
2	29 Jan 2019 15:48	Cim Created	Reg No: SHC2123E, Acct Date: 2019/01/26, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: MS First Capital Insurance Ltd (HQ), Workshop: Chunni Motor Work Pte Ltd - Amk (HQ)	[A] Lau Shu Pei
3	29 Jan 2019 15:48	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	29 Jan 2019 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/11	[A] Lau Shu Pei
5	29 Jan 2019 15:48	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	29 Jan 2019 15:49	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	29 Jan 2019 15:49	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] Lau Shu Pei
8	12 Feb 2019 19:48	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	12 Feb 2019 19:48	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	20 Feb 2019 17:24	Adj Mandate Request	Cur.Req:0.00:PODS Liability:TBA Remarks: Kindly assist to upload insured video in Merimen for our viewing.	[A] CHEW HSIAO TONG
11	21 Feb 2019 09:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/11, Mandate Remarks: We will check for video footage and upload same for your viewing	[I] Lalitha Krishnan
12	21 Feb 2019 09:36	Adj Mandate Set	Approved:0.00:We will check for video footage and upload same for your viewing	[I] Lalitha Krishnan

Date From



Date To

Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2063638	21/02/2019 09:56	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SHC2123E	Zuhaidah Bte Samsuri	xx.xx

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Jan 2019 15:48	Clim Veh Model Changed	(205164) HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A).	[A] Lau Shu Pei
2	29 Jan 2019 15:48	Clim Created	Reg No: SHC2123E, Acct Date: 2019/01/26, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: MS First Capital Insurance Ltd (HQ), Workshop: Chunni Motor Work Pte Ltd - Amk (HQ)	[A] Lau Shu Pei
3	29 Jan 2019 15:48	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	29 Jan 2019 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/11	[A] Lau Shu Pei
5	29 Jan 2019 15:48	Adj Mandate Set	Approved:0.00,Reinspr:Adj decides.	[A] Lau Shu Pei
6	29 Jan 2019 15:49	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	29 Jan 2019 15:49	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] Lau Shu Pei
8	12 Feb 2019 19:48	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	12 Feb 2019 19:48	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	20 Feb 2019 17:24	Adj Mandate Request	Cur.Req:0.00:PODS Liability:TBA Remarks: Kindly assist to upload insured video in Merimen for our viewing.	[A] CHEW HSIAO TONG
11	21 Feb 2019 09:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/11, Mandate Remarks: We will check for video footage and upload same for your viewing	[I] Lalitha Krishnan
12	21 Feb 2019 09:36	Adj Mandate Set	Approved:0.00:We will check for video footage and upload same for your viewing	[I] Lalitha Krishnan
13	09 Mar 2019 12:18	Video Downloaded	Downloaded Video - Accident(OID)	[A] BRYAN TANI
14	10 Mar 2019 21:56	Video Downloaded	Downloaded Video - Accident(OID)	[A] CHEW HSIAO TONG
15	10 Mar 2019 21:58	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Insured driver made a right turn on 2nd lane and collided with third party who was on 1st lane.	[A] CHEW HSIAO TONG
16	11 Mar 2019 11:40	Adj Mandate Set	Approved:0.00.	[I] Zuhaidah Bte Samsuri

Date From  Date To  Audit Type None  Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2063638	21/02/2019 09:56	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SHC2123E	Zuhaidah Bte Samsuri	xx.xx

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019 Edit Reg		29 Jan 2019 00:00 Edit Adj Rpt	S\$12,500.00 Edit Estimates	S\$12,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC2123E	Date of Loss:	26/01/2019 20:00 - :59 [13 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19010794	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA6022Y	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 11/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (02/05/2019): Alert - Adj Mandate Approved (S\$14631.00) - SHC2123E - Claim Handler: Sherini Pi... - III_SG (11/03/2019): Alert - Adj Mandate Approved (S\$0.00) - SHC2123E - Claim Handler: Sherini Pillai - III_SG (21/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SHC2123E - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC2123E (MCT19010794)
[SHA6022Y]
TP
COMFORT TRANSPORTATION PTE LTD
Jan 26 2019 8:00PM
[COMFORT TRANSPORTATION PTE LTD]
Chunni Motor Work Pte Ltd - Amk

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/02/19 09:56	Video - Accident(OID)	 Load MP4	☒
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/19 17:20	General View	 Load JPG	☒
2	20/02/19 17:20	General View	 Load JPG	☒
3	20/02/19 17:21	General View	 Load JPG	☒
4	20/02/19 17:21	General View	 Load JPG	☒
5	20/02/19 17:21	General View	 Load JPG	☒
6	20/02/19 17:21	General View	 Load JPG	☒
7	20/02/19 17:21	General View	 Load JPG	☒
8	20/02/19 17:21	General View	 Load JPG	☒
9	20/02/19 17:21	General View	 Load JPG	☒
10	20/02/19 17:21	General View	 Load JPG	☒
11	20/02/19 17:21	General View	 Load JPG	☒
12	20/02/19 17:21	General View	 Load JPG	☒
13	20/02/19 17:21	General View	 Load JPG	☒
14	20/02/19 17:21	General View	 Load JPG	☒
15	20/02/19 17:21	General View	 Load JPG	☒
16	20/02/19 17:21	General View	 Load JPG	☒
17	20/02/19 17:21	General View	 Load JPG	☒
18	20/02/19 17:21	General View	 Load JPG	☒
19	20/02/19 17:21	General View	 Load JPG	☒
20	20/02/19 17:21	General View	 Load JPG	☒
21	20/02/19 17:21	General View	 Load JPG	☒
22	20/02/19 17:21	General View	 Load JPG	☒
23	20/02/19 17:21	General View	 Load JPG	☒
24	20/02/19 17:21	General View	 Load JPG	☒
25	20/02/19 17:21	General View	 Load JPG	☒
26	20/02/19 17:21	General View	 Load JPG	☒
27	20/02/19 17:21	General View	 Load JPG	☒
28	20/02/19 17:21	General View	 Load JPG	☒
29	20/02/19 17:21	General View	 Load JPG	☒
30	20/02/19 17:21	General View	 Load JPG	☒
31	20/02/19 17:21	General View	 Load JPG	☒
32	20/02/19 17:21	General View	 Load JPG	☒
33	20/02/19 17:21	General View	 Load JPG	☒
34	20/02/19 17:21	General View	 Load JPG	☒
35	20/02/19 17:21	General View	 Load JPG	☒
36	20/02/19 17:21	General View	 Load JPG	☒
37	20/02/19 17:21	General View	 Load JPG	☒
38	20/02/19 17:21	General View	 Load JPG	☒
39	20/02/19 17:21	General View	 Load JPG	☒
40	20/02/19 17:21	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
41	20/02/19 17:21	General View	 Load JPG	☒
42	20/02/19 17:21	General View	 Load JPG	☒
43	20/02/19 17:21	General View	 Load JPG	☒
44	20/02/19 17:21	General View	 Load JPG	☒
45	20/02/19 17:21	General View	 Load JPG	☒
46	20/02/19 17:21	General View	 Load JPG	☒
47	20/02/19 17:21	General View	 Load JPG	☒
48	20/02/19 17:21	General View	 Load JPG	☒
49	20/02/19 17:21	General View	 Load JPG	☒
50	20/02/19 17:21	Chassis Number	 Load JPG	☒
51	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
52	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
53	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
54	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
55	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
56	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
57	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
58	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
59	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
60	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
61	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
62	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
63	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
64	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
65	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
66	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
67	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
68	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
69	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
70	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
71	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
72	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
73	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
74	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
75	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
76	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
77	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
78	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
79	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
80	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
81	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
82	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
83	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
84	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
85	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
86	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
87	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
88	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
89	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
90	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
91	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
92	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
93	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
94	09/03/19 12:38	Reinspection Photo	 Load JPG	☒
95	09/03/19 12:38	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
96	09/03/19 12:38	Reinspection Photo		☒
97	09/03/19 12:38	Reinspection Photo		☒
98	09/03/19 12:38	Reinspection Photo		☒
99	09/03/19 12:38	Reinspection Photo		☒
100	09/03/19 12:38	Reinspection Photo		☒
101	09/03/19 12:38	Reinspection Photo		☒
102	09/03/19 12:38	Reinspection Photo		☒
103	09/03/19 12:38	Reinspection Photo		☒
104	09/03/19 12:38	Reinspection Photo		☒
105	09/03/19 12:38	Reinspection Photo		☒
106	09/03/19 12:38	Reinspection Photo		☒
107	09/03/19 12:38	Reinspection Photo		☒
108	09/03/19 12:38	Reinspection Photo		☒
109	09/03/19 12:38	Reinspection Photo		☒
110	09/03/19 12:38	Reinspection Photo		☒
111	09/03/19 12:38	Reinspection Photo		☒
112	09/03/19 12:38	Reinspection Photo		☒
113	09/03/19 12:38	Reinspection Photo		☒
114	09/03/19 12:38	Reinspection Photo		☒
115	09/03/19 12:38	Reinspection Photo		☒
116	09/03/19 12:38	Reinspection Photo		☒
117	09/03/19 12:38	Reinspection Photo		☒
118	09/03/19 12:38	Reinspection Photo		☒
119	09/03/19 12:38	Reinspection Photo		☒
120	09/03/19 12:38	Reinspection Photo		☒
121	09/03/19 12:38	Reinspection Photo		☒
122	09/03/19 12:38	Reinspection Photo		☒
123	09/03/19 12:38	Reinspection Photo		☒
124	09/03/19 12:38	Reinspection Photo		☒
125	09/03/19 12:38	Reinspection Photo		☒
126	09/03/19 12:38	Reinspection Photo		☒
127	09/03/19 12:38	Reinspection Photo		☒
128	09/03/19 12:38	Reinspection Photo		☒
129	09/03/19 12:38	Reinspection Photo		☒
130	09/03/19 12:38	Reinspection Photo		☒
131	09/03/19 12:39	Finishing Photo		☒
132	09/03/19 12:39	Finishing Photo		☒
133	09/03/19 12:39	Finishing Photo		☒
134	09/03/19 12:39	Finishing Photo		☒
135	09/03/19 12:39	Finishing Photo		☒
136	09/03/19 12:39	Finishing Photo		☒
137	09/03/19 12:39	Finishing Photo		☒
138	09/03/19 12:39	Finishing Photo		☒
139	09/03/19 12:39	Finishing Photo		☒
140	09/03/19 12:39	Finishing Photo		☒
141	09/03/19 12:39	Finishing Photo		☒
142	09/03/19 12:39	Finishing Photo		☒
143	09/03/19 12:39	Finishing Photo		☒
144	09/03/19 12:39	Finishing Photo		☒
145	09/03/19 12:39	Finishing Photo		☒
146	09/03/19 12:39	Finishing Photo		☒
147	09/03/19 12:39	Finishing Photo		☒
148	09/03/19 12:39	Finishing Photo		☒
149	09/03/19 12:39	Finishing Photo		☒
150	09/03/19 12:39	Finishing Photo		☒
151	09/03/19 12:39	Finishing Photo		☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
152	09/03/19 12:39	Finishing Photo		☒
153	09/03/19 12:39	Finishing Photo		☒
154	09/03/19 12:39	Finishing Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/01/19 15:49	EMAIL FROM III DD 29012019		☐
2	29/01/19 15:49	TP EST & GIA REPORT		☐
3	31/01/19 16:46	TP ESTIMATE- MARKED		☐
4	15/04/19 11:00	RENTAL RECEIPT		☐
5	15/04/19 11:00	RENTAL MILEAGE		☐
6	15/04/19 11:00	LOD		☐
7	27/02/20 09:01	WORKSHOP INVOICE		☐
8	27/02/20 09:01	AUTHORISATION TO ACT FORM		☐
9	27/02/20 09:01	DISCHARGE VOUCHER		☐
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	30/01/19 08:39	Singapore Accident Statement		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19001885/DPS3Q2

Date: 27/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SHC2123E Insured Vehicle No: SHA6022Y
 Vehicle No : SHC2123E
 Date of Loss: 26/01/2019 Nature of Claim: TP Claim No: MCT19010794

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC2123E
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: D4FDHU730959
 Reg. Date: 20/12/2017 (Man. Year: 2016) Chassis No: KMHLB41UMHU100087
 Colour: Blue Odometer: 165922 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Campeon 5 mm Rear Left Side: Campeon 5 mm
 Front Right Side: Campeon 5 mm Rear Right Side: Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,575.64	13,828.52	6,747.12	32.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,360.00	2,040.00	4,320.00	67.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,935.64	15,868.52	11,067.12	41.09
Approved Total (Overridden) (S\$)		12,500.00		
(S\$)	26,935.64	12,500.00	14,435.64	53.59
+ GST 7.00/7.00% (S\$)	1,885.49	875.00	1,010.49	53.59
Nett Amount (S\$)	28,821.13	13,375.00	15,446.13	53.59
+ Loss of Use (8.0 x S\$40.00/day) (S\$)		320.00		
+ Car Rental (8.0 x S\$117.00/day) (S\$)		936.00		
Nett Liability (S\$)		14,631.00		

INSPECTION

Date of Assignment: 29/01/2019
 Date Inspected: 29/01/2019 Inspected At: Chunni Motor Work Pte Ltd - Amk (HQ)
 Blk 10 #01-05/06, AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2019)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2123E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Distorted	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET (LH)	Serviceable	24.60 FL	*- FL
3	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
4	1		*HEADLAMP (LH)	Mtg Cracked	1,388.00 FL	*1,388.00 FL
5	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
6	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
7	1		*FRONT FENDER SHIELD (LH)	Deformed	174.90 FL	*174.90 FL
8	1		*AIR CLEANER BOTTOM ASSY	Not Necessary	325.00 FL	*- FL
9	1		*FRONT DOOR (LH)	Repair	2,256.40 FL	*- FL
10	1		*FRONT DOOR MIRROR ASSY (LH)	Broken	670.00 FL	*670.00 FL
11	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
12	1		*FRONT WINDSCREEN PILLAR OUTER (LH)	Dented	1,745.50 FL	*1,745.50 FL
13	1		*FRONT WHEEL RIM (LH)	Distorted	325.30 FL	*325.30 FL
14	1		*FRONT WHEEL HUB CAP (LH)	Bent	107.10 FL	*107.10 FL
15	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
16	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	342.20 FL	*342.20 FL
17	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
18	1		*FRONT DRIVE SHAFT (LH)	Damaged	1,030.80 FL	*1,030.80 FL
19	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
20	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
21	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
22	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
23	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
24	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
25	1		*ABS SENSOR LH	Not Necessary	234.00 FL	*- FL
26	1		*WIRING -ENGINE	Broken	3,326.00 FL	*3,326.00 FL
27	1		*ELECTRIC POWER STEERING	Not Necessary	4,880.50 FL	*- FL
28	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
29	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
30	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,635.30	17,255.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,059.66	3,426.88
Total Parts (\$\$)	20,575.64	13,828.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	TRANSFER OF DOOR	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
10	REMOVE/REFIX ENGINE	New	450.00	0.00
11	REMOVE/REFIX DASHBOARD	New	450.00	150.00
12	REMOVE/REFIX FUSE BOX	New	180.00	50.00
13	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
14	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
15	RE-SET FRT ABS SYSTEM }	New	200.00	180.00
16	RE-SET FRT POWER WINDOW SYSTEM }	New	200.00	0.00
17	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (S\$)			6,360.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >