

REPAIR ESTIMATE*

DATE : 28.01.2019

TEL : 6542 5119

FAX : 6542 6039

India

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover distorted		\$	1,052.20 ✓
	Front Bumper Bracket (LH) s/c		\$	24.60 X
	Headlamp Support Panel Assy broken		\$	907.40 Z ✓
	Headlamp (LH) mostly broken		\$	1,388.00 ✓
	Front Fender (LH) dent		\$	566.30 ✓
	Front Fender Apron Panel (LH) bent dent		\$	637.00 Z ✓
	Front Fender Shield (LH) deformed		\$	174.90 ✓
	Air Cleaner Bottom Assy NH		\$	325.00 X
	Front Door (LH) rep - photo taken		\$	2,256.40 X
	Front Door Mirror Assy (LH) broken		\$	670.00 ✓
	Front Windscreen Moulding H/C		\$	113.30 * ✓
	Front Windscreen Pillar Outer(LH) bent dent		\$	1,745.50 X ✓
	Front Wheel Rim (LH) bent distorted		\$	325.30 Z ✓
	Front Wheel Hub Cap (LH) BT		\$	107.10 ✓
	Front Wheel Bearing bent down		\$	540.50 Z ✓
	Front Shock Absorber (Assy) (LH) bent distorted		\$	342.20 Z ✓
	Front Shock Absorber Mounting (LH) NH		\$	108.80 X
	Front Drive Shaft (LH) bent down		\$	1,030.80 Z ✓
	Rack & Pinion Assy bent down		\$	969.60 Z ✓
	STG Tie End bent distorted		\$	62.60 Z ✓
	Front Suspension Lower Arm (LH) bent distorted		\$	529.30 Z ✓
	Knuckle Arm (LH) bent distorted		\$	552.00 Z ✓
	Engine Under Cover NH		\$	334.60 X
	Engine Crossmember bent distorted		\$	2,094.40 Z ✓
	ABS Sensor, LH NH		\$	234.00 X
	Wiring-Engine H/C working broken		\$	3,326.00 * ✓
	Electric Power Steering NH		\$	4,880.50 X
	SUB TOTAL		\$	25,298.30
	LESS 20%		\$	5,059.66
	DISCOUNTED TOTAL		\$	20,238.64
	Front Door Comfort Logo (LH) H/C		\$	75.00 Nett ✓
	Front Windscreen Sealant H/C		\$	46.00 Nett * ✓
	Front Tyre (LH) s/c		\$	216.00 Nett X
			\$	337.00

SHC 2123E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 700/-
	Spray Painting Charge			\$ 1,400.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 44
	Transfer of Door			\$ 120.00 44
	Remove/Refix Undercarriage (FRT)			\$ 200.00 2150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 44
	Remove/Refix Engine			\$ 450.00 44
	Remove/Refix Dashboard			\$ 450.00 44 150/-
	Remove/Refix Fuse Box			\$ 180.00 44 50/-
	Remove/Refix Front Windscreen Glass			\$ 120.00 44 30/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 44
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 } 180/-
	TOTAL LABOUR			\$ 6,360.00
	ESTIMATE TOTAL			\$ 26,935.64
29/01/2019 e 1700hrs Nor Antwa 2/sum 6 days. <u>ryan</u> LKK Auto 8				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				