

ATTN:			Tehran Office - 29/01	
NO.	DESCRIPTION - PARTS		QTY	PRICE
1	FRONT FENDER LH	308 Jms	1	
2	FRONT FENDER COWLING LH	To. 2	1	
3	FRONT DOOR LH	45.6500	1	
4	FRONT DOOR WINDOW RUBBER LH	mm	1	
5	FRONT DOOR HANDLE LH	11 X	1	
6	FRONT DOOR HINGE UP AND DOWN LH	lower def.	2	
7	FRONT DOOR CHECKER LH	11 X	1	
8	FRONT DOOR REGULATOR LH	11 X	1	
9	FRONT DOOR POWER MOTOR LH	11 X	1	
10	FRONT DOOR WEATHER STRIP LH	mm	1	
11	FRONT DOOR INNER TRIM LH	mm	1	
12	FRONT DOOR SIDE MIRROR ASSY LH	cm	1	
13	FRONT DOOR INNER LOCK LH	11 X	1	
14	FRONT ABSORBER LH	11 X	1	
15	FRONT KNUCKLE LH	11 X	1	
16	FRONT KNUCKLE BEARING LH	11 X	1	
17	FRONT BEARING HUB LH	11 X	1	
18	FRONT STEERING RACK AND PINION ASSY	11 X	1	
			1	
		SUBTOTAL		\$ -
		LESS 10%		\$ -
		PARTS TOTAL		\$ -
	SPECIAL NETT		QTY	PRICE
1	FRONT FENDER COWLING CLIPS	mm 50	10	\$ 100.00
2	FRONT DOOR INNER TRIM CLIPS	mm 50	10	\$ 100.00
3	FRONT RIM LH	cng 4505.0	1	\$ 1,000.00
4	FRONT TYRE LH	su c X	1	\$ 800.00
		SPECIAL NETT TOTAL		\$ 2,000.00
	LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	500	1	\$ 800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	600	1	\$ 800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	60	1	\$ 120.00
4	TO RNR REAR FRONT DOOR MECHANISM	60	1	\$ 120.00
5	TO RNR UNDERCARRAIGE SYSTEM	11 X	1	\$ 250.00
6	TO CHECK WHEEL ALIGNMENT	60	1	\$ 150.00
7	TO DO WATER LEAK TEST .	11 X	1	\$ 120.00

	LABOUR TOTAL	\$ 2,360.00
	GRAND TOTAL COST	\$ 4,360.00

PAGE 2 OF 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification/s is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: