



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBF671H190124

Estimate

Customer	Page 01 - 02
Name: FWD Singapore Pte Ltd	Date: 28-01-19
Address: Motor Claims Department	Vehicle No: GBF671H
6 Temasek Boulevard #18-01	Model/Make: Fiat Doblo Cargo
Suntec Tower Four Singapore 038986	Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tailgate <i>20/Bent</i>	\$ 1,895.90	+
2	Tailgate "6 PAX" Sticker <i>nu</i>	\$ 12.00	SN 105.2
3	Tailgate "Green" Sticker <i>nu</i>	\$ 20.00	SN 105.2
4	Tailgate Inner Lock <i>twi 192.00</i>	\$ 382.20	+
5	Tailgate Weatherstrip <i>cu7</i>	\$ 297.00	+
6	Tailgate Glass Sealant <i>nu</i>	\$ 80.00	SN 405.2
7	Rear Lh Tailgate <i>20/Bent</i>	\$ 2,156.30	+
8	Tailgate "70 KM/H" Sticker <i>nu</i>	\$ 12.00	SN 105.2
9	Tailgate Inner Lock <i>nu</i>	\$ 275.00	x
10	Tailgate Glass Sealant <i>nu</i>	\$ 80.00	SN 405.2
11	Bumper Reflector <i>cre 65.00</i>	\$ 98.60	+
12	Number Plate and Base <i>svc</i>	\$ 48.00	SN x
13	Rear Bumper <i>20/pe 627</i>	\$ 745.00	+
14	Bumper Clips 1 set <i>nu</i>	\$ 65.00	+
15	Bumper Reinforcement <i>Bent</i>	\$ 475.30	+
16	Bumper Reverse Sensor <i>shhd</i>	\$ 220.00	SN 2005.2
17	Bumper Side Holder 02 pcs (@ \$35.60) <i>nu 102</i>	\$ 71.20	x
18	End Panel <i>nu</i>	\$ 485.00	x
19	End Panel Top Rubber <i>cu7 237</i>	\$ 347.70	+
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Remove & reinstall Tailgate 2 Glass to facilitate repairs & perform water	\$ 200.00	- 11
	Remove and refix rear reverse sensor	\$ 80.00	- 50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	- 520
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,000.00	- 800
	Remove and refix rear 2 tailgate components & wiper mechanism	\$ 180.00	- 120
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 100.00	- 80
	Remove and refix upholstery	\$ 100.00	- x nu

Total Parts & Labour of estimate for damaged vehicle \$ 10,356.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

not Authorised
2/5 \$ 6000
take ph. Appr 12/19
28/1/19
Hdy.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



M/s Liu's Brother Auto Engrg Wks

P- 60105
102
5409.45
7509.45
6007