



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Old Chin Kitchen
286 Jalan Besar Ho Tat Song Building Singapore
208949

Contact : 92365333 84691964

Code : C101894

Date in : 25/03/2019

Vehicle Num. : GBH4592R

Model : Toyota Hiace Van Turbo 5DR MT

Chassis/Eng# : JTFHT02P100243053/1KD2806098

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Front Door Side Mirror RH	1	982.40	982.40
Subtotal before discount			982.40
Percentage discount 25%			245.60
Sub-total 1			736.80
Parts-total			736.80

LABOUR

Description	Price
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	200.00
Labour Total	200.00
Parts & Labour Total	936.80

page 1

9-891.60
 252
 7-668.70
 100.00
 768.70

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
 The pro. After repair
 26/3/19
 1 day.
 768.70