

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 29 January 2019

To : LKK

By Fax: 62564315

Attn : Mr Bryan

Tel :

VEHICLE NO : FF 4887D

Yamaha RXZ

ACCIDENT DATE: 26th January 2019

Description	Qty	Quotation \$
1 Fuel Tank <i>Derish</i>	1	450.00 ✓
2 Head Lamp <i>cover broken</i>	1	390.00 ✓ ✓
3 Head Lamp Cover <i>cut</i>	1	190.00 ✓
4 Handle Bar <i>2 set</i>	1	155.00 ✓ ✓
5 RH Mirror <i>cut</i>	1	65.00 ✓
6 Head Lamp Stay <i>2 set</i>	1	125.00 ✓ ✓
7 Front Mudguard <i>cut</i>	1	155.00 ✓
8 Brake Lever <i>broken</i>	1	68.00 ✓
9 Balancer <i>cut o/s</i>	1 set	130.00 ✓
10 Fork Tube <i>2 distorted</i>	2	480.00 ✓ ✓
11 Front RH Signal <i>broken</i>	1	95.00 ✓
12 Brake Pedal <i>set</i>	1	95.00 ✓
13 Gear Shifter <i>set H-1</i>	1	80.00 X
14 Gear Pedal <i>set</i>	1	75.00 ✓
15 Exhaust Pipe <i>cut</i>	1	380.00 ✓
16 Rear Foot Rest Bracket <i>H-1</i>	1	95.00 X
17 Rear Foot Rest Rubber RH <i>broken</i>	1	60.00 ✓
18 Front Foot Rest RH <i>set</i>	1	88.00 ✓

Sub-Total 3,176.00

Less 10%

Sub-Total

317.60

2,858.40

Supplmt. Item.

Front left Hand Signal - 1 pc broken

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve damaged parts during resurvey
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification is allowed
- Supplemental form(s) must be resurveyed and is subject to removal from Insurance Cover

one

Sub-Total 3,176.00

Less 10%

Sub-Total 2,858.40

Acknowledged by Repairer

Signature: _____

Date: _____

VEHICLE NO : FF 4887D

Yamaha RXZ

Nett items

1 Towing fees	40.00 30/-
2 Remove & replace parts, align & etc	250.00 180/-
3 Remove & replace fork tube & top up fork oil seal	120.00 80/-
4 Putty, respray paint 2 tone	450.00 120/-
Sub-Total	860.00
Nett Total	3,718.40

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

30/01/2019 @ 1100 hrs

Kia Antenn

2/Sum

4 days

1 year

2 KK Antenn

8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: