



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLJ 4867 U

*Not Withain  
Penny B4 paint*

Parts (a) Cost / List Price Items	\$	7,125.81
Plus/Less 25%	\$	1,781.45
<b>Total of Cost / List</b>	<b>\$</b>	<b>5,344.36</b>
(b) Nett Price Items		
Less		
<b>Total of Nett Item</b>		
(c) <b>Special Nett Items</b>	<b>\$</b>	<b>45.00</b>
<b>Total Parts Cost</b>	<b>\$</b>	<b>5,389.36</b>
<b>Labour</b>	<b>\$</b>	<b>2,120.00</b>
<b>Total</b>	<b>\$</b>	<b>7,509.36</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Hennerth  
Company : LKK  
Survey conducted on : 28/1/19 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 28/1/19



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : **SLJ 4867 U**  
Make & Model : **TOYOTA PRIUS**  
Chassis No. : **JTDKB3FU803540046**

Submit By : **Carmen Lim**  
Year Manufacture : **2016**  
Engine No. :

## Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>B<sub>1</sub></i>	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		?
3	Bonnet <i>B<sub>1</sub></i>	1	\$812.40		✓
4	Bonnet lock <i>R</i>	1	\$130.00		X
5	Bonnet hinge LH <i>R</i>	1	\$57.80		X
6	Bonnet hinge RH <i>R</i>	1	\$57.80		X
7	Headlamp RH <i>CM</i>	1	\$2,531.60		✓
8	Front bumper <i>B<sub>1</sub></i>	1	\$450.80		✓
9	Front bumper clip <i>me</i>	10	\$40.00		✓
10	Front bumper reinforcement - upper	1	\$711.50		?
11	Front bumper reinforcement - lower	1	\$245.30		?
12	Front bumper side retainer RH <i>D<sub>1</sub></i>	1	\$107.20		✓
13	Front bumper side retainer LH <i>Sm</i>	1	\$107.20		X
14	Front bumper upper grille <i>CM</i>	1	\$321.90		✓
15	Front bumper lower grille	1	\$148.60		?
16	Front bumper emblem <i>me</i>	1	\$87.10		✓
17	Front bumper tow cover RH <i>Sm</i>	1	\$25.70		X
18	Front bumper tow cover LH <i>me</i>	1	\$25.70		✓
19	Front bumper sponge - upper	1	\$89.81		?
20	Front bumper sponge - lower	1	\$135.70		?
21	Fog lamp RH	1	\$910.70		?
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

