

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7301A

DATE 28/1/2019 14:13

MAKE :

MODEL : HYUNDAI i40

Lompau
JM
PIP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,110.10
	Radiator Grille H Emblem			\$ 39.50
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 99.20
	Front Bumper Reinforcement			\$ 402.10
	Front Bumper Bracket Top (LH/RH)		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH)		\$ 24.60	\$ 49.20
	SUB TOTAL			\$ 2,797.10
	LESS 20%			\$ 559.42
	DISCOUNTED TOTAL			\$ 2,237.68
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	TOWING			\$ 60.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 2,992.68

✓cc
✓MEC
XR
?
?
?
?
?
?
Nett ✓cc
Nett ✓cc'

200
200
✓

NA 2114K
28/1/19 1700
PIP
CHECK ITEMS (1400)
A FREE REPAIR (1400)
2 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.