

ASS. REC. BY:

REF: 08/CTI19001932/Jgd3 Special Instruction:

Survivor:

ASSIGNMENT (Office) ✓

From (Person): Irene Tay of CTI Date/Time: 29/1/19 @ 3:19pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 5206 X Insured: SKZ 2376K

at Workshop m/s World Auto Tel: 63621776

of No. 1 krunji ferop

Policy No: DMPCS N30453018000 Claim No: SNM19D200486C02

Sum Insured: Excess:

Make of Veh: D.O.A. 24/01/2019
(Client's Record) 30/1/19

CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement:

Date/Time: 4:14pm @ 29/1/19 Person Contacted: Aine Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 5206 X - X
	SKZ 2376 K - X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019		29 Jan 2019 15:19 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by Insurer\]](#)

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLJ5206X	Date of Loss:	24/01/2019 07:00 - :59
Claim Type:	TP / SNM19D200486C02	Policy/Cover Note No.:	DMPCSN30453018000
Vehicle Reg. No. (Insured):	SKZ2376K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

driver Tai-py

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 09:54
Date Of Accident	24/01/2019 07:05
Exact Location Of Accident	50 ANDERSON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ5206X
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995009
Cover Note Number	

Driver

Name of Driver	TEO AI SENG
NRIC No	S1243013B
Date Of Birth	31/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	06/12/1977
Driving Experience	41 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86994749
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 24/1/19 around 0705 hrs i Travelling
along 50 Andesson Road - when i was on
my lane Suddenly a vehicle SKZ 2376K
came out from the minor Road collided
with my vehicle on left hand side
portion

DECLARATION

I/We hereby declare foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

09.15 am
24/1/19

WORLD AUTO PTE LTD

47 Jalan Pernimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department

Contact : 6389 6111

Estimate : ES190046

Date : 24/01/2019

Vehicle Num. : SLJ 5206X (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/01/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	FRONT DOOR - LH	Repair	1,200.00 X
2.	1	REAR DOOR SUB RUBBER SEAL	DEP	188.00 /
3.	1	REAR DOOR - LH	BUC	1000 1,200.00 /
4.	1	REAR DOOR GLASS REGULATOR MOTOR LH	NN	466.00 X
5.	1	REAR DOOR HINGE LH LOWER	NN	120.00 X
6.	1	REAR DOOR HINGE LH UPPER	NN	120.00 X
7.	1	REAR DOOR CHECKER LH	NN	180.00 X
8.	1	ROCKER PANEL LH	Repair	450.00 X
9.	1	SIDE SKIRT LH	CRA	430.00 /
10.	1	REAR FENDER LH	BUC	1,100.00 /
11.	1/LH	REAR FENDER INNER TRIM BOARD	NN	350.00 X
12.	1	REAR FENDER UNDERDUST COVER LH	BUC	250.00 /
13.	1	REAR BUMPER	Repair	1,150.00 X
14.	1	REAR BUMPER RETAINER LH	NN	89.00 X
15.	1	REAR FENDER GLASS MOULDING	NEC NN	190.00 X
16.	1	REAR DOOR INNER TRIM BOARD	NN	380.00 X
17.	1	REAR FENDER AIR GRILLE LH	NN	

List TotalS\$:

7,863.00

20.00% Discount S\$:

1,572.60

6,290.40

SPECIAL NETT ITEMS :

1.	1	SIDE SKIRT CLIPS	NEC	30 40.00 /
2.	1	REAR FENDER INNER TRIM BOARD CLIPS	NN	40.00 X
3.	1	REAR FENDER UNDERDUST COVER CLIPS	NEC	30 40.00 /
4.	1	REAR WHEEL CAP LH	SCR	188.00 /
5.	1	REAR BUMPER CLIP	NN	40.00 X

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department

Contact : 6389 6111

Estimate : ES190046

Date : 24/01/2019

Vehicle Num. : SLJ 5206X (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/01/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

6.	2	FUEL LID RIVET	15.00	30.00 /
7.	1	REAR FENDER GLASS SEALANT <i>NEC</i>	30	30.00 /
8.	1	REAR DOOR INNER TRIM BOARD CLIPS <i>nn</i>		40.00 X
Special Nett Total S\$:				518.00
LABOUR :				
REMOVE & REPLACE FENDER 1/4 GLASS				80 180.00 /
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				40 180.00 /
TRANSFER DOOR MECHANISM (X2 DOORS)				50 360.00 /
LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS, INCLUDING PANEL BEAT & REPLACE ABOVE PARTS.				1000 1200 1,700.00 /
PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)				1000 1200 1,400.00 /
TO REMOVE AND REFIT FUEL TANK TO FACILITATE THE PANEL B AND CUT OUT DAMAGED PANELS.				250.00 X
COMPUTERISED ALIGNMENT				80 180.00 /
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)				200 450.00 X /
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST				120 450.00 /

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department

Contact : 6389 6111

Estimate : ES190046

Date : 24/01/2019

Vehicle Num. : SLJ 5206X (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 24/01/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES

TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS
REVERSE SENSORS AND START/STOP UNIT CAPACITORS

30 180.00 /

Labour Total S\$:

5,330.00

Total - \$5272.40

E. & O.E.

Total S\$:

12,138.40

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
1/2/19

Hue Jie - Lkk

30/1/19

P/P 6 days

Photo before paint

[Signature]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019		29 Jan 2019 15:19 Edit Adj Rpt	S\$5,272.40 Edit Estimates	S\$5,272.40 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLJ5206X	Date of Loss:	24/01/2019 07:00 - :59 [25 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200486C02	Policy/Cover Note No.:	DMPCSN30453018000
Vehicle Reg. No. (Insured):	SKZ2376K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 11/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ5206X (SNM19D200486C02)
[SKZ2376K]

TP

LCRF PTE LTD

Jan 24 2019 7:00AM

[-]

World Auto Pte Ltd - Kranji

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/19 16:35	General View	 Load JPG	☒
2	31/01/19 16:35	General View	 Load JPG	☒
3	31/01/19 16:35	General View	 Load JPG	☒
4	31/01/19 16:35	General View	 Load JPG	☒
5	31/01/19 16:35	General View	 Load JPG	☒
6	31/01/19 16:35	General View	 Load JPG	☒
7	31/01/19 16:35	General View	 Load JPG	☒
8	31/01/19 16:35	General View	 Load JPG	☒
9	31/01/19 16:35	General View	 Load JPG	☒
10	31/01/19 16:35	General View	 Load JPG	☒
11	31/01/19 16:35	General View	 Load JPG	☒
12	31/01/19 16:35	General View	 Load JPG	☒
13	31/01/19 16:35	General View	 Load JPG	☒
14	31/01/19 16:35	General View	 Load JPG	☒
15	31/01/19 16:35	General View	 Load JPG	☒
16	31/01/19 16:35	General View	 Load JPG	☒
17	31/01/19 16:35	General View	 Load JPG	☒
18	31/01/19 16:35	General View	 Load JPG	☒
19	31/01/19 16:35	General View	 Load JPG	☒
20	31/01/19 16:35	General View	 Load JPG	☒
21	31/01/19 16:35	General View	 Load JPG	☒
22	31/01/19 16:35	General View	 Load JPG	☒
23	31/01/19 16:35	General View	 Load JPG	☒
24	31/01/19 16:35	General View	 Load JPG	☒
25	31/01/19 16:35	General View	 Load JPG	☒
26	31/01/19 16:35	General View	 Load JPG	☒
27	31/01/19 16:35	General View	 Load JPG	☒
28	31/01/19 16:35	General View	 Load JPG	☒
29	31/01/19 16:35	General View	 Load JPG	☒
30	31/01/19 16:35	General View	 Load JPG	☒
31	31/01/19 16:35	General View	 Load JPG	☒
32	05/03/19 10:42	Replacement Part Photo	 Load JPG	☒
33	05/03/19 10:42	Replacement Part Photo	 Load JPG	☒
34	05/03/19 10:42	Replacement Part Photo	 Load JPG	☒
35	05/03/19 10:42	Replacement Part Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19001932/JQD3S2

Date: 12/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30453018000
Claimant Vehicle No:	SLJ5206X	Insured Vehicle No:	SKZ2376K
Date of Loss:	24/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200486C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ5206X	Engine No:	LEB4265211
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71045112
Reg. Date:	14/12/2016 (Man. Year: 2016)	Odometer:	187048 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,808.40	2,672.40	4,136.00	60.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,330.00	2,600.00	2,730.00	51.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,138.40	5,272.40	6,866.00	56.56
+ GST 7.00/7.00% (S\$)	849.69	369.07	480.62	56.56
Nett Amount (S\$)	12,988.09	5,641.47	7,346.62	56.56

INSPECTION

Date of Assignment:	29/01/2019		
Date Inspected:	30/01/2019	Inspected At:	World Auto Pte Ltd No 1 Kranji Loop Singapore 739535
Estimated Period of Repair:	6.0 days		

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Mar 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ5206X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Repair	1,200.00 FL	*- FL
2	1		*REAR DOOR SUB RUBBER SEAL	Deformed	188.00 FL	*188.00 FL
3	1		*REAR DOOR - LH	Buckled	1,200.00 FL	*1,000.00 FL
4	1		*REAR DOOR GLASS REGULATOR MOTOR LH	Not Necessary	466.00 FL	*- FL
5	1		*REAR DOOR HINGE LH LOWER	Not Necessary	120.00 FL	*- FL
6	1		*REAR DOOR HINGE LH UPPER	Not Necessary	120.00 FL	*- FL
7	1		*REAR DOOR CHECKER LH	Not Necessary	180.00 FL	*- FL
8	1		*ROCKER PANEL LH	Repair	450.00 FL	*- FL
9	1		*SIDE SKIRT LH	Cracked	430.00 FL	*430.00 FL
10	1		*REAR FENDER LH	Buckled	1,100.00 FL	*1,100.00 FL
11	1		*LH REAR FENDER INNER TRIM BOARD	Not Necessary	350.00 FL	*- FL
12	1		*REAR FENDER UNDERDUCT COVER LH	Buckled	250.00 FL	*250.00 FL
13	1		*REAR BUMPER	Repair	1,150.00 FL	*- FL
14	1		*REAR BUMPER RETAINER LH	Not Necessary	89.00 FL	*- FL
15	1		*REAR FENDER GLASS MOULDING	Not Necessary	190.00 FL	*- FL
16	1		*REAR DOOR INNER TRIM BOARD	Not Necessary	380.00 FL	*- FL
17	1		*REAR FENDER AIR GRILLE LH (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*SIDE SKIRT CLIPS	Necessary	40.00 FS	*30.00 FS
19	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
20	1		*REAR FENDER UNDERDUST COVER CLIPS	Necessary	40.00 FS	*30.00 FS
21	1		*REAR WHEEL CAP LH	Scratched	188.00 FS	*188.00 FS
22	1		*REAR BUMPER CLIP	Not Necessary	40.00 FS	*- FS
23	2		*FUEL LID RIVET	Necessary	30.00 FS	*20.00 FS
24	1		*REAR FENDER GLASS SEALANT	Necessary	100.00 FS	*30.00 FS
25	1		*REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,381.00	3,266.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,572.60	593.60
Total Parts (S\$)	6,808.40	2,672.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE FENDER 1/4 GLASS.	New	180.00	80.00
2	TO APPLY RUSTPROOFING / TUFF COATING TREATMENT TO REPLACED PARTS.	New	180.00	40.00
3	TRANSFER DOOR MECHANISM.	New	360.00	50.00
4	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS, INCLUDING PANEL BEAT & REPLACE ABOVE PARTS.	New	1,700.00	1,000.00
5	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER / OUTER)	New	1,400.00	1,000.00
6	TO REMOVE AND REFIT FUEL TANK TO FACILITATE THE PANEL B AND CUT OUT DAMAGED PANELS.	New	250.00	0.00
7	COMPUTERISED ALIGNMENT.	New	180.00	80.00
8	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIR AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	200.00
9	PERFORM WHOLE VEHICLE DIAGNOSTIC INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIR. (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	120.00
10	TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND STARTS / STOP UNIT CAPACITORS.	New	180.00	30.00
Gross Labour Cost (S\$)			5,330.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >